





report date: 2024-03-29

### General information

Make	FORD
Model	FUSION FUSION 2
Colour	Black
Year of manufacture	2005
Top speed	101 mph
0 - 60 mph	13.7 seconds
Gearbox	5 speed Manual

### Engine & fuel consumption

Power	79 BHP
Max. torque	124 Nm at 3.500 rpm
Engine capacity	1.388 сс
Cylinders	4
Fuel type	Petrol
Consumption city	32.1 mpg
Consumption extra urban	52.3 mpg
Consumption combined	42.2 mpg
CO2 emission	155 g/km
CO2 label	G



CarCheck.co.uk page 1/14




Internet history

Entry 1

Date 2021-10-14

Pictures 14

Listing price <u>View report</u>









source: autotrader.co.uk

CarCheck.co.uk page 2/14



MOT history

MOT expiry date	2024-03-03
MOT pass rate	73 %
MOT passed	16
Failed MOT tests	6
Total advice items	15
Total items failed	15

MOT #22		2023-03-02 09:37
MOT test	number	434334269945
Result		✓ Passed
Next expi	ry date	2024-03-03
Advice	Offside Front Inner Tyre worn close to legal limit/worn on edge (5.2.3 (e))	
Advice	Nearside Front Inner Tyre worn close to legal limit/worn on edge (5.2.3 (e))	

IOT #21		2023-03-02 09:37
IOT test number		841569366521
esult		🗙 Failed
Pass with rectification	Offside Front Position lamp not working (4.2.1 (a) (ii))	
Advice Offside Front Inn	er Tyre worn close to legal limit/worn on edge (5.2.3 (e))	
Pass with rectification	Nearside Front Position lamp not working (4.2.1 (a) (ii))	
Advice Nearside Front II	nner Tyre worn close to legal limit/worn on edge (5.2.3 (e))	
Pass with rectification	Offside Rear Stop lamp(s) not working (4.3.1 (a) (ii))	
Pass with rectification	Offside Front Outer Drive shaft joint constant velocity boot	split or insecure, no

MOT #20	2022-03-04 15:47
MOT test number	869732620966
Result	✓ Passed

CarCheck.co.uk page 3/14



report date: 2024-03-29

× Failed

**MOT #19** 2022-03-02 14:00

**MOT test number** 215242608059

Result

**Fail** Offside Stop lamp(s) adversely affected by the operation of another lamp Bulb not fitted correctly (4.3.3 (b))

Fail Offside Rear Brake pipe excessively corroded (1.1.11 (c))

**Fail** Offside Rear fog lamp not working (4.5.1 (a) (ii))

**Fail** Offside Outer Drive shaft joint constant velocity boot split or insecure, no longer prevents the ingress of dirt Split (6.1.7 (g) (ii))

Advice Offside Brake pipe corroded, covered in grease or other material Centre to rear (1.1.11 (c))

MOT #18 2021-03-03 13:09

**MOT test number** 247159821865

Result \rightarrow Passed

**MOT #17** 2020-02-11 09:08

**MOT test number** 592535266296

**Result** ✓ Passed

**MOT #16** 2020-02-10 12:02

MOT test number 126878094407

Result × Failed

Fail Registration plate lamp inoperative in the case of a single lamp or all lamps (4.7.1 (b) (ii))

**Fail** Rear Exhaust system insecure (6.1.2 (a))

**Fail** Offside Front Drive shaft joint constant velocity boot split or insecure, no longer prevents the ingress of dirt (6.1.7 (g) (ii))

Fail Nearside Front Position lamp not working (4.2.1 (a) (ii))

**MOT #15** 2019-02-15 10:17

**MOT test number** 257324516759

**Result** ✓ Passed

CarCheck.co.uk page 4/14



**Advice** 

**BD55VYO** 

report date: 2024-03-29

MOT #14		2018-02-19 12:19
MOT test number		437738128555
Result		✓ Passed
MOT #13		2018-02-19 12:19
MOT test number		318132127648
Result		<b>X</b> Failed
Pass with rectification	Registration plate lamp not working (1.1.C.1d)	

MOT #12	2017-03-20 08:38
MOT test number	282791893557
Result	✓ Passed
MOT #11	2016-06-30 08:05
MOT test number	397354560785
Result	✓ Passed
MOT #10	2015-06-22 10:32
MOT test number	517013175156
Result	✓ Passed
Advice Offside Front Direction indicator slightly discoloured (1.4.A.2f)	

MOT #9	2014-07-03 09:47
MOT test number	197964584148
Result	✓ Passed
Advice Offside Front Shock absorber has a light misting of oil (2.7.3)	

Nearside Front Direction indicator slightly discoloured (1.4.A.2f)

CarCheck.co.uk page 5/14



report date: 2024-03-29

MOT test number

Result

Advice Offside Front Tyre worn close to the legal limit (4.1.E.1)

Advice Nearside Front Tyre worn close to the legal limit (4.1.E.1)

MOT #7

MOT test number

637349563145

Result

Fail Nearside Front coil spring incomplete (2.4.C.1a)

Advice Nearside Front Tyre worn close to the legal limit (4.1.E.1)

MOT #6

MOT test number

Result

Advice Front Brake pad(s) wearing thin (3.5.1g)

MOT test number

Result

Advice Front Brake pad(s) wearing thin (3.5.1g)

Fail Nearside Rear Tyre tread depth below requirements of 1.6mm (4.1.E.1)

 MOT #4
 2011-06-24 09:28

 MOT test number
 987765271112

 Result
 ✓ Passed

CarCheck.co.uk page 6/14



report date: 2024-03-29

MOT #3 2010-06-23 09:08

**MOT test number** 464134370196

MOT #2 2009-05-21 15:01

MOT test number 102421549136

**Result** 
✓ Passed

**Advice** Nearside Front Tyre worn close to the legal limit (4.1.E.1)

MOT #1 2008-05-28 14:22

**MOT test number** 203219348473

**Advice** Rear Exhaust has a minor leak of exhaust gases (7.1.2)

CarCheck.co.uk page 7/14



### Tax & MOT check



X MOT

Expired: 3 March 2024

Tax status	Expired at 1 October 2023
Days left	212 days too late
MOT expiry date	3 March 2024
Full MOT history	See MOT history

### Tax calculation

Vehicle class	48
Band	G
Single payment (12 months)	£ 240,00,-
Single six month payment	£ 132,00,-
Total payable by 12 monthly instalments	£ 252,00,-

CarCheck.co.uk page 8/14



report date: 2024-03-29

### Damage history

Check the damage history for this FORD. See if, where and when this FORD had damage and the car repair costs. We also check if this FORD was scrapped. Download the premium report <u>here</u> for the results.

Damage 1
Date
Category
Type
Damage 2
Date
Category
Type



#### Extra FORD salvage check



If this vehicle was seen at a salvage auction we offer: vehicle pictures, salvage location, retail value. Download the premium report <u>here</u> for more information.

More info >

CarCheck.co.uk page 9/14



Vehicle valuation

What is this car worth? See the vehicle value of this FORD in the premium report. We check: purchase value, age, mileage, MOT history, damages and online sale prices.

**Trade retail value** 

**Auction value** 

Average private trade value

More info >

CarCheck.co.uk page 10/14



# Owner history

For how long did the current and previous owner(s) have this FORD? How many owners of Check it in the premium report and see all owner registrations. Download the full report is	
***************************************	
***************************************	
	More info >
Plate changes	
See in this check if this FORD had different number plates.	
Number of plates	
Current registration	UK UK
Plate since	
Current registration	OK SIE
Plate since	
	More info >

CarCheck.co.uk page 11/14



Finance check

Check if this FORD is financed, has an outstanding loan or finance agreement. If you are purchasing a vehicle it is smart to ensure that any finance that may have been taken out on this FORD has been settled.

If not, and you buy this FORD then you could lose the money and the car you paid for.

Download the premium report <u>here</u> and check if this FORD is financed.

Finance company	
Date of agreement	
Agreement type	
Agreement term	
Agreement number	
Contact info	


More info >

CarCheck.co.uk page 12/14



Mileage check

Odometer	In miles
Mileage registrations	24
First mileage registration	2005-12-07
Last registration	2023-03-02
Complete history	See info



Registration #1	2005-12-07	27 mi
Registration #2	2008-05-28	12.602 mi
Registration #3	2009-05-21	17.673 mi
Registration #4	2010-06-23	20.683 mi
Registration #5	2011-06-24	28.136 mi
Registration #6	2012-06-25	35.153 mi
Registration #7	2012-06-25	35.153 mi
Registration #8	2013-06-18	41.037 mi
Registration #9	2013-06-18	41.037 mi
Registration #10	2014-07-03	47.192 mi
Registration #11	2015-06-22	53.612 mi
Registration #12	2016-06-30	60.144 mi
Registration #13		11.777 es
Registration #14		11.777 es
Registration #15		11.277 mi
Registration #16		11.777 es
Registration #17		11.777 es
Registration #18		11.777 es
Registration #19		11.777 es
Registration #20		11.177 es
Registration #21		11.777 es
Registration #22		11.177 es
Registration #23		11.777 es
Registration #24		77,777 44

More info >



## Car features

S0225	Air conditioning
S0295	
50482	
S0501	
S0566	
S0567	
S0569	

# Safety ratings

NCAP rating	****
Video	see crash video



# Dimensions & weight

Width	1952 mm
Height	1534 mm
Length	4020 mm
Wheel base	2485 mm
Kerb weight	1082 kg
Max. allowed weight	1605 kg

# Additional information

Fuel tank capacity	45 I
Fuel delivery	Multi-Point Injection
Number of doors	5
Number of seats CarCheck.co.uk	5 page 14/: