



report date: 2024-03-28

## General information

Make	VOLVO
Model	S80 D5 SE
Colour	Blue
Year of manufacture	2008
Top speed	143 mph
0 - 60 mph	8.0 seconds
Gearbox	6 speed Manual

## Engine & fuel consumption

Power	182 BHP
Max. torque	400 Nm at 2.000 rpm
Engine capacity	2.401 cc
Cylinders	5
Fuel type	Diesel
Consumption city	32.1 mpg
Consumption extra urban	56.5 mpg
Consumption combined	44.1 mpg
CO2 emission	169 g/km
CO2 label	H





Internet history

Entry 2

Date	2022-03-02
Pictures	20
Listing price	<a href="#">View report</a>



source: [autotrader.co.uk](https://www.autotrader.co.uk)

Entry 1

Date	2021-12-03
Pictures	20
Listing price	<a href="#">View report</a>



source: [autotrader.co.uk](https://www.autotrader.co.uk)



MOT history

MOT expiry date	2024-03-24
MOT pass rate	79 %
MOT passed	11
Failed MOT tests	3
Total advice items	19
Total items failed	8

MOT #14	2023-03-25 13:10
MOT test number	583250086924
Result	✓ Passed
Next expiry date	2024-03-24
Advice	Rear Sub-frame corroded but not seriously weakened (5.3.3 (b) (i))
Advice	Nearside Front Track rod end ball joint has slight play (2.1.3 (b) (i))
Advice	Offside Front Tyre worn close to legal limit/worn on edge (5.2.3 (e))
Advice	Rear Coil spring corroded both (5.3.1 (b) (i))

MOT #13	2023-03-25 11:26
MOT test number	927649088050
Result	✗ Failed
Advice	Rear Coil spring corroded both (5.3.1 (b) (i))
Fail	Engine MIL inoperative or indicates a malfunction (8.2.1.2 (h))
Advice	Rear Sub-frame corroded but not seriously weakened (5.3.3 (b) (i))
Advice	Offside Front Tyre worn close to legal limit/worn on edge (5.2.3 (e))
Advice	Nearside Front Track rod end ball joint has slight play (2.1.3 (b) (i))

**MOT #12** 2022-01-20 15:41**MOT test number** 400968979554**Result** ✓ Passed**Advice** Rear Coil spring corroded (5.3.1 (b) (i))**MOT #11** 2022-01-11 17:48**MOT test number** 401839823594**Result** ✗ Failed**Fail** Rear Registration plate lamp inoperative in the case of a single lamp or all lamps (4.7.1 (b) (ii))**Fail** Offside Front Suspension arm pin or bush excessively worn (5.3.4 (a) (i))**Fail** Offside Front Wheel bearing rough when rotated (5.1.3 (b) (i))**Advice** Rear Coil spring corroded (5.3.1 (b) (i))**MOT #10** 2020-12-01 13:11**MOT test number** 742115547349**Result** ✓ Passed**Advice** Rear Brake pad(s) wearing thin Both sides (1.1.13 (a) (ii))**Advice** Front Brake pad(s) wearing thin Both sides (1.1.13 (a) (ii))**MOT #9** 2019-05-22 11:36**MOT test number** 471140246209**Result** ✓ Passed**Advice** Front Brake pad(s) wearing thin (1.1.13 (a) (ii))**Advice** Offside Rear Inner Tyre worn close to legal limit/worn on edge (5.2.3 (e))**MOT #8** 2018-05-19 11:23**MOT test number** 613451000695**Result** ✓ Passed

**MOT #7** 2017-05-25 10:38**MOT test number** 408257844422**Result** ✓ Passed**MOT #6** 2015-12-07 13:02**MOT test number** 225126175014**Result** ✓ Passed**MOT #5** 2014-11-19 16:24**MOT test number** 876063724391**Result** ✓ Passed**MOT #4** 2013-12-13 16:09**MOT test number** 166517643317**Result** ✓ Passed**Advice** Offside Rear Shock absorber has a light misting of oil (2.7.3)**Advice** Front Brake pad(s) wearing thin (3.5.1g)**MOT #3** 2012-11-21 16:51**MOT test number** 395576922310**Result** ✓ Passed



MOT #2 2012-11-21 10:06

MOT test number 635616222339

Result		✗ Failed
Advice	Nearside Rear Tyre worn close to the legal limit (4.1.E.1)	
Fail	Front registration plate character(s) incorrectly spaced (6.3.4a)	
Fail	Offside Rear Tyre has a lump, caused by separation or partial failure of its structure (4.1.D.1b)	
Advice	Offside Front Tyre worn close to the legal limit (4.1.E.1)	
Fail	Rear Brake pad(s) less than 1.5 mm thick (3.5.1g)	
Fail	Rear registration plate character(s) incorrectly spaced (6.3.4a)	
Advice	Nearside Front Tyre worn close to the legal limit (4.1.E.1)	

MOT #1 2011-11-25 09:14

MOT test number 219609021321

Result		✓ Passed
--------	--	----------



Tax & MOT check

✓  
**Taxed**  
  
Tax due:  
1 March 2025

✗  
**MOT**  
  
Expired:  
24 March 2024

Tax status	Valid until 1 March
Days left	307
MOT expiry date	24 March 2024
Full MOT history	<a href="#">See MOT history</a>

Tax calculation

Vehicle class	49
Band	H
Single payment (12 months)	£ 290,00,-
Single six month payment	£ 159,50,-
Total payable by 12 monthly instalments	£ 304,50,-



Damage history

Check the damage history for this VOLVO. See if, where and when this VOLVO had damage and the car repair costs. We also check if this VOLVO was scrapped. Download the premium report [here](#) for the results.

Damage 1

Date	
Category	
Type	

Damage 2

Date	
Category	
Type	



Extra VOLVO salvage check



If this vehicle was seen at a salvage auction we offer: vehicle pictures, salvage location, retail value. Download the premium report [here](#) for more information.

More info >





Vehicle valuation

What is this car worth? See the vehicle value of this VOLVO in the premium report. We check: purchase value, age, mileage, MOT history, damages and online sale prices.

Trade retail value	£ 19,299
Auction value	£ 19,299
Average private trade value	£ 19,299

More info >



Owner history

For how long did the current and previous owner(s) have this VOLVO? How many owners did this VOLVO have? Check it in the premium report and see all owner registrations. Download the full report [here](#).

Owner	Start date
Owner	Start date
Owner	Start date
Owner	Start date
Owner	Start date
Owner	Start date
Owner	Start date

More info >

Plate changes

See in this check if this VOLVO had different number plates.

Number of plates	1
Current registration	<b>XXXXXX</b>
Plate since	2024-03-28
Current registration	<b>XXXXXX</b>
Plate since	2024-03-28

More info >



Finance check

Check if this VOLVO is financed, has an outstanding loan or finance agreement. If you are purchasing a vehicle it is smart to ensure that any finance that may have been taken out on this VOLVO has been settled.

If not, and you buy this VOLVO then you could lose the money and the car you paid for.

Download the premium report [here](#) and check if this VOLVO is financed.

Finance company	XXXXXXXXXX	XXXX
Date of agreement	XXXXXXXXXX	XXXX
Agreement type	XXXXXXXXXX	XXXX
Agreement term	XXXXXXXXXX	XXXX
Agreement number	XXXXXXXXXX	XXXX
Contact info	XXXXXXXXXX	XXXX

More info >



Mileage check

Odometer	In miles
Mileage registrations	17
First mileage registration	2008-11-27
Last registration	2023-03-25
Complete history	<a href="#">See info</a>



Registration #1	2008-11-27	7 mi
Registration #2	2011-11-25	52.412 mi
Registration #3	2012-11-21	79.442 mi
Registration #4	2012-11-21	79.442 mi
Registration #5	2013-12-13	103.100 mi
Registration #6	2014-11-19	114.662 mi
Registration #7	2015-12-07	126.367 mi
Registration #8	2017-05-25	142.121 mi
Registration #9	2018-05-19	155.467 mi
Registration #10	2019-05-20	155.467 mi
Registration #11	2019-05-20	155.467 mi
Registration #12	2019-05-20	155.467 mi
Registration #13	2019-05-20	155.467 mi
Registration #14	2019-05-20	155.467 mi
Registration #15	2019-05-20	155.467 mi
Registration #16	2019-05-20	155.467 mi
Registration #17	2019-05-20	155.467 mi

More info >



Car features

The VOLVO factory car options list is only available in the premium report.

S0225	Air conditioning
S0295	
S0482	
S0501	
S0566	
S0567	
S0569	

View the complete VOLVO factory list for this vehicle [here](#).

More info >

Safety ratings

NCAP rating

Video [see crash video](#)



Dimensions & weight

Width	1861 mm
Height	1490 mm
Length	4851 mm
Wheel base	2835 mm
Kerb weight	1570 kg
Max. allowed weight	2190 kg

Additional information

Fuel tank capacity	70 l
Fuel delivery	Direct Injection
Number of doors	4
Number of seats	5

<b>Number of axles</b>	2
<b>Engine number</b>	587270