



report date: 2024-03-28

General information

Make	FIAT
Model	PUNTO ACTIVE SPORT
Colour	Grey
Year of manufacture	2007
Top speed	103 mph
0 - 60 mph	13.2 seconds
Gearbox	5 speed Manual

Engine & fuel consumption

Power	76 BHP
Max. torque	115 Nm at 3.000 rpm
Engine capacity	1.368 cc
Cylinders	4
Fuel type	Petrol
Consumption city	36.7 mpg
Consumption extra urban	54.3 mpg
Consumption combined	46.3 mpg
CO2 emission	139 g/km
CO2 label	E





Internet history

Entry 2

Date	2021-06-15
Pictures	12
Listing price	View report



source: [autotrader.co.uk](#)

Entry 1

Date	2021-05-24
Pictures	12
Listing price	View report



source: [autotrader.co.uk](#)

**MOT history**

MOT expiry date	2025-01-07
MOT pass rate	70 %
MOT passed	14
Failed MOT tests	6
Total advice items	27
Total items failed	9

MOT #20 2024-01-03 12:08**MOT test number** 935063321709**Result** Passed**Next expiry date** 2025-01-07

- Advice** Coil spring corroded (5.3.1 (b) (i))
- Advice** Oil leak, but not excessive (8.4.1 (a) (i))
- Minor** Front Headlamp lens slightly defective (4.1.1 (b) (i))

MOT #19 2023-01-03 10:23**MOT test number** 923150360175**Result** Passed

- Advice** Offside Front Headlamp has a product on the lens but not seriously reducing light output (4.1.4 (b))
- Advice** Child Seat fitted not allowing full inspection of adult belt
- Advice** Nearside Front Headlamp has a product on the lens but not seriously reducing light output (4.1.4 (b))
- Advice** Oil leak, but not excessive (8.4.1 (a) (i))
- Advice** Sump plug has slight crack

MOT #18 2022-01-07 12:21**MOT test number** 561242675473**Result** Passed

**MOT #17** 2021-01-08 16:06**MOT test number** 441894291826**Result** ✓ Passed**Advice** Front Exhaust has a minor leak of exhaust gases (6.1.2 (a))**MOT #16** 2021-01-05 12:36**MOT test number** 403451966394**Result** ✗ Failed**Advice** Front Exhaust has a minor leak of exhaust gases (6.1.2 (a))**Fail** Parking brake efficiency below requirements (1.4.2 (a) (i))**MOT #15** 2019-11-23 12:32**MOT test number** 627616452296**Result** ✓ Passed**MOT #14** 2018-09-25 07:22**MOT test number** 599376641480**Result** ✓ Passed**Advice** Oil leak, but not excessive (8.4.1 (a) (i))**Advice** Front Exhaust has a minor leak of exhaust gases flexi (6.1.2 (a))**MOT #13** 2018-09-25 07:22**MOT test number** 728495255739**Result** ✗ Failed**Pass with rectification** Offside Stop lamp(s) not working (4.3.1 (a) (ii))**Advice** Front Exhaust has a minor leak of exhaust gases flexi (6.1.2 (a))**Advice** Oil leak, but not excessive (8.4.1 (a) (i))

**MOT #12** 2017-09-30 08:00**MOT test number** 433833859031**Result** ✓ Passed**MOT #11** 2017-09-29 09:16**MOT test number** 237884573188**Result** ✗ Failed**Advice** Nearside Rear coil spring corroded (2.4.C.1b)**Advice** Nearside Rear Tyre worn close to the legal limit (4.1.E.1)**Fail** Offside Front Anti-roll bar linkage ball joint dust cover excessively damaged so that it no longer prevents the ingress of dirt (2.4.G.2)**Advice** Offside Rear coil spring corroded (2.4.C.1b)**Advice** Offside Rear tyre perishing inner and outer walls**MOT #10** 2016-09-20 12:45**MOT test number** 626303809971**Result** ✓ Passed**Advice** Nearside Front Anti-roll bar linkage has slight play in a ball joint (2.4.G.2)**MOT #9** 2015-10-05 15:52**MOT test number** 884329299237**Result** ✓ Passed**Advice** Offside Front Tyre worn close to the legal limit (4.1.E.1)**Advice** Nearside Front Tyre worn close to the legal limit (4.1.E.1)**MOT #8** 2014-07-01 10:14**MOT test number** 237102484432**Result** ✓ Passed

**MOT #7** 2014-06-28 12:02**MOT test number** 307939874110**Result** ✗ Failed**Fail** Nearside Front position lamp(s) not working (1.1.A.3b)**Fail** Front Brake pad(s) less than 1.5 mm thick (3.5.1g)**MOT #6** 2013-07-05 12:38**MOT test number** 416736483161**Result** ✓ Passed**Notice** Items removed from driver's view prior to test**Advice** Front Brake pad(s) wearing thin (3.5.1g)**Notice** Play in steering rack inner joint(s)**MOT #5** 2013-06-28 10:41**MOT test number** 269839973170**Result** ✗ Failed**Fail** Nearside Registration plate lamp not working (1.1.C.1d)**Advice** Front Brake pad(s) wearing thin (3.5.1g)**Notice** Items removed from driver's view prior to test**Fail** Nearside Front coil spring broken (2.4.C.1a)**Notice** Play in steering rack inner joint(s)**MOT #4** 2012-06-14 12:15**MOT test number** 858776762127**Result** ✓ Passed



MOT #3	2011-06-06 16:23
MOT test number	425627251185
Result	✓ Passed

MOT #2	2011-06-02 12:08
MOT test number	149203251128
Result	✗ Failed
Fail	Nearside Front Tyre tread depth below requirements of 1.6mm (4.1.E.1)
Fail	Offside Obligatory mirror seriously damaged, affecting the rear view (8.1.2a)

MOT #1	2010-06-03 14:50
MOT test number	574694050189
Result	✓ Passed



Tax & MOT check

✓
Taxed
Tax due:
1 July 2024

✓
MOT
Expires:
7 January 2025

Tax status	Valid until 1 July
Days left	63
MOT expiry date	7 January 2025
Full MOT history	See MOT history

Tax calculation

Vehicle class	48
Band	E
Single payment (12 months)	£ 180,00,-
Single six month payment	£ 99,00,-
Total payable by 12 monthly instalments	£ 189,00,-



Damage history

Check the damage history for this FIAT. See if, where and when this FIAT had damage and the car repair costs. We also check if this FIAT was scrapped. Download the premium report [here](#) for the results.

Damage 1

Date	
Category	
Type	

Damage 2

Date	
Category	
Type	



Extra FIAT salvage check



If this vehicle was seen at a salvage auction we offer: vehicle pictures, salvage location, retail value. Download the premium report [here](#) for more information.

More info >



Vehicle valuation

What is this car worth? See the vehicle value of this FIAT in the premium report. We check: purchase value, age, mileage, MOT history, damages and online sale prices.

Trade retail value	£ 19,999
Auction value	£ 19,999
Average private trade value	£ 19,999

More info >



Owner history

For how long did the current and previous owner(s) have this FIAT? How many owners did this FIAT have? Check it in the premium report and see all owner registrations. Download the full report [here](#).

Owner	Since
Owner	Since
Owner	Since
Owner	Since
Owner	Since
Owner	Since
Owner	Since

More info >

Plate changes

See in this check if this FIAT had different number plates.

Number of plates	1
Current registration	
Plate since	2024-03-28
Current registration	
Plate since	2024-03-28

More info >



Finance check

Check if this FIAT is financed, has an outstanding loan or finance agreement. If you are purchasing a vehicle it is smart to ensure that any finance that may have been taken out on this FIAT has been settled.

If not, and you buy this FIAT then you could lose the money and the car you paid for.

Download the premium report [here](#) and check if this FIAT is financed.

Finance company	XXXXXXXX	XXXX
Date of agreement	XXXXXXXX	XXXX
Agreement type	XXXXXXXX	XXXX
Agreement term	XXXXXXXX	XXXX
Agreement number	XXXXXXXX	XXXX
Contact info	XXXXXXXX	XXXX

More info >



Mileage check

Odometer	In miles
Mileage registrations	23
First mileage registration	2007-05-30
Last registration	2024-01-03
Complete history	See info



Registration #1	2007-05-30	22 mi
Registration #2	2010-06-03	22.092 mi
Registration #3	2011-06-02	31.924 mi
Registration #4	2011-06-06	32.148 mi
Registration #5	2012-06-14	37.074 mi
Registration #6	2013-06-28	42.988 mi
Registration #7	2013-07-05	43.006 mi
Registration #8	2014-06-28	46.223 mi
Registration #9	2014-07-01	46.228 mi
Registration #10	2015-10-05	51.038 mi
Registration #11	2016-09-20	56.183 mi
Registration #12	2017-09-29	59.941 mi
Registration #13	2018-05-29	65.277 mi
Registration #14	2019-05-29	70.277 mi
Registration #15	2020-05-29	75.277 mi
Registration #16	2021-05-29	80.277 mi
Registration #17	2022-05-29	85.277 mi
Registration #18	2023-05-29	90.277 mi
Registration #19	2024-01-03	95.277 mi
Registration #20		
Registration #21		
Registration #22		
Registration #23		

More info >



Car features

The FIAT factory car options list is only available in the premium report.

S0225	Air conditioning
S0295	
S0482	
S0501	
S0566	
S0567	
S0569	

View the complete FIAT factory list for this vehicle [here](#).

More info >

Safety ratings

NCAP rating	★★★★★
Video	see crash video



Dimensions & weight

Width	1687 mm
Height	1490 mm
Length	4030 mm
Wheel base	2510 mm
Kerb weight	1025 kg
Max. allowed weight	1585 kg

Additional information

Fuel tank capacity	45 l
Fuel delivery	Multi-Point Injection
Number of doors	3
Number of seats	5

Number of axles	2
Engine number	4087547