





report date: 2024-03-28

General information

Make	VOLKSWAGEN
Model	BEETLE LUNA 8V
Colour	Blue
Year of manufacture	-
Top speed	111 mph
0 - 60 mph	11.6 seconds
Gearbox	5 speed Manual

Engine & fuel consumption

Power	102 BHP
Max. torque	147 Nm at 3.800 rpm
Cylinders	4
Fuel type	Petrol
Consumption city	26.9 mpg
Consumption extra urban	47.1 mpg
Consumption combined	36.7 mpg



CarCheck.co.uk page 1/12



report date: 2024-03-28

Internet history

Entry 1

Date 2022-08-03


Pictures 7

Listing price <u>View report</u>









source: cargurus.co.uk

CarCheck.co.uk page 2/12



report date: 2024-03-28

MOT history

Advice

Advice

MOT #15 2023-08-31 09:06 **MOT** test number 614586798002 Result × Failed **Advice** Offside Rear Tyre worn close to legal limit/worn on edge (5.2.3 (e)) Fail Exhaust Lambda reading after 2nd fast idle outside specified limits (8.2.1.2 (c)) Fail Exhaust carbon monoxide content after 2nd fast idle exceeds manufacturer's specified limits (8.2.1.2 (a)) Offside Play in steering rack inner joint(s) **Advice** Nearside Track rod end ball joint dust cover excessively damaged or deteriorated so that it no longer Fail prevents the ingress of dirt (2.1.3 (g) (ii)) Front Service brake fluctuating, but not excessively (1.2.1 (e)) **Advice** Fail Nearside Front passenger door likely to open inadvertently or not remain closed (6.2.3 (b) (ii)) Fail Nearside Side repeater not working (4.4.1 (a) (ii)) Fail Exhaust hydrocarbon content after 2nd fast idle exceeds manufacturer's specified limits (8.2.1.2 (a)) **Advice** Exhaust emits blue smoke during acceleration (8.2.1.2 (g))

MOT #14	2022-08-16 08:54
MOT test number	178389960584

Offside Front Service brake binding but not excessively (1.2.1 (f))

Stop lamp(s) non-obligatory stop lamp not working (4.3.1 (a) (ii))

Result ✓ Passed

Advice Slightly blue smoke intermittently for exhaust

CarCheck.co.uk page 3/12



report date: 2024-03-28

MOT #13 2022-08-16 08:54

MOT test number 741919414747

Result X Failed

Pass with rectification Nearside Front Position lamp not working (4.2.1 (a) (ii))

Pass with rectification Nearside Headlamp not working on main beam (4.1.1 (a) (ii))

Advice Slightly blue smoke intermittently for exhaust

Pass with rectification Nearside Headlamp not working on dipped beam (4.1.1 (a) (ii))

MOT #12 2021-05-20 09:58

MOT test number 534871096663

Result \square Passed

Minor Nearside Track rod end ball joint dust cover damaged or deteriorated, but preventing the ingress of dirt (2.1.3 (g) (i))

Advice Nearside Macpherson strut pin or bush worn but not resulting in excessive movement (5.3.4 (a) (i))

Minor Front Windscreen damaged but not adversely affecting driver's view (3.2 (a) (i))

Minor Offside Track rod end ball joint dust cover damaged or deteriorated, but preventing the ingress of dirt (2.1.3 (g) (i))

Advice Offside Macpherson strut pin or bush worn but not resulting in excessive movement (5.3.4 (a) (i))

Advice Rear Brake pad(s) wearing thin (1.1.13 (a) (ii))

MOT #11 2020-04-20 10:53

MOT test number 867918577031

MOT #10 2019-04-05 07:46

MOT test number 938061362318

Result
✓ Passed

CarCheck.co.uk page 4/12



report date: 2024-03-28

MOT #9 2019-04-05 07:46

MOT test number 577960174136

Result X Failed

Pass with rectification Engine MIL inoperative or indicates a malfunction (8.2.1.2 (h))

MOT #8 2018-02-24 12:29

MOT test number 997092916853

Result

Passed

Advice Front Tyre worn close to the legal limit BOTH (4.1.E.1)

MOT #7 2017-02-21 14:47

MOT test number 186600661305

Result ✓ Passed

Advice Front brake disc worn, pitted or scored, but not seriously weakened both (3.5.1i)

Advice Front Brake pad(s) wearing thin (3.5.1g)

Advice Engine light on

MOT #6 2017-02-21 14:47

MOT test number 754950904599

Result X Failed

Advice Front brake disc worn, pitted or scored, but not seriously weakened both (3.5.1i)

Advice Engine light on

Advice Front Brake pad(s) wearing thin (3.5.1g)

Pass with rectification Front Headlamp not working on dipped beam both (1.7.5a)

MOT #5 2015-05-01 12:39

MOT test number 445731825179

Result ✓ Passed

CarCheck.co.uk page 5/12



report date: 2024-03-28

MOT test number

648875584078

Result

Advice Offside Rear Tyre worn close to the legal limit (4.1.E.1)

Advice Front Tyre worn close to the legal limit (4.1.E.1)

MOT test number

Result

Advice
Front brake disc worn, pitted or scored, but not seriously weakened (3.5.1i)

Advice
Windscreen has damage to an area less than a 40mm circle outside zone 'A' (8.3.1d)

Notice
Advise N/S/R tyre wearing out of shape

Advice
Nearside Rear Brake pad(s) wearing thin (3.5.1g)

MOT #2

MOT test number

Fesult

Advice Nearside Rear Shock absorber has a light misting of oil (2.7.3)

 MOT #1
 2011-03-16 14:03

 MOT test number
 747815171014

 Result
 ✓ Passed

CarCheck.co.uk page 6/12



report date: 2024-03-28

Damage history

Check the damage history for this VOLKSWAGEN. See if, where and when this VOLKSWAGEN had damage and the car repair costs. We also check if this VOLKSWAGEN was scrapped. Download the premium report here for the results.

Damage 1

Date	
Category	
Туре	
Damage 2	
Date	
Category	
Туре	



Extra VOLKSWAGEN salvage check



If this vehicle was seen at a salvage auction we offer: vehicle pictures, salvage location, retail value. Download the premium report <u>here</u> for more information.

More info >

CarCheck.co.uk page 7/12



report date: 2024-03-28

Vehicle valuation

What is this car worth? See the vehicle value of this VOLKSWAGEN in the premium report. We check: purchase value, age, mileage, MOT history, damages and online sale prices.

Trade retail value

Auction value

Average private trade value

More info >

CarCheck.co.uk page 8/12



report date: 2024-03-28

Owner history

For how long did the current and previous owner(s) have this VOLKSWAGEN? How many VOLKSWAGEN have? Check it in the premium report and see all owner registrations. Dow here.	

	More info >
Plate changes	
See in this check if this VOLKSWAGEN had different number plates.	
Number of plates	,
Current registration	UK SIPE
Plate since	
Current registration	UK UK
Plate since	
	Moro info

CarCheck.co.uk page 9/12



report date: 2024-03-28

Finance check

Check if this VOLKSWAGEN is financed, has an outstanding loan or finance agreement. If you are purchasing a vehicle it is smart to ensure that any finance that may have been taken out on this VOLKSWAGEN has been settled.

If not, and you buy this VOLKSWAGEN then you could lose the money and the car you paid for.

Download the premium report <u>here</u> and check if this VOLKSWAGEN is financed.

Finance company

Date of agreement

Agreement type

Agreement term

Agreement number

Contact info

More info >

CarCheck.co.uk page 10/12



report date: 2024-03-28

Mileage check

Odometer	In miles
Mileage registrations	17
First mileage registration	2008-03-31
Last registration	2023-08-31
Complete history	See info



Registration #1	2008-03-31	12 mi
Registration #2	2011-03-16	38.542 mi
Registration #3	2012-03-23	51.731 mi
Registration #4	2013-03-20	71.125 mi
Registration #5	2014-03-26	83.833 mi
Registration #6	2015-05-01	93.149 mi
Registration #7	2017-02-21	103.958 mi
Registration #8	2017-02-21	103.958 mi
Registration #9	2018-02-24	108.139 mi
Registration #10		11.777 es
Registration #11		11.777 es
Registration #12		11.777 es
Registration #13		11.777 es
Registration #14		11.777 es
Registration #15		11.777 es
Registration #16		

More info >

CarCheck.co.uk page 11/12



report date: 2024-03-28

Car features

S0225	Air conditioning
S0295	
S0482	
S0501	
S0566	
S0567	
S0569	

Safety ratings

NCAP rating	****
Video	see crash video



Dimensions & weight

Width	1724 mm
Height	1502 mm
Length	4081 mm
Wheel base	2515 mm
Kerb weight	1314 kg
Max. allowed weight	1680 kg

Additional information

Fuel tank capacity	55 I
Fuel delivery	Multi-Point Injection
Number of doors	3
	70/70

CarCheck.co.uk page 12/12

Number of seats	4
Number of axles	2
Engine number	BFS 062931