





report date: 2024-03-29

#### General information

Make	FIAT
Model	DOBLO 16V MULTIJET
Colour	Red
Year of manufacture	2016
Top speed	102 mph
Gearbox	6 speed Manual

## Engine & fuel consumption

Power	105 BHP
Max. torque	290 Nm at 1.500 rpm
Engine capacity	1.598 cc
Cylinders	4
Fuel type	Diesel
Consumption city	45.6 mpg
Consumption extra urban	61.4 mpg
Consumption combined	54.3 mpg
CO2 emission	144 g/km
CO2 label	F



CarCheck.co.uk page 1/12



report date: 2024-03-29

#### Internet history

#### Entry 1

Date 2022-02-27

Pictures 7

Listing price <u>View report</u>









source: cargurus.co.uk

CarCheck.co.uk page 2/12



**Total items failed** 

**BV66BPK** 

report date: 2024-03-29

MOT history	
MOT expiry date	2025-03-01
MOT pass rate	75 %
MOT passed	6
Failed MOT tests	2
Total advice items	18

0

MOT #8	2024-02-29 13:44
MOT test number	535460983326
Result	✓ Passed
Next expiry date	2025-03-01

MOT #7	2023-03-01 10:43
MOT test number	543168904101
Result	✓ Passed


MOT #6	2022-02-24 16:12
MOT test number	789549037752
Result	✓ Passed

MOT #5		2021-09-01 13:51
MOT test	number	408016935488
Result		<b>✓</b> Passed
Advice	Nearside Front Tyre worn close to legal limit/worn on edge (5.2.3 (e))	
Advice	Rear tyres worn on inner edges	
Advice	Rear silencer deteriorated	
Advice	Nearside Rear Shock absorbers has light misting of oil (5.3.2 (b))	
Advice	Offside Front Tyre worn close to legal limit/worn on edge (5.2.3 (e))	

CarCheck.co.uk page 3/12



report date: 2024-03-29



MOT #3		2020-08-17 09:43
MOT test number	er	771380671554
Result		✓ Passed
MOT #2		2019-09-12 12:58
MOT test number	er	479767878315
Result		✓ Passed
<b>Advice</b> Oil le	ak, but not excessive gearbox (8.4.1 (a) (i))	
<b>Advice</b> N/s/f	tyre worn on inner edge	

CarCheck.co.uk page 4/12



report date: 2024-03-29

MOT #1 2019-09-04 09:42 **MOT test number** 441006541973 Result **X** Failed Advice N/s/f tyre worn on inner edge **MAJOR** Nearside Rear Shock absorbers has a serious fluid leak (5.3.2 (b)) Advice Oil leak, but not excessive gearbox (8.4.1 (a) (i)) Advice Offside Front Upper Macpherson strut top mounting stiff Offside Rear Shock absorbers has a serious fluid leak (5.3.2 (b)) **MAJOR** 

CarCheck.co.uk page 5/12



report date: 2024-03-29

#### Tax & MOT check



Tax status	Valid until 1 March
Days left	306
MOT expiry date	1 March 2025
Full MOT history	See MOT history

#### Tax calculation

Vehicle class	39
Standard rate (12 months)	£ 275,00,-
Standard rate (6 months)	£ 151,25,-

CarCheck.co.uk page 6/12



report date: 2024-03-29

#### Damage history

Check the damage history for this FIAT. See if, where and when this FIAT had damage and the car repair costs. We also check if this FIAT was scrapped. Download the premium report <u>here</u> for the results.

Damage 1
Date
Category
Type
Damage 2
Date
Category
Type



#### Extra FIAT salvage check



If this vehicle was seen at a salvage auction we offer: vehicle pictures, salvage location, retail value. Download the premium report <u>here</u> for more information.

More info >

CarCheck.co.uk page 7/12



report date: 2024-03-29

#### Vehicle valuation

What is this car worth? See the vehicle value of this FIAT in the premium report. We check: purchase value, age, mileage, MOT history, damages and online sale prices.

**Trade retail value** 

**Auction value** 

Average private trade value

More info >

CarCheck.co.uk page 8/12



report date: 2024-03-29

$^{\prime}$	wn	Δr	h	ic	t٥	'n

For how long did the current and previous owner(s) have this FIAT? How many owners did Check it in the premium report and see all owner registrations. Download the full report I	
**********	
***************************************	
********	
***************************************	
	More info >
Plate changes	
See in this check if this FIAT had different number plates.	
Number of plates	,
Current registration	UK UK
Plate since	
Current registration	UK NA
Plate since	
	More info >

CarCheck.co.uk page 9/12



report date: 2024-03-29

#### Finance check

Check if this FIAT is financed, has an outstanding loan or finance agreement. If you are purchasing a vehicle it is smart to ensure that any finance that may have been taken out on this FIAT has been settled.

If not, and you buy this FIAT then you could lose the money and the car you paid for.

Download the premium report <u>here</u> and check if this FIAT is financed.

Finance company	
Date of agreement	
Agreement type	
Agreement term	
Agreement number	
Contact info	

**Contact info** 

More info >

CarCheck.co.uk page 10/12



report date: 2024-03-29

## Mileage check

Odometer	In miles
Mileage registrations	10
First mileage registration	2016-09-01
Last registration	2024-02-29
Complete history	See info



Registration #1	2016-09-01	6 mi
Registration #2	2019-09-04	42.790 mi
Registration #3	2019-09-12	42.795 mi
Registration #4	2020-08-17	61.660 mi
Registration #5	2021-09-01	90.031 mi
Registration #6		71,777 es
Registration #6 Registration #7		11,777 es
-		11.777 ea 11.777 ea
Registration #7		11,777 ea 11,777 ea 11,777 ea

More info >

CarCheck.co.uk page 11/12



report date: 2024-03-29

### Car features

50225	Air conditioning
50295	
50482	
50501	
60566	
60567	
50569	

## Safety ratings

NCAP rating	***
Video	see crash video



## Dimensions & weight

Width	1832 mm
Height	1880 mm
Length	4740 mm
Wheel base	2750 mm
Kerb weight	1445 kg
Max. allowed weight	2370 kg

# Additional information

Fuel tank capacity	60 I
Fuel delivery	Direct Injection
Number of seats	2
Number of axles CarCheck.co.uk	2 page 12/3