






report date: 2024-03-29

General information

Make	JAGUAR
Model	XJS C V12
Colour	Blue
Year of manufacture	1987
Top speed	150 mph
Gearbox	3 speed automatic

Engine & fuel consumption

Power	217 BHP
Max. torque	58 Nm at 3.250 rpm
Engine capacity	5.343 сс
Cylinders	12
Fuel type	Petrol



CarCheck.co.uk page 1/11



Internet history

Entry 2

Date 2022-11-06

Pictures 11

Listing price <u>View report</u>









source: cargurus.co.uk

Entry 1

Date	2021-01-31	
Pictures	1	
Listing price	<u>View report</u>	



source: autoonline.co.uk

CarCheck.co.uk page 2/11



MOT history

MOT expiry date	2016-04-01
MOT pass rate	64 %
MOT passed	7
Failed MOT tests	4
Total advice items	4
Total items failed	8

MOT #11	2015-04-02 11:20
MOT test number	737512495005
Result	✓ Passed
Next expiry date	2016-04-01
Notice Oil leak	

MOT #10	2013-08-06 15:56
MOT test number	485428213287
Result	✓ Passed
MOT #9	2012-08-13 15:13
MOT test number	195636922256
Result	✓ Passed
MOT #8	2012-08-13 13:28
MOT test number	975506022286

MOT test number 975506022286

Result × Failed

Advice Power steering pipe(s) or hose(s) has slight seepage from a seal (2.3.3b)

Fail Parking brake: efficiency below requirements (3.7.B.7)

CarCheck.co.uk page 3/11



MOT #7 2011-08-04 12:05 **MOT test number** 768196711257 ✓ Passed Result MOT #6 2011-07-23 09:13 396684201449 **MOT test number X** Failed Result Fail Power steering pump drive system defective (2.3.6) Power steering pipe(s) or hose(s) leaking (2.3.3b) Fail

Fail Parking brake: efficiency below requirements (3.7.B.7)		
MOT #5	2010-07-27 14:37	
MOT test number	702908000264	
Result	✓ Passed	
MOT #4	2007-09-14 13:25	
MOT test number	634667557258	
Result	✓ Passed	
MOT #3	2007-09-13 10:21	
MOT test number	743526957242	

MOT #3	2007-09-13 10:21	
MOT test number	743526957242	
Result	× Failed	
Fail Nearside rear brake binding (3.7.B.1)		
Fail Nearside Front Direction indicator not working (1.4.A.2c)		
Advice Rear Brake pad(s) wearing thin (3.5.1g)		

CarCheck.co.uk page 4/11



MOT test number

Result

Rear Registration plate lamp insecure (1.1.C.1c)

Notice Unable to rotate N/S/R wheel

Fail Nearside Front Direction indicator not working (1.4.A.2c)

 MOT #1
 2006-08-14 17:03

 MOT test number
 322856426417

 Result
 ✓ Passed


CarCheck.co.uk page 5/11



Damage history

Check the damage history for this JAGUAR. See if, where and when this JAGUAR had damage and the car repair costs. We also check if this JAGUAR was scrapped. Download the premium report <u>here</u> for the results.

Damage 1	
Date	
Category	
Туре	
Damage 2	
Date	
Category	
Туре	



Extra JAGUAR salvage check



If this vehicle was seen at a salvage auction we offer: vehicle pictures, salvage location, retail value. Download the premium report <u>here</u> for more information.

More info >

CarCheck.co.uk page 6/11



Vehicle valuation

What is this car worth? See the vehicle value of this JAGUAR in the premium report. We check: purchase value, age, mileage, MOT history, damages and online sale prices.

Trade retail value

Auction value

Average private trade value

More info >

CarCheck.co.uk page 7/11



Owner history

For how long did the current and previous owner(s) have this JAGUAR? How many owners have? Check it in the premium report and see all owner registrations. Download the full respectively.		ΔR

	More info	>
Plate changes		
See in this check if this JAGUAR had different number plates.		
Number of plates		
Current registration	UK UK	
Plate since		
Current registration	OK SIES	
Plate since		
	More info	>

CarCheck.co.uk page 8/11



Finance check

Check if this JAGUAR is financed, has an outstanding loan or finance agreement. If you are purchasing a vehicle it is smart to ensure that any finance that may have been taken out on this JAGUAR has been settled.

If not, and you buy this JAGUAR then you could lose the money and the car you paid for.

Download the premium report <u>here</u> and check if this JAGUAR is financed.

Finance company	
Date of agreement	
Agreement type	
Agreement term	
Agreement number	
Contact info	

Contact info

More info >

CarCheck.co.uk page 9/11



Mileage check

Registration #14

Odometer	In miles
Mileage registrations	14
First mileage registration	1987-08-19
Last registration	2015-04-02
Complete history	See info



Registration #1	1987-08-19	11 mi
Registration #2	2006-08-14	70.421 mi
Registration #3	2007-09-12	70.458 mi
Registration #4	2007-09-13	70.467 mi
Registration #5	2007-09-14	70.467 mi
Registration #6	2010-07-27	70.574 mi
Registration #7	2011-07-23	71.107 mi
Registration #8		11.777 es
Registration #9		9.777 es
Registration #10		11.777 es
Registration #11		91.777 esi
Registration #12		11.777 es
Registration #13		11.777 es

mn.n.n

More info >

77.777 86

CarCheck.co.uk page 10/11



Dimensions & weight

Width	1793 mm
Height	1261 mm
Length	4764 mm

Additional information

Engine number	8S053913HA
---------------	------------

CarCheck.co.uk page 11/11