



HYUNDAI



report date: 2024-03-28

General information

Make	HYUNDAI
Model	GETZ GSI
Colour	Silver
Year of manufacture	2007
Top speed	93 mph
0 - 60 mph	16.1 seconds
Gearbox	5 speed Manual

Engine & fuel consumption

Power	62 BHP
Max. torque	94 Nm at 3.200 rpm
Engine capacity	1.086 cc
Cylinders	4
Fuel type	Petrol
Consumption city	39.2 mpg
Consumption extra urban	56.5 mpg
Consumption combined	48.7 mpg
CO2 emission	130 g/km
CO2 label	D





Internet history

Entry 1

Date	2021-11-08
Pictures	0
Listing price	View report

source: cargurus.co.uk



MOT history

MOT expiry date	2024-09-14
MOT pass rate	78 %
MOT passed	14
Failed MOT tests	4
Total advice items	9
Total items failed	6

MOT #18	2023-09-15 14:36
MOT test number	502878189776
Result	✓ Passed
Next expiry date	2024-09-14
Advice	Rear Coil spring corroded both rear springs corroded (5.3.1 (b) (i))

MOT #17	2023-09-15 10:45
MOT test number	753884721739
Result	✗ Failed
Fail	Nearside Front Anti-roll bar ball joint dust cover no longer prevents the ingress of dirt (5.3.4 (b) (ii))
Fail	Nearside Front Outer Drive shaft joint constant velocity boot split or insecure, no longer prevents the ingress of dirt (6.1.7 (g) (ii))
Advice	Rear Coil spring corroded both rear springs corroded (5.3.1 (b) (i))

MOT #16	2022-07-01 11:18
MOT test number	247714302048
Result	✓ Passed

**MOT #15** 2022-06-30 14:22**MOT test number** 439772185011**Result** ✗ Failed**Fail** Front Registration plate does not conform to the specified requirements (0.1 (d))**Fail** Rear Registration plate does not conform to the specified requirements (0.1 (d))**MOT #14** 2021-07-02 10:56**MOT test number** 683294590929**Result** ✓ Passed**MOT #13** 2020-10-16 14:48**MOT test number** 669372732081**Result** ✓ Passed**Advice** Offside Rear Shock absorbers light misting of oil or has limited damping effect (5.3.2 (b))**Advice** Offside Front Tyre worn close to legal limit/worn on edge (5.2.3 (e))**Advice** Front Service brake fluctuating, but not excessively (1.2.1 (e))**MOT #12** 2019-06-15 09:01**MOT test number** 618408769203**Result** ✓ Passed**MOT #11** 2018-06-09 08:50**MOT test number** 254375796475**Result** ✓ Passed**Advice** Front Brake pad(s) wearing thin (1.1.13 (a) (ii))**MOT #10** 2017-06-14 14:09**MOT test number** 120449415277**Result** ✓ Passed

**MOT #9** 2017-06-14 14:09**MOT test number** 852980178929**Result** ✗ Failed**Pass with rectification** Offside Front Windscreen wiper does not clear the windscreen effectively (8.2.2)**MOT #8** 2016-06-16 09:05**MOT test number** 749541917173**Result** ✓ Passed**MOT #7** 2015-06-15 15:49**MOT test number** 766606565151**Result** ✓ Passed**MOT #6** 2014-06-12 11:31**MOT test number** 998213064152**Result** ✓ Passed**MOT #5** 2013-06-18 14:11**MOT test number** 796489763142**Result** ✓ Passed**Advice** Offside Front Tyre worn close to the legal limit (4.1.E.1)**MOT #4** 2013-06-18 11:10**MOT test number** 886699063186**Result** ✗ Failed**Advice** Offside Front Tyre worn close to the legal limit (4.1.E.1)**Fail** Nearside Front position lamp(s) not working (1.1.A.3b)



MOT #3	2012-05-18 09:41
MOT test number	805889532190
Result	✓ Passed
MOT #2	2011-05-24 12:51
MOT test number	937414341134
Result	✓ Passed
MOT #1	2010-05-14 15:03
MOT test number	383994330112
Result	✓ Passed
Advice	Offside Front Tyre worn close to the legal limit (4.1.E.1)



Tax & MOT check

✓
Taxed
Tax due:
1 November 2024

✓
MOT
Expires:
14 September 2024

Tax status	Valid until 1 November
Days left	187
MOT expiry date	14 September 2024
Full MOT history	See MOT history

Tax calculation

Vehicle class	48
Band	D
Single payment (12 months)	£ 150,00,-
Single six month payment	£ 82,50,-
Total payable by 12 monthly instalments	£ 157,50,-



Damage history

Check the damage history for this HYUNDAI. See if, where and when this HYUNDAI had damage and the car repair costs. We also check if this HYUNDAI was scrapped. Download the premium report [here](#) for the results.

Damage 1

Date	
Category	
Type	

Damage 2

Date	
Category	
Type	



Extra HYUNDAI salvage check



If this vehicle was seen at a salvage auction we offer: vehicle pictures, salvage location, retail value. Download the premium report [here](#) for more information.

More info >



Vehicle valuation

What is this car worth? See the vehicle value of this HYUNDAI in the premium report. We check: purchase value, age, mileage, MOT history, damages and online sale prices.

Trade retail value	£ 19,999
Auction value	£ 19,999
Average private trade value	£ 19,999

More info >



Owner history

For how long did the current and previous owner(s) have this HYUNDAI? How many owners did this HYUNDAI have? Check it in the premium report and see all owner registrations. Download the full report [here](#).

Owner	Registration
Owner	Registration
Owner	Registration
Owner	Registration
Owner	Registration
Owner	Registration
Owner	Registration

More info >

Plate changes

See in this check if this HYUNDAI had different number plates.

Number of plates	1
Current registration	XXXXXX
Plate since	2024-03-28
Current registration	XXXXXX
Plate since	2024-03-28

More info >



Finance check

Check if this HYUNDAI is financed, has an outstanding loan or finance agreement. If you are purchasing a vehicle it is smart to ensure that any finance that may have been taken out on this HYUNDAI has been settled.

If not, and you buy this HYUNDAI then you could lose the money and the car you paid for.

Download the premium report [here](#) and check if this HYUNDAI is financed.

Finance company	XXXXXXXX XX
Date of agreement	XXXXXXXX XX
Agreement type	XXXXXXXX XX
Agreement term	XXXXXXXX XX
Agreement number	XXXXXXXX XX
Contact info	XXXXXXXX XX

More info >



Mileage check

Odometer	In miles
Mileage registrations	20
First mileage registration	2007-05-25
Last registration	2023-09-15
Complete history	See info



Registration #1	2007-05-25	14 mi
Registration #2	2010-05-14	6.157 mi
Registration #3	2011-05-24	9.803 mi
Registration #4	2012-05-18	13.107 mi
Registration #5	2013-06-18	16.643 mi
Registration #6	2013-06-18	16.643 mi
Registration #7	2014-06-12	22.128 mi
Registration #8	2015-06-15	25.572 mi
Registration #9	2016-06-16	27.210 mi
Registration #10	2017-06-14	29.208 mi
Registration #11	2018-06-14	31.208 mi
Registration #12	2019-06-14	33.208 mi
Registration #13	2020-06-14	35.208 mi
Registration #14	2021-06-14	37.208 mi
Registration #15	2022-06-14	39.208 mi
Registration #16	2023-06-14	41.208 mi
Registration #17	2024-06-14	43.208 mi
Registration #18	2025-06-14	45.208 mi
Registration #19	2026-06-14	47.208 mi
Registration #20	2027-06-14	49.208 mi

More info >



Car features

The HYUNDAI factory car options list is only available in the premium report.

S0225	Air conditioning
S0295	
S0482	
S0501	
S0566	
S0567	
S0569	

View the complete HYUNDAI factory list for this vehicle [here](#).

More info >

Safety ratings

NCAP rating ★★★★★

Video [see crash video](#)



Dimensions & weight

Width	1665 mm
Height	1490 mm
Length	3810 mm
Wheel base	2455 mm
Kerb weight	998 kg

Additional information

Fuel tank capacity	45 l
Fuel delivery	Multi-Point Injection
Number of doors	3
Number of seats	5
Number of axles	2

Engine number

G4HG7240589