



HONDA



report date: 2024-03-29

General information

Make	HONDA
Model	ACCORD I-DTEC ES GT
Colour	Silver
Year of manufacture	2010
Top speed	132 mph
0 - 60 mph	9.6 seconds
Gearbox	6 speed Manual

Engine & fuel consumption

Power	148 BHP
Max. torque	150 Nm at 4.000 rpm
Engine capacity	2.199 cc
Cylinders	4
Fuel type	Diesel
Consumption city	37.7 mpg
Consumption extra urban	57.6 mpg
Consumption combined	47.9 mpg
CO2 emission	157 g/km
CO2 label	G



Internet history

Entry 1

Date	2021-09-22
Pictures	2
Listing price	View report



source: autotrader.co.uk



MOT history

MOT expiry date	2024-10-26
MOT pass rate	68 %
MOT passed	13
Failed MOT tests	6
Total advice items	31
Total items failed	3

MOT #19	2023-10-26 15:51
MOT test number	315113649546
Result	✓ Passed
Next expiry date	2024-10-26
Minor	Nearside Front Headlamp lens slightly defective (4.1.1 (b) (i))
Advice	Offside Rear Service brake binding but not excessively (1.2.1 (f))
Minor	Offside Front Headlamp lens slightly defective (4.1.1 (b) (i))
Advice	Offside Front Tyre worn close to legal limit/worn on edge (5.2.3 (e))
Advice	Nearside Rear Service brake binding but not excessively (1.2.1 (f))

**MOT #18**

2023-10-26 09:37

MOT test number

959847978105

Result**✗ Failed**

- Advice** Nearside Rear Service brake binding but not excessively (1.2.1 (f))
- MAJOR** Offside Front Headlamp not working on dipped beam (4.1.1 (a) (ii))
- Advice** Offside Front Tyre worn close to legal limit/worn on edge (5.2.3 (e))
- MAJOR** Nearside Side repeater not working (4.4.1 (a) (ii))
- MAJOR** Offside Front Suspension arm ball joint excessively worn (5.3.4 (a) (i))
- Minor** Offside Front Headlamp lens slightly defective (4.1.1 (b) (i))
- Advice** Offside Rear Service brake binding but not excessively (1.2.1 (f))
- DANGEROUS** Nearside Front Anti-roll bar linkage ball joint likely to become detached (5.3.4 (a) (ii))
- MAJOR** Offside Front Position lamp not working (4.2.1 (a) (ii))
- MAJOR** Nearside Front Suspension arm ball joint excessively worn (5.3.4 (a) (i))
- Minor** Nearside Front Headlamp lens slightly defective (4.1.1 (b) (i))

MOT #17

2022-10-19 10:35

MOT test number

813527860668

Result**✓ Passed****MOT #16**

2021-10-27 13:43

MOT test number

656256689955

Result**✓ Passed**

**MOT #15**

2021-10-20 10:41

MOT test number

402747475459

Result**✗ Failed**

- Advice** Nearside Front Brake disc worn, pitted or scored, but not seriously weakened (1.1.14 (a) (ii))
- MAJOR** Offside Front Service brake excessively binding (1.2.1 (f))
- Advice** Offside Rear Inner Tyre worn close to legal limit/worn on edge (5.2.3 (e))
- MAJOR** Offside Rear Brake disc significantly and obviously worn (1.1.14 (a) (i))
- MAJOR** Offside Rear Road wheel fixing missing (5.2.1 (a) (i))
- Advice** Offside Front Brake disc worn, pitted or scored, but not seriously weakened (1.1.14 (a) (ii))
- MAJOR** Nearside Rear Brake disc significantly and obviously worn (1.1.14 (a) (i))
- Advice** Nearside Front Upper Macpherson strut mounting corroded but not seriously weakened bearing noisy (5.3.3 (b) (i))

MOT #14

2021-01-05 12:30

MOT test number

861462784402

Result**✓ Passed****MOT #13**

2021-01-05 11:46

MOT test number

664995246283

Result**✓ Passed**

- Advice** Offside Front Brake pad(s) wearing thin (1.1.13 (a) (ii))
- Advice** Nearside Front Brake pad(s) wearing thin (1.1.13 (a) (ii))

MOT #12

2020-01-15 14:22

MOT test number

660782636857

Result**✓ Passed**

**MOT #11** 2019-01-11 15:05**MOT test number** 601454227454**Result** ✓ Passed**MOT #10** 2019-01-11 11:07**MOT test number** 789908135749**Result** ✗ Failed**Advice** Nearside Rear Service brake binding but not excessively (1.2.1 (f))**MAJOR** Offside Windscreen wiper does not clear the windscreen effectively (3.4 (b) (ii))**MAJOR** Offside Rear Service brake excessively binding (1.2.1 (f))**MOT #9** 2018-01-23 09:35**MOT test number** 380521804603**Result** ✓ Passed**MOT #8** 2018-01-19 15:24**MOT test number** 265009313214**Result** ✗ Failed**Fail** Offside Rear coil spring broken (2.4.C.1a)**MOT #7** 2017-01-09 16:49**MOT test number** 221079150900**Result** ✓ Passed**Advice** Nearside Front Tyre worn close to the legal limit (4.1.E.1)**Advice** Offside Front Tyre worn close to the legal limit (4.1.E.1)**MOT #6** 2015-12-30 14:27**MOT test number** 481268710643**Result** ✓ Passed

**MOT #5** 2015-01-06 10:23**MOT test number** 515946905086**Result** Passed**MOT #4** 2015-01-05 17:13**MOT test number** 179385105449**Result** Failed**Fail** Offside Front Windscreen wiper does not clear the windscreen effectively (8.2.2)**MOT #3** 2014-01-15 16:38**MOT test number** 505825714016**Result** Passed**MOT #2** 2014-01-15 12:10**MOT test number** 359185114076**Result** Failed**Fail** Nearside Front Tyre has ply or cords exposed (4.1.D.1b)**MOT #1** 2013-01-18 12:58**MOT test number** 185938213459**Result** Passed



Tax & MOT check

✓
Taxed
Tax due:
1 February 2025

✓
MOT
Expires:
26 October 2024

Tax status	Valid until 1 February
Days left	278
MOT expiry date	26 October 2024
Full MOT history	See MOT history

Tax calculation

Vehicle class	49
Band	G
Single payment (12 months)	£ 240,00,-
Single six month payment	£ 132,00,-
Total payable by 12 monthly instalments	£ 252,00,-



Damage history

Check the damage history for this HONDA. See if, where and when this HONDA had damage and the car repair costs. We also check if this HONDA was scrapped. Download the premium report [here](#) for the results.

Damage 1

Date	
Category	
Type	

Damage 2

Date	
Category	
Type	



Extra HONDA salvage check



If this vehicle was seen at a salvage auction we offer: vehicle pictures, salvage location, retail value. Download the premium report [here](#) for more information.

More info >



Vehicle valuation

What is this car worth? See the vehicle value of this HONDA in the premium report. We check: purchase value, age, mileage, MOT history, damages and online sale prices.

Trade retail value	£ 19,999
Auction value	£ 19,999
Average private trade value	£ 19,999

More info >



Owner history

For how long did the current and previous owner(s) have this HONDA? How many owners did this HONDA have? Check it in the premium report and see all owner registrations. Download the full report [here](#).

Owner	Since
Owner	Since
Owner	Since
Owner	Since
Owner	Since
Owner	Since
Owner	Since

More info >

Plate changes

See in this check if this HONDA had different number plates.

Number of plates	1
Current registration	
Plate since	2019-09-29
Current registration	
Plate since	2019-09-29

More info >



Finance check

Check if this HONDA is financed, has an outstanding loan or finance agreement. If you are purchasing a vehicle it is smart to ensure that any finance that may have been taken out on this HONDA has been settled.

If not, and you buy this HONDA then you could lose the money and the car you paid for.

Download the premium report [here](#) and check if this HONDA is financed.

Finance company	XXXXXXXX XX
Date of agreement	XXXXXXXX XX
Agreement type	XXXXXXXX XX
Agreement term	XXXXXXXX XX
Agreement number	XXXXXXXX XX
Contact info	XXXXXXXX XX

More info >



Mileage check

Odometer	In miles
Mileage registrations	21
First mileage registration	2010-01-22
Last registration	2023-10-26
Complete history	See info



Registration #1	2010-01-22	11 mi
Registration #2	2013-01-18	29.558 mi
Registration #3	2014-01-15	38.465 mi
Registration #4	2014-01-15	38.465 mi
Registration #5	2015-01-05	50.009 mi
Registration #6	2015-01-06	50.009 mi
Registration #7	2015-12-30	59.837 mi
Registration #8	2017-01-09	73.129 mi
Registration #9	2018-01-19	86.937 mi
Registration #10	2018-01-23	86.953 mi
Registration #11	2019-01-11	102.540 mi
Registration #12	2019-01-11	102.540 mi
Registration #13	2019-01-11	102.540 mi
Registration #14	2019-01-11	102.540 mi
Registration #15	2019-01-11	102.540 mi
Registration #16	2019-01-11	102.540 mi
Registration #17	2019-01-11	102.540 mi
Registration #18	2019-01-11	102.540 mi
Registration #19	2019-01-11	102.540 mi
Registration #20	2019-01-11	102.540 mi
Registration #21	2019-01-11	102.540 mi

More info >



Safety ratings

NCAP rating	★★★★★
Adult	86%
Children	79%
Pedestrian	54%
Safety systems	86%
Overall rating	78%
Video	see crash video



Dimensions & weight

Width	1840 mm
Height	1440 mm
Length	4740 mm
Wheel base	2705 mm
Kerb weight	1559 kg

Additional information

Fuel tank capacity	65 l
Fuel delivery	Direct Injection
Number of doors	5
Number of seats	5
Engine number	N22B11103670