



RENAULT

**BN55UME**

report date: 2024-03-29

General information

Make	RENAULT
Model	MEGANE DYNAMIQUE DCI 130
Colour	Black
Year of manufacture	2005
Top speed	124 mph
0 - 60 mph	9.6 seconds
Gearbox	6 speed Manual

Engine & fuel consumption

Power	130 BHP
Max. torque	300 Nm at 2.000 rpm
Engine capacity	1.870 cc
Cylinders	4
Fuel type	Diesel
Consumption city	39.8 mpg
Consumption extra urban	58.9 mpg
Consumption combined	50.4 mpg
CO2 emission	148 g/km
CO2 label	F





MOT history

MOT expiry date	2021-10-06
MOT pass rate	59 %
MOT passed	13
Failed MOT tests	9
Total advice items	38
Total items failed	31

MOT #22	2020-10-07 08:43
MOT test number	781491423690
Result	✓ Passed
Next expiry date	2021-10-06
Advice	Nearside Non obligatory mirror damaged

MOT #21	2020-09-29 14:32
MOT test number	721284847971
Result	✗ Failed
Fail	Windscreen damaged and affecting the driver's view of the road (3.2 (a) (ii))
Fail	Offside Stop lamp(s) not working (4.3.1 (a) (ii))
Advice	Nearside Non obligatory mirror damaged
Fail	Nearside Front Outer Drive shaft joint constant velocity boot split or insecure, no longer prevents the ingress of dirt (6.1.7 (g) (ii))
Advice	Offside Front Tyre worn close to legal limit/worn on edge (5.2.3 (e))
Fail	Offside Windscreen washer not working (3.5 (a))
Fail	Nearside Headlamp aim too low (4.1.2 (a))

**MOT #20** 2019-04-02 13:32**MOT test number** 240503795643**Result** ✓ Passed**Minor** Windscreen damaged but not adversely affecting driver's view (3.2 (a) (i))**MOT #19** 2019-04-02 09:43**MOT test number** 974263600410**Result** ✗ Failed**Fail** Nearside Headlamp aim too low (4.1.2 (a))**Minor** Windscreen damaged but not adversely affecting driver's view (3.2 (a) (i))**Fail** Offside Obligatory mirror seriously damaged, affecting the rear view (3.3 (b) (ii))**MOT #18** 2018-03-23 10:50**MOT test number** 217723865034**Result** ✓ Passed

**MOT #17** 2018-03-22 11:28**MOT test number** 771477839076**Result** ✗ Failed

- Fail** Offside Front coil spring broken (2.4.C.1a)
- Fail** Offside Rear Tyre tread depth below requirements of 1.6mm (4.1.E.1)
- Fail** Nearside Registration plate lamp not working (1.1.C.1d)
- Fail** Nearside Stop lamp not working (1.2.1b)
- Fail** Nearside Windscreen wiper does not clear the windscreen effectively (8.2.2)
- Fail** Nearside Outer Front constant velocity joint gaiter insecure to the extent that it no longer prevents the ingress of dirt etc (2.5.C.1a)
- Fail** Windscreen washer provides insufficient washer liquid (8.2.3)
- Fail** Nearside Rear Tyre has a cut in excess of the requirements deep enough to reach the ply or cords (4.1.D.1a)
- Fail** Offside Registration plate lamp not working (1.1.C.1d)
- Fail** Nearside Headlamp aim too high (1.8)

**MOT #16** 2017-03-30 09:56**MOT test number** 200797525434**Result** ✓ Passed

- Advice** Both rear wheel valve stems perishing

**MOT #15** 2017-03-30 09:14**MOT test number** 204150102809**Result** ✗ Failed

- Fail** Steering lock fails to engage (2.1.4b)
- Advice** Both rear wheel valve stems perishing
- Pass with rectification** Offside Steering rack gaiter insecure (2.2.D.2d)
- Pass with rectification** Nearside Steering rack gaiter insecure (2.2.D.2d)

**MOT #14** 2015-09-28 09:16**MOT test number** 346908965893**Result** ✓ Passed**MOT #13** 2014-10-03 14:39**MOT test number** 775936174209**Result** ✓ Passed**MOT #12** 2014-10-03 14:39**MOT test number** 795976574247**Result** ✗ Failed**Pass with rectification** Nearside Windscreen washer provides insufficient washer liquid (8.2.3)**Pass with rectification** Offside Windscreen washer provides insufficient washer liquid (8.2.3)**MOT #11** 2013-04-03 12:54**MOT test number** 688563693060**Result** ✓ Passed**Advice** Offside Rear Tyre worn close to the legal limit (4.1.E.1)**Notice** Play in steering rack inner joint(s)**MOT #10** 2012-04-02 16:44**MOT test number** 799513092063**Result** ✓ Passed**Notice** Play in steering rack inner joint(s)**Advice** Offside Rear Tyre worn close to the legal limit (4.1.E.1)

**MOT #9** 2012-04-02 16:44**MOT test number** 425253392069**Result** ✗ Failed**Notice** Play in steering rack inner joint(s)**Advice** Offside Rear Tyre worn close to the legal limit (4.1.E.1)**Pass with rectification** Offside Front Headlamp not working on dipped beam (1.7.5a)**MOT #8** 2011-10-17 15:55**MOT test number** 415250091278**Result** ✓ Passed**Advice** Nearside Front Lower Suspension arm has slight play in a ball joint (2.4.G.2)**Advice** Offside Rear Tyre worn close to the legal limit (4.1.E.1)**Notice** Battery insecure**Notice** Play in nearside front steering arm**Advice** Windscreen has damage to an area less than a 10mm circle within zone 'A' (8.3.1a)**Advice** Offside Front Tyre worn close to the legal limit (4.1.E.1)**Notice** Windscreen washer jets poorly adjusted

**MOT #7** 2011-10-12 17:09**MOT test number** 285615281206**Result** ✗ Failed

- Notice** Play in nearside front steering arm
- Advice** Offside Rear Tyre worn close to the legal limit (4.1.E.1)
- Fail** Offside Headlamp aim too low (1.8)
- Advice** Windscreen has damage to an area less than a 10mm circle within zone 'A' (8.3.1a)
- Notice** Windscreen washer jets poorly adjusted
- Advice** Offside Front Tyre worn close to the legal limit (4.1.E.1)
- Advice** Rear Brake pad(s) wearing thin (3.5.1g)
- Fail** Nearside Rear reflector not red in colour (1.5.1d)
- Fail** Offside Rear brake disc in such a condition that it is seriously weakened (3.5.1i)
- Notice** Battery insecure
- Advice** Nearside Front Lower Suspension arm has slight play in a ball joint (2.4.G.2)

**MOT #6** 2011-03-04 16:51**MOT test number** 119333961499**Result** ✓ Passed

- Advice** Nearside Rear Tyre worn close to the legal limit (4.1.E.1)
- Advice** Nearside Front Steering pivot point has slight play (2.2.B.1g)

**MOT #5** 2010-09-11 12:56**MOT test number** 663594350296**Result** ✓ Passed

**MOT #4** 2010-09-11 09:59**MOT test number** 112684250250**Result** ✗ Failed**Fail** Nearside Front Tyre has a cut in excess of the requirements deep enough to reach the ply or cords (4.1.D.1a)**Notice** Front and rear brake disc worn**Fail** Nearside Front Headlamp excessively deteriorated so that the light output is severely reduced (1.7.5a)**Fail** Offside Front Windscreen wiper does not clear the windscreen effectively (8.2.2)**Advice** Windscreen has damage to an area less than a 10mm circle within zone 'A' (8.3.1a)**Notice** N/s/r tyre close to legal limit**Fail** Nearside Front Windscreen wiper does not clear the windscreen effectively (8.2.2)**MOT #3** 2009-09-12 10:03**MOT test number** 463135859275**Result** ✓ Passed**Advice** Nearside Front Tyre worn close to the legal limit (4.1.E.1)**Advice** Windscreen has damage to an area less than a 10mm circle within zone 'A' (8.3.1a)**MOT #2** 2009-09-12 10:03**MOT test number** 334085859427**Result** ✗ Failed**Pass with rectification** Nearside Headlamp not working on dipped beam (1.7.5a)**Advice** Nearside Front Tyre worn close to the legal limit (4.1.E.1)**Advice** Windscreen has damage to an area less than a 10mm circle within zone 'A' (8.3.1a)





MOT #1	2008-09-02 14:49
MOT test number	384336548220
Result	✓ Passed
<div>Notice Offside front shock absorber top mounting slightly noisy</div>	



Damage history

Check the damage history for this RENAULT. See if, where and when this RENAULT had damage and the car repair costs. We also check if this RENAULT was scrapped. Download the premium report [here](#) for the results.

Damage 1

Date	
Category	
Type	

Damage 2

Date	
Category	
Type	



Extra RENAULT salvage check



If this vehicle was seen at a salvage auction we offer: vehicle pictures, salvage location, retail value. Download the premium report [here](#) for more information.

More info >



Vehicle valuation

What is this car worth? See the vehicle value of this RENAULT in the premium report. We check: purchase value, age, mileage, MOT history, damages and online sale prices.

Trade retail value	£ 19,999
Auction value	£ 19,999
Average private trade value	£ 19,999

More info >



Owner history

For how long did the current and previous owner(s) have this RENAULT? How many owners did this RENAULT have? Check it in the premium report and see all owner registrations. Download the full report [here](#).

Owner	Since
Owner	Since
Owner	Since
Owner	Since
Owner	Since
Owner	Since
Owner	Since

More info >

Plate changes

See in this check if this RENAULT had different number plates.

Number of plates	1
Current registration	<b>BN55 UME</b>
Plate since	2019-03-29
Current registration	<b>BN55 UME</b>
Plate since	2019-03-29

More info >



Finance check

Check if this RENAULT is financed, has an outstanding loan or finance agreement. If you are purchasing a vehicle it is smart to ensure that any finance that may have been taken out on this RENAULT has been settled.

If not, and you buy this RENAULT then you could lose the money and the car you paid for.

Download the premium report [here](#) and check if this RENAULT is financed.

Finance company	RENAULT FINANCE
Date of agreement	01/01/2024
Agreement type	FINANCE
Agreement term	36 months
Agreement number	123456789
Contact info	0123 456789

More info >



Mileage check

Odometer	In miles
Mileage registrations	20
First mileage registration	2005-09-06
Last registration	2020-10-07
Complete history	<a href="#">See info</a>



Registration #1	2005-09-06	14 mi
Registration #2	2008-09-02	42.319 mi
Registration #3	2009-09-12	55.876 mi
Registration #4	2010-09-11	68.495 mi
Registration #5	2010-09-11	68.495 mi
Registration #6	2011-03-04	73.657 mi
Registration #7	2011-10-12	77.850 mi
Registration #8	2011-10-17	77.850 mi
Registration #9	2012-04-02	81.922 mi
Registration #10	2013-04-03	97.877 mi
Registration #11	2013-04-03	97.877 mi
Registration #12	2013-04-03	97.877 mi
Registration #13	2013-04-03	97.877 mi
Registration #14	2013-04-03	97.877 mi
Registration #15	2013-04-03	97.877 mi
Registration #16	2013-04-03	97.877 mi
Registration #17	2013-04-03	97.877 mi
Registration #18	2013-04-03	97.877 mi
Registration #19	2013-04-03	97.877 mi
Registration #20	2013-04-03	97.877 mi

More info >



Car features

The RENAULT factory car options list is only available in the premium report.

S0225	Air conditioning
S0295	
S0482	
S0501	
S0566	
S0567	
S0569	

View the complete RENAULT factory list for this vehicle [here](#).

More info >

Safety ratings

NCAP rating ★★★★★

Video [see crash video](#)



Dimensions & weight

Width	2026 mm
Height	1458 mm
Length	4209 mm
Wheel base	2625 mm
Max. allowed weight	1820 kg

Additional information

Fuel tank capacity	60 l
Fuel delivery	Direct Injection
Number of doors	5
Number of seats	5
Number of axles	2

