





### General information

Make	JAGUAR	
Model	XF D PORTFOLIO SPORTBRAKE	
Colour	Green	
Year of manufacture	2013	
Top speed	134 mph	
Gearbox	8 speed automatic	

# Engine & fuel consumption

Power	200 BHP
Max. torque	450 Nm at 2.000 rpm
Engine capacity	2.179 сс
Cylinders	4
Fuel type	Diesel
Consumption city	46.3 mpg
Consumption extra urban	65.7 mpg
Consumption combined	52.3 mpg
CO2 emission	139 g/km
CO2 label	E





Internet history	
Entry 1	
Date	2021-01-31
Pictures	0
Listing price	View report

source: autoonline.co.uk



# MOT history

MOT expiry date	2025-03-24
MOT pass rate	82 %
MOT passed	9
Failed MOT tests	2
Total advice items	15
Total items failed	4

MOT #11		2024-03-20 15:25
MOT test	number	135573626464
Result		✓ Passed
Next exp	iry date	2025-03-24
Minor	Nearside Front Upper Suspension arm ball joint dust cover severely deter	iorated (5.3.4 (b) (i))
<b>Advice</b> Offside Rear Upper Suspension arm pin or bush worn but not resulting in excessive movement (5.3.4 (a) (i))		
Minor	Offside Rear Anti-roll bar linkage ball joint dust cover severely deteriorate	ed (5.3.4 (b) (i))
Minor	Offside Front Upper Suspension arm ball joint dust cover severely deterio	rated (5.3.4 (b) (i))

MOT #10	2024-03-15 13:03	
MOT test number	385898995408	
Result	× Failed	
Minor Offside Rear Anti-roll bar linkage ball joint dust cover severely deteriorated	d (5.3.4 (b) (i))	
Minor Offside Front Upper Suspension arm ball joint dust cover severely deteriorated (5.3.4 (b) (i))		
Fail         Windscreen washer provides insufficient washer liquid (3.5 (a))		
Minor Nearside Front Upper Suspension arm ball joint dust cover severely deteriorated (5.3.4 (b) (i))		
<b>Fail</b> Offside Headlamp cleaning device for LED or HID headlamp inoperative (4.1.	6 (a) (ii))	
Advice Offside Rear Upper Suspension arm pin or bush worn but not resulting in (5.3.4 (a) (i))	excessive movement	





MOT #9		2023-03-24 16:08
MOT test	number	291911896921
Result		✓ Passed
Minor	Nearside Front Upper Suspension arm ball joint dust cover severely deteriorat	ted (5.3.4 (b) (i))
Advice slight at t	Offside Rear Upper Suspension arm pin or bush worn but not resulting in exc his stage (5.3.4 (a) (i))	cessive movement
Minor	Offside Front Upper Suspension arm ball joint dust cover severely deteriorate	d (5.3.4 (b) (i))
MOT #8		2022-03-18 13:37
MOT test	number	493749862286
Result		✓ Passed
Advice Front Tyre worn close to legal limit/worn on edge both sides, worn on inner edges (5.2.3 (e))		
MOT #7		2021-03-25 15:55
MOT test	number	318927569800
Result		✓ Passed
MOT #6		2020-01-08 10:21
MOT test	number	792678071733
Result		✓ Passed

Advice Offside Rear Child Seat fitted not allowing full inspection of adult belt

MOT #5	2019-01-09 13:41
MOT test number	711278114266
Result	✓ Passed
	e to legal limit/worn on edge (5.2.3 (e)) se to legal limit/worn on edge (5.2.3 (e))





MOT #4	2018-01-10 10:47	
MOT test number	142749473476	
Result	✓ Passed	
MOT #3	2017-01-11 11:01	
MOT test number	647695794245	
Result	✓ Passed	
MOT #2	2016-01-27 11:49	
MOT test number	761581302827	
Result	✓ Passed	
MOT #1	2016-01-27 10:01	
MOT test number	473752751418	
Result	🗙 Failed	
<b>Fail</b> Offside Rear Tyre tread depth below requirements of 1.6mm (4.1.E.1)		
Fail         Nearside Rear Tyre tread depth below requirements of 1.6mm (4.1.E.1)		



Tax & MOT check

√ Taxed	√ MOT
Tax due: 1 March 2025	Expires: 24 March 2025
Tax status	Valid until 1 March
Days left	306
MOT expiry date	24 March 2025
Full MOT history	See MOT history

### Tax calculation

Vehicle class	49
Band	E
Single payment (12 months)	£ 180,00,-
Single six month payment	£ 99,00,-
Total payable by 12 monthly instalments	£ 189,00,-





### Damage history

Check the damage history for this JAGUAR. See if, where and when this JAGUAR had damage and the car repair costs. We also check if this JAGUAR was scrapped. Download the premium report <u>here</u> for the results.

Damage 1	
Date	
Category	Lamp
Туре	
Damage 2	AMPL
	E Store
Date	1. E
Category	amt
Туре	

#### Extra JAGUAR salvage check

If this vehicle was seen at a salvage auction we offer: vehicle pictures, salvage location, retail value. Download the premium report <u>here</u> for more information.





### Vehicle valuation

What is this car worth? See the vehicle value of this JAGUAR in the premium report. We check: purchase value, age, mileage, MOT history, damages and online sale prices.

Trade retail value	4 10.000
Auction value	4 10.000
Average private trade value	4 10.200





### Owner history

For how long did the current and previous owner(s) have this JAGUAR? How many owners did this JAGUAR have? Check it in the premium report and see all owner registrations. Download the full report <u>here</u>.

And a second sec	
**********	
********	
and the second se	
***********	
********	
	More info >
Plate changes	
See in this check if this JAGUAR had different number plates.	
Number of plates	,
Carrent registration	
Plate since	
Carrent registration	
Plate since	





#### Finance check

Check if this JAGUAR is financed, has an outstanding loan or finance agreement. If you are purchasing a vehicle it is smart to ensure that any finance that may have been taken out on this JAGUAR has been settled.

If not, and you buy this JAGUAR then you could lose the money and the car you paid for.

Download the premium report <u>here</u> and check if this JAGUAR is financed.

Finance company	
Date of agreement	
Agreement type	
Agreement term	
Agreement number	
Contact info	





# Mileage check

Odometer	In miles
Mileage registrations	13
First mileage registration	2013-01-04
Last registration	2024-03-20
Complete history	See info



Registration #1	2013-01-04	11 mi
Registration #2	2016-01-27	53.305 mi
Registration #3	2016-01-27	53.305 mi
Registration #4	2017-01-11	60.325 mi
Registration #5	2018-01-10	65.165 mi
Registration #6	2019-01-09	69.732 mi
Registration #7	2020-01-08	74.546 mi
Registration #8		11.777 esi
Registration #9		11.777 mi
Registration #10		11.777 esi
Registration #11		11.777 esi
Registration #12		11.777 esi
Registration #13		





# Safety ratings

NCAP rating	****
Adult	79%
Children	73%
Pedestrian	62%
Safety systems	71%
Overall rating	74%
Video	see crash video



Dimensions & weight	
Width	1877 mm
Height	1460 mm
Length	4966 mm
Wheel base	2909 mm
Kerb weight	1824 kg
Max. allowed weight	2390 kg
Additional information	
Additional information Fuel tank capacity	70 I
	70 l Direct Injection
Fuel tank capacity	
Fuel tank capacity Fuel delivery	Direct Injection
Fuel tank capacity Fuel delivery Number of doors	Direct Injection 5