





report date: 2024-03-28

General information

| Make | HONDA |
|---------------------|-----------------------|
| Model | CR-Z I-VTEC IMA SPORT |
| Colour | Black |
| Year of manufacture | 2012 |
| Top speed | 124 mph |
| 0 - 60 mph | 10.0 seconds |
| Gearbox | 6 speed Manual |

Engine & fuel consumption

| Power | 113 BHP |
|-------------------------|---------------------|
| Max. torque | 145 Nm at 4.800 rpm |
| Engine capacity | 1.497 cc |
| Cylinders | 4 |
| Fuel type | Hybrid / Electric |
| Consumption city | 46.3 mpg |
| Consumption extra urban | 64.2 mpg |
| Consumption combined | 56.5 mpg |
| CO2 emission | 117 g/km |
| CO2 label | С |



CarCheck.co.uk page 1/12



Internet history

| Entry | 1 |
|-------|---|
|-------|---|

| Date | 2022-05-06 |
|---------------|-------------|
| Pictures | 0 |
| Listing price | View report |

source: cargurus.co.uk

CarCheck.co.uk page 2/12



MOT history

| MOT expiry date | 2024-10-17 |
|--------------------|------------|
| MOT pass rate | 100 % |
| MOT passed | 9 |
| Failed MOT tests | 0 |
| Total advice items | 16 |
| Total items failed | 0 |

| MOT #9 | | 2023-10-18 11:11 |
|----------------|----------------------------------------------------------------------------------------|------------------|
| MOT test nu | ımber | 706167058648 |
| Result | | ✓ Passed |
| Next expiry | date | 2024-10-17 |
| Advice | Offside Rear Tyre slightly damaged/cracking or perishing (5.2.3 (d) (ii)) | |
| Advice | Nearside Rear Service brake binding but not excessively (1.2.1 (f)) | |
| Minor O | ffside Front Anti-roll bar ball joint dust cover severely deteriorated (5.3.4 (b) (i)) | |

| MOT #8 | | 2022-10-18 09:26 |
|----------|------------------------------------------------------------------------------------|-------------------|
| MOT test | number | 842603897520 |
| Result | | ✓ Passed |
| Advice | Offside Rear Tyre slightly damaged/cracking or perishing (5.2.3 (d) (ii)) | |
| Advice | Nearside Rear Brake disc worn, pitted or scored, but not seriously weakened | (1.1.14 (a) (ii)) |
| Advice | Nearside Front Tyre slightly damaged/cracking or perishing (5.2.3 (d) (ii)) | |
| Advice | Offside Front Tyre slightly damaged/cracking or perishing (5.2.3 (d) (ii)) | |
| Minor | Offside Front Anti-roll bar ball joint dust cover severely deteriorated (5.3.4 (b) | (i)) |

CarCheck.co.uk page 3/12



Passed

MOT #7 2021-09-03 15:35

MOT test number 243016493288

Result \rightarrow Passed

Advice Nearside Front Anti-roll bar corroded but not seriously weakened (5.3.3 (b) (i))

Advice Offside Front Anti-roll bar corroded but not seriously weakened (5.3.3 (b) (i))

MOT #6 2020-08-24 08:54

MOT test number 842243349186

Advice Nearside Rear Upper Shock absorbers has a slightly worn bush (5.3.2 (c))

Advice Oil leak, but not excessive (8.4.1 (a) (i))

Result

Advice

Advice Offside Rear Upper Shock absorbers has a slightly worn bush (5.3.2 (c))

MOT #5 2019-09-06 11:21

MOT test number 549954226901

Front Tyre worn close to legal limit/worn on edge both (5.2.3 (e))

MOT #4 2018-09-07 17:30

MOT test number 110114940773

Result

Passed

Advice Nearside Rear Brake disc worn, pitted or scored, but not seriously weakened (1.1.14 (a) (ii))

Advice Offside Rear Brake disc worn, pitted or scored, but not seriously weakened (1.1.14 (a) (ii))

MOT #3 2017-05-31 11:48

MOT test number 556347844950

CarCheck.co.uk page 4/12



| MOT #2 | 2016-11-18 13:28 |
|-----------------|------------------|
| MOT test number | 924920133393 |
| Result | ✓ Passed |
| | |
| MOT #1 | 2015-11-19 16:02 |
| MOT test number | E7077166274E |
| MOT test number | 570771663745 |

CarCheck.co.uk page 5/12



Tax & MOT check



| Tax status | Valid until 1 May |
|------------------|-------------------|
| Days left | 368 |
| MOT expiry date | 17 October 2024 |
| Full MOT history | See MOT history |

Tax calculation

| Vehicle class | 59 |
|-----------------------------------------|----------------|
| Band | С |
| Single payment (12 months) | £ 25,00,- |
| Single six month payment | Not applicable |
| Total payable by 12 monthly instalments | £ 26,25,- |

CarCheck.co.uk page 6/12



Damage history

Check the damage history for this HONDA. See if, where and when this HONDA had damage and the car repair costs. We also check if this HONDA was scrapped. Download the premium report <u>here</u> for the results.

| Damage 1 | |
|----------|--|
| Date | |
| Category | |
| Туре | |
| Damage 2 | |
| Date | |
| Category | |
| Туре | |



Extra HONDA salvage check



If this vehicle was seen at a salvage auction we offer: vehicle pictures, salvage location, retail value. Download the premium report <u>here</u> for more information.

More info >

CarCheck.co.uk page 7/12



Vehicle valuation

What is this car worth? See the vehicle value of this HONDA in the premium report. We check: purchase value, age, mileage, MOT history, damages and online sale prices.

Trade retail value

Auction value

Average private trade value

More info >

CarCheck.co.uk page 8/12



RE62OCJ

report date: 2024-03-28

| Owner history | |
|---------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------|-------------|
| For how long did the current and previous owner(s) have this HONDA? How many owners have? Check it in the premium report and see all owner registrations. Download the full report and see all owner registrations. | |
| ********* | |
| *************************************** | |
| *********** | |
| *************************************** | |
| *************************************** | |
| *************************************** | |
| Plate changes | More info > |
| See in this check if this HONDA had different number plates. | |
| Number of plates | |
| Correct registration | UK UK |
| Plate since | |
| Current registration | AK UK |
| Plate since | |
| | More info > |

CarCheck.co.uk page 9/12



Finance check

Check if this HONDA is financed, has an outstanding loan or finance agreement. If you are purchasing a vehicle it is smart to ensure that any finance that may have been taken out on this HONDA has been settled.

If not, and you buy this HONDA then you could lose the money and the car you paid for.

Download the premium report <u>here</u> and check if this HONDA is financed.

| Finance company | |
|-------------------|--|
| Date of agreement | |
| Agreement type | |
| Agreement term | |
| Agreement number | |
| Contact info | |

Contact info


More info >

CarCheck.co.uk page 10/12



Mileage check

| Odometer | In miles |
|----------------------------|------------|
| Mileage registrations | 11 |
| First mileage registration | 2012-11-22 |
| Last registration | 2023-10-18 |
| Complete history | See info |



| Registration #1 | 2012-11-22 | 13 mi |
|------------------|------------|------------|
| Registration #2 | 2015-11-19 | 32.257 mi |
| Registration #3 | 2016-11-18 | 42.072 mi |
| Registration #4 | 2017-05-31 | 45.386 mi |
| Registration #5 | 2018-09-07 | 55.760 mi |
| Registration #6 | 2019-09-06 | 65.171 mi |
| Registration #7 | | 0.777 es |
| Registration #8 | | 11.777 es |
| Registration #9 | | 9.777 es |
| Registration #10 | | 71.777 66 |
| Registration #11 | | D. 277 esc |

More info >

CarCheck.co.uk page 11/12



Safety ratings

| NCAP rating | **** |
|----------------|-----------------|
| Adult | 93% |
| Children | 80% |
| Pedestrian | 71% |
| Safety systems | 86% |
| Overall rating | 85% |
| Video | see crash video |



Dimensions & weight

| Width | 2014 mm |
|-------------|---------|
| Height | 1395 mm |
| Length | 4080 mm |
| Wheel base | 2425 mm |
| Kerb weight | 1198 kg |

Additional information

| Fuel tank capacity | 40 I |
|--------------------|-----------------------|
| Fuel delivery | Multi-Point Injection |
| Number of doors | 3 |
| Number of seats | 4 |
| Number of axles | 2 |
| Engine number | LEA1 1017966 |

CarCheck.co.uk page 12/12