




report date: 2024-03-28

General information

Make	VOLVO
Model	S40 D3 R-DESIGN
Colour	Silver
Year of manufacture	2011
Top speed	134 mph
Gearbox	6 speed automatic

Engine & fuel consumption

Power	161 BHP
Max. torque	400 Nm at 1.400 rpm
Engine capacity	1.984 cc
Cylinders	5
Fuel type	Diesel
Consumption city	39.8 mpg
Consumption extra urban	58.9 mpg
Consumption combined	49.6 mpg
CO2 emission	149 g/km
CO2 label	F





Internet history

Entry 1

Date	2021-11-06
Pictures	44
Listing price	View report



source: autotrader.co.uk



MOT history

MOT expiry date	2024-10-23
MOT pass rate	77 %
MOT passed	10
Failed MOT tests	3
Total advice items	18
Total items failed	3

MOT #13	2023-10-24 11:28
MOT test number	769440325329
Result	✓ Passed
Next expiry date	2024-10-23

MOT #12	2022-10-07 10:16
MOT test number	296478987976
Result	✓ Passed
Advice	Nearside Front Tyre worn close to legal limit/worn on edge (5.2.3 (e))
Minor	Nearside Windscreen wiper blade defective (3.4 (b) (i))
Advice	Nearside Rear Tyre worn close to legal limit/worn on edge (5.2.3 (e))
Advice	Offside Front Brake pad(s) wearing thin (1.1.13 (a) (ii))
Advice	Offside Front Tyre worn close to legal limit/worn on edge (5.2.3 (e))
Advice	Nearside Front Brake pad(s) wearing thin (1.1.13 (a) (ii))

MOT #11	2021-09-09 13:59
MOT test number	165731431124
Result	✓ Passed



MOT #10 2020-09-11 08:17

MOT test number 318397675902

Result ✓ Passed

MOT #9 2020-07-29 10:51

MOT test number 563232790564

Result ✗ Failed

Advice Nearside Rear Brake pad(s) wearing thin (1.1.13 (a) (ii))

MAJOR Nearside Front Coil spring fractured or broken (5.3.1 (b) (i))

MAJOR Offside Rear Hydraulic brake calliper leaking (1.1.16 (b) (i))

Advice Offside Rear Brake pad(s) wearing thin (1.1.13 (a) (ii))

Minor Brake fluid warning lamp illuminated (1.1.10 (f))

MOT #8 2019-05-22 14:08

MOT test number 399163347452

Result ✓ Passed

MOT #7 2019-05-22 14:08

MOT test number 914990940494

Result ✗ Failed

Pass with rectification Nearside Windscreen wiper does not clear the windscreen effectively (3.4 (b) (ii))

MOT #6 2018-05-29 11:59

MOT test number 459469195929

Result ✓ Passed

MOT #5 2017-06-23 12:18

MOT test number 938253554194

Result ✓ Passed



MOT #4 2017-06-23 09:32

MOT test number 503375226319

Result ✗ Failed

- Fail** Offside Rear Lower Suspension arm rubber bush bonding deteriorated resulting in excessive movement (2.4.G.2)
- Fail** Nearside Rear Lower Suspension arm rubber bush bonding deteriorated resulting in excessive movement (2.4.G.2)
- Advice** Front Brake pad(s) wearing thin (3.5.1g)

MOT #3 2016-06-28 16:32

MOT test number 107593033610

Result ✓ Passed

- Advice** Nearside Front Tyre worn close to the legal limit (4.1.E.1)
- Advice** Nearside Rear Tyre worn close to the legal limit (4.1.E.1)
- Advice** Nearside Front Brake pad(s) wearing thin (3.5.1g)
- Advice** Offside Front Tyre worn close to the legal limit (4.1.E.1)
- Advice** Offside Rear Tyre worn close to the legal limit (4.1.E.1)
- Advice** Offside Front Brake pad(s) wearing thin (3.5.1g)

MOT #2 2015-06-19 13:49

MOT test number 298400275418

Result ✓ Passed

MOT #1 2014-06-16 11:17

MOT test number 648547264138

Result ✓ Passed



Tax & MOT check

✓
Taxed

Tax due:
1 November 2024

✓
MOT

Expires:
23 October 2024

Tax status	Valid until 1 November
Days left	187
MOT expiry date	23 October 2024
Full MOT history	See MOT history

Tax calculation

Vehicle class	49
Band	F
Single payment (12 months)	£ 200,00,-
Single six month payment	£ 110,00,-
Total payable by 12 monthly instalments	£ 210,00,-




Damage history

Check the damage history for this VOLVO. See if, where and when this VOLVO had damage and the car repair costs. We also check if this VOLVO was scrapped. Download the premium report [here](#) for the results.

Damage 1

Date	
Category	
Type	



Damage 2

Date	
Category	
Type	



Extra VOLVO salvage check



If this vehicle was seen at a salvage auction we offer: vehicle pictures, salvage location, retail value. Download the premium report [here](#) for more information.

More info >



Vehicle valuation

What is this car worth? See the vehicle value of this VOLVO in the premium report. We check: purchase value, age, mileage, MOT history, damages and online sale prices.

Trade retail value	£ 19,999
Auction value	£ 19,999
Average private trade value	£ 19,999

[More info >](#)



Owner history

For how long did the current and previous owner(s) have this VOLVO? How many owners did this VOLVO have? Check it in the premium report and see all owner registrations. Download the full report [here](#).

Owner	Start	End

More info >

Plate changes

See in this check if this VOLVO had different number plates.

Number of plates	1
Current registration	VA11CKV
Plate since	2024-03-28
Current registration	VA11CKV
Plate since	2024-03-28

More info >



Finance check

Check if this VOLVO is financed, has an outstanding loan or finance agreement. If you are purchasing a vehicle it is smart to ensure that any finance that may have been taken out on this VOLVO has been settled. If not, and you buy this VOLVO then you could lose the money and the car you paid for. Download the premium report [here](#) and check if this VOLVO is financed.

Finance company	REDACTED
Date of agreement	REDACTED
Agreement type	REDACTED
Agreement term	REDACTED
Agreement number	REDACTED
Contact info	REDACTED

More info >



Mileage check

Odometer	In miles
Mileage registrations	15
First mileage registration	2011-06-30
Last registration	2023-10-24
Complete history	See info



Registration #1	2011-06-30	24 mi
Registration #2	2014-06-16	10.681 mi
Registration #3	2015-06-19	18.216 mi
Registration #4	2016-06-28	25.661 mi
Registration #5	2017-06-23	32.385 mi
Registration #6	2017-06-23	32.385 mi
Registration #7	2018-05-29	37.390 mi
Registration #8	2019-05-22	43.544 mi
Registration #9	2019-05-22	43.544 mi
Registration #10	2019-05-22	43.544 mi
Registration #11	2019-05-22	43.544 mi
Registration #12	2019-05-22	43.544 mi
Registration #13	2019-05-22	43.544 mi
Registration #14	2019-05-22	43.544 mi
Registration #15	2019-05-22	43.544 mi

[More info >](#)



Car features

The VOLVO factory car options list is only available in the premium report.

S0225	Air conditioning
S0295	
S0482	
S0501	
S0566	
S0567	
S0569	

View the complete VOLVO factory list for this vehicle [here](#).

More info >

Safety ratings

NCAP rating ★★★★★

Video [see crash video](#)



Dimensions & weight

Width	1865 mm
Height	1484 mm
Length	4628 mm
Wheel base	2778 mm
Kerb weight	1685 kg
Max. allowed weight	2200 kg

Additional information

Fuel tank capacity	67 l
Fuel delivery	Direct Injection
Number of doors	5
Number of seats	5

Number of axles	2
Engine number	1061345