





report date: 2024-03-28

General information

Make	FORD
Model	FIESTA EDGE
Colour	Blue
Year of manufacture	2010
Top speed	94 mph
0 - 60 mph	16.9 seconds
Gearbox	5 speed Manual

Engine & fuel consumption

Power	59 BHP
Max. torque	109 Nm at 3.600 rpm
Engine capacity	1.242 cc
Cylinders	4
Fuel type	Petrol
Consumption city	38.7 mpg
Consumption extra urban	64.2 mpg
Consumption combined	51.4 mpg
CO2 emission	127 g/km
CO2 label	D



CarCheck.co.uk page 1/15



AV10PZU report date: 2024-03-28

Internet history

Entry 1

Date	2021-01-30	
Pictures	1	
Listing price	<u>View report</u>	



source: autoonline.co.uk

CarCheck.co.uk page 2/15



report date: 2024-03-28

MOT history

MOT expiry date	2025-04-21
MOT pass rate	71 %
MOT passed	12
Failed MOT tests	5
Total advice items	42
Total items failed	12

MOT #17	2024-04-18 14:55
MOT test number	350631471620
Result	✓ Passed
Next expiry date	2025-04-21
Advice Nearside Front Road wheel slightly distorted (5.2.2 (c) (i))	

MOT #16	2024-04-18 13:20
MOT test number	660236068850
Result	X Failed
Fail Nearside Front Lower Suspension component ball joint excessively worn (5.3.4 (a) (Advice Nearside Front Road wheel slightly distorted (5.2.2 (c) (i))	i))

MOT #15	2023-04-18 13:49
MOT test number	742435569179
Result	✓ Passed
Advice Offside Front Tyre slightly damaged/cracking or perishing (5.2.3 (d) (ii)) Advice Front Inner Tyre worn close to legal limit/worn on edge both sides (5.2.3 (e))	

CarCheck.co.uk page 3/15



report date: 2024-03-28

MOT test number

Result

Advice Rear Axle swivel pins and bushes swivel pin and/or bush slightly worn (5.1.2 (b) (i))

Advice Front Tyre worn close to legal limit/worn on edge (5.2.3 (e))

Advice Nearside Front Tyre slightly damaged/cracking or perishing (5.2.3 (d) (ii))

MOT test number

602437394282

Result

Exhaust carbon monoxide content after 2nd fast idle exceeds default limits (8.2.1.2 (b))

Advice

Front Tyre worn close to legal limit/worn on edge (5.2.3 (e))

Advice

Nearside Front Tyre slightly damaged/cracking or perishing (5.2.3 (d) (ii))

Advice

Rear Axle swivel pins and bushes swivel pin and/or bush slightly worn (5.1.2 (b) (i))

MOT #12

MOT test number

838940114640

Result

Advice

Offside Front Outer Track rod end ball joint has slight play (2.1.3 (b) (i))

 MOT #11
 2020-01-22 17:18

 MOT test number
 227322341350

 Result
 ✓ Passed

CarCheck.co.uk page 4/15



report date: 2024-03-28

MOT #10 2020-01-18 12:18

MOT test number 375326751805

Result × Failed

Advice Nearside Suspension arm ball joint has slight play (5.3.4 (a) (i))

Advice Front Brake disc worn, pitted or scored, but not seriously weakened (1.1.14 (a) (ii))

Advice Heat shield loose

Fail Offside Rear Direction indicator incorrect colour (4.4.3 (a))

Fail Offside Front Suspension arm ball joint excessively worn (5.3.4 (a) (i))

Advice Nearside Play in steering rack inner joint(s)

Fail Supplementary restraint system warning lamp indicates a fault (7.1.6 (a))

Advice Knock in steering rack

Fail Offside Front Drive shaft joint constant velocity boot split or insecure, no longer prevents the ingress of dirt (6.1.7 (g) (ii))

MOT #9 2019-04-15 11:34

MOT test number 641368283696

Result
✓ Passed

Advice Nearside Rear Tyre worn close to legal limit/worn on edge (5.2.3 (e))

Minor Offside Front Outer Drive shaft joint constant velocity boot severely deteriorated (6.1.7 (g) (i))

Advice Offside Play in steering rack inner joint(s)

Advice Nearside Rear Road wheel slightly distorted (5.2.2 (c) (i))


Advice Offside Rear Tyre worn close to legal limit/worn on edge (5.2.3 (e))

Advice Knock felt at steering wheel.

CarCheck.co.uk page 5/15



report date: 2024-03-28



MOT #7		2018-04-23 07:33
MOT test	number	817248550538
Result		✓ Passed
Advice	Items removed from driver's view prior to test	
Advice	Front flexi exhaust deteriorated.	
Advice	Front brake disc worn, pitted or scored, but not seriously weakened (3.5.1i)	
Advice	Offside Rear Direction indicator slightly discoloured (1.4.A.2f)	
Advice	O/S/F slight play detected at wheel.	

CarCheck.co.uk page 6/15



report date: 2024-03-28

MOT #6 2018-04-12 11:09 **MOT test number** 159263129976 Result × Failed Fail Windscreen has damage to an area in excess of a 10mm circle within zone 'A' (8.3.1a) Fail Nearside Stop lamp not working (1.2.1b) Advice Offside Rear Direction indicator slightly discoloured (1.4.A.2f) Advice Front brake disc worn, pitted or scored, but not seriously weakened (3.5.1i) O/S/F slight play detected at wheel. Advice Advice Items removed from driver's view prior to test Fail Offside Stop lamp not working (1.2.1b) Rear registration plate deteriorated (6.3.1d) Fail **Advice** Front flexi exhaust deteriorated.

MOT #5		2017-05-08 08:38
MOT test	number	720012910136
Result		✓ Passed
Advice	Nearside Front Tyre worn close to the legal limit (4.1.E.1)	
Advice	Rear registration plate deteriorated but not likely to be misread (6.3.1d)	
Advice	Front Brake pad(s) wearing thin (3.5.1g)	
Advice	Offside Front Tyre worn close to the legal limit (4.1.E.1)	

MOT #4	2016-04-27 11:15
MOT test number	157806027121
Result	✓ Passed

CarCheck.co.uk page 7/15



report date: 2024-03-28

MOT #3	2015-05-18 08:38
MOT test number	859078535176
Result	✓ Passed
MOT #2	2014-05-13 15:21
MOT test number	348593234171
Result	✓ Passed
MOT #1	2013-04-26 07:39
MOT test number	465946613149
Result	✓ Passed

CarCheck.co.uk page 8/15



report date: 2024-03-28

Tax & MOT check



Tax status	Valid until 1 April
Days left	337
MOT expiry date	21 April 2025
Full MOT history	See MOT history

Tax calculation

Vehicle class	48
Band	D
Single payment (12 months)	£ 150,00,-
Single six month payment	£ 82,50,-
Total payable by 12 monthly instalments	£ 157,50,-

CarCheck.co.uk page 9/15




report date: 2024-03-28

Damage history

Check the damage history for this FORD. See if, where and when this FORD had damage and the car repair costs. We also check if this FORD was scrapped. Download the premium report <u>here</u> for the results.

Damage 1
Date
Category
Type
Damage 2
Date
Category
Type



Extra FORD salvage check



If this vehicle was seen at a salvage auction we offer: vehicle pictures, salvage location, retail value. Download the premium report <u>here</u> for more information.

More info >

CarCheck.co.uk page 10/15



report date: 2024-03-28

Vehicle valuation

What is this car worth? See the vehicle value of this FORD in the premium report. We check: purchase value, age, mileage, MOT history, damages and online sale prices.

Trade retail value

Auction value

Average private trade value

More info >

CarCheck.co.uk page 11/15



report date: 2024-03-28

Owner history

For how long did the current and previous owner(s) have this FORD? How many owners of Check it in the premium report and see all owner registrations. Download the full report		ave?

	More info	>
Plate changes		
See in this check if this FORD had different number plates.		
Number of plates		
Current registration	UK UK	
Plate since		
Current registration	UK UK	
Plate since		
	More info	

page 12/15 CarCheck.co.uk



AV10PZU report date: 2024-03-28

Finance check

Check if this FORD is financed, has an outstanding loan or finance agreement. If you are purchasing a vehicle it is smart to ensure that any finance that may have been taken out on this FORD has been settled.

If not, and you buy this FORD then you could lose the money and the car you paid for.

Download the premium report <u>here</u> and check if this FORD is financed.

Finance company	
Date of agreement	
Agreement type	
Agreement term	
Agreement number	
Contact info	

More info >

CarCheck.co.uk page 13/15



report date: 2024-03-28

Mileage check

Odometer	In miles
Mileage registrations	19
First mileage registration	2010-05-26
Last registration	2024-04-18
Complete history	See info



Registration #1	2010-05-26	22 mi
Registration #2	2013-04-26	31.003 mi
Registration #3	2014-05-13	39.430 mi
Registration #4	2015-05-18	47.493 mi
Registration #5	2016-04-27	54.258 mi
Registration #6	2017-05-08	60.052 mi
Registration #7	2018-04-12	65.527 mi
Registration #8	2018-04-23	65.687 mi
Registration #9	2019-04-15	74.450 mi
Registration #10	2019-04-15	74.450 mi
Registration #11		11.777 es
Registration #12		11.777 es
Registration #13		11.777 es
Registration #14		11.777 es
Registration #15		91.777 es
Registration #16		11.777 es
Registration #17		11.777 es
Registration #18		11.777 es
Registration #19		

More info >

CarCheck.co.uk page 14/15



AV10PZU report date: 2024-03-28

Car features

S0225	Air conditionir
S0295	
S0482	
S0501	
S0566	
S0567	
S0569	

Safety ratings

NCAP rating	****
Video	see crash video



Dimensions & weight

Width	1973 mm
Height	1481 mm
Length	3950 mm
Kerb weight	1098 kg
Max. allowed weight	1490 kg

Additional information

Fuel tank capacity	42
Fuel delivery	Multi-Point Injection
Number of doors	3
Number of seats	5
Number of axles CarCheck.co.uk	2 page 15/15

Engine number

9K62960