





report date: 2024-03-29

# General information

Make	RENAULT
Model	GRAND SCENIC GRAND DYNAMIQUE TOMTOM DCI FAP
Colour	Blue
Year of manufacture	2011
Top speed	112 mph
Gearbox	6 speed Manual

# Engine & fuel consumption

Power	110 BHP
Max. torque	260 Nm at 1.750 rpm
Engine capacity	1.461 cc
Cylinders	4
Fuel type	Diesel
Consumption city	62.8 mpg
Consumption extra urban	72.4 mpg
Consumption combined	68.9 mpg
CO2 emission	128 g/km
CO2 label	D



CarCheck.co.uk page 1/13



report date: 2024-03-29


# Internet history

# Entry 1

Date 2021-10-30

Pictures 14

Listing price <u>View report</u>









source: cargurus.co.uk

CarCheck.co.uk page 2/13



report date: 2024-03-29

	~-				
10/1/	TC	h		-	r\ /
1011		ш	51	LUI	l V
	•			-	. ,

MOT expiry date	2024-11-07
MOT pass rate	69 %
MOT passed	11
Failed MOT tests	5
Total advice items	25
Total items failed	7

MOT #16	2023-10-31 16:56
MOT test number	685363902413
Result	✓ Passed
Next expiry date	2024-11-07

MOT a	<b>#15</b>	2023-10-31 13:59
MOT t	est number	474722790738
Resul	t	<b>×</b> Failed
Fail	Offside Stop lamp(s) not working (4.3.1 (a) (ii))	
Fail	Nearside Stop lamp(s) not working (4.3.1 (a) (ii))	
Fail	Nearside Track rod end ball joint has excessive play (2.1.3 (b) (i))	

MOT #14	2022-10-19 10:20
MOT test number	175043011064
Result	✓ Passed
Advice Offside Rear Tyre slightly damaged/cracking or perishing (5.2.3 (d) (ii))	

MOT #13		2021-11-08 15:11
MOT test	number	253041833939
Result		<b>✓</b> Passed
Advice	Offside Front Tyre slightly damaged/cracking or perishing outer e	dge perishing (5.2.3 (d) (ii))

CarCheck.co.uk page 3/13



report date: 2024-03-29

**MOT #12** 2021-11-08 15:11

**MOT test number** 627339670726

**Result** X Failed

Advice Offside Front Tyre slightly damaged/cracking or perishing outer edge perishing (5.2.3 (d) (ii))

**Pass with rectification** Spare wheel carrier insecure (6.1.5 (a))

**MOT #11** 2021-03-15 14:30

MOT test number 242135011531

Result \sqrt{Passed}

Advice Nearside Front Tyre worn close to legal limit/worn on edge (5.2.3 (e))

Advice Offside Front Tyre slightly damaged/cracking or perishing (5.2.3 (d) (ii))

**Advice** Offside Front Tyre worn close to legal limit/worn on edge (5.2.3 (e))

**Advice** Offside Front Coil spring corroded (5.3.1 (b) (i))

**MOT #10** 2021-03-15 09:29

**MOT test number** 376339711512

**Result** X Failed

**Advice** Offside Front Tyre worn close to legal limit/worn on edge (5.2.3 (e))

**Fail** Offside Rear Coil spring fractured or broken (5.3.1 (b) (i))

Advice Nearside Front Tyre worn close to legal limit/worn on edge (5.2.3 (e))

**Advice** Offside Front Coil spring corroded (5.3.1 (b) (i))

Advice Offside Front Tyre slightly damaged/cracking or perishing (5.2.3 (d) (ii))

CarCheck.co.uk page 4/13



report date: 2024-03-29

MOT #9

MOT test number

275675347455

Result

Advice Rear Registration plate deteriorated but not likely to be misread (0.1 (b))

Advice Nearside Rear Tyre slightly damaged/cracking or perishing 3mm (5.2.3 (d) (ii))

**MOT #8** 2020-03-12 11:48 **MOT** test number 761225274158 Result **X** Failed **Advice** Front Brake disc worn, pitted or scored, but not seriously weakened (1.1.14 (a) (ii)) Fail Nearside Front Headlamp not working on dipped beam (4.1.1 (a) (ii)) Rear Service brake binding but not excessively Both (1.2.1 (f)) Advice **Advice** Front Brake pad(s) wearing thin (1.1.13 (a) (ii)) Advice Nearside Rear Tyre slightly damaged/cracking or perishing 3mm (5.2.3 (d) (ii)) **Advice** Rear Registration plate deteriorated but not likely to be misread (0.1 (b))

MOT #7		2019-03-26 16:17
MOT test nur	nber	403313206620
Result		<b>✓</b> Passed
<b>Advice</b> No. (5.3.4 (a) (i))	earside Front Inner Suspension arm pin or bush worn but not resultii	ng in excessive movement
<b>Advice</b> Re	ear Registration plate deteriorated but not likely to be misread (0.1	(b))
<b>Advice</b> Of (5.3.4 (a) (i))	ffside Front Inner Suspension arm pin or bush worn but not resulting	g in excessive movement

CarCheck.co.uk page 5/13



report date: 2024-03-29

MOT #6 2019-03-26 11:01

**MOT test number** 922047949765

Result X Failed

Advice Rear Registration plate deteriorated but not likely to be misread (0.1 (b))

Fail Nearside Front Tyre tread depth below requirements of 1.6mm (5.2.3 (e))

**Advice** Offside Front Inner Suspension arm pin or bush worn but not resulting in excessive movement (5.3.4 (a) (i))

Advice Nearside Front Inner Suspension arm pin or bush worn but not resulting in excessive movement (5.3.4 (a) (i))

MOT #5 2018-03-27 08:12

MOT test number 263349462834

**MOT #4** 2017-03-24 08:49

**MOT test number** 740966537168

**Result** 
✓ Passed

**Advice** Offside Front Tyre worn close to the legal limit Edges (4.1.E.1)

MOT #3 2016-03-07 11:32

MOT test number 474574032367

**Result** 
✓ Passed

MOT #2 2015-03-03 15:33

**MOT test number** 845042565034

**MOT #1** 2014-02-27 10:49

**MOT test number** 508788354017

Result 

Passed

CarCheck.co.uk page 6/13



HV11POF report date: 2024-03-29

# Tax & MOT check



Tax status	Valid until 1 November
Days left	186
MOT expiry date	7 November 2024
Full MOT history	See MOT history

# Tax calculation

Vehicle class	49
Band	D
Single payment (12 months)	£ 150,00,-
Single six month payment	£ 82,50,-
Total payable by 12 monthly instalments	£ 157,50,-

CarCheck.co.uk page 7/13




report date: 2024-03-29

## Damage history

Check the damage history for this RENAULT. See if, where and when this RENAULT had damage and the car repair costs. We also check if this RENAULT was scrapped. Download the premium report <a href="https://example.com/here">here</a> for the results.

Damage 1
Date
Category
Type
Damage 2
Date
Category
Type



### Extra RENAULT salvage check



If this vehicle was seen at a salvage auction we offer: vehicle pictures, salvage location, retail value. Download the premium report <u>here</u> for more information.

More info >

CarCheck.co.uk page 8/13



HV11POF report date: 2024-03-29

Vehicle valuation

What is this car worth? See the vehicle value of this RENAULT in the premium report. We check: purchase value, age, mileage, MOT history, damages and online sale prices.

**Trade retail value** 

**Auction value** 

Average private trade value

More info >

CarCheck.co.uk page 9/13



faste since

**HV11POF** 

report date: 2024-03-29

# Owner history For how long did the current and previous owner(s) have this RENAULT? How many owners did this RENAULT have? Check it in the premium report and see all owner registrations. Download the full report here. More info > Plate changes See in this check if this RENAULT had different number plates.

More info >

CarCheck.co.uk page 10/13



HV11POF report date: 2024-03-29

Finance check

Check if this RENAULT is financed, has an outstanding loan or finance agreement. If you are purchasing a vehicle it is smart to ensure that any finance that may have been taken out on this RENAULT has been settled.

If not, and you buy this RENAULT then you could lose the money and the car you paid for.

Download the premium report <u>here</u> and check if this RENAULT is financed.

Finance company	
Date of agreement	
Agreement type	
Agreement term	
Agreement number	

**Contact info** 

More info >

CarCheck.co.uk page 11/13



report date: 2024-03-29

# Mileage check

Odometer	In miles
Mileage registrations	18
First mileage registration	2011-03-10
Last registration	2023-10-31
Complete history	See info



Registration #1	2011-03-10	25 mi
Registration #2	2014-02-27	18.969 mi
Registration #3	2015-03-03	25.063 mi
Registration #4	2016-03-07	31.432 mi
Registration #5	2017-03-24	37.379 mi
Registration #6	2018-03-27	44.779 mi
Registration #7	2019-03-26	50.970 mi
Registration #8	2019-03-26	50.970 mi
Registration #9	2020-03-12	56.048 mi
Registration #10		11.777 es
Registration #11		11.777 es
Registration #12		11.777 es
Registration #13		11.777 es
Registration #14		11.777 es
Registration #15		11.777 es
Registration #16		11.777 es
Registration #17		11.777 es
Registration #18		71.777 es

More info >

CarCheck.co.uk page 12/13



HV11POF report date: 2024-03-29

# Car features

S0225	Air conditioning
S0295	
50482	
S0501	
S0566	
S0567	
S0569	

# Safety ratings

NCAP rating	****
Adult	91%
Children	76%
Pedestrian	42%
Safety systems	99%
Overall rating	79%
Video	see crash video



# Dimensions & weight

Width	1845 mm
Height	1672 mm
Length	4573 mm
Wheel base	2770 mm
Kerb weight	1430 kg
Max. allowed weight	2128 kg

# Additional information

Fuel delivery	Direct Injection	
Number of doors	5	
Number of seats	7	
Number of axles CarCheck.co.uk	2	page 13/13