





report date: 2024-03-29

General information

Make	CITROEN
Model	BERLINGO HDI PLATINUM PICASSO
Colour	Silver
Year of manufacture	2013
Top speed	112 mph
0 - 60 mph	12.8 seconds
Gearbox	6 speed Manual

Engine & fuel consumption

Power	110 BHP
Max. torque	285 Nm at 1.750 rpm
Engine capacity	1.560 cc
Cylinders	4
Fuel type	Diesel
Consumption city	45.6 mpg
Consumption extra urban	61.4 mpg
Consumption combined	54.3 mpg
CO2 emission	135 g/km
CO2 label	E



CarCheck.co.uk page 1/13



report date: 2024-03-29


Internet history

Entry 1

Date 2021-01-22

Pictures 36

Listing price <u>View report</u>









source: yesauto.com

CarCheck.co.uk page 2/13



WG62XBE report date: 2024-03-29

MOT history

MOT expiry date	2025-02-07
MOT pass rate	75 %
MOT passed	9
Failed MOT tests	3
Total advice items	10
Total items failed	14

MOT #12	2024-02-08 16:55
MOT test number	227647078687
Result	✓ Passed
Next expiry date	2025-02-07
Advice Rear seats missing at time of test	

CarCheck.co.uk page 3/13



Fail

WG62XBE

report date: 2024-03-29

MOT #11 2024-01-31 10:13 **MOT** test number 433920715398 Result **X** Failed Fail Offside Rear Direction indicator incorrect colour (4.4.3 (a)) Fail Offside Front Service brake excessively fluctuating (1.2.1 (e)) Fail Front Headlamp aim unable to be tested (4.1.2 (b)) Advice Rear seats missing at time of test Nearside Front Brake pad(s) less than 1.5 mm thick (1.1.13 (a) (ii)) Fail Fail Offside Front Upper Macpherson strut pin or bush excessively worn top strut mounting (5.3.4 (a) (i)) Fail Offside Rear Tyre tread depth below requirements of 1.6mm (5.2.3 (e)) Fail Nearside Rear Service brake excessively binding (1.2.1 (f)) Fail Rear Brakes imbalanced across an axle 35% imbalance (1.2.1 (b) (i)) Fail Front Headlamp has a product on the lens so that the light output is severely reduced (4.1.4 (b)) Fail Rear Registration plate lamp inoperative in the case of a single lamp or all lamps (4.7.1 (b) (ii)) **Advice** Rear Brake pad(s) wearing thin (1.1.13 (a) (ii)) Fail Nearside Front Service brake excessively binding (1.2.1 (f))

MOT #10		2023-01-11 11:26
MOT test	number	877495076403
Result		✓ Passed
Advice	Offside Front Tyre worn close to legal limit/worn on edge (5.2.3 (e))	
Advice	Nearside Front Tyre worn close to legal limit/worn on edge (5.2.3 (e))	
Advice	Nearside Rear Tyre worn close to legal limit/worn on edge (5.2.3 (e))	
Minor (i))	Offside Registration plate lamp inoperative in the case of multiple lamps or ligh	t sources (4.7.1 (b)

Front Brakes imbalanced across an axle 58% imbalance (1.2.1 (b) (i))

CarCheck.co.uk page 4/13



report date: 2024-03-29

MOT #9 2022-01-07 16:27

MOT test number 599032876834

Result
✓ Passed

MOT #8 2022-01-07 11:31

MOT test number 133941822126

Result ★ Failed

Fail Nearside Front Windscreen wiper does not clear the windscreen effectively wiper blade split (3.4 (b) (ii))

MOT #7 2021-01-15 11:08

MOT test number 511773766779

MOT #6 2021-01-06 17:16

MOT test number 771851706950

Result X Failed

Advice Offside Front Tyre slightly damaged/cracking or perishing (5.2.3 (d) (ii))

Advice Nearside Tyre slightly damaged/cracking or perishing Front and Rear (5.2.3 (d) (ii))

Fail Nearside Front Position lamp not working (4.2.1 (a) (ii))

Advice Rear Brake pad(s) wearing thin (1.1.13 (a) (ii))

MOT #5 2020-02-19 10:03

MOT test number 324594433878

Result \(\sqrt{Passed} \)

MOT #4 2019-02-27 09:08

MOT test number 168278676698

CarCheck.co.uk page 5/13



report date: 2024-03-29

MOT #3 2018-03-06 10:54 **MOT test number** 370901498799 ✓ Passed Result MOT #2 2017-03-07 16:00 **MOT test number** 634215352643 Result ✓ Passed MOT #1 2016-02-02 10:58 533273673500 **MOT test number** Result ✓ Passed

CarCheck.co.uk page 6/13



report date: 2024-03-29

Tax & MOT check



Tax status	Valid until 1 February
Days left	277
MOT expiry date	7 February 2025
Full MOT history	See MOT history

Tax calculation

Vehicle class	49
Band	Е
Single payment (12 months)	£ 180,00,-
Single six month payment	£ 99,00,-
Total payable by 12 monthly instalments	£ 189,00,-

CarCheck.co.uk page 7/13




report date: 2024-03-29

Damage history

Check the damage history for this CITROEN. See if, where and when this CITROEN had damage and the car repair costs. We also check if this CITROEN was scrapped. Download the premium report <u>here</u> for the results.

Damage 1
Date
Category
Type
Damage 2
Date
Category
Type



Extra CITROEN salvage check



If this vehicle was seen at a salvage auction we offer: vehicle pictures, salvage location, retail value. Download the premium report <u>here</u> for more information.

More info >

CarCheck.co.uk page 8/13



report date: 2024-03-29

Vehicle valuation

What is this car worth? See the vehicle value of this CITROEN in the premium report. We check: purchase value, age, mileage, MOT history, damages and online sale prices.

Trade retail value

Auction value

Average private trade value

More info >

CarCheck.co.uk page 9/13



report date: 2024-03-29

\sim	MID.	~ r	hi	cti	200
יטי	wn	er.	ш	SU	ע וכ

For how long did the current and previous owner(s) have this CITROEN? How many owners did this CITROEN have? Check it in the premium report and see all owner registrations. Download the full report here. More info > Plate changes See in this check if this CITROEN had different number plates. More info >		
See in this check if this CITROEN had different number plates.		
See in this check if this CITROEN had different number plates.		
See in this check if this CITROEN had different number plates.		
See in this check if this CITROEN had different number plates.		
See in this check if this CITROEN had different number plates.		
See in this check if this CITROEN had different number plates.	*********	
See in this check if this CITROEN had different number plates.		
See in this check if this CITROEN had different number plates.	***************************************	
See in this check if this CITROEN had different number plates.		More info >
器 UK UK	Plate changes	
THE REPORT OF THE PROPERTY OF	See in this check if this CITROEN had different number plates.	
THE REPORT OF THE PROPERTY OF	Number of plates	,
Plate since	Current registration	UK SIE
Plate since	Plate since	
More info >	Current registration	NK SIN
More info >	Plate since	
		More info >

CarCheck.co.uk page 10/13



report date: 2024-03-29

Finance check

Check if this CITROEN is financed, has an outstanding loan or finance agreement. If you are purchasing a vehicle it is smart to ensure that any finance that may have been taken out on this CITROEN has been settled.

If not, and you buy this CITROEN then you could lose the money and the car you paid for.

Download the premium report <u>here</u> and check if this CITROEN is financed.

Finance company

Date of agreement

Agreement type

Agreement term

Agreement number

Contact info

More info >

CarCheck.co.uk page 11/13



report date: 2024-03-29

Mileage check

Registration #14

Odometer	In miles
Mileage registrations	14
First mileage registration	2013-01-31
Last registration	2024-02-08
Complete history	See info



Registration #1	2013-01-31	13 mi
Registration #2	2016-02-02	27.537 mi
Registration #3	2017-03-07	32.637 mi
Registration #4	2018-03-06	36.147 mi
Registration #5	2019-02-27	39.105 mi
Registration #6	2020-02-19	41.380 mi
Registration #7	2021-01-06	42.858 mi
Registration #8		77.777-00
Registration #9		7.77 44
Registration #10		77.777 44
Registration #11		71.777 46
Registration #12		77.777 460
Registration #13		11.177 es

mn.n.n

More info >

77.777 86

CarCheck.co.uk page 12/13



WG62XBE report date: 2024-03-29

Safety ratings

NCAP rating	****
Adult	90%
Children	85%
Pedestrian	43%
Safety systems	97%
Overall rating	80%
Video	see crash video



Dimensions & weight

Width	1830 mm
Height	1680 mm
Length	4470 mm
Wheel base	2728 mm
Kerb weight	1430 kg
Max. allowed weight	2050 kg

Additional information

Fuel delivery	Direct Injection
Number of doors	5
Number of seats	5
Number of axles	2
Engine number	JBER3194270

CarCheck.co.uk page 13/13