



report date: 2024-03-29

General information

Make	MAZDA
Model	MX-5 I ROADSTER
Colour	Silver
Year of manufacture	2008
Top speed	122 mph
0 - 60 mph	9.4 seconds
Gearbox	5 speed Manual

Engine & fuel consumption

Power	124 BHP
Max. torque	167 Nm at 4.500 rpm
Engine capacity	1.798 cc
Cylinders	4
Fuel type	Petrol
Consumption city	28.5 mpg
Consumption extra urban	48.7 mpg
Consumption combined	38.7 mpg
CO2 emission	174 g/km
CO2 label	H





Internet history

Entry 1

Date	2021-06-16
Pictures	9
Listing price	View report



source: autotrader.co.uk



MOT history

MOT expiry date	2024-06-14
MOT pass rate	76 %
MOT passed	13
Failed MOT tests	4
Total advice items	13
Total items failed	5

MOT #17 2023-05-30 13:50

MOT test number 991260043963

Result ✓ Passed

Next expiry date 2024-06-14

Advice Central Rear Subframe mounting prescribed area is corroded but not considered excessive (5.3.6 (a) (i))

Advice Nearside Front Headlamp has a product on the light source but not seriously reducing light output (4.1.4 (b))

Advice Central Brake pipe corroded, covered in grease or other material x2 hard pipes on underside going to rear starting beside gearbox coated in grease/sealer (1.1.11 (c))

MOT #16 2022-06-13 12:14

MOT test number 500168147260

Result ✓ Passed

MOT #15 2021-06-15 15:55

MOT test number 627842871434

Result ✓ Passed

MOT #14 2020-10-08 12:37

MOT test number 827908471318

Result ✓ Passed

Advice Exhaust has a minor leak of exhaust gases (6.1.2 (a))

**MOT #13** 2019-05-16 07:34**MOT test number** 694245135135**Result** ✓ Passed**Advice** Exhaust has a minor leak of exhaust gases (6.1.2 (a))**Advice** Heavy surface corrosion underneath**MOT #12** 2018-05-24 13:37**MOT test number** 157515841762**Result** ✓ Passed**Advice** Offside Rear Anti-roll bar linkage ball joint has slight play (5.3.4 (a) (i))**MOT #11** 2018-05-24 11:27**MOT test number** 441221093611**Result** ✗ Failed**Advice** Offside Rear Anti-roll bar linkage ball joint has slight play (5.3.4 (a) (i))**Fail** Nearside Front Anti-roll bar linkage ball joint excessively worn (5.3.4 (a) (i))**Advice** Nearside Front Slight Brake Bind**MOT #10** 2017-06-14 12:37**MOT test number** 464771917419**Result** ✓ Passed**MOT #9** 2016-10-05 08:29**MOT test number** 684639817660**Result** ✓ Passed

**MOT #8** 2016-10-04 13:48**MOT test number** 793589858534**Result** ✗ Failed**Fail** Exhaust emissions Lambda reading after 2nd fast idle outside specified limits (7.3.D.3)**MOT #7** 2015-10-28 09:24**MOT test number** 886388454013**Result** ✓ Passed**MOT #6** 2014-09-27 10:12**MOT test number** 129190774233**Result** ✓ Passed**Advice** Offside Front Anti-roll bar linkage worn but not seriously weakened (2.4.G.1)**Advice** Front Brake pad(s) wearing thin (3.5.1g)**MOT #5** 2013-10-11 16:55**MOT test number** 936634083262**Result** ✓ Passed**MOT #4** 2013-10-11 11:49**MOT test number** 129474483259**Result** ✗ Failed**Fail** Nearside Front coil spring broken (2.4.C.1a)**Notice** Items removed from driver's view prior to test**Fail** Offside Registration plate lamp not working (1.1.C.1d)**Advice** Offside Rear Tyre worn close to the legal limit (4.1.E.1)



MOT #3	2012-10-13 12:49
MOT test number	618447482237
Result	✓ Passed

MOT #2	2012-10-13 12:11
MOT test number	649377182241
Result	✗ Failed
<div><div>Fail</div>Offside Registration plate lamp not working (1.1.C.1d)</div>	

MOT #1	2011-10-01 12:38
MOT test number	205754471269
Result	✓ Passed



Tax & MOT check

✓
Taxed

Tax due:
1 April 2025

✓
MOT

Expires:
14 June 2024

Tax status	Valid until 1 April
Days left	337
MOT expiry date	14 June 2024
Full MOT history	See MOT history

Tax calculation

Vehicle class	48
Band	H
Single payment (12 months)	£ 290,00,-
Single six month payment	£ 159,50,-
Total payable by 12 monthly instalments	£ 304,50,-



Damage history

Check the damage history for this MAZDA. See if, where and when this MAZDA had damage and the car repair costs. We also check if this MAZDA was scrapped. Download the premium report [here](#) for the results.

Damage 1	
Date	
Category	
Type	
Damage 2	
Date	
Category	
Type	



Extra MAZDA salvage check



If this vehicle was seen at a salvage auction we offer: vehicle pictures, salvage location, retail value. Download the premium report [here](#) for more information.

More info >



Vehicle valuation

What is this car worth? See the vehicle value of this MAZDA in the premium report. We check: purchase value, age, mileage, MOT history, damages and online sale prices.

Trade retail value	£ 19,999
Auction value	£ 19,999
Average private trade value	£ 19,999

More info >



Owner history

For how long did the current and previous owner(s) have this MAZDA? How many owners did this MAZDA have? Check it in the premium report and see all owner registrations. Download the full report [here](#).

Owner	Start date
Owner	Start date
Owner	Start date
Owner	Start date
Owner	Start date
Owner	Start date
Owner	Start date

More info >

Plate changes

See in this check if this MAZDA had different number plates.

Number of plates	1
Current registration	YR58MXU
Plate since	2019-03-29
Current registration	YR58MXU
Plate since	2019-03-29

More info >



Finance check

Check if this MAZDA is financed, has an outstanding loan or finance agreement. If you are purchasing a vehicle it is smart to ensure that any finance that may have been taken out on this MAZDA has been settled.

If not, and you buy this MAZDA then you could lose the money and the car you paid for.

Download the premium report [here](#) and check if this MAZDA is financed.

Finance company	XXXXXXXXXX	XXXX
Date of agreement	XXXXXXXXXX	XXXX
Agreement type	XXXXXXXXXX	XXXX
Agreement term	XXXXXXXXXX	XXXX
Agreement number	XXXXXXXXXX	XXXX
Contact info	XXXXXXXXXX	XXXX

More info >



Mileage check

Odometer	In miles
Mileage registrations	19
First mileage registration	2008-09-30
Last registration	2023-05-30
Complete history	See info



Registration #1	2008-09-30	7 mi
Registration #2	2011-10-01	21.074 mi
Registration #3	2012-10-13	32.378 mi
Registration #4	2012-10-13	32.378 mi
Registration #5	2013-10-11	42.626 mi
Registration #6	2013-10-11	42.626 mi
Registration #7	2014-09-27	54.108 mi
Registration #8	2015-10-28	60.306 mi
Registration #9	2016-10-04	62.064 mi
Registration #10	2016-10-05	62.064 mi
Registration #11	2016-10-05	62.064 mi
Registration #12	2016-10-05	62.064 mi
Registration #13	2016-10-05	62.064 mi
Registration #14	2016-10-05	62.064 mi
Registration #15	2016-10-05	62.064 mi
Registration #16	2016-10-05	62.064 mi
Registration #17	2016-10-05	62.064 mi
Registration #18	2016-10-05	62.064 mi
Registration #19	2016-10-05	62.064 mi

More info >



Safety ratings

NCAP rating	★★★★☆
Video	see crash video



Dimensions & weight

Width	1720 mm
Height	1245 mm
Length	3995 mm
Wheel base	2330 mm
Kerb weight	1155 kg
Max. allowed weight	1365 kg

Additional information

Fuel tank capacity	50 l
Fuel delivery	Multi-Point Injection
Number of doors	2
Number of seats	2
Engine number	L8 20260874