





### General information

Make	RENAULT
Model	MEGANE DYNAMIQUE VVT 111
Colour	Blue
Year of manufacture	2008
Top speed	116 mph
0 - 60 mph	13.6 seconds
Gearbox	4 speed automatic

### Engine & fuel consumption

Power	110 BHP
Max. torque	152 Nm at 4.200 rpm
Engine capacity	1.598 cc
Cylinders	4
Fuel type	Petrol
Consumption city	26.2 mpg
Consumption extra urban	46.3 mpg
Consumption combined	36.2 mpg
CO2 emission	187 g/km
CO2 label	J








Internet history	
Entry 1	
Date	2021-08-05
Pictures	17
Listing price	View report







PLEASE CALL OUR TRADE CENTRE ON **07950 7448<u>87</u>** 

source: cargurus.co.uk



# MOT history

MOT expiry date	2024-08-28
MOT pass rate	76 %
MOT passed	13
Failed MOT tests	4
Total advice items	38
Total items failed	10

MOT #17	2023-08-29 14:39
MOT test number	916288153379
Result	🗸 Passed
Next expiry date	2024-08-28
Advice Nearside Rear tyre worn outer edge	
Advice Offside Front Headlamp has a product on the lens but not seriously reducing light output (4.1.4 (b))	
<b>Minor</b> Offside Rear Registration plate lamp inoperative in the case of multiple lamps or light sources (4.7.1 (b) (i))	
Advice Oil leak, but not excessive (8.4.1 (a) (i))	

MOT #16	2022-08-19 13:28
MOT test	number 341821649295
Result	✓ Passed
Advice (b))	Offside Front Headlamp has a product on the lens but not seriously reducing light output (4.1.4
Advice	Oil leak, but not excessive (8.4.1 (a) (i))





MOT #15	2022-08-18 10:24	
MOT test number	271138748469	
Result	🗙 Failed	
<b>Fail</b> Supplementary restraint system warning lamp indicates a fault (7.1.6 (a))		
Advice Oil leak, but not excessive (8.4.1 (a) (i))		
Fail (g) (ii))Nearside Front Steering rack gaiter missing or no longer prevents the ingress of dirt insecure (2.1.3		
Advice Offside Front Headlamp has a product on the lens but not seriously reducin (b))	ng light output (4.1.4	

MOT #14	2021-08-28 12:34
MOT test number	579660766730
Result	✓ Passed

MOT #13		2020-07-07 12:52
MOT test	number	363595816778
Result		✓ Passed
Advice	Offside Rear Tyre worn close to legal limit/worn on edge (5.2.3 (e))	
Advice	Nearside Front Road wheel slightly distorted inner rim (5.2.2 (c) (i))	





MOT #12	2020-07-01 07:59
MOT test number	109722645996
Result	🗙 Failed
Advice Offside Front Steering linkage ball joint has slight play inner tie rod (2.1.3 (b) (i)	)
Advice Nearside Front Tyre worn close to legal limit/worn on edge on the limit (5.2.3 (e	))
Fail Nearside Rear Wheel bearing has excessive play (5.1.3 (a) (i))	
Advice Nearside Front Steering linkage ball joint has slight play inner tie rod (2.1.3 (b) (	(i))
Advice Nearside Front Road wheel slightly distorted inner rim (5.2.2 (c) (i))	
Advice Offside Rear Tyre worn close to legal limit/worn on edge (5.2.3 (e))	
FailOffside Rear Wheel bearing has excessive play (5.1.3 (a) (i))	

MOT #11		2019-07-05 13:42
MOT test	number	876706337274
Result		✓ Passed
Advice	Nearside Rear Tyre slightly damaged/cracking or perishing (5.2.3 (d) (ii))	
Advice	Nearside Front Road wheel slightly distorted (5.2.2 (c) (i))	
Advice	Nearside Rear Wheel bearing slightly noisy on limit (5.1.3 (b) (i))	
Advice	Nearside Rear Wheel bearing has slight play on limit (5.1.3 (a) (i))	
Advice	Offside Front Tyre worn close to legal limit/worn on edge (5.2.3 (e))	
Advice	Offside Rear Tyre slightly damaged/cracking or perishing (5.2.3 (d) (ii))	
Advice	Shock absorbers has slight external damage to the casing all corroded (5.3.2 (b))	)
Advice	Offside Rear Wheel bearing slightly noisy on limit (5.1.3 (b) (i))	
Advice	Play in steering rack inner joint(s) on limit	
Advice	Offside Rear Wheel bearing has slight play on limit (5.1.3 (a) (i))	
Advice	Engine cover and under tray fitted	





MOT #10	2018-07-26 10:29
MOT test number	420086840860
Result	✓ Passed
Advice Front both top strut mounts stiff/ noisy	
MOT #9	2018-07-25 12:55
MOT test number	825989736085
Result	🗙 Failed
<b>Fail</b> Nearside Front Headlamp are incorrectly positioned (4.1.4 (a))	
FailFront Bumper insecure (6.1.4 (a) (i))	
<b>Fail</b> Front Headlamp insecure both sides (4.1.1 (c))	
Advice Front both top strut mounts stiff/ noisy	
<b>Fail</b> Front Headlamp aim too low both sides (4.1.2 (a))	

MOT #8	2017-07-25 13:20
MOT test number	565466578493
Result	✓ Passed

MOT #7		2017-07-25 13:20
MOT test number		446937679878
Result		🗙 Failed
Pass with rectification	Offside Front Headlamp not working on main beam (1.7.5a)	
Pass with rectification	Headlamp aim too low both front (1.8)	

МОТ #6	2016-07-02 15:41
MOT test number	655831611561
Result	✓ Passed



MOT #5	2	015-07-03 12:01
MOT test	number	959864985117
Result		✓ Passed
Advice	Nearside Front Brake pad(s) wearing thin (3.5.1g)	
Notice	Both front tyres scrubbed on inner edges and cracking	
Advice	Nearside Front Steering system has slight free play detected at steering wheel (2.2	.A.1b)
Notice	Play in steering rack inner joint(s)	
Advice	Offside Front Brake pad(s) wearing thin (3.5.1g)	

MOT #4		2014-07-26 11:03
MOT test	number	145017904276
Result		✓ Passed
Advice	Offside Front Brake pad(s) wearing thin (3.5.1g)	
Advice	Offside Front Tyre worn close to the legal limit (4.1.E.1)	
Advice	Nearside Front Brake pad(s) wearing thin (3.5.1g)	
Advice	Nearside Front Tyre worn close to the legal limit (4.1.E.1)	

MOT #3	2013-07-27 15:04
MOT test number	197298103233
Result	✓ Passed
MOT #2	2012-07-26 13:35
MOT test number	917248902280

🗸 Passed

MC08ZWK

report date: 2024-03-28





MOT #1	2011-03-22 11:51
MOT test number	429331181035
Result	✓ Passed
<b>Notice</b> Near side front wing has been taped over to prevent sharp edge	



Tax & MOT check

X Untaxed Tax expired: 4 November 2023	<b>MOT</b> Expires: 28 August 2024
Tax status	Expired at 4 November 2023
Days left	176 days too late
MOT expiry date	28 August 2024
Full MOT history	See MOT history
Tax calculation	

Vehicle class	48
Band	J
Single payment (12 months)	£ 365,00,-
Single six month payment	£ 200,75,-
Total payable by 12 monthly instalments	£ 383,25,-





#### Damage history

Check the damage history for this RENAULT. See if, where and when this RENAULT had damage and the car repair costs. We also check if this RENAULT was scrapped. Download the premium report <u>here</u> for the results.

Damage 1	
Date	FER I
Category	 A PLANE
Туре	
Damage 2	AMPLE
Damage 2	E Stand
Date	*
Category	 ante.
Туре	

#### Extra RENAULT salvage check

If this vehicle was seen at a salvage auction we offer: vehicle pictures, salvage location, retail value. Download the premium report <u>here</u> for more information.





#### Vehicle valuation

What is this car worth? See the vehicle value of this RENAULT in the premium report. We check: purchase value, age, mileage, MOT history, damages and online sale prices.

Trade retail value	4.00.000
Auction value	4 10.000
Average private trade value	4 10.200





### Owner history

For how long did the current and previous owner(s) have this RENAULT? How many owners did this RENAULT have? Check it in the premium report and see all owner registrations. Download the full report <u>here</u>.

ana	
***********	
*******	
******	
***********	
*******	
	More info >
Plate changes	
See in this check if this RENAULT had different number plates.	
Number of plates	,
Current registration	
Plate since	
Current registration	
Rule sizes	





#### Finance check

Check if this RENAULT is financed, has an outstanding loan or finance agreement. If you are purchasing a vehicle it is smart to ensure that any finance that may have been taken out on this RENAULT has been settled.

If not, and you buy this RENAULT then you could lose the money and the car you paid for.

Download the premium report <u>here</u> and check if this RENAULT is financed.

Finance company	
Date of agreement	
Agreement type	
Agreement term	
Agreement number	
Contact info	





### Mileage check

Odometer	In miles
Mileage registrations	19
First mileage registration	2008-04-21
Last registration	2023-08-29
Complete history	See info



Registration #1	2008-04-21	22 mi
Registration #2	2011-03-22	20.468 mi
Registration #3	2012-07-26	27.286 mi
Registration #4	2013-07-27	32.358 mi
Registration #5	2014-07-26	37.322 mi
Registration #6	2015-07-03	39.640 mi
Registration #7	2016-07-02	45.121 mi
Registration #8	2017-07-25	49.458 mi
Registration #9	2017-07-25	49.458 mi
Registration #10	2018-07-25	52.808 mi
Registration #11		11.777 mi
Registration #12		11.777 esi
Registration #13		11.777 mi
Registration #14		11.777 esi
Registration #15		11.777 mi
Registration #16		11.777 esi
Registration #17		11.777 mi
Registration #18		11.777 mi
Registration #19		





### Car features

S0225	Air conditioning
\$0295	
50482	
50501	
60566	
60567	
60569	

## Safety ratings

**NCAP** rating

Video

\*\*\*\* see crash video



Dimensions & weight	
Width	2026 mm
Height	1404 mm
Length	4355 mm
Wheel base	2522 mm
Kerb weight	1365 kg
Max. allowed weight	1800 kg
Additional information	
Fuel tank capacity	60 I
Fuel delivery	Multi-Point Injection
Number of doors	2
Number of seats CarCheck.co.uk	4 page 15/15

Number of axles	2
Engine number	D035368