





report date: 2024-03-29

General information

Make	MINI
Model	MINI ONE
Colour	White
Year of manufacture	2011
Top speed	116 mph
0 - 60 mph	10.5 seconds
Gearbox	6 speed Manual

Engine & fuel consumption

Power	98 BHP
Max. torque	153 Nm at 4.250 rpm
Engine capacity	1.598 cc
Cylinders	4
Fuel type	Petrol
Consumption city	39.2 mpg
Consumption extra urban	64.2 mpg
Consumption combined	52.3 mpg
CO2 emission	127 g/km
CO2 label	D



CarCheck.co.uk page 1/12



Internet history

Entry 1

Date 2021-02-02


Pictures 9

Listing price <u>View report</u>









source: autoonline.co.uk

CarCheck.co.uk page 2/12



MOT history

MOT expiry date	2024-06-25
MOT pass rate	77 %
MOT passed	10
Failed MOT tests	3
Total advice items	13
Total items failed	6

MOT #13		2023-06-13 14:54
MOT test	number	393711936268
Result		✓ Passed
Next expi	ry date	2024-06-25
Advice	Offside Front Tyre worn close to legal limit/worn on edge (5.2.3 (e))	
Advice	Nearside Front Tyre worn close to legal limit/worn on edge (5.2.3 (e))	

MOT #12	2022-06-01 09:54
MOT test	number 685509268216
Result	✓ Passed
Advice	Nearside Front Tyre worn close to legal limit/worn on edge Edges wearing (5.2.3 (e))
Advice (b))	Nearside Headlamp has a product on the light source but not seriously reducing light output (4.1.4
Advice (b))	Offside Headlamp has a product on the light source but not seriously reducing light output (4.1.4

CarCheck.co.uk page 3/12



Advice

(b))

LC11FLD report date: 2024-03-29

MOT test number

Result

Pass with rectification

Nearside Headlamp aim too low (4.1.2 (a))

Advice
(b))

Pass with rectification

Offside Headlamp aim too low (4.1.2 (a))

Advice
Nearside Front Tyre worn close to legal limit/worn on edge Edges wearing (5.2.3 (e))

Offside Headlamp has a product on the light source but not seriously reducing light output (4.1.4

 MOT #10
 2021-06-01 09:33

 MOT test number
 322516096149

 Result
 ✓ Passed

 MOT #9
 2020-06-26 12:11

 MOT test number
 762806551022

 Result
 ✓ Passed

 Advice
 Offside Front Tyre worn close to legal limit/worn on edge (5.2.3 (e))

MOT test number

262798429872

Result

Fail Offside Front Position lamp not working (4.2.1 (a) (ii))

Fail Nearside Front Anti-roll bar linkage ball joint dust cover no longer prevents the ingress of dirt (5.3.4 (b) (ii))

Advice Offside Front Tyre worn close to legal limit/worn on edge (5.2.3 (e))

MOT #7	2019-04-30 07:35
MOT test number	747648702597
Result	✓ Passed

CarCheck.co.uk page 4/12



MOT #6 2018-04-30 08:02

MOT test number 290196036369

Result ✓ Passed

MOT #5 2018-04-30 08:02

MOT test number 936472416440

Result X Failed

Pass with rectification Offside Registration plate lamp does not illuminate simultaneously with the

position lamps (1.1.C.1a)

Pass with rectification Offside Headlamp not working on dipped beam (1.7.5a)

MOT #4 2017-05-02 07:32

MOT test number 245247246945

Result
✓ Passed

Advice Windscreen has damage to an area less than a 10mm circle within zone 'A' (8.3.1a)

MOT #3 2016-04-25 07:27

MOT test number 880093000127

Result
✓ Passed

Advice Front brake disc worn, pitted or scored, but not seriously weakened (3.5.1i)

Advice Rear Brake pad(s) wearing thin (3.5.1g)

MOT #2 2015-05-05 08:34

MOT test number 467535925158

Result ✓ Passed

MOT #1 2014-05-07 14:48

MOT test number 249147224173

Result

Passed

CarCheck.co.uk page 5/12



Tax & MOT check



Tax status	Valid until 1 June
Days left	32
MOT expiry date	25 June 2024
Full MOT history	See MOT history

Tax calculation

Vehicle class	48
Band	D
Single payment (12 months)	£ 150,00,-
Single six month payment	£ 82,50,-
Total payable by 12 monthly instalments	£ 157,50,-

CarCheck.co.uk page 6/12



Damage history

Check the damage history for this MINI. See if, where and when this MINI had damage and the car repair costs. We also check if this MINI was scrapped. Download the premium report <u>here</u> for the results.

Damage 1
Date
Category
Type
Damage 2
Date
Category
Type



Extra MINI salvage check



If this vehicle was seen at a salvage auction we offer: vehicle pictures, salvage location, retail value. Download the premium report <u>here</u> for more information.

More info >

CarCheck.co.uk page 7/12



Vehicle valuation

What is this car worth? See the vehicle value of this MINI in the premium report. We check: purchase value, age, mileage, MOT history, damages and online sale prices.

Trade retail value

Auction value

Average private trade value

More info >

CarCheck.co.uk page 8/12



Owner history

For how long did the current and previous owner(s) have this MINI? How many owners di Check it in the premium report and see all owner registrations. Download the full report <u>l</u>	
THE PARTY OF THE P	

THE PARTY OF THE P	

	More info >
Plate changes	
See in this check if this MINI had different number plates.	
Number of plates	
Current registration	NE ZIS
Plate since	
Current registration	OK OK
Plate since	
	More info >

CarCheck.co.uk page 9/12



Finance check

Check if this MINI is financed, has an outstanding loan or finance agreement. If you are purchasing a vehicle it is smart to ensure that any finance that may have been taken out on this MINI has been settled.

If not, and you buy this MINI then you could lose the money and the car you paid for.

Download the premium report <u>here</u> and check if this MINI is financed.

Finance company	
Date of agreement	
Agreement type	
Agreement term	
Agreement number	
Contact info	

Contact info

More info >

CarCheck.co.uk page 10/12



Mileage check

Odometer	In miles
Mileage registrations	15
First mileage registration	2011-06-18
Last registration	2023-06-13
Complete history	See info



Registration #1	2011-06-18	19 mi
Registration #2	2014-05-07	18.596 mi
Registration #3	2015-05-05	26.345 mi
Registration #4	2016-04-25	33.611 mi
Registration #5	2017-05-02	40.901 mi
Registration #6	2018-04-30	48.312 mi
Registration #7	2018-04-30	48.312 mi
Registration #8	2019-04-30	55.843 mi
Registration #9		11.777 es
Registration #10		11.777 es
Registration #11		11.777 es
Registration #12		11.777 es
Registration #13		9.77 es
Registration #14		0.00 44
Registration #15		D.777 es

More info >

CarCheck.co.uk page 11/12



Car features

S0225	Air conditioning
S0295	
S0482	
S0501	
S0566	
S0567	
S0569	

Safety ratings

NCAP rating	****
Video	see crash video



Dimensions & weight

Width	1683 mm
Height	1407 mm
Length	3699 mm
Wheel base	2467 mm
Kerb weight	1060 kg
Max. allowed weight	1520 kg

Additional information

Fuel tank capacity	40 I
Fuel delivery	Multi-Point Injection
Number of doors	3
Number of seats CarCheck.co.uk	4 page 12/12

Number of axles2Engine numberB560J085