





report date: 2024-03-28

#### General information

Make	MINI
Model	COUNTRYMAN COOPER D ALL4
Colour	Black
Year of manufacture	2018
Top speed	127 mph
0 - 60 mph	8.8 seconds
Gearbox	6 speed Manual

#### Engine & fuel consumption

Power	150 BHP
Max. torque	330 Nm at 2.750 rpm
Engine capacity	1.995 сс
Cylinders	4
Fuel type	Diesel
Consumption city	50.4 mpg
Consumption extra urban	64.2 mpg
Consumption combined	58.9 mpg
CO2 emission	127 g/km
CO2 label	D



CarCheck.co.uk page 1/11



#### Internet history

#### Entry 3

Date 2022-01-04

Pictures 35

Listing price <u>View report</u>









source: autotrader.co.uk

#### Entry 2

Date	2021-12-28
Pictures	2

Listing price <u>View report</u>





source: cargurus.co.uk

#### Entry 1

Date	2021-12-28	
Pictures	0	
Listing price	View report	

source: heycar.co.uk

CarCheck.co.uk page 2/11



report date: 2024-03-28

MOT history	ΜO	Γh	nist	orv	
-------------	----	----	------	-----	--

MOT expiry date	2025-04-12
MOT pass rate	67 %
MOT passed	4
Failed MOT tests	2
Total advice items	8
Total items failed	0

MOT #6	2024-03-14 10:55
MOT test number	957517249038
Result	✓ Passed
Next expiry date	2025-04-12

MOT #5	2023-04-13 11:29
MOT test number	148233065686
Result	✓ Passed

MOT #4		2023-04-13 08:15
<b>MOT</b> test	number	103465956148
Result		🗙 Failed
MAJOR	Nearside Rear Tyre(s) of different sizes are fitted on the same axle. (5.2.3 (b))	

MOT #3	2022-12-19 15:02
MOT test number	819266889041
Result	✓ Passed
Advice Offside Rear Tyre worn close to legal limit/worn on edge (5.2.3 (e))  Advice Nearside Rear Tyre worn close to legal limit/worn on edge (5.2.3 (e))	
, , , , , , , , , , , , , , , , , , ,	

CarCheck.co.uk page 3/11



report date: 2024-03-28

MOT #2 2022-12-10 15:18 **MOT test number** 678199478319 Result **X** Failed **MAJOR** Windscreen washer provides insufficient washer liquid (3.5 (a)) Nearside Rear Tyre worn close to legal limit/worn on edge (5.2.3 (e)) Advice Advice Rear Registration plate deteriorated but not likely to be misread (0.1 (b)) Advice Coolant leak Advice Offside Rear Tyre worn close to legal limit/worn on edge (5.2.3 (e))

MOT #1	2021-12-09 09:13
MOT test number	260321103936
Result	✓ Passed

CarCheck.co.uk page 4/11



Tax & MOT check



Tax status	Valid until 1 April
Days left	336
MOT expiry date	12 April 2025
Full MOT history	See MOT history

#### Tax calculation

Vehicle class	49
Band	G
First licence fee (12 months)	£ 210,00,-
First licence fee diesel non RDE2 tested (12 months)	£ 255,00,-
Standard rate (12 months)	£ 180,00,-
Standard rate (6 months)	£ 99,00,-
Premium rate (12 months)	£ 570,00,-
Premium rate (6 months)	£ 313,50,-


CarCheck.co.uk page 5/11



Damage history

Check the damage history for this MINI. See if, where and when this MINI had damage and the car repair costs. We also check if this MINI was scrapped. Download the premium report <u>here</u> for the results.

Damage 1	
Date	
Category	
Туре	
Damage 2	
Date	
Category	
Туре	



#### Extra MINI salvage check



If this vehicle was seen at a salvage auction we offer: vehicle pictures, salvage location, retail value. Download the premium report <u>here</u> for more information.

More info >

CarCheck.co.uk page 6/11



report date: 2024-03-28

#### Vehicle valuation

What is this car worth? See the vehicle value of this MINI in the premium report. We check: purchase value, age, mileage, MOT history, damages and online sale prices.

**Trade retail value** 

**Auction value** 

Average private trade value

More info >

CarCheck.co.uk page 7/11



faste since

RA68KLZ

report date: 2024-03-28

More info >

# Owner history For how long did the current and previous owner(s) have this MINI? How many owners did this MINI have? Check it in the premium report and see all owner registrations. Download the full report <u>here</u>. More info > Plate changes See in this check if this MINI had different number plates. ober of plates

CarCheck.co.uk page 8/11



#### Finance check

Check if this MINI is financed, has an outstanding loan or finance agreement. If you are purchasing a vehicle it is smart to ensure that any finance that may have been taken out on this MINI has been settled.

If not, and you buy this MINI then you could lose the money and the car you paid for.

Download the premium report <u>here</u> and check if this MINI is financed.

Finance company	
Date of agreement	
Agreement type	
Agreement term	
Agreement number	
Contact info	

Contact info


More info >

CarCheck.co.uk page 9/11



Mileage check

Odometer	In miles
Mileage registrations	10
First mileage registration	2018-12-20
Last registration	2024-03-14
Complete history	See info



Registration #1	2018-12-20	20 mi
Registration #2	2021-12-09	33.003 mi
Registration #3		91.777 es
Registration #4		11.777 es
Registration #5		91.777 es
Registration #6		11.777 es
Registration #7		91.777 es
Registration #8		11.777 es
Registration #9		11.777 es
Registration #10		11.777 es

More info >

CarCheck.co.uk page 10/11



report date: 2024-03-28

#### Car features

S0225	Air conditioning
S0295	
50482	
50501	
50566	
60567	
50569	

## Safety ratings

NCAP rating	****
Adult	90%
Children	80%
Pedestrian	64%
Safety systems	51%
Overall rating	75%
Video	see crash video



## Dimensions & weight

Width	2005 mm
Height	1557 mm
Length	4299 mm
Wheel base	2670 mm
Kerb weight	1485 kg
Max. allowed weight	2090 kg

## Additional information

Fuel tank capacity	51 l
Fuel delivery	Direct Injection
Number of doors	5
Number of seats CarCheck.co.uk	5 page 11/11