





report date: 2024-03-29

### General information

Make	PEUGEOT
Model	207 S
Colour	Blue
Year of manufacture	-
Top speed	115 mph
0 - 60 mph	12.8 seconds
Gearbox	5 speed Manual

### Engine & fuel consumption

Power	95 BHP
Max. torque	136 Nm at 4.000 rpm
Cylinders	4
Fuel type	Petrol
Consumption city	35.8 mpg
Consumption extra urban	58.9 mpg
Consumption combined	47.9 mpg



CarCheck.co.uk page 1/12



report date: 2024-03-29

## Internet history

### Entry 1

Date 2021-06-10

Pictures 34

Listing price <u>View report</u>









source: autotrader.co.uk

CarCheck.co.uk page 2/12



report date: 2024-03-29

# MOT history

MOT #15	2022-01-29 13:38
MOT test number	213464518288
Result	✓ Passed
Next expiry date	2023-01-28
Advice Rear Exhaust has a minor leak of exhaust gases (6.1.2 (a))	

MOT #14	2021-01-16 15:00
MOT test number	533740300320
Result	<b>✓</b> Passed
Advice Vehicle presented in wet conditions	

MOT #13		2019-04-11 11:47
MOT test	number	442866066068
Result		✓ Passed
Advice Advice	Offside Rear Service brake binding but not excessively (1.2.1 (f))  Offside Front Coil spring corroded (5.3.1 (b) (i))	

MOT #12	2018-04-16 15:21
MOT test number	226405153943
Result	✓ Passed
Advice Rear Exhaust has a minor leak of exhaust gases (7.1.2)	

MOT #11	2018-04-16 11:38
MOT test number	853132254041
Result	<b>×</b> Failed
Fail Offside Front Front constant velocity joint gaiter insecure to the extent that ingress of dirt etc (2.5.C.1a)  Advice Rear Exhaust has a minor leak of exhaust gases (7.1.2)	t it no longer prevents the

CarCheck.co.uk page 3/12



report date: 2024-03-29

MOT test number

Result

Advice

Offside Rear Tyre worn close to the legal limit 3mm (4.1.E.1)

Advice

Nearside Rear Tyre worn close to the legal limit 4mm (4.1.E.1)

MOT test number

Result

Advice Nearside Rear Tyre worn close to the legal limit 4mm (4.1.E.1)

Advice Offside Rear Tyre worn close to the legal limit 3mm (4.1.E.1)

Fail Offside Front Anti-roll bar linkage has excessive play in a ball joint (2.4.G.2)

Fail Nearside Rear Registration plate lamp not working (1.1.C.1d)

MOT #8

MOT test number

Result

Advice

Offside Front Anti-roll bar linkage has slight play in a ball joint (2.4.G.2)

MOT #7

MOT test number

289674305181

Result

Advice

Nearside Front Upper Macpherson strut has slight movement at the upper attachment (2.5.A.1c)

CarCheck.co.uk page 4/12



report date: 2024-03-29

MOT #6 2015-04-14 14:25

**MOT test number** 697094405194

**Result** X Failed

**Advice** Nearside Front Upper Macpherson strut has slight movement at the upper attachment (2.5.A.1c)

**Pass with rectification** Nearside Rear position lamp(s) not working (1.1.A.3b)

**MOT #5** 2014-04-16 09:46

MOT test number 998566204199

**Notice** Coolant leak

MOT #4 2013-04-15 16:59

**MOT test number** 517565603134

**Result** ✓ Passed

MOT #3 2013-04-15 09:04

**MOT test number** 616155703149

Result × Failed

Fail Rear Exhaust system not adequately supported (7.1.1)

**Advice** Front Brake pad(s) wearing thin (3.5.1g)

**Fail** Nearside Rear position lamp(s) not working (1.1.A.3b)

**Fail** Rear registration plate non-reflective border wider than permitted (6.3.4h)

MOT #2 2012-04-24 12:26

**MOT test number** 957605312121

**Result** 
✓ Passed

CarCheck.co.uk page 5/12



AF09KVS
report date: 2024-03-29

MOT #1 2012-03-06 12:27

**MOT test number** 385636862090

**Result** ✓ Passed

**Advice** Front Brakes imbalanced requirements only just met. It would appear that the braking system requires adjustment or repair. (3.7.B.5b)

CarCheck.co.uk page 6/12



AF09KVS
report date: 2024-03-29

Damage history

Check the damage history for this PEUGEOT. See if, where and when this PEUGEOT had damage and the car repair costs. We also check if this PEUGEOT was scrapped. Download the premium report <u>here</u> for the results.

Damage 1
Date
Category
Type
Damage 2
Date
Category
Type



#### Extra PEUGEOT salvage check



If this vehicle was seen at a salvage auction we offer: vehicle pictures, salvage location, retail value. Download the premium report <u>here</u> for more information.

More info >

CarCheck.co.uk page 7/12



report date: 2024-03-29

#### Vehicle valuation

What is this car worth? See the vehicle value of this PEUGEOT in the premium report. We check: purchase value, age, mileage, MOT history, damages and online sale prices.

**Trade retail value** 

**Auction value** 

Average private trade value

More info >

CarCheck.co.uk page 8/12



report date: 2024-03-29

Owner history	
For how long did the current and previous owner(s) have this PEUGEOT? How many owner have? Check it in the premium report and see all owner registrations. Download the full is	
*********	
***************************************	
*********	
***************************************	
************	
	More info >
Plate changes  See in this check if this PEUGEOT had different number plates.	
Number of plates	
Current registration	NIE WIE
Plate since	
Current registration	NE NE
Plate since	
	More info >

CarCheck.co.uk page 9/12



report date: 2024-03-29

#### Finance check

Check if this PEUGEOT is financed, has an outstanding loan or finance agreement. If you are purchasing a vehicle it is smart to ensure that any finance that may have been taken out on this PEUGEOT has been settled.

If not, and you buy this PEUGEOT then you could lose the money and the car you paid for.

Download the premium report <u>here</u> and check if this PEUGEOT is financed.

Finance company	
Date of agreement	
Agreement type	
Agreement term	
Agreement number	
0.1.116	

**Contact info** 

More info >

CarCheck.co.uk page 10/12



report date: 2024-03-29

# Mileage check

Registration #16

Odometer	In miles
Mileage registrations	16
First mileage registration	2009-03-16
Last registration	2022-01-29
Complete history	See info



Registration #1	2009-03-16	28 mi
Registration #2	2012-03-06	21.527 mi
Registration #3	2012-04-24	21.684 mi
Registration #4	2013-04-15	31.511 mi
Registration #5	2013-04-15	31.511 mi
Registration #6	2014-04-16	40.597 mi
Registration #7	2015-04-14	49.414 mi
Registration #8	2016-04-22	57.957 mi
Registration #9		9.777 es
Registration #10		11.777 es
Registration #11		91.777 es
Registration #12		11.777 es
Registration #13		91.777 es
Registration #14		11.777 es
Registration #15		11.777 es

PRIN. 20. 20

More info >

71.777 mi

CarCheck.co.uk page 11/12




report date: 2024-03-29

## Car features

50225	Air conditioning
50295	
60482	
60501	
60566	
60567	
60569	

# Safety ratings

NCAP rating	****
Video	see crash video



# Dimensions & weight

Width	1748 mm
Height	1502 mm
Length	4030 mm
Wheel base	2540 mm
Kerb weight	1245 kg
Max. allowed weight	1640 kg

# Additional information

Fuel tank capacity	50 l
Fuel delivery	Multi-Point Injection
Number of doors	5
Number of seats CarCheck.co.uk	5 page 12/12