



TOYOTA



report date: 2024-03-29

General information

|                     |                   |
|---------------------|-------------------|
| Make                | TOYOTA            |
| Model               | STARLET SE        |
| Colour              | Turquoise         |
| Year of manufacture | 1999              |
| Top speed           | 102 mph           |
| 0 - 60 mph          | 12.5 seconds      |
| Gearbox             | 3 speed automatic |

Engine & fuel consumption

|                         |                     |
|-------------------------|---------------------|
| Power                   | 84 BHP              |
| Max. torque             | 120 Nm at 4.200 rpm |
| Engine capacity         | 1.332 cc            |
| Cylinders               | 4                   |
| Fuel type               | Petrol              |
| Consumption city        | 28.0 mpg            |
| Consumption extra urban | 42.8 mpg            |
| Consumption combined    | 35.8 mpg            |



LABEL UNKNOWN



Internet history

Entry 2

|               |                             |
|---------------|-----------------------------|
| Date          | 2021-09-22                  |
| Pictures      | 9                           |
| Listing price | <a href="#">View report</a> |



source: cargurus.co.uk

Entry 1

|               |                             |
|---------------|-----------------------------|
| Date          | 2021-09-21                  |
| Pictures      | 9                           |
| Listing price | <a href="#">View report</a> |



source: autotrader.co.uk



## MOT history

|                    |            |
|--------------------|------------|
| MOT expiry date    | 2022-10-11 |
| MOT pass rate      | 70 %       |
| MOT passed         | 16         |
| Failed MOT tests   | 7          |
| Total advice items | 62         |
| Total items failed | 16         |

MOT #23 2021-10-12 09:54

MOT test number 659723387437

Result ✓ Passed

Next expiry date 2022-10-11

**Advice** Rear Lower Subframe mounting prescribed area is corroded but not considered excessive (5.3.6 (a) (i))

**Advice** Front Suspension arm corroded but not seriously weakened both (5.3.3 (b) (i))

**Advice** Lower Oil leak, but not excessive (8.4.1 (a) (i))

MOT #22 2021-10-12 09:54

MOT test number 682684476395

Result ✗ Failed

**Advice** Rear Lower Subframe mounting prescribed area is corroded but not considered excessive (5.3.6 (a) (i))

**Pass with rectification** Front Power steering component insecure and steering adversely affected (2.1.5 (d) (ii))

**Advice** Front Suspension arm corroded but not seriously weakened both (5.3.3 (b) (i))

**Advice** Lower Oil leak, but not excessive (8.4.1 (a) (i))

**MOT #21** 2020-10-09 10:29**MOT test number** 175639856787**Result** ✓ Passed**Advice** Front Registration plate deteriorated but not likely to be misread (0.1 (b))**Advice** Offside Front Tyre worn close to legal limit/worn on edge (5.2.3 (e))**MOT #20** 2020-10-01 12:39**MOT test number** 100381648889**Result** ✗ Failed**Fail** Offside Front Anti-roll bar pin or bush excessively worn (5.3.4 (a) (i))**Advice** Offside Front Tyre worn close to legal limit/worn on edge (5.2.3 (e))**Fail** Nearside Windscreen wiper does not clear the windscreen effectively (3.4 (b) (ii))**Fail** Nearside Front Anti-roll bar pin or bush excessively worn (5.3.4 (a) (i))**Advice** Power steering component has slight seepage from a component (2.1.5 (a))**Fail** Offside Windscreen wiper does not clear the windscreen effectively (3.4 (b) (ii))



MOT #192019-09-05 15:02

MOT test number184550907038

| Result |   | ✓ Passed |
|--------|---|----------|
| Advice | All shock absorber bump stop covers damaged   |          |
| Advice | Front Anti-roll bar linkage pin or bush worn but not resulting in excessive movement both (5.3.4 (a) (i)) |          |
| Advice | Both front outer cv boots perishing   |          |
| Advice | Misting of oil around steering rack   |          |
| Advice | Oil around engine lower   |          |
| Advice | Central Front Exhaust has a minor leak of exhaust gases (6.1.2 (a))                                       |          |
| Advice | Nearside front tyre on 3mm  |          |
| Advice | Wash / wiper doesnt work  |          |

**MOT #18** 2019-09-05 11:06**MOT test number** 943859606929**Result** ✗ Failed

- Advice** Wash / wiper doesnt work
- Advice** Front Anti-roll bar linkage pin or bush worn but not resulting in excessive movement both (5.3.4 (a) (i))
- Advice** Oil around engine lower
- Advice** Both front outer cv boots perishing
- Fail** Battery insecure and likely to cause a short circuit (4.13 (a) (ii))
- Advice** Misting of oil around steering rack
- Fail** Offside Front Headlamp aim too low + pattern poor (4.1.2 (a))
- Fail** Front Brake pad(s) less than 1.5 mm thick (1.1.13 (a) (ii))
- Advice** Engine coolant below minimum
- Advice** Central Front Exhaust has a minor leak of exhaust gases (6.1.2 (a))
- Advice** All shock absorber bump stop covers damaged
- Advice** Nearside front tyre on 3mm
- Fail** Offside Front Headlamp insecure (4.1.1 (c))

**MOT #17** 2018-09-06 15:18**MOT test number** 806611980973**Result** ✓ Passed**MOT #16** 2018-09-06 15:18**MOT test number** 502836658531**Result** ✗ Failed

- Pass with rectification** Rear Registration plate inscription illegible (0.1 (b))
- Pass with rectification** Offside Stop lamp(s) not working (4.3.1 (a) (ii))



MOT #15

2017-09-07 09:54

MOT test number

146008074222

Result

✓ Passed

Advice

Rear registration plate deteriorated but not likely to be misread (6.3.1d)

MOT #14

2017-09-07 09:54

MOT test number

960592329652

Result

✗ Failed

Advice

Rear registration plate deteriorated but not likely to be misread (6.3.1d)

Pass with rectification

Rear Exhaust has a major leak of exhaust gases silencer (7.1.2)

MOT #13

2016-09-08 11:09

MOT test number

430066917082

Result

✓ Passed

Advice

Slightly engine oil leak

Advice

Driver seatbelt buckle button sticks in

Advice

Nearside rear tyre perishing + nail in tread

Advice

Rear registration plate delaminated but not likely to be misread (6.3.1d)

Advice

Nearside front tyre wearing on edges

Advice

Offside rear tyre perishing + 2x nails in tread

Advice

Rear Exhaust has a minor leak of exhaust gases borderline pass (7.1.2)

**MOT #12**

2016-09-08 09:39

**MOT test number**

861593728528

**Result****✗ Failed****Fail** Offside Rear Stop lamp not working (1.2.1b)**Advice** Nearside front tyre wearing on edges**Advice** Rear registration plate delaminated but not likely to be misread (6.3.1d)**Advice** Engine coolant on minimum**Advice** Offside rear tyre perishing + 2x nails in tread**Fail** Centre Rear Stop lamp not working (1.2.1b)**Advice** Rear Exhaust has a minor leak of exhaust gases borderline pass (7.1.2)**Advice** Slightly engine oil leak**Advice** Driver seatbelt buckle button sticks in**Advice** Nearside rear tyre perishing + nail in tread**MOT #11**

2015-09-11 08:56

**MOT test number**

329932715234

**Result****✓ Passed****Advice** Rear registration plate deteriorated but not likely to be misread (6.3.1d)**Advice** Offside rear tyre nail in tread**Advice** Offside Seat belt anchorage prescribed area is distorted but not considered excessive (5.2.6)



**MOT #10**

2014-09-11 10:27

**MOT test number**

196354754299

**Result**

✓ Passed

- Notice** Nail in offside rear tyre
- Advice** Offside Rear Shock absorber has a light misting of oil (2.7.3)
- Advice** Rear registration plate deteriorated but not likely to be misread (6.3.1d)
- Notice** Front brake discs starting to corrode.
- Notice** N/s/f tyre perished.
- Advice** Front registration plate deteriorated but not likely to be misread (6.3.1d)
- Notice** Small cut in n/s/f tyre outer side wall.

**MOT #9**

2014-09-11 10:27

**MOT test number**

777524354222

**Result**

✗ Failed

- Advice** Front registration plate deteriorated but not likely to be misread (6.3.1d)
- Notice** Front brake discs starting to corrode.
- Notice** N/s/f tyre perished.
- Pass with rectification** Nearside Windscreen wiper does not clear the windscreen effectively (8.2.2)
- Advice** Offside Rear Shock absorber has a light misting of oil (2.7.3)
- Advice** Rear registration plate deteriorated but not likely to be misread (6.3.1d)
- Notice** Small cut in n/s/f tyre outer side wall.
- Notice** Nail in offside rear tyre
- Pass with rectification** Offside Windscreen wiper does not clear the windscreen effectively (8.2.2)



|                        |   |
|------------------------|---|
| <b>MOT #8</b>          | 2013-04-24 10:11  |
| <b>MOT test number</b> | 928124913171  |
| <b>Result</b>          | ✓ Passed  |
| <b>Advice</b>          | Nearside Front Tyre worn close to the legal limit (4.1.E.1) |

|                        |                  |
|------------------------|------------------|
| <b>MOT #7</b>          | 2012-04-23 14:12 |
| <b>MOT test number</b> | 486334012146     |
| <b>Result</b>          | ✓ Passed         |

|                        |                  |
|------------------------|------------------|
| <b>MOT #6</b>          | 2011-04-21 15:14 |
| <b>MOT test number</b> | 787411011145     |
| <b>Result</b>          | ✓ Passed         |

|                        |                  |
|------------------------|------------------|
| <b>MOT #5</b>          | 2010-04-15 11:22 |
| <b>MOT test number</b> | 741015000149     |
| <b>Result</b>          | ✓ Passed         |

|                        |                  |
|------------------------|------------------|
| <b>MOT #4</b>          | 2009-04-21 13:36 |
| <b>MOT test number</b> | 972211019190     |
| <b>Result</b>          | ✓ Passed         |

|                        |                  |
|------------------------|------------------|
| <b>MOT #3</b>          | 2008-04-21 10:21 |
| <b>MOT test number</b> | 584012118187     |
| <b>Result</b>          | ✓ Passed         |

|                        |                  |
|------------------------|------------------|
| <b>MOT #2</b>          | 2007-04-19 10:22 |
| <b>MOT test number</b> | 401249207102     |
| <b>Result</b>          | ✓ Passed         |



|                 |                  |
|-----------------|------------------|
| MOT #1          | 2006-04-28 10:53 |
| MOT test number | 501038716153     |
| Result          | ✓ Passed         |



Damage history

Check the damage history for this TOYOTA. See if, where and when this TOYOTA had damage and the car repair costs. We also check if this TOYOTA was scrapped. Download the premium report [here](#) for the results.

Damage 1

|          |  |
|----------|--|
| Date     |  |
| Category |  |
| Type     |  |

Damage 2

|          |  |
|----------|--|
| Date     |  |
| Category |  |
| Type     |  |



Extra TOYOTA salvage check



If this vehicle was seen at a salvage auction we offer: vehicle pictures, salvage location, retail value. Download the premium report [here](#) for more information.

More info >



Owner history

For how long did the current and previous owner(s) have this TOYOTA? How many owners did this TOYOTA have? Check it in the premium report and see all owner registrations. Download the full report [here](#).

|       |              |
|-------|--------------|
| Owner | Registration |
| Owner | Registration |
| Owner | Registration |
| Owner | Registration |
| Owner | Registration |
| Owner | Registration |
| Owner | Registration |

More info >

Plate changes

See in this check if this TOYOTA had different number plates.

|                      |                |
|----------------------|----------------|
| Number of plates     | 1              |
| Current registration | <b>V775GVW</b> |
| Plate since          | 2024-03-29     |
| Current registration | <b>V775GVW</b> |
| Plate since          | 2024-03-29     |

More info >



Finance check

Check if this TOYOTA is financed, has an outstanding loan or finance agreement. If you are purchasing a vehicle it is smart to ensure that any finance that may have been taken out on this TOYOTA has been settled. If not, and you buy this TOYOTA then you could lose the money and the car you paid for. Download the premium report [here](#) and check if this TOYOTA is financed.

|                   |            |      |
|-------------------|------------|------|
| Finance company   | XXXXXXXXXX | XXXX |
| Date of agreement | XXXXXXXXXX | XXXX |
| Agreement type    | XXXXXXXXXX | XXXX |
| Agreement term    | XXXXXXXXXX | XXXX |
| Agreement number  | XXXXXXXXXX | XXXX |
| Contact info      | XXXXXXXXXX | XXXX |

More info >



Mileage check

|                            |                          |
|----------------------------|--------------------------|
| Odometer                   | In miles                 |
| Mileage registrations      | 25                       |
| First mileage registration | 1999-09-30               |
| Last registration          | 2021-10-12               |
| Complete history           | <a href="#">See info</a> |



|                  |            |           |
|------------------|------------|-----------|
| Registration #1  | 1999-09-30 | 28 mi     |
| Registration #2  | 2006-04-28 | 27.649 mi |
| Registration #3  | 2007-04-19 | 30.435 mi |
| Registration #4  | 2008-04-21 | 34.061 mi |
| Registration #5  | 2009-04-21 | 35.822 mi |
| Registration #6  | 2010-04-15 | 38.965 mi |
| Registration #7  | 2011-04-21 | 42.617 mi |
| Registration #8  | 2012-04-23 | 45.484 mi |
| Registration #9  | 2013-04-24 | 47.995 mi |
| Registration #10 | 2014-09-11 | 50.021 mi |
| Registration #11 | 2015-09-11 | 56.429 mi |
| Registration #12 | 2016-09-08 | 64.171 mi |
| Registration #13 | 2016-09-08 | 64.171 mi |
| Registration #14 | 2016-09-08 | 64.171 mi |
| Registration #15 | 2016-09-08 | 64.171 mi |
| Registration #16 | 2016-09-08 | 64.171 mi |
| Registration #17 | 2016-09-08 | 64.171 mi |
| Registration #18 | 2016-09-08 | 64.171 mi |
| Registration #19 | 2016-09-08 | 64.171 mi |
| Registration #20 | 2016-09-08 | 64.171 mi |
| Registration #21 | 2016-09-08 | 64.171 mi |
| Registration #22 | 2016-09-08 | 64.171 mi |
| Registration #23 | 2016-09-08 | 64.171 mi |
| Registration #24 | 2016-09-08 | 64.171 mi |
| Registration #25 | 2016-09-08 | 64.171 mi |



Car features

The TOYOTA factory car options list is only available in the premium report.

|       |                  |
|-------|------------------|
| S0225 | Air conditioning |
| S0295 |                  |
| S0482 |                  |
| S0501 |                  |
| S0566 |                  |
| S0567 |                  |
| S0569 |                  |

View the complete TOYOTA factory list for this vehicle [here](#).

More info >

Safety ratings

NCAP rating

Video [see crash video](#)



Additional information

|                    |                       |
|--------------------|-----------------------|
| Fuel tank capacity | 50 l                  |
| Fuel delivery      | Multi-Point Injection |
| Number of doors    | 5                     |
| Number of axles    | 2                     |
| Engine number      | 4E2901407             |