





report date: 2024-03-28

General information

Make	TOYOTA
Model	COROLLA VERSO D-4D T3
Colour	Red
Year of manufacture	2007
Top speed	122 mph
0 - 60 mph	9.4 seconds
Gearbox	6 speed Manual

Engine & fuel consumption

Power	134 BHP
Max. torque	310 Nm at 2.800 rpm
Engine capacity	2.231 cc
Cylinders	4
Fuel type	Diesel
Consumption city	35.3 mpg
Consumption extra urban	53.3 mpg
Consumption combined	44.8 mpg
CO2 emission	167 g/km
CO2 label	Н



CarCheck.co.uk page 1/13



FL57GHD report date: 2024-03-28

Internet history

E ~	+	, 1
	ILI V	, .

Elitiy 1	
Date	2022-01-07
Pictures	0
Listing price	View report

source: cargurus.co.uk

CarCheck.co.uk page 2/13



report date: 2024-03-28

	_				
11/1/	TC	n		$\overline{}$	r\/
IVIL	, ,		51	LU.	ıv
					. ,

MOT expiry date	2024-10-04
MOT pass rate	88 %
MOT passed	14
Failed MOT tests	2
Total advice items	18
Total items failed	3

MOT #16	2023-09-07 14:38
MOT test number	780163291557
Result	✓ Passed
Next expiry date	2024-10-04
Advice Surface corrosion through out	

MOT #15	2022-09-05 08:42
MOT test	number 587752864525
Result	✓ Passed
Advice	Rear Vehicle structure is corroded but structural rigidity is not significantly reduced (6.1.1 (c) (i))
Advice	Rear Brake pipe corroded, covered in grease or other material (1.1.11 (c))

MOT #14	2021-09-27 10:11
MOT test number	100633714108
Result	✓ Passed
Advice Offside Rear Tyre worn close to legal limit/worn on edge (5.2.3 (e))	

MOT #13	2020-09-28 08:16
MOT test number	478008599165
Result	✓ Passed

CarCheck.co.uk page 3/13



sides (4.1.4 (b))

FL57GHD

report date: 2024-03-28

MOT test number
976260688916

Result

Advice Offside Rear Tyre worn close to legal limit/worn on edge (5.2.3 (e))

Advice Front Headlamp has a product on the light source but not seriously reducing light output both

Minor Windscreen damaged but not adversely affecting driver's view (3.2 (a) (i))

MOT test number
627890011721

Result
Minor
Windscreen damaged but not adversely affecting driver's view small chip in screen. (3.2 (a) (i))

Advice
Nearside Front tyre wearing close to limit

Advice
Nearside Rear Seat belt webbing slightly damaged or frayed (7.1.2 (b) (ii))

MOT test number

Result

Advice

Windscreen has damage to an area less than a 10mm circle within zone 'A' (8.3.1a)

Advice

Nearside Rear Seat belt cut but webbing not significantly weakened (5.2.2a)

 MOT #9
 2016-10-25 16:00

 MOT test number
 760956241329

 Result
 ✓ Passed

 MOT #8
 2015-10-26 11:38

 MOT test number
 885882945221

 Result
 ✓ Passed

CarCheck.co.uk page 4/13



report date: 2024-03-28

MOT #7 2014-10-28 09:29 MOT test number 497861304413

Advice Offside Front Tyre worn close to the legal limit (4.1.E.1)

Advice Front Tyre worn close to the legal limit (4.1.E.1)

MOT #6 2013-10-25 16:30

MOT test number 359678893468

Result \sqrt{Passed}

Advice Windscreen has damage to an area less than a 10mm circle within zone 'A' (8.3.1a)

MOT #5 2012-11-16 11:27

MOT test number 725321222330

Result ✓ Passed

Notice Under-trays fitted obscuring some underside components

MOT #4 2012-11-16 09:23

MOT test number 909771722314

Result X Failed

Fail Nearside Front Windscreen wiper does not clear the windscreen effectively (8.2.2)

Advice Rear Brake pad(s) wearing thin (3.5.1g)

Notice Under-trays fitted obscuring some underside components

Fail Offside Front Windscreen wiper does not clear the windscreen effectively (8.2.2)

MOT #3 2011-10-31 15:15

MOT test number 106104201397

Result ✓ Passed

CarCheck.co.uk page 5/13



report date: 2024-03-28

X Failed

 MOT #2
 2010-08-25 12:25

 MOT test number
 454867230263

 Result
 ✓ Passed

MOT #1 2010-08-25 12:25

MOT test number 422927230241

Pass with rectification

Result

Front registration plate delaminated (6.3.1d)

CarCheck.co.uk page 6/13



report date: 2024-03-28

Tax & MOT check



Tax status	Valid until 1 January
Days left	247
MOT expiry date	4 October 2024
Full MOT history	See MOT history

Tax calculation

Vehicle class	49
Band	Н
Single payment (12 months)	£ 290,00,-
Single six month payment	£ 159,50,-
Total payable by 12 monthly instalments	£ 304,50,-

CarCheck.co.uk page 7/13



report date: 2024-03-28

Damage history

Check the damage history for this TOYOTA. See if, where and when this TOYOTA had damage and the car repair costs. We also check if this TOYOTA was scrapped. Download the premium report here for the results.

Damage 1
Date
Category
Type
Damage 2
Date
Category
Type



Extra TOYOTA salvage check



If this vehicle was seen at a salvage auction we offer: vehicle pictures, salvage location, retail value. Download the premium report <u>here</u> for more information.

More info >

CarCheck.co.uk page 8/13



report date: 2024-03-28

Vehicle valuation

What is this car worth? See the vehicle value of this TOYOTA in the premium report. We check: purchase value, age, mileage, MOT history, damages and online sale prices.

Trade retail value

Auction value

Average private trade value

More info >

CarCheck.co.uk page 9/13



funder scincole

FL57GHD

report date: 2024-03-28

More info >

Owner history For how long did the current and previous owner(s) have this TOYOTA? How many owners did this TOYOTA have? Check it in the premium report and see all owner registrations. Download the full report <u>here</u>. More info > Plate changes See in this check if this TOYOTA had different number plates. ober of plates

CarCheck.co.uk page 10/13



report date: 2024-03-28

Finance check

Check if this TOYOTA is financed, has an outstanding loan or finance agreement. If you are purchasing a vehicle it is smart to ensure that any finance that may have been taken out on this TOYOTA has been settled.

If not, and you buy this TOYOTA then you could lose the money and the car you paid for.

Download the premium report <u>here</u> and check if this TOYOTA is financed.

Finance company	
Date of agreement	
Agreement type	
Agreement term	
Agreement number	
Contact info	

More info >


CarCheck.co.uk page 11/13



report date: 2024-03-28

Mileage check

Odometer	In miles
Mileage registrations	17
First mileage registration	2007-09-03
Last registration	2023-09-07
Complete history	See info



Registration #1	2007-09-03	12 mi
Registration #2	2010-08-25	42.942 mi
Registration #3	2011-10-31	47.412 mi
Registration #4	2012-11-16	51.857 mi
Registration #5	2012-11-16	51.857 mi
Registration #6	2013-10-25	55.288 mi
Registration #7	2014-10-28	62.284 mi
Registration #8	2015-10-26	74.558 mi
Registration #9	2016-10-25	83.344 mi
Registration #10		11.777 es
Registration #11		11.777 es
Registration #12		11.777 es
Registration #13		11.777 es
Registration #14		11.777 es
Registration #15		11.777 es
Registration #16		D.777 es
Registration #17		10.377 es

More info >

CarCheck.co.uk page 12/13



report date: 2024-03-28

Car features

50225	Air conditioning
50295	
50482	
50501	
50566	
50567	
50569	

Safety ratings

NCAP rating	****
Video	see crash video



Dimensions & weight

Width	1770 mm
Height	1660 mm
Length	4360 mm
Wheel base	2750 mm
Kerb weight	1495 kg
Max. allowed weight	2160 kg

Additional information

Fuel tank capacity	60 I
Fuel delivery	Direct Injection
Number of doors	5
Number of seats CarCheck.co.uk	7 page 13/1.

Number of axles 2

Engine number 2AD521824