



report date: 2024-03-28

General information

Make	VOLVO
Model	V50 D DRIVE SE LUX
Colour	Blue
Year of manufacture	2010
Top speed	118 mph
0 - 60 mph	10.9 seconds
Gearbox	5 speed Manual

Engine & fuel consumption

Power	109 BHP
Max. torque	240 Nm at 1.750 rpm
Engine capacity	1.560 cc
Cylinders	4
Fuel type	Diesel
Consumption city	57.7 mpg
Consumption extra urban	83.1 mpg
Consumption combined	72.4 mpg
CO2 emission	104 g/km
CO2 label	B





Internet history

Entry 1

Date	2021-07-01
Pictures	1
Listing price	View report



source: [autotrader.co.uk](https://www.autotrader.co.uk)



MOT history

MOT expiry date	2024-07-18
MOT pass rate	73 %
MOT passed	11
Failed MOT tests	4
Total advice items	37
Total items failed	7

MOT #15	2023-06-30 08:39
MOT test number	608471714479
Result	✓ Passed
Next expiry date	2024-07-18
Advice	Offside Front Items removed from driver's view prior to test
Advice	Rear Suspension component mounting prescribed area is corroded but not considered excessive nsr/osr (5.3.6 (a) (i))

MOT #14	2022-07-11 17:11
MOT test number	407545309234
Result	✓ Passed
Minor	Offside Registration plate lamp inoperative in the case of multiple lamps or light sources (4.7.1 (b) (i))
Advice	Rear Suspension component mounting prescribed area is corroded but not considered excessive o/s and n/s (5.3.6 (a) (i))

**MOT #13**

2022-07-11 10:37

MOT test number

237436805668

Result

✗ Failed

Advice Nearside Front Tyre worn close to legal limit/worn on edge (5.2.3 (e))**Fail** Nearside Front Lower Suspension arm ball joint dust cover no longer prevents the ingress of dirt (5.3.4 (b) (ii))**Advice** Rear Suspension component mounting prescribed area is corroded but not considered excessive o/s and n/s (5.3.6 (a) (i))**Fail** Offside Front Tyre has ply or cords exposed (5.2.3 (d) (ii))**Minor** Offside Registration plate lamp inoperative in the case of multiple lamps or light sources (4.7.1 (b) (i))**Fail** Nearside Front Lower Suspension arm ball joint excessively worn (5.3.4 (a) (i))**Advice** Front Lower Suspension arm pin or bush worn but not resulting in excessive movement o/s and n/s (5.3.4 (a) (i))**MOT #12**

2021-07-19 10:48

MOT test number

946650704403

Result

✓ Passed

MOT #11

2020-09-25 11:20

MOT test number

240813632759

Result

✓ Passed

Advice Offside Rear Brake pad(s) wearing thin (1.1.13 (a) (ii))**Advice** Offside Rear Brake disc worn, pitted or scored, but not seriously weakened (1.1.14 (a) (ii))**Advice** Nearside Rear Brake pad(s) wearing thin (1.1.13 (a) (ii))**Advice** Nearside Rear Brake disc worn, pitted or scored, but not seriously weakened (1.1.14 (a) (ii))**Advice** Nearside Rear Tyre worn close to legal limit/worn on edge (5.2.3 (e))**MOT #10**

2019-09-25 10:41

MOT test number

311623732741

Result

✓ Passed

**MOT #9** 2019-09-23 08:06**MOT test number** 185396037903**Result** ✗ Failed**Minor** Nearside Lower Windscreen damaged but not adversely affecting driver's view (3.2 (a) (i))**Fail** Brake pedal anti-slip provision missing (1.1.2 (c))**Fail** Offside Service brake excessively binding (1.2.1 (f))**MOT #8** 2018-08-22 09:37**MOT test number** 951479145380**Result** ✓ Passed**Advice** Offside Rear Brake pad(s) wearing thin (1.1.13 (a) (ii))**Advice** Offside Front tyre worn on inner edge**MOT #7** 2017-09-21 14:30**MOT test number** 100475724305**Result** ✓ Passed**MOT #6** 2017-09-21 10:49**MOT test number** 223765872118**Result** ✗ Failed**Fail** Nearside Front Lower Suspension arm rubber bush deteriorated resulting in excessive movement (2.4.G.2)**Advice** Offside Front Lower Suspension arm rubber bush deteriorated but not resulting in excessive movement (2.4.G.2)**MOT #5** 2016-10-05 09:28**MOT test number** 713639096484**Result** ✓ Passed**Advice** Nearside Front Lower Suspension arm rubber bush deteriorated but not resulting in excessive movement (2.4.G.2)**Advice** Offside Front Lower Suspension arm rubber bush deteriorated but not resulting in excessive movement (2.4.G.2)

**MOT #4** 2015-10-07 16:10**MOT test number** 653425448140**Result** ✓ Passed**Advice** Windscreen has damage to an area less than a 40mm circle outside zone 'A' (8.3.1d)**Advice** Wear nearside front arm rearward bush**Advice** Front Road wheel with a slightly distorted bead rim both (4.2.A.1a)**MOT #3** 2014-10-16 10:03**MOT test number** 407869184210**Result** ✓ Passed**Advice** Front Road wheel with a slightly distorted bead rim (4.2.A.1a)**Notice** Handbrake travel nearing limit**Advice** Windscreen has damage to an area less than a 40mm circle outside zone 'A' (8.3.1d)**MOT #2** 2013-10-23 17:06**MOT test number** 549746193259**Result** ✓ Passed**Advice** Offside Road wheel with a slightly distorted bead rim (4.2.A.1a)**Advice** Nearside front brake fluctuating, but not excessively (3.7.B.3)**Advice** Nearside Rear Shock absorber has a light misting of oil (2.7.3)**Advice** Windscreen has damage to an area less than a 40mm circle outside zone 'A' (8.3.1d)**Advice** Offside Rear Brake pad(s) wearing thin (3.5.1g)**Notice** Handbrake travel nearing limit



MOT #12013-10-23 17:06

MOT test number918816593279

Result

Failed

- Advice

Offside Rear Brake pad(s) wearing thin (3.5.1g)
- Advice

Offside Road wheel with a slightly distorted bead rim (4.2.A.1a)
- Notice

Handbrake travel nearing limit
- Advice

Nearside front brake fluctuating, but not excessively (3.7.B.3)
- Advice

Nearside Rear Shock absorber has a light misting of oil (2.7.3)
- Advice

Windscreen has damage to an area less than a 40mm circle outside zone 'A' (8.3.1d)
- Pass with rectification

Offside Headlamp aim too low (1.8)



Tax & MOT check

✓
Taxed
Tax due:
1 July 2024

✓
MOT
Expires:
18 July 2024

Tax status	Valid until 1 July
Days left	64
MOT expiry date	18 July 2024
Full MOT history	See MOT history

Tax calculation

Vehicle class	49
Band	B
Single payment (12 months)	£ 20,00,-
Single six month payment	Not applicable
Total payable by 12 monthly instalments	£ 21,00,-



Damage history

Check the damage history for this VOLVO. See if, where and when this VOLVO had damage and the car repair costs. We also check if this VOLVO was scrapped. Download the premium report [here](#) for the results.

Damage 1

Date	
Category	
Type	

Damage 2

Date	
Category	
Type	



Extra VOLVO salvage check



If this vehicle was seen at a salvage auction we offer: vehicle pictures, salvage location, retail value. Download the premium report [here](#) for more information.

More info >



Vehicle valuation

What is this car worth? See the vehicle value of this VOLVO in the premium report. We check: purchase value, age, mileage, MOT history, damages and online sale prices.

Trade retail value	£ 19,999
Auction value	£ 19,999
Average private trade value	£ 19,999

More info >



Owner history

For how long did the current and previous owner(s) have this VOLVO? How many owners did this VOLVO have? Check it in the premium report and see all owner registrations. Download the full report [here](#).

Owner	Start date
Owner	Start date
Owner	Start date
Owner	Start date
Owner	Start date
Owner	Start date
Owner	Start date

More info >

Plate changes

See in this check if this VOLVO had different number plates.

Number of plates	1
Current registration	
Plate since	2024-03-28
Current registration	
Plate since	2024-03-28

More info >



Finance check

Check if this VOLVO is financed, has an outstanding loan or finance agreement. If you are purchasing a vehicle it is smart to ensure that any finance that may have been taken out on this VOLVO has been settled.

If not, and you buy this VOLVO then you could lose the money and the car you paid for.

Download the premium report [here](#) and check if this VOLVO is financed.

Finance company	XXXXXXXXXX	XXXX
Date of agreement	XXXXXXXXXX	XXXX
Agreement type	XXXXXXXXXX	XXXX
Agreement term	XXXXXXXXXX	XXXX
Agreement number	XXXXXXXXXX	XXXX
Contact info	XXXXXXXXXX	XXXX

More info >



Mileage check

Odometer	In miles
Mileage registrations	16
First mileage registration	2010-03-05
Last registration	2023-06-30
Complete history	See info



Registration #1	2010-03-05	11 mi
Registration #2	2013-10-23	49.684 mi
Registration #3	2014-10-16	60.212 mi
Registration #4	2015-10-07	67.558 mi
Registration #5	2016-10-05	75.350 mi
Registration #6	2017-09-21	81.973 mi
Registration #7	2017-09-21	81.973 mi
Registration #8	2018-08-22	91.552 mi
Registration #9	2019-06-20	95.277 mi
Registration #10	2019-06-20	95.277 mi
Registration #11	2019-06-20	95.277 mi
Registration #12	2019-06-20	95.277 mi
Registration #13	2019-06-20	95.277 mi
Registration #14	2019-06-20	95.277 mi
Registration #15	2019-06-20	95.277 mi
Registration #16	2019-06-20	95.277 mi

More info >



Car features

The VOLVO factory car options list is only available in the premium report.

S0225	Air conditioning
S0295	
S0482	
S0501	
S0566	
S0567	
S0569	

View the complete VOLVO factory list for this vehicle [here](#).

More info >

Safety ratings

NCAP rating ★★★★★

Video [see crash video](#)



Dimensions & weight

Width	1770 mm
Height	1457 mm
Length	4522 mm
Wheel base	2640 mm
Kerb weight	1437 kg
Max. allowed weight	1900 kg

Additional information

Fuel tank capacity	52 l
Fuel delivery	Direct Injection
Number of doors	5
Number of seats	5

Number of axles	2
Engine number	1260602