



report date: 2024-03-29

General information

Make	KIA
Model	SOUL CRDI ECHO
Colour	Black
Year of manufacture	2011
Top speed	113 mph
0 - 60 mph	10.9 seconds
Gearbox	5 speed Manual

Engine & fuel consumption

Power	126 BHP
Max. torque	260 Nm at 1.900 rpm
Engine capacity	1.582 cc
Cylinders	4
Fuel type	Diesel
Consumption city	44.8 mpg
Consumption extra urban	61.4 mpg
Consumption combined	45.6 mpg
CO2 emission	137 g/km
CO2 label	E





Internet history

Entry 1

Date	2021-06-28
Pictures	5
Listing price	View report



source: [autotrader.co.uk](#)



MOT history

MOT expiry date	2022-08-11
MOT pass rate	73 %
MOT passed	8
Failed MOT tests	3
Total advice items	27
Total items failed	5

MOT #11 2021-08-12 15:50

MOT test number 389254330315

Result ✓ Passed

Next expiry date 2022-08-11

- Advice** Nearside Rear Brake pipe corroded, covered in grease or other material (1.1.11 (c))
- Advice** Front Inner Brake disc worn, pitted or scored, but not seriously weakened (1.1.14 (a) (ii))
- Advice** Nearside Rear Brake hose has slight corrosion to ferrule (1.1.12 (f) (i))

MOT #10 2021-08-09 10:27

MOT test number 679495535898

Result ✗ Failed

- Advice** Nearside Rear Brake pipe corroded, covered in grease or other material (1.1.11 (c))
- Advice** Nearside Rear Brake hose has slight corrosion to ferrule (1.1.12 (f) (i))
- Fail** Offside Rear Brake pipe excessively corroded (1.1.11 (c))
- Advice** Front Inner Brake disc worn, pitted or scored, but not seriously weakened (1.1.14 (a) (ii))
- Fail** Offside Rear Brake hose ferrule excessively corroded (1.1.12 (f) (i))

**MOT #9**

2020-09-25 09:25

MOT test number

415583418917

Result

✓ Passed

Advice Rear Brake pipe corroded, covered in grease or other material both rear brake pipes corroded (1.1.11 (c))

Advice Brake disc worn, pitted or scored, but not seriously weakened front and rear discs heavily corroded (1.1.14 (a) (ii))

Minor Nearside Front Outer Suspension arm ball joint dust cover severely deteriorated (5.3.4 (b) (i))

MOT #8

2020-09-23 10:56

MOT test number

150242044369

Result

✗ Failed

Advice Rear Brake pipe corroded, covered in grease or other material both rear brake pipes corroded (1.1.11 (c))

Minor Nearside Front Outer Suspension arm ball joint dust cover severely deteriorated (5.3.4 (b) (i))

Fail Nearside Front Position lamp not working (4.2.1 (a) (ii))

Fail Offside Front Outer Suspension arm ball joint dust cover no longer prevents the ingress of dirt (5.3.4 (b) (ii))

Advice Brake disc worn, pitted or scored, but not seriously weakened front and rear discs heavily corroded (1.1.14 (a) (ii))

MOT #7

2019-08-27 12:47

MOT test number

818453682681

Result

✓ Passed

Advice Brake pipe corroded, covered in grease or other material Front to back section (1.1.11 (c))

Advice Offside Front Brake disc worn, pitted or scored, but not seriously weakened (1.1.14 (a) (ii))

Advice Offside Front Tyre worn close to legal limit/worn on edge inner edge worn (5.2.3 (e))

Advice Offside Rear Brake pipe corroded, covered in grease or other material (1.1.11 (c))

Advice Nearside Front Brake disc worn, pitted or scored, but not seriously weakened (1.1.14 (a) (ii))

Advice Nearside Front Tyre worn close to legal limit/worn on edge Both edges (5.2.3 (e))

Advice Nearside Rear Brake pipe corroded, covered in grease or other material (1.1.11 (c))

**MOT #6** 2018-08-24 12:17**MOT test number** 352505196727**Result** ✓ Passed**Advice** Offside Rear Brake pipe corroded, covered in grease or other material (1.1.11 (c))**Advice** Nearside Rear Brake pipe corroded, covered in grease or other material (1.1.11 (c))**MOT #5** 2018-08-24 12:17**MOT test number** 592295750082**Result** ✗ Failed**Advice** Nearside Rear Brake pipe corroded, covered in grease or other material (1.1.11 (c))**Pass with rectification** Rear Registration plate lamp inoperative in the case of a single lamp or all lamps both lamps (4.7.1 (b) (ii))**Advice** Offside Rear Brake pipe corroded, covered in grease or other material (1.1.11 (c))**MOT #4** 2017-07-03 10:30**MOT test number** 844696447613**Result** ✓ Passed**Advice** Offside Front Tyre worn close to the legal limit (4.1.E.1)**Advice** Nearside Front Tyre worn close to the legal limit (4.1.E.1)**Advice** Parking brake lever has little reserve travel (3.1.6b)**MOT #3** 2016-07-04 09:03**MOT test number** 701628142027**Result** ✓ Passed**MOT #2** 2015-06-15 16:06**MOT test number** 696846865105**Result** ✓ Passed



MOT #1	2014-09-10 14:21
MOT test number	416513254218
Result	✓ Passed
Advice	Windscreen has damage to an area less than a 10mm circle within zone 'A' (8.3.1a)



Tax & MOT check

X

Untaxed

Tax expired:
15 October 2021

X

MOT

Expired:
11 August 2022

Tax status	Expired at 15 October 2021
Days left	926 days too late
MOT expiry date	11 August 2022
Full MOT history	See MOT history

Tax calculation

Vehicle class	49
Band	E
Single payment (12 months)	£ 180,00,-
Single six month payment	£ 99,00,-
Total payable by 12 monthly instalments	£ 189,00,-



Damage history

Check the damage history for this KIA. See if, where and when this KIA had damage and the car repair costs. We also check if this KIA was scrapped. Download the premium report [here](#) for the results.

Damage 1

Date	
Category	
Type	

Damage 2

Date	
Category	
Type	



Extra KIA salvage check



If this vehicle was seen at a salvage auction we offer: vehicle pictures, salvage location, retail value. Download the premium report [here](#) for more information.

More info >



Vehicle valuation

What is this car worth? See the vehicle value of this KIA in the premium report. We check: purchase value, age, mileage, MOT history, damages and online sale prices.

Trade retail value	£ 19,999
Auction value	£ 19,999
Average private trade value	£ 19,999

More info >



Owner history

For how long did the current and previous owner(s) have this KIA? How many owners did this KIA have? Check it in the premium report and see all owner registrations. Download the full report [here](#).

Owner	Registration
Owner	Registration
Owner	Registration
Owner	Registration
Owner	Registration
Owner	Registration
Owner	Registration

More info >

Plate changes

See in this check if this KIA had different number plates.

Number of plates	1
Current registration	XXXXXX
Plate since	2024-03-29
Current registration	XXXXXX
Plate since	2024-03-29

More info >



Finance check

Check if this KIA is financed, has an outstanding loan or finance agreement. If you are purchasing a vehicle it is smart to ensure that any finance that may have been taken out on this KIA has been settled.

If not, and you buy this KIA then you could lose the money and the car you paid for.

Download the premium report [here](#) and check if this KIA is financed.

Finance company	XXXXXXXXXX	XXXX
Date of agreement	XXXXXXXXXX	XXXX
Agreement type	XXXXXXXXXX	XXXX
Agreement term	XXXXXXXXXX	XXXX
Agreement number	XXXXXXXXXX	XXXX
Contact info	XXXXXXXXXX	XXXX

More info >



Mileage check

Odometer	In miles
Mileage registrations	13
First mileage registration	2011-09-08
Last registration	2021-08-12
Complete history	See info



Registration #1	2011-09-08	24 mi
Registration #2	2014-09-10	61.825 mi
Registration #3	2015-06-15	77.516 mi
Registration #4	2016-07-04	91.913 mi
Registration #5	2017-07-03	99.981 mi
Registration #6	2018-08-24	103.559 mi
Registration #7	2018-08-24	103.559 mi
Registration #8	2019-08-24	103.559 mi
Registration #9	2019-08-24	103.559 mi
Registration #10	2019-08-24	103.559 mi
Registration #11	2019-08-24	103.559 mi
Registration #12	2019-08-24	103.559 mi
Registration #13	2019-08-24	103.559 mi

More info >



Car features

The KIA factory car options list is only available in the premium report.

S0225	Air conditioning
S0295	
S0482	
S0501	
S0566	
S0567	
S0569	

View the complete KIA factory list for this vehicle [here](#).

More info >

Safety ratings

NCAP rating	★★★★★
Adult	87%
Children	86%
Pedestrian	39%
Safety systems	86%
Overall rating	77%
Video	see crash video



Dimensions & weight

Width	1785 mm
Height	1610 mm
Length	4105 mm
Wheel base	2550 mm
Kerb weight	1429 kg
Max. allowed weight	1780 kg

Additional information

Fuel tank capacity	48 l
Fuel delivery	Direct Injection
Number of doors	5
Number of seats	5

Number of axles	2
Engine number	D4FBAH532535