



report date: 2024-03-28

General information

Make	FORD
Model	GALAXY GHIA TDCI
Colour	Silver
Year of manufacture	2007
Top speed	120 mph
Gearbox	6 speed Manual

Engine & fuel consumption

Power	143 BHP
Max. torque	340 Nm at 2.000 rpm
Engine capacity	1.997 cc
Cylinders	4
Fuel type	Diesel
Consumption city	34.5 mpg
Consumption extra urban	51.4 mpg
Consumption combined	43.5 mpg
CO2 emission	172 g/km
CO2 label	H






Internet history

Entry 1

Date	2021-12-09
Pictures	20
Listing price	View report



source: [autotrader.co.uk](https://www.autotrader.co.uk)



MOT history

MOT expiry date	2025-01-04
MOT pass rate	64 %
MOT passed	14
Failed MOT tests	8
Total advice items	47
Total items failed	22

MOT #22	2023-12-06 15:10
---------	------------------

MOT test number	956847231094
-----------------	--------------

Result	✓ Passed
--------	----------

Next expiry date	2025-01-04
------------------	------------

- Advice** Nearside Rear Tyre worn close to legal limit/worn on edge (5.2.3 (e))
- Advice** Offside Rear Coil spring corroded (5.3.1 (b) (i))
- Advice** Offside Rear light unit damaged
- Advice** Exhaust has a minor leak of exhaust gases (6.1.2 (a))
- Minor** Nearside Headlamp lens slightly defective (4.1.1 (b) (i))
- Advice** Offside Front Tyre slightly damaged (5.2.3 (d) (ii))
- Advice** Nearside Rear Coil spring corroded (5.3.1 (b) (i))
- Advice** Offside Front Brake pad(s) wearing thin look low (1.1.13 (a) (ii))
- Advice** Oil leak, but not excessive (8.4.1 (a) (i))
- Advice** Steering system slightly rough (2.1.1 (a))
- Minor** Offside Headlamp lens slightly defective (4.1.1 (b) (i))

**MOT #21**

2022-12-06 11:44

MOT test number

584227499066

Result

✓ Passed

Advice Nearside Headlamp has a product on the light source but not seriously reducing light output (4.1.4 (b))

Advice Offside Front Tyre worn close to legal limit/worn on edge (5.2.3 (e))

Advice Nearside Rear Coil spring corroded (5.3.1 (b) (i))

Advice Offside Headlamp has a product on the light source but not seriously reducing light output (4.1.4 (b))

Advice Offside Rear Tyre worn close to legal limit/worn on edge (5.2.3 (e))

Advice Offside Rear Coil spring corroded (5.3.1 (b) (i))

MOT #20

2022-12-05 15:02

MOT test number

513208150106

Result

✗ Failed

Advice Offside Headlamp has a product on the light source but not seriously reducing light output (4.1.4 (b))

Advice Offside Rear Coil spring corroded (5.3.1 (b) (i))

Advice Offside Front Tyre worn close to legal limit/worn on edge (5.2.3 (e))

Advice Nearside Headlamp has a product on the light source but not seriously reducing light output (4.1.4 (b))

Advice Nearside Rear Coil spring corroded (5.3.1 (b) (i))

Fail Bonnet cannot be secured in the closed position (3.1 (b) (i))

Advice Offside Rear Tyre worn close to legal limit/worn on edge (5.2.3 (e))

Fail Nearside Front Upper Anti-roll bar linkage ball joint dust cover no longer prevents the ingress of dirt (5.3.4 (b) (ii))

**MOT #19**

2021-12-07 12:48

MOT test number

256179215671

Result

✓ Passed

Advice Offside Rear Suspension arm pin or bush worn but not resulting in excessive movement Trailing arm front bush. (5.3.4 (a) (i))

Minor Nearside Front Upper Anti-roll bar ball joint dust cover severely deteriorated (5.3.4 (b) (i))

Advice Nearside Rear Suspension arm pin or bush worn but not resulting in excessive movement Trailing arm front bush. (5.3.4 (a) (i))

MOT #18

2021-12-06 10:10

MOT test number

883356427592

Result

✗ Failed

Minor Nearside Front Upper Anti-roll bar ball joint dust cover severely deteriorated (5.3.4 (b) (i))

Advice Nearside Rear Suspension arm pin or bush worn but not resulting in excessive movement Trailing arm front bush. (5.3.4 (a) (i))

Fail Bonnet cannot be secured in the closed position (3.1 (b) (i))

Fail Nearside Rear Tyre has ply or cords exposed (5.2.3 (d) (ii))

Advice Offside Rear Suspension arm pin or bush worn but not resulting in excessive movement Trailing arm front bush. (5.3.4 (a) (i))

MOT #17

2020-12-08 15:27

MOT test number

762683114488

Result

✓ Passed

Advice Offside Front Tyre worn close to legal limit/worn on edge (5.2.3 (e))

Advice Nearside Front Tyre worn close to legal limit/worn on edge (5.2.3 (e))

**MOT #16**

2020-12-08 10:12

MOT test number

861041622659

Result**✗ Failed****Advice** Nearside Front Tyre worn close to legal limit/worn on edge (5.2.3 (e))**Fail** Offside Front Headlamp light intensity severely reduced no image (4.1.4 (a))**Fail** Offside Front Position lamp not working (4.2.1 (a) (ii))**Fail** Front Bonnet cannot be secured in the closed position (3.1 (b) (i))**Advice** Offside Front Tyre worn close to legal limit/worn on edge (5.2.3 (e))**Fail** Nearside Front Position lamp not working (4.2.1 (a) (ii))**MOT #15**

2019-12-10 12:25

MOT test number

553988713861

Result**✓ Passed****MOT #14**

2019-12-09 11:39

MOT test number

664729971670

Result**✗ Failed****Advice** Rear pads low**Fail** Nearside Rear Tyre tread depth below requirements of 1.6mm (5.2.3 (e))**Fail** Offside Front Position lamp not working (4.2.1 (a) (ii))**Minor** Offside Rear Registration plate lamp inoperative in the case of multiple lamps or light sources (4.7.1 (b) (i))**Fail** Nearside Front Headlamp not working on dipped beam (4.1.1 (a) (ii))**Advice** Offside Rear Tyre worn close to legal limit/worn on edge (5.2.3 (e))**Minor** Nearside Rear Registration plate lamp insecure (4.7.1 (c) (i))

**MOT #13** 2018-12-12 14:24**MOT test number** 686797328402**Result** ✓ Passed**MOT #12** 2018-12-12 11:55**MOT test number** 449324368179**Result** ✗ Failed**Fail** Nearside Rear Anti-roll bar linkage pin or bush excessively worn (5.3.4 (a) (i))**Minor** Nearside Registration plate lamp inoperative in the case of multiple lamps or light sources (4.7.1 (b) (i))**MOT #11** 2017-12-11 15:55**MOT test number** 844724397712**Result** ✓ Passed**MOT #10** 2017-12-06 15:13**MOT test number** 403859822041**Result** ✗ Failed**Fail** Exhaust system not adequately supported centre pipe (7.1.1)**Fail** Offside Rear Brake pad(s) less than 1.5 mm thick (3.5.1g)**Fail** Nearside Stop lamp not working (1.2.1b)**Fail** Nearside Front position lamp(s) not working (1.1.A.3b)**Fail** Exhaust has a major leak of exhaust gases centre pipe (7.1.2)**Fail** Offside Front Anti-roll bar linkage ball joint dust cover excessively damaged so that it no longer prevents the ingress of dirt drop link (2.4.G.2)**Fail** Offside Stop lamp not working (1.2.1b)

**MOT #9** 2016-12-14 11:31**MOT test number** 336389394093**Result** ✓ Passed**Advice** Nearside Front Tyre worn close to the legal limit (4.1.E.1)**Advice** Front pads low.**Advice** Offside Front Tyre worn close to the legal limit (4.1.E.1)**MOT #8** 2015-12-17 11:57**MOT test number** 584966276254**Result** ✓ Passed**MOT #7** 2015-12-09 14:34**MOT test number** 293448231958**Result** ✗ Failed**Fail** Offside Rear Anti-roll bar has excessive play in a ball joint drop link (2.4.G.2)**Advice** All tyres worn edge on legal limit**Fail** Exhaust has a major leak of exhaust gases (7.1.2)**MOT #6** 2015-01-05 12:02**MOT test number** 956805105049**Result** ✓ Passed**Notice** Slight play o/s r drop link.**MOT #5** 2013-09-30 16:01**MOT test number** 185533573235**Result** ✓ Passed

**MOT #4** 2013-09-27 15:11**MOT test number** 109580073274**Result** ✗ Failed**Notice** Osf tyre on 2mm nsr worn inner edge**Fail** Nearside Front Tyre has a cut in excess of the requirements deep enough to reach the ply or cords (4.1.D.1a)**MOT #3** 2012-10-02 08:33**MOT test number** 437726472284**Result** ✓ Passed**Advice** Nearside Rear Tyre worn close to the legal limit (4.1.E.1)**Advice** Rear Brake pad(s) wearing thin (3.5.1g)**Advice** Offside Rear Tyre worn close to the legal limit (4.1.E.1)**MOT #2** 2011-09-13 10:20**MOT test number** 629976451218**Result** ✓ Passed**MOT #1** 2010-09-17 11:36**MOT test number** 573870960214**Result** ✓ Passed



Tax & MOT check

✓
Taxed
Tax due:
1 February 2025

✓
MOT
Expires:
4 January 2025

Tax status	Valid until 1 February
Days left	278
MOT expiry date	4 January 2025
Full MOT history	See MOT history

Tax calculation

Vehicle class	49
Band	H
Single payment (12 months)	£ 290,00,-
Single six month payment	£ 159,50,-
Total payable by 12 monthly instalments	£ 304,50,-



Damage history

Check the damage history for this FORD. See if, where and when this FORD had damage and the car repair costs. We also check if this FORD was scrapped. Download the premium report [here](#) for the results.

Damage 1

Date	
Category	
Type	

Damage 2

Date	
Category	
Type	



Extra FORD salvage check



If this vehicle was seen at a salvage auction we offer: vehicle pictures, salvage location, retail value. Download the premium report [here](#) for more information.

More info >



Vehicle valuation

What is this car worth? See the vehicle value of this FORD in the premium report. We check: purchase value, age, mileage, MOT history, damages and online sale prices.

Trade retail value	£ 19,999
Auction value	£ 19,999
Average private trade value	£ 19,999

More info >



Owner history

For how long did the current and previous owner(s) have this FORD? How many owners did this FORD have? Check it in the premium report and see all owner registrations. Download the full report [here](#).

*****	*****
*****	*****
*****	*****
*****	*****
*****	*****
*****	*****
*****	*****

More info >

Plate changes

See in this check if this FORD had different number plates.

Number of plates	1
Current registration	*****
Plate since	2019-06-29
Current registration	*****
Plate since	2019-06-29

More info >



Finance check

Check if this FORD is financed, has an outstanding loan or finance agreement. If you are purchasing a vehicle it is smart to ensure that any finance that may have been taken out on this FORD has been settled.

If not, and you buy this FORD then you could lose the money and the car you paid for.

Download the premium report [here](#) and check if this FORD is financed.

Finance company	XXXXXXXXXX	XXXX
Date of agreement	XXXXXXXXXX	XXXX
Agreement type	XXXXXXXXXX	XXXX
Agreement term	XXXXXXXXXX	XXXX
Agreement number	XXXXXXXXXX	XXXX
Contact info	XXXXXXXXXX	XXXX

More info >



Mileage check

Odometer	In miles
Mileage registrations	24
First mileage registration	2007-05-14
Last registration	2023-12-06
Complete history	See info



Registration #1	2007-05-14	17 mi
Registration #2	2010-09-17	48.210 mi
Registration #3	2011-09-13	61.905 mi
Registration #4	2012-10-02	79.617 mi
Registration #5	2013-09-27	89.698 mi
Registration #6	2013-09-30	89.705 mi
Registration #7	2015-01-05	104.339 mi
Registration #8	2015-12-09	111.606 mi
Registration #9	2015-12-17	111.955 mi
Registration #10	2016-12-14	120.214 mi
Registration #11	2017-12-06	132.015 mi
Registration #12	2017-12-11	132.122 mi
Registration #13	2019-05-20	151.377 mi
Registration #14	2019-05-20	151.377 mi
Registration #15	2019-05-20	151.377 mi
Registration #16	2019-05-20	151.377 mi
Registration #17	2019-05-20	151.377 mi
Registration #18	2019-05-20	151.377 mi
Registration #19	2019-05-20	151.377 mi
Registration #20	2019-05-20	151.377 mi
Registration #21	2019-05-20	151.377 mi
Registration #22	2019-05-20	151.377 mi
Registration #23	2019-05-20	151.377 mi
Registration #24	2019-05-20	151.377 mi

More info >



Car features

The FORD factory car options list is only available in the premium report.

S0225	Air conditioning
S0295	
S0482	
S0501	
S0566	
S0567	
S0569	

View the complete FORD factory list for this vehicle [here](#).

More info >

Safety ratings

NCAP rating ★★★★★

Video [see crash video](#)



Dimensions & weight

Width	1884 mm
Height	1736 mm
Length	4820 mm
Wheel base	2850 mm
Kerb weight	1933 kg
Max. allowed weight	2505 kg

Additional information

Fuel tank capacity	70 l
Fuel delivery	Direct Injection
Number of doors	5
Number of seats	7

Number of axles	2
Engine number	7D52640