




report date: 2024-03-28

General information

Make	VOLKSWAGEN
Model	TOUAREG TDI SPORT
Colour	Grey
Year of manufacture	2004
Top speed	114 mph
0 - 60 mph	12.9 seconds
Gearbox	6 speed automatic

Engine & fuel consumption

Power	174 BHP
Max. torque	400 Nm at 2.000 rpm
Engine capacity	2.460 cc
Cylinders	5
Fuel type	Diesel
Consumption city	21.9 mpg
Consumption extra urban	33.6 mpg
Consumption combined	28.5 mpg
CO2 emission	273 g/km
CO2 label	M



**MOT history**

<b>MOT expiry date</b>	2020-10-16
<b>MOT pass rate</b>	71 %
<b>MOT passed</b>	12
<b>Failed MOT tests</b>	5
<b>Total advice items</b>	14
<b>Total items failed</b>	12

**MOT #17** 2019-04-15 15:24**MOT test number** 614991756567**Result** Passed**Next expiry date** 2020-10-16

- Advice** Nearside Play in steering rack inner joint(s)
- Advice** Travel on parking brake lever
- Advice** Nearside Rear Anti-roll bar linkage ball joint has slight play (5.3.4 (a) (i))

**MOT #16** 2018-04-17 11:13**MOT test number** 380794952928**Result** Passed**MOT #15** 2017-04-05 15:40**MOT test number** 191549206034**Result** Passed

- Advice** Front Brake hose slightly deteriorated nearside and offside (3.6.B.4d)

**MOT #14** 2017-03-30 12:55**MOT test number** 896033905443**Result** ✗ Failed**Fail** Supplementary Restraint System warning lamp indicates a fault airbag (5.4.2)**Advice** Front Brake hose slightly deteriorated nearside and offside (3.6.B.4d)**MOT #13** 2016-03-15 15:30**MOT test number** 370540086663**Result** ✓ Passed**MOT #12** 2016-03-12 11:36**MOT test number** 875363429292**Result** ✗ Failed**Fail** Supplementary Restraint System warning lamp indicates a fault (5.4.2)**Fail** Offside Rear coil spring broken (2.4.C.1a)**Fail** Offside Rear Stop lamp remains on when the brakes are released (1.2.1e)**Fail** Nearside Rear Tyre has ply or cords exposed damaged on outer sidewall (4.1.D.1b)**MOT #11** 2015-03-11 19:10**MOT test number** 239360875074**Result** ✓ Passed**MOT #10** 2014-05-28 12:37**MOT test number** 575798144121**Result** ✓ Passed

**MOT #9** 2014-05-27 11:13**MOT test number** 507657544120**Result** ✗ Failed**Fail** Offside Stop lamp not working (1.2.1b)**Fail** Nearside Rear coil spring broken (2.4.C.1a)**Fail** Front Headlamp aim too low (1.8)**MOT #8** 2013-05-13 13:40**MOT test number** 646723033136**Result** ✓ Passed**Advice** Offside Front Tyre worn close to the legal limit (4.1.E.1)**MOT #7** 2012-07-11 15:03**MOT test number** 788083392118**Result** ✓ Passed**Advice** Nearside Rear Tyre worn close to the legal limit (4.1.E.1)**Advice** Offside Front Tyre worn close to the legal limit (4.1.E.1)**Advice** Offside Rear Tyre worn close to the legal limit (4.1.E.1)

**MOT #6** 2012-07-11 13:23**MOT test number** 596913092190**Result** ✗ Failed**Fail** Parking brake lever ratchet mechanism is excessively worn (3.1.5)**Fail** Offside Stop lamp not working (1.2.1b)**Advice** Offside Rear Tyre worn close to the legal limit (4.1.E.1)**Fail** Offside Headlamp not working on dipped beam (1.7.5a)**Advice** Nearside Rear Tyre worn close to the legal limit (4.1.E.1)**Advice** Offside Front Tyre worn close to the legal limit (4.1.E.1)**MOT #5** 2010-07-22 11:25**MOT test number** 984163400230**Result** ✓ Passed**MOT #4** 2009-06-30 10:03**MOT test number** 963361689122**Result** ✓ Passed**Advice** Nearside Rear Tyre worn close to the legal limit (4.1.E.1)**Advice** Offside Rear Tyre worn close to the legal limit (4.1.E.1)**MOT #3** 2008-06-06 11:05**MOT test number** 782528058175**Result** ✓ Passed**MOT #2** 2008-06-06 09:30**MOT test number** 443078658120**Result** ✗ Failed**Fail** Offside Stop lamp not working (1.2.1b)



MOT #1	2007-01-19 11:54
MOT test number	984229717009
Result	✓ Passed



Damage history


Check the damage history for this VOLKSWAGEN. See if, where and when this VOLKSWAGEN had damage and the car repair costs. We also check if this VOLKSWAGEN was scrapped. Download the premium report [here](#) for the results.

Damage 1

Date	
Category	
Type	

Damage 2

Date	
Category	
Type	



Extra VOLKSWAGEN salvage check



If this vehicle was seen at a salvage auction we offer: vehicle pictures, salvage location, retail value. Download the premium report [here](#) for more information.

More info >



Vehicle valuation

What is this car worth? See the vehicle value of this VOLKSWAGEN in the premium report. We check: purchase value, age, mileage, MOT history, damages and online sale prices.

Trade retail value	£ 19,999
Auction value	£ 19,999
Average private trade value	£ 19,999

More info >





Owner history

For how long did the current and previous owner(s) have this VOLKSWAGEN? How many owners did this VOLKSWAGEN have? Check it in the premium report and see all owner registrations. Download the full report [here](#).

Owner	Registration
Owner	Registration
Owner	Registration
Owner	Registration
Owner	Registration
Owner	Registration
Owner	Registration

More info >

Plate changes

See in this check if this VOLKSWAGEN had different number plates.

Number of plates	1
Current registration	 <b>PK04VJU</b>
Plate since	2024-03-28
Current registration	 <b>PK04VJU</b>
Plate since	2024-03-28

More info >



Finance check

Check if this VOLKSWAGEN is financed, has an outstanding loan or finance agreement. If you are purchasing a vehicle it is smart to ensure that any finance that may have been taken out on this VOLKSWAGEN has been settled.

If not, and you buy this VOLKSWAGEN then you could lose the money and the car you paid for.

Download the premium report [here](#) and check if this VOLKSWAGEN is financed.

Finance company	REDACTED	REDACTED
Date of agreement	REDACTED	REDACTED
Agreement type	REDACTED	REDACTED
Agreement term	REDACTED	REDACTED
Agreement number	REDACTED	REDACTED
Contact info	REDACTED	REDACTED

More info >



Mileage check

Odometer	In miles
Mileage registrations	18
First mileage registration	2004-05-28
Last registration	2019-04-15
Complete history	<a href="#">See info</a>



Registration #1	2004-05-28	29 mi
Registration #2	2007-01-19	33.448 mi
Registration #3	2008-06-06	46.283 mi
Registration #4	2008-06-06	46.293 mi
Registration #5	2009-06-30	56.343 mi
Registration #6	2010-07-22	61.765 mi
Registration #7	2012-07-11	81.240 mi
Registration #8	2012-07-11	81.240 mi
Registration #9	2013-05-13	89.420 mi
Registration #10	2019-04-15	95.377 mi
Registration #11	2019-04-15	95.377 mi
Registration #12	2019-04-15	95.377 mi
Registration #13	2019-04-15	95.377 mi
Registration #14	2019-04-15	95.377 mi
Registration #15	2019-04-15	95.377 mi
Registration #16	2019-04-15	95.377 mi
Registration #17	2019-04-15	95.377 mi
Registration #18	2019-04-15	95.377 mi

More info >



Car features

The VOLKSWAGEN factory car options list is only available in the premium report.

S0225	Air conditioning
S0295	
S0482	
S0501	
S0566	
S0567	
S0569	

View the complete VOLKSWAGEN factory list for this vehicle [here](#).

More info >

Safety ratings

NCAP rating ★★★★★

Video [see crash video](#)



Dimensions & weight

Width	1928 mm
Height	1726 mm
Length	4754 mm
Wheel base	2855 mm
Kerb weight	2510 kg
Max. allowed weight	2850 kg

Additional information

Fuel delivery	Direct Injection
Number of doors	5
Number of seats	5

Number of axles	2
Engine number	BAC 029969