





report date: 2024-03-28

General information

| Make | LAND ROVER |
|---------------------|-------------------|
| Model | FREELANDER SD4 GS |
| Colour | Black |
| Year of manufacture | 2014 |
| Top speed | 118 mph |
| 0 - 100 km/h | 9.5 seconds |
| 0 - 60 mph | 8.7 seconds |
| Gearbox | 6 speed automatic |

Engine & fuel consumption

| Power | 140 kW / 191 HP / 190 BHP |
|-------------------------|---------------------------|
| Max. torque | 420 Nm at 1.750 rpm |
| Engine capacity | 2.179 сс |
| Cylinders | 4 |
| Fuel type | Diesel |
| Consumption city | 32.5 mpg |
| Consumption extra urban | 48.7 mpg |
| Consumption combined | 40.4 mpg |
| CO2 emission | 185 g/km |
| CO2 label | I |



CarCheck.co.uk page 1/11



report date: 2024-03-28

Internet history

Entry 4

Date 2021-11-25


Pictures 10

Listing price <u>View report</u>









source: autoonline.co.uk

Entry 3

| Date | 2021-11-01 |
|------|------------|
| | |

Pictures 41

Listing price <u>View report</u>









source: autotrader.co.uk

Entry 2

| Date | 2021-10-08 | |
|---------------|--------------------|--|
| Pictures | 0 | |
| Listing price | <u>View report</u> | |

source: heycar.co.uk

Entry 1

| Date | 2021-10-05 |
|---------------|-------------|
| Pictures | 41 |
| Listing price | View report |

CarCheck.co.uk page 2/11









source: autotrader.co.uk



report date: 2024-03-28

| | _ | | | | |
|-------|-----|---|----|---------------|-----|
| 11/1/ | TC | n | | $\overline{}$ | r\/ |
| IVIL | , , | | 51 | LU. | ıv |
| | | | | | . , |

| MOT expiry date | 2024-09-13 |
|--------------------|------------|
| MOT pass rate | 78 % |
| MOT passed | 7 |
| Failed MOT tests | 2 |
| Total advice items | 11 |
| Total items failed | 1 |

| MOT #9 | 2023-08-21 15:48 |
|--|-------------------|
| MOT test number | 717117681324 |
| Result | ✓ Passed |
| Next expiry date | 2024-09-13 |
| Minor Offside Front Track rod end ball joint dust cover damaged or deteriorated, but ingress of dirt burst boot (2.1.3 (g) (i)) Advice Rear Brake pad(s) wearing thin (1.1.13 (a) (ii)) Advice Offside Rear Shock absorbers has light misting of oil (5.3.2 (b)) | it preventing the |

| MOT #8 | 2022-09-08 13:58 |
|-----------------|------------------|
| MOT test number | 100381636994 |
| Result | ✓ Passed |
| | |
| MOT #7 | 2021-08-17 15:26 |
| MOT test number | 608152969338 |
| Result | ✓ Passed |
| | |
| MOT #6 | 2020-09-11 12:15 |
| MOT test number | 967381833501 |
| Result | ✓ Passed |

CarCheck.co.uk page 3/11



report date: 2024-03-28

MOT test number

Result

Advice Front Brake pad(s) wearing thin (1.1.13 (a) (ii))

Advice Offside Rear Nail in tyre

Advice Nearside Rear Tyre worn close to legal limit/worn on edge (5.2.3 (e))

MOT test number

465518794742

Result

Advice Front Brake pad(s) wearing thin (1.1.13 (a) (ii))

Advice Offside Rear Nail in tyre

Advice Nearside Rear Tyre worn close to legal limit/worn on edge (5.2.3 (e))

DANGEROUS Rear Brake pad(s) less than 1.5 mm thick (1.1.13 (a) (ii))

MOT #3

MOT test number

Result

MOT #2

2018-09-14 08:49

742029216160

✓ Passed

MOT test number 268791060177

Result × Failed

Pass with rectification Offside Front Windscreen wiper does not clear the windscreen effectively (3.4 (b) (ii))

MOT #1

MOT test number

Result

Advice Rear Inner Brake pad(s) wearing thin 3mm (3.5.1g)

CarCheck.co.uk page 4/11



report date: 2024-03-28

Tax & MOT check





Expires: 13 September 2024

| Tax status | Valid until 1 November |
|------------------|------------------------|
| Days left | 186 |
| MOT expiry date | 13 September 2024 |
| Full MOT history | See MOT history |

Tax calculation

| Vehicle class | 49 |
|---|------------|
| | 1 |
| Band | ı |
| Single payment (12 months) | £ 320,00,- |
| Single six month payment | £ 176,00,- |
| Total payable by 12 monthly instalments | £ 336,00,- |

CarCheck.co.uk page 5/11



report date: 2024-03-28

Damage history

Check the damage history for this LAND ROVER. See if, where and when this LAND ROVER had damage and the car repair costs. We also check if this LAND ROVER was scrapped. Download the premium report <u>here</u> for the results.

Damage 1

Date
Category
Type

Damage 2

Date

Category

Type



Extra LAND ROVER salvage check



If this vehicle was seen at a salvage auction we offer: vehicle pictures, salvage location, retail value. Download the premium report <u>here</u> for more information.

More info >

CarCheck.co.uk page 6/11



report date: 2024-03-28

Vehicle valuation

What is this car worth? See the vehicle value of this LAND ROVER in the premium report. We check: purchase value, age, mileage, MOT history, damages and online sale prices.

Trade retail value

Auction value

Average private trade value

More info >

CarCheck.co.uk page 7/11



report date: 2024-03-28

Owner history

| For how long did the current and previous owner(s) have this LAND ROVER? How many o ROVER have? Check it in the premium report and see all owner registrations. Download to | |
|---|---|
| *************************************** | |
| | |
| *************************************** | |
| *************************************** | |
| | |
| *************************************** | |
| | More info > |
| Plate changes | |
| See in this check if this LAND ROVER had different number plates. | |
| Number of plates | |
| Current registration | NIE |
| Plate since | |
| Current registration | NK NE |
| Plate since | |
| | More info > |

CarCheck.co.uk page 8/11



report date: 2024-03-28

Finance check

Check if this LAND ROVER is financed, has an outstanding loan or finance agreement. If you are purchasing a vehicle it is smart to ensure that any finance that may have been taken out on this LAND ROVER has been settled.

If not, and you buy this LAND ROVER then you could lose the money and the car you paid for.

Download the premium report <u>here</u> and check if this LAND ROVER is financed.

| Finance company | |
|-------------------|--|
| Date of agreement | |
| Agreement type | |
| Agreement term | |
| Agreement number | |
| | |

Contact info

More info >

CarCheck.co.uk page 9/11



report date: 2024-03-28

Mileage check

Registration #14

| Odometer | In miles |
|----------------------------|------------|
| Mileage registrations | 14 |
| First mileage registration | 2014-09-02 |
| Last registration | 2023-08-21 |
| Complete history | See info |



| Registration #1 | 2014-09-02 | 25 mi |
|------------------|------------|-----------|
| Registration #2 | 2017-09-13 | 26.203 mi |
| Registration #3 | 2018-09-14 | 28.707 mi |
| Registration #4 | 2018-09-14 | 28.707 mi |
| Registration #5 | 2019-09-12 | 31.997 mi |
| Registration #6 | 2019-09-12 | 31.997 mi |
| Registration #7 | 2020-09-11 | 35.240 mi |
| Registration #8 | | 11.777 ea |
| Registration #9 | | 11.777 es |
| Registration #10 | | 11.777 es |
| Registration #11 | | 11.177 mi |
| Registration #12 | | 77.777 mg |
| | | |
| Registration #13 | | 11.777 es |

mn.n.n

More info >

77.777 86

CarCheck.co.uk page 10/11



OU64ZFG report date: 2024-03-28

Safety ratings

| NCAP rating | *** |
|-------------|-----|
|-------------|-----|

Video <u>see crash video</u>



Dimensions & weight

| Width | 2005 mm |
|---------------------|---------|
| Height | 1740 mm |
| Length | 4500 mm |
| Wheel base | 2660 mm |
| Kerb weight | 1745 kg |
| Max. allowed weight | 2505 kg |

Additional information

| Fuel tank capacity | 68 I |
|--------------------|------------------|
| Fuel delivery | Direct Injection |
| Number of doors | 5 |
| Number of axles | 2 |
| Engine number | DZ784181354224DT |

CarCheck.co.uk page 11/11