



report date: 2024-03-28

General information

Make	NISSAN
Model	350 Z V6
Colour	Grey
Year of manufacture	2009
Top speed	155 mph
0 - 60 mph	5.8 seconds
Gearbox	6 speed Manual

Engine & fuel consumption

Power	296 BHP
Max. torque	358 Nm at 4.800 rpm
Engine capacity	3.498 cc
Cylinders	6
Fuel type	Petrol
Consumption city	16.9 mpg
Consumption extra urban	31.7 mpg
Consumption combined	24.1 mpg
CO2 emission	280 g/km
CO2 label	M






Internet history

Entry 1

Date	2022-05-18
Pictures	36
Listing price	View report



source: yesauto.com



MOT history

MOT expiry date	2024-01-31
MOT pass rate	73 %
MOT passed	11
Failed MOT tests	4
Total advice items	21
Total items failed	9

MOT #15	2023-02-01 17:58
MOT test number	681364333162
Result	✓ Passed
Next expiry date	2024-01-31

MOT #14	2023-02-01 17:58
MOT test number	493813418566
Result	✗ Failed
Pass with rectification	Nearside Front Headlamp not working on dipped beam (4.1.1 (a) (ii))
Pass with rectification	Nearside Front Tyre tread depth below requirements of 1.6mm (5.2.3 (e))

MOT #13	2022-06-21 13:36
MOT test number	611262825917
Result	✓ Passed

MOT #12	2022-06-21 13:36
MOT test number	754519902541
Result	✗ Failed
Pass with rectification	Offside Front Headlamp has a product on the light source so that the light output is severely reduced (4.1.4 (b))
Pass with rectification	Nearside Front Headlamp has a product on the light source so that the light output is severely reduced (4.1.4 (b))

**MOT #11** 2021-10-15 16:50**MOT test number** 918512431242**Result** ✓ Passed**MOT #10** 2020-01-24 16:09**MOT test number** 292280967676**Result** ✓ Passed**MOT #9** 2020-01-21 14:52**MOT test number** 171505804223**Result** ✗ Failed

- Fail** Offside Front Lower Suspension arm pin or bush excessively worn (5.3.4 (a) (i))
- Fail** Offside Front Lower Suspension arm pin or bush likely to become detached (5.3.4 (a) (ii))
- Fail** Nearside Front Lower Suspension arm pin or bush excessively worn (5.3.4 (a) (i))
- Fail** Nearside Front Lower Suspension arm pin or bush likely to become detached (5.3.4 (a) (ii))

MOT #8 2018-11-14 11:29**MOT test number** 741766958005**Result** ✓ Passed

- Advice** Offside Front Brake pipe corroded, covered in grease or other material (1.1.11 (c))
- Advice** Nearside Front Tyre worn close to legal limit/worn on edge (5.2.3 (e))
- Advice** Advise front and rear number plates starting to fade
- Advice** Nearside Front Brake pipe corroded, covered in grease or other material at ends (1.1.11 (c))

**MOT #7** 2017-09-08 10:32**MOT test number** 613935932605**Result** ✓ Passed**Advice** Nearside Front Brake pipe slightly corroded just passing low mot criteria (3.6.B.2c)**Advice** Brake pipe slightly corroded just passing low mot criteria (3.6.B.2c)**Advice** Slight noise from the n/s/f wheel, possible bearing starting to wear not yet rough**MOT #6** 2016-08-22 15:18**MOT test number** 626186036521**Result** ✓ Passed**Advice** Brake pipe slightly corroded o/s/f and n/s/f (3.6.B.2c)**Advice** Advise slight noise from the n/s/f wheel not yet rough but should be checked**Advice** Rear brake fluctuating, but not excessively o/s/r and n/s/r just passing low mot criteria (3.7.B.3)**Advice** Tyre worn close to the legal limit o/s/f and o/s/r very low and just passing low mot criteria (4.1.E.1)**Advice** Park brake low on the o/s/r**MOT #5** 2015-07-03 12:00**MOT test number** 738814285125**Result** ✓ Passed**Advice** Offside Rear Tyre worn close to the legal limit (4.1.E.1)**Advice** Offside Front Tyre worn close to the legal limit (4.1.E.1)**MOT #4** 2014-07-09 10:19**MOT test number** 395690994161**Result** ✓ Passed**Advice** Offside Rear Tyre worn close to the legal limit (4.1.E.1)**Notice** Nail in nearside front tyre

**MOT #3** 2013-01-21 12:07**MOT test number** 976451423043**Result** ✓ Passed**Notice** Advise o/s/f and n/s/f tyres in poor condition**MOT #2** 2012-01-11 12:25**MOT test number** 578811612072**Result** ✓ Passed**Advice** Offside Rear Tyre worn close to the legal limit (4.1.E.1)**Advice** Offside Front Tyre worn close to the legal limit (4.1.E.1)**MOT #1** 2012-01-10 11:46**MOT test number** 827240912032**Result** ✗ Failed**Advice** Offside Front Tyre worn close to the legal limit (4.1.E.1)**Fail** Nearside Rear Tyre tread depth below requirements of 1.6mm (4.1.E.1)**Advice** Offside Rear Tyre worn close to the legal limit (4.1.E.1)



Tax & MOT check

✕
Untaxed

Tax expired:
10 October 2023

✕
MOT

Expired:
31 January 2024

Tax status	Expired at 10 October 2023
Days left	201 days too late
MOT expiry date	31 January 2024
Full MOT history	See MOT history

Tax calculation

Vehicle class	48
Band	M
Single payment (12 months)	£ 695,00,-
Single six month payment	£ 382,25,-
Total payable by 12 monthly instalments	£ 729,75,-



Damage history

Check the damage history for this NISSAN. See if, where and when this NISSAN had damage and the car repair costs. We also check if this NISSAN was scrapped. Download the premium report [here](#) for the results.

Damage 1

Date	
Category	
Type	

Damage 2

Date	
Category	
Type	



Extra NISSAN salvage check



If this vehicle was seen at a salvage auction we offer: vehicle pictures, salvage location, retail value. Download the premium report [here](#) for more information.

More info >



Vehicle valuation

What is this car worth? See the vehicle value of this NISSAN in the premium report. We check: purchase value, age, mileage, MOT history, damages and online sale prices.

Trade retail value	£ 19,999
Auction value	£ 19,999
Average private trade value	£ 19,999

More info >



Owner history

For how long did the current and previous owner(s) have this NISSAN? How many owners did this NISSAN have? Check it in the premium report and see all owner registrations. Download the full report [here](#).

Owner	Registration
Owner	Registration
Owner	Registration
Owner	Registration
Owner	Registration
Owner	Registration
Owner	Registration

More info >

Plate changes

See in this check if this NISSAN had different number plates.

Number of plates	1
Current registration	 XXXXXX
Plate since	2024-03-28
Current registration	 XXXXXX
Plate since	2024-03-28

More info >



Finance check

Check if this NISSAN is financed, has an outstanding loan or finance agreement. If you are purchasing a vehicle it is smart to ensure that any finance that may have been taken out on this NISSAN has been settled.

If not, and you buy this NISSAN then you could lose the money and the car you paid for.

Download the premium report [here](#) and check if this NISSAN is financed.

Finance company	XXXXXXXX XX
Date of agreement	XXXXXXXX XX
Agreement type	XXXXXXXX XX
Agreement term	XXXXXXXX XX
Agreement number	XXXXXXXX XX
Contact info	XXXXXXXX XX

More info >



Mileage check

Odometer	In miles
Mileage registrations	17
First mileage registration	2009-01-09
Last registration	2023-02-01
Complete history	See info



Registration #1	2009-01-09	8 mi
Registration #2	2012-01-10	15.577 mi
Registration #3	2012-01-11	15.577 mi
Registration #4	2013-01-21	17.737 mi
Registration #5	2014-07-09	19.685 mi
Registration #6	2015-07-03	20.368 mi
Registration #7	2016-08-22	21.825 mi
Registration #8	2017-09-08	23.744 mi
Registration #9	2018-11-14	26.244 mi
Registration #10	2019-01-01	26.244 mi
Registration #11	2019-01-01	26.244 mi
Registration #12	2019-01-01	26.244 mi
Registration #13	2019-01-01	26.244 mi
Registration #14	2019-01-01	26.244 mi
Registration #15	2019-01-01	26.244 mi
Registration #16	2019-01-01	26.244 mi
Registration #17	2019-01-01	26.244 mi

More info >



Car features

The NISSAN factory car options list is only available in the premium report.

S0225	Air conditioning
S0295	
S0482	
S0501	
S0566	
S0567	
S0569	

View the complete NISSAN factory list for this vehicle [here](#).

More info >

Dimensions & weight

Width	1815 mm
Height	1325 mm
Length	4315 mm
Wheel base	2650 mm
Max. allowed weight	1820 kg

Additional information

Fuel tank capacity	80 l
Fuel delivery	Multi-Point Injection
Number of doors	2
Number of seats	2
Number of axles	2
Engine number	VQ35-607799