



HYUNDAI



report date: 2024-03-29

General information

Make	HYUNDAI
Model	I40 CRDI ACTIVE BLUE DRIVE
Colour	White
Year of manufacture	2013
Top speed	119 mph
0 - 60 mph	12.9 seconds
Gearbox	6 speed Manual

Engine & fuel consumption

Power	114 BHP
Max. torque	260 Nm at 2.750 rpm
Engine capacity	1.685 cc
Cylinders	4
Fuel type	Diesel
Consumption city	53.3 mpg
Consumption extra urban	76.4 mpg
Consumption combined	65.7 mpg
CO2 emission	113 g/km
CO2 label	C







Internet history

Entry 1

Date	2021-09-09
Pictures	29
Listing price	<a href="#">View report</a>



source: autotrader.co.uk



## MOT history

MOT expiry date	2024-09-20
MOT pass rate	69 %
MOT passed	9
Failed MOT tests	4
Total advice items	11
Total items failed	8

MOT #13	2023-09-18 10:43
MOT test number	915101301089
Result	✓ Passed
Next expiry date	2024-09-20
Advice	Rear Suspension arm corroded but not seriously weakened all (5.3.3 (b) (i))

MOT #12	2023-09-18 09:12
MOT test number	775466988080
Result	✗ Failed
Advice	Rear Suspension arm corroded but not seriously weakened all (5.3.3 (b) (i))
Fail	Offside Front Track rod end ball joint has excessive play (2.1.3 (b) (i))

MOT #11	2022-09-13 13:16
MOT test number	288700544754
Result	✓ Passed

MOT #10	2021-09-21 12:41
MOT test number	501321187349
Result	✓ Passed

**MOT #9** 2021-09-20 13:25**MOT test number** 749567110884**Result** ✗ Failed

- Fail** Nearside Front Inner Brake disc significantly and obviously worn (1.1.14 (a) (i))
- Fail** Nearside Front Track rod end ball joint has excessive play (2.1.3 (b) (i))
- Fail** Registration plate lamp inoperative in the case of a single lamp or all lamps both (4.7.1 (b) (ii))
- Fail** Nearside Front Coil spring fractured or broken (5.3.1 (b) (i))

**MOT #8** 2021-03-16 11:44**MOT test number** 889971132763**Result** ✓ Passed

- Advice** Front Both tyres are worn on inner edges and have cracks on sidewalls.225/45/18

**MOT #7** 2020-03-30 11:35**MOT test number** 623622930528**Result** ✓ Passed

- Advice** Nearside Front Tyre worn close to legal limit/worn on edge 225/45/18 (5.2.3 (e))
- Advice** Nearside Rear Tyre slightly damaged/cracking or perishing (5.2.3 (d) (ii))
- Advice** Nearside Front bead slightly damaged
- Advice** Offside Front Tyre worn close to legal limit/worn on edge (5.2.3 (e))
- Advice** Nearside Rear Tyre worn close to legal limit/worn on edge (5.2.3 (e))

**MOT #6** 2019-03-25 12:08**MOT test number** 609717654568**Result** ✓ Passed

**MOT #5** 2019-03-22 16:05**MOT test number** 272273901537**Result** ✗ Failed**Fail** Nearside Front Track rod end ball joint has excessive play (2.1.3 (b) (i))**Fail** Offside Front Track rod end ball joint has excessive play (2.1.3 (b) (i))**MOT #4** 2018-03-20 11:40**MOT test number** 310590129691**Result** ✓ Passed**Advice** Front Brake pad(s) wearing thin (3.5.1g)**MOT #3** 2017-03-04 09:02**MOT test number** 603879944004**Result** ✓ Passed**MOT #2** 2016-02-29 10:46**MOT test number** 343287883956**Result** ✓ Passed**Advice** Front Brake pad(s) wearing thin (3.5.1g)**MOT #1** 2016-02-29 10:46**MOT test number** 396570236773**Result** ✗ Failed**Pass with rectification** Front Windscreen wiper does not clear the windscreen effectively (8.2.2)**Advice** Front Brake pad(s) wearing thin (3.5.1g)



Tax & MOT check

X

Untaxed

Tax expired:  
15 April 2024

✓

MOT

Expires:  
20 September 2024

Tax status	Expired at 15 April 2024
Days left	15 days too late
MOT expiry date	20 September 2024
Full MOT history	<a href="#">See MOT history</a>

Tax calculation

Vehicle class	49
Band	C
Single payment (12 months)	£ 35,00,-
Single six month payment	Not applicable
Total payable by 12 monthly instalments	£ 36,75,-



Damage history

Check the damage history for this HYUNDAI. See if, where and when this HYUNDAI had damage and the car repair costs. We also check if this HYUNDAI was scrapped. Download the premium report [here](#) for the results.

Damage 1

Date	
Category	
Type	

Damage 2

Date	
Category	
Type	



Extra HYUNDAI salvage check



If this vehicle was seen at a salvage auction we offer: vehicle pictures, salvage location, retail value. Download the premium report [here](#) for more information.

More info >



Vehicle valuation

What is this car worth? See the vehicle value of this HYUNDAI in the premium report. We check: purchase value, age, mileage, MOT history, damages and online sale prices.

Trade retail value	£ 19,999
Auction value	£ 19,999
Average private trade value	£ 19,999

More info >





Owner history

For how long did the current and previous owner(s) have this HYUNDAI? How many owners did this HYUNDAI have? Check it in the premium report and see all owner registrations. Download the full report [here](#).

Owner	Registration
Owner	Registration
Owner	Registration
Owner	Registration
Owner	Registration
Owner	Registration
Owner	Registration

More info >

Plate changes

See in this check if this HYUNDAI had different number plates.

Number of plates	1
Current registration	EX13XJW
Plate since	2019-03-29
Current registration	EX13XJW
Plate since	2019-03-29

More info >



Finance check

Check if this HYUNDAI is financed, has an outstanding loan or finance agreement. If you are purchasing a vehicle it is smart to ensure that any finance that may have been taken out on this HYUNDAI has been settled.

If not, and you buy this HYUNDAI then you could lose the money and the car you paid for.

Download the premium report [here](#) and check if this HYUNDAI is financed.

Finance company	XXXXXXXXXX	XXXX
Date of agreement	XXXXXXXXXX	XXXX
Agreement type	XXXXXXXXXX	XXXX
Agreement term	XXXXXXXXXX	XXXX
Agreement number	XXXXXXXXXX	XXXX
Contact info	XXXXXXXXXX	XXXX

More info >



Mileage check

Odometer	In miles
Mileage registrations	15
First mileage registration	2013-03-23
Last registration	2023-09-18
Complete history	<a href="#">See info</a>



Registration #1	2013-03-23	22 mi
Registration #2	2016-02-29	17.119 mi
Registration #3	2016-02-29	17.119 mi
Registration #4	2017-03-04	19.455 mi
Registration #5	2018-03-20	23.347 mi
Registration #6	2019-03-22	27.138 mi
Registration #7	2019-03-25	27.145 mi
Registration #8	2020-03-30	30.519 mi
Registration #9	2020-03-30	30.519 mi
Registration #10	2020-03-30	30.519 mi
Registration #11	2020-03-30	30.519 mi
Registration #12	2020-03-30	30.519 mi
Registration #13	2020-03-30	30.519 mi
Registration #14	2020-03-30	30.519 mi
Registration #15	2020-03-30	30.519 mi

More info >



Car features

The HYUNDAI factory car options list is only available in the premium report.

S0225	Air conditioning
S0295	
S0482	
S0501	
S0566	
S0567	
S0569	

View the complete HYUNDAI factory list for this vehicle [here](#).

More info >

Safety ratings

NCAP rating	★★★★★
Adult	92%
Children	86%
Pedestrian	43%
Safety systems	86%
Overall rating	80%
Video	<a href="#">see crash video</a>



Dimensions & weight

Width	1815 mm
Height	1470 mm
Length	4740 mm
Wheel base	2770 mm
Kerb weight	1601 kg
Max. allowed weight	2080 kg

Additional information

Fuel tank capacity	70 l
Fuel delivery	Direct Injection
Number of doors	4
Number of seats	5

<b>Number of axles</b>	2
<b>Engine number</b>	D4FDDU322027