





report date: 2024-03-28

# General information

Make	MERCEDES-BENZ
Model	S-Class S350 BLUETEC L SE LINE
Colour	Black
Year of manufacture	2014
Top speed	155 mph
0 - 100 km/h	6.8 seconds
0 - 60 mph	6.8 seconds
Gearbox	7 speed automatic

# Engine & fuel consumption

Power	190 kW / 259 HP / 255 BHP
Max. torque	620 Nm at 1.600 rpm
Engine capacity	2.987 сс
Cylinders	6
Fuel type	Diesel
Consumption city	39.8 mpg
Consumption extra urban	58.9 mpg
Consumption combined	50.4 mpg
CO2 emission	148 g/km
CO2 label	F



CarCheck.co.uk page 1/12



# Internet history

Fn	trv	1
	ILI Y	-

Life y 1	
Date	2021-07-06
Pictures	0
Listing price	View report

source: autotrader.co.uk

CarCheck.co.uk page 2/12



MOT history

MOT expiry date	2022-01-31
MOT pass rate	92 %
MOT passed	12
Failed MOT tests	1
Total advice items	9
Total items failed	1

MOT #13	2021-02-01 12:45
MOT test number	160774213087
Result	✓ Passed
Next expiry date	2022-01-31

MOT #12	2021-02-01 10:13
MOT tes	t number 905413573623
Result	✓ Passed
Minor	Nearside Front Headlamp lens slightly defective (4.1.1 (b) (i))
Minor	Nearside Front Side repeater lens defective which has no effect on emitted light (4.4.1 (b) (i))

MOT #11	2020-08-14 13:49
MOT test number	868468609580
Result	✓ Passed

MOT #10	2020-02-01 10:38
MOT test number	958911577699
Result	<b>✓</b> Passed
Advice Offside Rear Nail in tyre	

CarCheck.co.uk page 3/12



MOT #9	2019-08-03 10:21
--------	------------------

**MOT test number** 671446735887

MOT #8 2019-02-05 16:26

**MOT test number** 594330484653

Result 

Passed

MOT #7 2018-08-06 11:46

**MOT test number** 916505095150

**Result** ✓ Passed

MOT #6 2018-02-06 12:31

**MOT test number** 701017142681

**Advice** Tyre worn close to the legal limit Both rear (4.1.E.1)

MOT #5 2018-02-02 10:20

**MOT test number** 672270654827

**Result** X Failed

**Advice** Tyre worn close to the legal limit Both rear (4.1.E.1)

**Fail** Rear fog lamp not working (1.3.2b)

MOT #4 2017-08-11 14:02

**MOT test number** 540399011170

**Result** ✓ Passed

**Advice** Engine covers fitted obscuring components

**Advice** Under tray covers fitted obscuring components

CarCheck.co.uk page 4/12



MOT test number

Result

MOT test number

A21362279444

Result

MOT #2

2016-10-13 12:06

MOT test number

416677961265

Result

Advice

Nearside Rear Tyre worn close to the legal limit (4.1.E.1)

MOT #1

MOT test number

Result

Advice Offside Rear Tyre worn close to the legal limit (4.1.E.1)

CarCheck.co.uk page 5/12





31 January 2022

# Tax & MOT check

Tax expired: 31 August 2021



Expired: 31 January 2022 X MOT

Tax status Expired at 31 August 2021

Days left 971 days too late

Full MOT history See MOT history

# Tax calculation

**MOT** expiry date

Vehicle class	49
Band	F
Single payment (12 months)	£ 200,00,-
Single six month payment	£ 110,00,-
Total payable by 12 monthly instalments	£ 210,00,-

CarCheck.co.uk page 6/12



# Damage history

Check the damage history for this MERCEDES-BENZ. See if, where and when this MERCEDES-BENZ had damage and the car repair costs. We also check if this MERCEDES-BENZ was scrapped. Download the premium report <u>here</u> for the results.


### Damage 1

Date	
Category	
Туре	
Damage 2	

**Date** 

Category

**Type** 



#### Extra MERCEDES-BENZ salvage check



If this vehicle was seen at a salvage auction we offer: vehicle pictures, salvage location, retail value. Download the premium report <u>here</u> for more information.

More info >

CarCheck.co.uk page 7/12



# Vehicle valuation

What is this car worth? See the vehicle value of this MERCEDES-BENZ in the premium report. We check: purchase value, age, mileage, MOT history, damages and online sale prices.

**Trade retail value** 

**Auction value** 

Average private trade value

More info >

CarCheck.co.uk page 8/12



O	والمراجعة والمراجعة
Owner	nistorv

owner mistery	
For how long did the current and previous owner(s) have this MERCEDES-BENZ? How material MERCEDES-BENZ have? Check it in the premium report and see all owner registrations. It report here.	
*********	
,,,,,,,,,,,,,,,,,,,,,,,,,,,,,,,,,,,,,,,	
***************************************	
***************************************	
***************************************	
	More info >
Plate changes	
See in this check if this MERCEDES-BENZ had different number plates.	
Number of plates	,
Current registration	UK UK
Plate since	
Current registration	UK UK
Plate since	
	More info >

CarCheck.co.uk page 9/12



# Finance check

Check if this MERCEDES-BENZ is financed, has an outstanding loan or finance agreement. If you are purchasing a vehicle it is smart to ensure that any finance that may have been taken out on this MERCEDES-BENZ has been settled.

If not, and you buy this MERCEDES-BENZ then you could lose the money and the car you paid for.

Download the premium report <u>here</u> and check if this MERCEDES-BENZ is financed.

Finance company

Date of agreement

Agreement type

Agreement term

Agreement number

**Contact info** 

More info >

CarCheck.co.uk page 10/12



# Mileage check

Odometer	In miles
Mileage registrations	15
First mileage registration	2014-03-01
Last registration	2021-02-01
Complete history	See info



Registration #1	2014-03-01	19 mi
Registration #2	2016-03-15	81.785 mi
Registration #3	2016-10-13	111.336 mi
Registration #4	2017-02-13	121.105 mi
Registration #5	2017-08-11	133.926 mi
Registration #6	2018-02-02	143.477 mi
Registration #7	2018-02-06	143.487 mi
Registration #8	2018-08-06	154.655 mi
Registration #9		11.777 es
Registration #10		71.777 es
Registration #11		9.70 es
Registration #12		11.777 es
Registration #13		9.70 es
Registration #14		11.777 es
Registration #15		11.117 es

More info >

CarCheck.co.uk page 11/12



# Car features

S0225	Air conditioning
S0295	
S0482	
S0501	
S0566	
S0567	
S0569	
View the complete MERCEDES-BENZ factory list for this vehicle here.	More info >

# Safety ratings

NCAP rating	****
Video	see crash video



# Dimensions & weight

Width	1899 mm
Height	1496 mm
Length	5246 mm
Wheel base	3165 mm
Kerb weight	1875 kg
Max. allowed weight	2690 kg

# Additional information

Fuel tank capacity	70 I
Fuel delivery	Direct Injection
Number of doors	4
	10/10

CarCheck.co.uk page 12/12

Number of axles	2
Engine number	64286141568687