





report date: 2024-03-29

General information

| Make | BMW |
|---------------------|------------------------------|
| Model | 218 218D SPORT ACTIVE TOURER |
| Colour | Grey |
| Year of manufacture | 2015 |
| Top speed | 130 mph |
| 0 - 60 mph | 8.9 seconds |
| Gearbox | 8 speed automatic |

Engine & fuel consumption

| Power | 148 BHP |
|-------------------------|---------------------|
| Max. torque | 330 Nm at 1.750 rpm |
| Engine capacity | 1.499 сс |
| Cylinders | 4 |
| Fuel type | Petrol |
| Consumption city | 60.1 mpg |
| Consumption extra urban | 74.3 mpg |
| Consumption combined | 68.9 mpg |
| CO2 emission | 119 g/km |
| CO2 label | С |



CarCheck.co.uk page 1/11



Internet history

Entry 1

Date 2021-06-16

Pictures 33

Listing price <u>View report</u>









source: autotrader.co.uk

CarCheck.co.uk page 2/11



2023-05-16 13:31

MOT history

MOT #7

| MOT expiry date | 2024-06-12 |
|--------------------|------------|
| MOT pass rate | 75 % |
| MOT passed | 6 |
| Failed MOT tests | 2 |
| Total advice items | 6 |
| Total items failed | 2 |

| MOT #8 | 2023-05-16 16:39 |
|------------------|------------------|
| MOT test number | 515099853861 |
| Result | ✓ Passed |
| Next expiry date | 2024-06-12 |

| MOT test number | 127174390978 |
|--|------------------------|
| Result | X Failed |
| Advice Nearside Rear Nail in tyre Fail Nearside Front Inner Drive shaft joint constant velocity boot split or insecure, | no longer prevents the |
| ingress of dirt (6.1.7 (g) (ii)) | |

| MOT #6 | | 2022-06-13 12:23 |
|----------|---|------------------|
| MOT test | number | 183539169173 |
| Result | | ✓ Passed |
| Advice | Offside Front Brake pad(s) wearing thin approx 60 $\%$ worn (1.1.13 (a) (ii)) | |
| Advice | Nearside Front Brake pad(s) wearing thin approx 60% worn (1.1.13 (a) (ii)) | |

CarCheck.co.uk page 3/11



MOT test number

Result

Advice Offside Front Brake pad(s) wearing thin approx 60 % worn (1.1.13 (a) (ii))

Advice Nearside Front Brake pad(s) wearing thin approx 60% worn (1.1.13 (a) (ii))

Fail Tyre pressure monitoring system malfunctioning or obviously inoperative (5.2.3 (h))

MOT #4

MOT test number

881587104015

Result

Advice Nearside Rear Child Seat fitted not allowing full inspection of adult belt

 MOT #3
 2020-02-17 09:55

 MOT test number
 849922335913

 Result
 ✓ Passed

MOT #2 2019-02-25 09:33

MOT test number 525565619730

Result ✓ Passed

MOT #1 2018-02-19 13:41

MOT test number 151309474013

Result ✓ Passed

CarCheck.co.uk page 4/11



Tax & MOT check



| Tax status | Valid until 1 July |
|------------------|--------------------|
| Days left | 62 |
| MOT expiry date | 12 June 2024 |
| Full MOT history | See MOT history |

Tax calculation

| Vehicle class | 48 |
|---|----------------|
| Band | С |
| Single payment (12 months) | £ 35,00,- |
| Single six month payment | Not applicable |
| Total payable by 12 monthly instalments | £ 36,75,- |

CarCheck.co.uk page 5/11



Damage history

Check the damage history for this BMW. See if, where and when this BMW had damage and the car repair costs. We also check if this BMW was scrapped. Download the premium report here for the results.

Damage 1
Date
Category
Type
Damage 2
Date
Category
Type



Extra BMW salvage check



If this vehicle was seen at a salvage auction we offer: vehicle pictures, salvage location, retail value. Download the premium report <u>here</u> for more information.

More info >

CarCheck.co.uk page 6/11



Vehicle valuation

What is this car worth? See the vehicle value of this BMW in the premium report. We check: purchase value, age, mileage, MOT history, damages and online sale prices.

Trade retail value

Auction value

Average private trade value

More info >

CarCheck.co.uk page 7/11



Owner history

| For how long did the current and previous owner(s) have this BMW? How many owners di Check it in the premium report and see all owner registrations. Download the full report <u>k</u> | |
|---|-------------|
| | |
| ************************************** | |
| | |
| *************************************** | |
| ********* | |
| *************************************** | |
| *************************************** | |
| | More info > |
| Plate changes | |
| See in this check if this BMW had different number plates. | |
| Number of plates | , |
| Current registration | UK UK |
| Plate since | |
| Current registration | NIE UK |
| Plate since | |
| | More info > |

CarCheck.co.uk page 8/11



Finance check

Check if this BMW is financed, has an outstanding loan or finance agreement. If you are purchasing a vehicle it is smart to ensure that any finance that may have been taken out on this BMW has been settled.

If not, and you buy this BMW then you could lose the money and the car you paid for.

Download the premium report <u>here</u> and check if this BMW is financed.

| Finance company | |
|-------------------|--|
| Date of agreement | |
| Agreement type | |
| Agreement term | |
| Agreement number | |
| Control info | |

Contact info

More info >

CarCheck.co.uk page 9/11



Mileage check

| Odometer | In miles |
|----------------------------|------------|
| Mileage registrations | 10 |
| First mileage registration | 2015-03-06 |
| Last registration | 2023-05-16 |
| Complete history | See info |



| Registration #1 | 2015-03-06 | 29 mi |
|---------------------------------|------------|-------------------------------------|
| Registration #2 | 2018-02-19 | 16.101 mi |
| Registration #3 | 2019-02-25 | 22.402 mi |
| Registration #4 | 2020-02-17 | 28.398 mi |
| Registration #5 | 2021-02-15 | 33.876 mi |
| | | |
| Registration #6 | | 71.777 es |
| Registration #6 Registration #7 | | 11,777 es |
| - | | 11,777 ea 11,777 ea |
| Registration #7 | | 11,777 ea 11,777 ea 11,777 ea |

More info >

CarCheck.co.uk page 10/11



Car features

| 50225 | Air conditioning |
|-------|------------------|
| S0295 | |
| S0482 | |
| S0501 | |
| 50566 | |
| S0567 | |
| S0569 | |

Dimensions & weight

| Width | 1800 mm |
|---------------------|---------|
| Height | 1596 mm |
| Length | 4342 mm |
| Wheel base | 2670 mm |
| Kerb weight | 1410 kg |
| Max. allowed weight | 1910 kg |

Additional information

| Fuel tank capacity | 51 I |
|--------------------|------------------|
| Fuel delivery | Direct Injection |
| Number of doors | 5 |
| Number of seats | 5 |
| Number of axles | 2 |
| Engine number | F7641068 |

CarCheck.co.uk page 11/11