





report date: 2024-03-29

General information

Make	CITROEN
Model	GRAND C4 PICASSO HDI VTR PLUS GRAND PICASSO
Colour	Bronze
Year of manufacture	2010
Top speed	112 mph
0 - 60 mph	12.7 seconds
Gearbox	5 speed Manual

Engine & fuel consumption

Power	107 BHP
Max. torque	240 Nm at 1.750 rpm
Engine capacity	1.560 cc
Cylinders	4
Fuel type	Diesel
Consumption city	40.9 mpg
Consumption extra urban	60.1 mpg
Consumption combined	51.4 mpg
CO2 emission	140 g/km
CO2 label	E



CarCheck.co.uk page 1/14



report date: 2024-03-29

Internet history

Entry 1

Date 2021-09-23

Pictures 14

Listing price <u>View report</u>









source: cargurus.co.uk

CarCheck.co.uk page 2/14



report date: 2024-03-29

B 4	\sim $-$		
10.71	$^{\prime}$	hic	tory
101	C I	1115	I OI V
	•		,

MOT expiry date	2024-10-17
MOT pass rate	73 %
MOT passed	11
Failed MOT tests	4
Total advice items	31
Total items failed	9

MOT #15		2023-10-18 15:47
MOT test	number	217074968413
Result		✓ Passed
Next exp	iry date	2024-10-17
Advice	Nearside Front Anti-roll bar ball joint has slight play (5.3.4 (a) (i))	
Minor	Nearside Front Drive shaft joint constant velocity boot severely deteriorate	d (6.1.7 (g) (i))
Advice	Nearside Rear Tyre worn close to legal limit/worn on edge (5.2.3 (e))	
Advice	Nearside Rear Service brake binding but not excessively (1.2.1 (f))	
Advice	Front Tyre worn close to legal limit/worn on edge both (5.2.3 (e))	
Advice	Rear Brake pad(s) wearing thin both (1.1.13 (a) (ii))	

MOT #14	21	022-05-27 08:42
MOT test	number	123459440057
Result		✓ Passed
Advice	Front Brake disc worn, pitted or scored, but not seriously weakened (1.1.14 (a) (ii))	
Advice	Offside Front Tyre worn close to legal limit/worn on edge 3mm (5.2.3 (e))	
Advice	Front Brake pad(s) wearing thin (1.1.13 (a) (ii))	
Advice	Nearside Front Tyre worn close to legal limit/worn on edge 3mm (5.2.3 (e))	

CarCheck.co.uk page 3/14



report date: 2024-03-29

MOT #13 2022-05-27 08:42 285600975697 **MOT** test number Result × Failed **Advice** Front Brake pad(s) wearing thin (1.1.13 (a) (ii)) Advice Nearside Front Tyre worn close to legal limit/worn on edge 3mm (5.2.3 (e)) **Pass with rectification** Windscreen washer not working (3.5 (a)) Pass with rectification Offside Front Position lamp not working (4.2.1 (a) (ii)) Front Brake disc worn, pitted or scored, but not seriously weakened (1.1.14 (a) (ii)) **Advice** Advice Offside Front Tyre worn close to legal limit/worn on edge 3mm (5.2.3 (e)) **Pass with rectification** Nearside Front Position lamp not working (4.2.1 (a) (ii))

MOT #12		2021-05-19 11:36
MOT test	number	933505075610
Result		✓ Passed
Advice	Front Tyre worn close to legal limit/worn on edge n/s and o/s (5.2.3 (e))	
Advice	Offside Front Nail in tyre	
Advice	Front Brake disc worn, pitted or scored, but not seriously weakened (1.1.14 (a) (i	i))
Advice	Nearside Rear Nail in tyre	

CarCheck.co.uk page 4/14



report date: 2024-03-29

MOT #11 2021-05-19 09:27 **MOT** test number 118716554237 Result × Failed **Advice** Front Tyre worn close to legal limit/worn on edge n/s and o/s (5.2.3 (e)) **Advice** Offside Front Nail in tyre Fail Nearside Front Position lamp not working (4.2.1 (a) (ii)) Front Brake disc worn, pitted or scored, but not seriously weakened (1.1.14 (a) (ii)) Advice **Advice** Nearside Rear Nail in tyre Offside Front Coil spring fractured or broken (5.3.1 (b) (i)) Fail

MOT test number

Result

Advice

Nearside Rear Child Seat fitted not allowing full inspection of adult belt

Advice

Offside Rear Tyre slightly damaged/cracking or perishing (5.2.3 (d) (ii))

Advice

Oil leak, but not excessive (8.4.1 (a) (i))

MOT #9 2020-06-02 11:37 **MOT** test number 738595960846 Result × Failed Fail Front Windscreen washer provides insufficient washer liquid (3.5 (a)) Advice Oil leak, but not excessive (8.4.1 (a) (i)) Fail Offside Rear Stop lamp(s) not working (4.3.1 (a) (ii)) **Advice** Nearside Rear Child Seat fitted not allowing full inspection of adult belt Fail Nearside Rear Shock absorbers has a serious fluid leak (5.3.2 (b)) **Advice** Offside Rear Tyre slightly damaged/cracking or perishing (5.2.3 (d) (ii))

CarCheck.co.uk page 5/14



report date: 2024-03-29

MOT #8	2019-03-28 12:56
MOT test number	385847163191
Result	✓ Passed
MOT #7	2018-03-29 15:16
MOT test number	202995685734
Result	✓ Passed
MOT #6	2017-07-31 15:19
MOT test number	706768219424
Result	✓ Passed
MOT #5	2016-10-15 09:39
MOT test number	961824139078
Result	✓ Passed
MOT #4	2016-10-15 09:05
MOT test number	953024587593
Result	× Failed
Fail Registration plate lamp not working (1.1.C.1d)	

MOT #3	2015-10-16 08:23
MOT test number	452761484993
Result	✓ Passed
Advice Offside Front Tyre worn close to the legal limit (4.1.E.1) Advice Nearside Front Tyre worn close to the legal limit (4.1.E.1)	

CarCheck.co.uk page 6/14



report date: 2024-03-29

MOT #2

MOT test number

618131094263

Result

Very Passed

Under-trays fitted obscuring some underside components

 MOT #1
 2013-10-21 15:50

 MOT test number
 697824793289

 Result
 ✓ Passed

CarCheck.co.uk page 7/14



report date: 2024-03-29

Tax & MOT check



Tax status	Valid until 1 May
Days left	3
MOT expiry date	17 October 2024
Full MOT history	See MOT history

Tax calculation

Vehicle class	49
Band	Е
Single payment (12 months)	£ 180,00,-
Single six month payment	£ 99,00,-
Total payable by 12 monthly instalments	£ 189,00,-

CarCheck.co.uk page 8/14



report date: 2024-03-29

Damage history

Check the damage history for this CITROEN. See if, where and when this CITROEN had damage and the car repair costs. We also check if this CITROEN was scrapped. Download the premium report here for the results.

Damage 1
Date
Category
Type
Damage 2
Date
Category
Type



Extra CITROEN salvage check



If this vehicle was seen at a salvage auction we offer: vehicle pictures, salvage location, retail value. Download the premium report <u>here</u> for more information.

More info >

CarCheck.co.uk page 9/14



report date: 2024-03-29

Vehicle valuation

What is this car worth? See the vehicle value of this CITROEN in the premium report. We check: purchase value, age, mileage, MOT history, damages and online sale prices.

Trade retail value

Auction value

Average private trade value

More info >

CarCheck.co.uk page 10/14



report date: 2024-03-29

Owner history

For how long did the current and previous owner(s) have this CITROEN? How many owner have? Check it in the premium report and see all owner registrations. Download the full is	

	More info >
Plate changes	
See in this check if this CITROEN had different number plates.	
Number of plates	,
Current registration	UK SIR
Plate since	
Current registration	UK SIP
Plate since	
	More info >

CarCheck.co.uk page 11/14



report date: 2024-03-29

Finance check

Check if this CITROEN is financed, has an outstanding loan or finance agreement. If you are purchasing a vehicle it is smart to ensure that any finance that may have been taken out on this CITROEN has been settled.

If not, and you buy this CITROEN then you could lose the money and the car you paid for.

Download the premium report <u>here</u> and check if this CITROEN is financed.

Finance company

Date of agreement

Agreement type

Agreement term

Agreement number

Contact info

More info >

CarCheck.co.uk page 12/14



report date: 2024-03-29

Mileage check

Odometer	In miles
Mileage registrations	17
First mileage registration	2010-11-23
Last registration	2023-10-18
Complete history	See info



Registration #1	2010-11-23	14 mi
Registration #2	2013-10-21	19.535 mi
Registration #3	2014-10-18	30.712 mi
Registration #4	2015-10-16	52.981 mi
Registration #5	2016-10-15	72.083 mi
Registration #6	2016-10-15	72.083 mi
Registration #7	2017-07-31	82.287 mi
Registration #8	2018-03-29	88.517 mi
Registration #9	2019-03-28	91.754 mi
Registration #10		11.777 au
Registration #10 Registration #11		11.777 es
_		11.777 es
Registration #11		11.777 es 11.777 es 11.777 es
Registration #11 Registration #12		11.777 es 11.777 es 11.777 es
Registration #11 Registration #12 Registration #13		11.777 es 11.777 es 11.777 es 11.777 es
Registration #11 Registration #12 Registration #13 Registration #14		11.777 es 11.777 es 11.777 es 11.777 es 11.777 es

More info >

CarCheck.co.uk page 13/14



ML60VDD report date: 2024-03-29

Safety ratings

NCAP rating	****
Adult	87%
Children	78%
Pedestrian	46%
Safety systems	89%
Overall rating	77%
Video	see crash video



Dimensions & weight

Width	2100 mm
Height	1710 mm
Length	4590 mm
Wheel base	2728 mm
Kerb weight	1530 kg
Max. allowed weight	2250 kg

Additional information

Fuel tank capacity	60 I
Fuel delivery	Direct Injection
Number of doors	5
Number of seats	7
Number of axles	2
Engine number	JBCV0086665

CarCheck.co.uk page 14/14