



report date: 2024-03-29

General information

Make	KIA
Model	SORENTO CRDI KX-1 ISG
Colour	Grey
Year of manufacture	2015
Top speed	124 mph
0 - 60 mph	9.0 seconds
Gearbox	6 speed Manual

Engine & fuel consumption

Power	197 BHP
Max. torque	441 Nm at 1.750 rpm
Engine capacity	2.199 cc
Cylinders	4
Fuel type	Diesel
Consumption city	40.9 mpg
Consumption extra urban	57.7 mpg
Consumption combined	49.6 mpg
CO2 emission	149 g/km
CO2 label	F






Internet history

Entry 3

Date 2024-03-27

Pictures 13

Listing price [View report](#)



source: cargurus.co.uk

Entry 2

Date 2021-06-07

Pictures 19

Listing price [View report](#)



source: yesauto.com

Entry 1

Date 2021-05-28

Pictures 10

Listing price [View report](#)



source: autoonline.co.uk



MOT history

MOT expiry date	2025-03-20
MOT pass rate	78 %
MOT passed	7
Failed MOT tests	2
Total advice items	27
Total items failed	3

MOT #9	2024-03-21 14:37
MOT test number	601956629244
Result	✓ Passed
Next expiry date	2025-03-20

MOT #8	2024-03-20 12:02
MOT test number	183492150447
Result	✗ Failed
Fail	Rear Brake disc in such a condition that it is seriously weakened (1.1.14 (a) (ii))
Fail	Front Brake disc in such a condition that it is seriously weakened (1.1.14 (a) (ii))



MOT #7

2023-05-24 15:39

MOT test number

770996548319

Result

✓ Passed

- Advice

Nearside Front Suspension arm ball joint has slight play (5.3.4 (a) (i))
- Advice

Offside Rear Brake disc worn, pitted or scored, but not seriously weakened (1.1.14 (a) (ii))
- Advice

Offside Front Brake disc worn, pitted or scored, but not seriously weakened (1.1.14 (a) (ii))
- Advice

Nearside Rear Suspension arm pin or bush worn but not resulting in excessive movement trail arm bush (5.3.4 (a) (i))
- Advice

Offside Rear tyre inner edge feathered
- Advice

Nearside Rear Brake disc worn, pitted or scored, but not seriously weakened (1.1.14 (a) (ii))
- Advice

Offside Front Suspension arm ball joint has slight play (5.3.4 (a) (i))
- Advice

Nearside Front Brake disc worn, pitted or scored, but not seriously weakened (1.1.14 (a) (ii))
- Advice

Nearside Rear Nail in tyre inner edge feathered

**MOT #6**

2023-05-23 10:35

MOT test number

944612031372

Result**✗ Failed**

- Advice** Offside Front Brake disc worn, pitted or scored, but not seriously weakened (1.1.14 (a) (ii))
- Advice** Nearside Rear Nail in tyre inner edge feathered
- Fail** Offside Rear Suspension arm pin or bush excessively worn trail arm bush (5.3.4 (a) (i))
- Advice** Nearside Rear Brake disc worn, pitted or scored, but not seriously weakened (1.1.14 (a) (ii))
- Advice** Nearside Front Suspension arm ball joint has slight play (5.3.4 (a) (i))
- Advice** Nearside Front Brake disc worn, pitted or scored, but not seriously weakened (1.1.14 (a) (ii))
- Advice** Nearside Rear Suspension arm pin or bush worn but not resulting in excessive movement trail arm bush (5.3.4 (a) (i))
- Advice** Offside Rear Brake disc worn, pitted or scored, but not seriously weakened (1.1.14 (a) (ii))
- Advice** Offside Front Suspension arm ball joint has slight play (5.3.4 (a) (i))
- Advice** Offside Rear tyre inner edge feathered

MOT #5

2022-06-09 09:20

MOT test number

772710754734

Result**✓ Passed**

- Advice** Nearside Rear Suspension arm pin or bush worn but not resulting in excessive movement (5.3.4 (a) (i))
- Advice** Offside Front Suspension arm ball joint has slight play (5.3.4 (a) (i))
- Advice** Offside Rear Suspension arm pin or bush worn but not resulting in excessive movement (5.3.4 (a) (i))
- Advice** Nearside Front Suspension arm ball joint has slight play (5.3.4 (a) (i))

MOT #4

2021-06-08 15:44

MOT test number

106496830841

Result**✓ Passed**



MOT #3	2020-09-12 09:51
MOT test number	218110183579
Result	✓ Passed

MOT #2	2019-09-04 12:29
MOT test number	822410296514
Result	✓ Passed
Minor	Offside Windscreen wiper blade defective worn (3.4 (b) (i))
Advice	Rear seats cannot be inspected boot full or seat belts

MOT #1	2018-09-17 11:37
MOT test number	487153130444
Result	✓ Passed
Advice	Nearside Rear Nail in tyre Not repairable
Advice	Offside Rear Nail in tyre
Advice	Unable to fully inspect rear seat belts



Tax & MOT check

✓
Taxed
Tax due:
1 October 2024

✓
MOT
Expires:
20 March 2025

Tax status	Valid until 1 October
Days left	155
MOT expiry date	20 March 2025
Full MOT history	See MOT history

Tax calculation

Vehicle class	49
Band	F
Single payment (12 months)	£ 200,00,-
Single six month payment	£ 110,00,-
Total payable by 12 monthly instalments	£ 210,00,-



Damage history

Check the damage history for this KIA. See if, where and when this KIA had damage and the car repair costs. We also check if this KIA was scrapped. Download the premium report [here](#) for the results.

Damage 1

Date	
Category	
Type	

Damage 2

Date	
Category	
Type	



Extra KIA salvage check



If this vehicle was seen at a salvage auction we offer: vehicle pictures, salvage location, retail value. Download the premium report [here](#) for more information.

More info >



Vehicle valuation

What is this car worth? See the vehicle value of this KIA in the premium report. We check: purchase value, age, mileage, MOT history, damages and online sale prices.

Trade retail value	£ 19,999
Auction value	£ 19,999
Average private trade value	£ 19,999

More info >



Owner history

For how long did the current and previous owner(s) have this KIA? How many owners did this KIA have? Check it in the premium report and see all owner registrations. Download the full report [here](#).

Owner	From	To
Owner	From	To
Owner	From	To
Owner	From	To
Owner	From	To
Owner	From	To
Owner	From	To

More info >

Plate changes

See in this check if this KIA had different number plates.

Number of plates	1
Current registration	FG65WWE
Plate since	2019-03-29
Current registration	FG65WWE
Plate since	2019-03-29

More info >



Finance check

Check if this KIA is financed, has an outstanding loan or finance agreement. If you are purchasing a vehicle it is smart to ensure that any finance that may have been taken out on this KIA has been settled.

If not, and you buy this KIA then you could lose the money and the car you paid for.

Download the premium report [here](#) and check if this KIA is financed.

Finance company	XXXXXXXX XX
Date of agreement	XXXXXXXX XX
Agreement type	XXXXXXXX XX
Agreement term	XXXXXXXX XX
Agreement number	XXXXXXXX XX
Contact info	XXXXXXXX XX

More info >



Mileage check

Odometer	In miles
Mileage registrations	13
First mileage registration	2015-09-30
Last registration	2024-03-21
Complete history	See info



Registration #1	2015-09-30	20 mi
Registration #2	2018-09-17	37.063 mi
Registration #3	2019-09-04	41.929 mi
Registration #4	2020-09-12	45.944 mi
Registration #5	2021-06-08	48.183 mi
Registration #6		
Registration #7		
Registration #8		
Registration #9		
Registration #10		
Registration #11		
Registration #12		
Registration #13		

More info >



Car features

The KIA factory car options list is only available in the premium report.

S0225	Air conditioning
S0295	
S0482	
S0501	
S0566	
S0567	
S0569	

View the complete KIA factory list for this vehicle [here](#).

More info >

Safety ratings

NCAP rating	★★★★★
Adult	90%
Children	83%
Pedestrian	67%
Safety systems	71%
Overall rating	80%
Video	see crash video



Dimensions & weight

Width	1890 mm
Height	1685 mm
Length	4780 mm
Wheel base	2780 mm
Kerb weight	1932 kg
Max. allowed weight	2590 kg

Additional information

Fuel tank capacity	71 l
Fuel delivery	Direct Injection
Number of doors	5
Number of seats	7

Number of axles	2
Engine number	D4HBFH215470