





report date: 2024-03-29

General information

Make	TOYOTA
Model	PRIUS VVT-I T SPIRIT
Colour	Blue
Year of manufacture	2011
Top speed	112 mph
Gearbox	1 speed CVT

Engine & fuel consumption

Power	135 BHP
Max. torque	350 Nm at 4.000 rpm
Engine capacity	1.797 cc
Cylinders	4
Fuel type	Hybrid / Electric
Consumption city	70.6 mpg
Consumption extra urban	74.3 mpg
Consumption combined	70.6 mpg
CO2 emission	92 g/km
CO2 label	A



CarCheck.co.uk page 1/13



Internet history

Entry 1

Date	2021-02-05
Pictures	1
Listing price	View report



source: autoonline.co.uk

CarCheck.co.uk page 2/13



MOT history

MOT expiry date	2025-04-10
MOT pass rate	80 %
MOT passed	12
Failed MOT tests	3
Total advice items	13
Total items failed	12

MOT #15		2024-04-11 15:47
MOT test	number	478373436368
Result		✓ Passed
Next expi	ry date	2025-04-10
Advice	Offside Front Anti-roll bar linkage ball joint has slight play (5.3.4 (a) (i))	
Advice	Nearside Front Tyre worn close to legal limit/worn on edge (5.2.3 (e))	
Advice (i))	Offside Front Suspension arm pin or bush worn but not resulting in excessi	ive movement (5.3.4 (a)
Advice	Oil leak, but not excessive (8.4.1 (a) (i))	
Advice	Nearside Front Anti-roll bar linkage ball joint has slight play (5.3.4 (a) (i))	
Advice (a) (i))	Nearside Front Suspension arm pin or bush worn but not resulting in excess	ssive movement (5.3.4
Advice	Offside Front Inner Tyre worn close to legal limit/worn on edge (5.2.3 (e))	
Advice	Offside Front Suspension arm ball joint has slight play (5.3.4 (a) (i))	

MOT #14	2023-02-27 17:37
MOT test number	700682053795
Result	✓ Passed

CarCheck.co.uk page 3/13



report date: 2024-03-29

MOT #13 2023-02-23 13:14 **MOT** test number 235649177903 Result × Failed Fail Offside Headlamp not working on main beam (4.1.1 (a) (ii)) Fail Offside Front Position lamp not working (4.2.1 (a) (ii)) Nearside Front Tyre tread depth below requirements of 1.6mm (5.2.3 (e)) Fail Nearside Front Lower Suspension arm pin or bush excessively worn rear (5.3.4 (a) (i)) Fail Nearside Registration plate lamp inoperative in the case of a single lamp or all lamps (4.7.1 (b) (ii)) Fail Fail Nearside Front Position lamp not working (4.2.1 (a) (ii)) Offside Front Tyre tread depth below requirements of 1.6mm (5.2.3 (e)) Fail Fail Offside Front Lower Suspension arm pin or bush excessively worn rear (5.3.4 (a) (i))

MOT #12

MOT test number

Result

Advice Offside Front Tyre worn close to legal limit/worn on edge edges worn (5.2.3 (e))

MOT #11 2022-03-14 14:10
MOT test number 823324253934
Result Passed

MOT #10

MOT test number

Result

Advice Nearside Rear Service brake binding but not excessively (1.2.1 (f))

CarCheck.co.uk page 4/13



report date: 2024-03-29

MOT #9

MOT test number

467055016352

Result

Advice Nearside Rear Service brake binding but not excessively (1.2.1 (f))

Pass with rectification Offside Front Headlamp aim too high (4.1.2 (a))

MOT #8 2020-11-12 12:05 **MOT** test number 600416165281 Result ✓ Passed **MOT #7** 2019-10-04 08:49 **MOT test number** 443189553819 Result Passed **MOT #6** 2018-10-12 10:26 **MOT** test number 194357199163 Result Passed **MOT #5** 2018-10-12 10:26 **MOT** test number 329737645376 Result

Result

Pass with rectification

Front Windscreen wiper does not clear the windscreen effectively (3.4 (b) (ii))

Pass with rectification

Rear Brake pad(s) less than 1.5 mm thick (1.1.13 (a) (ii))

Pass with rectification

Front Headlamp aim too high (4.1.2 (a))

MOT #4

MOT test number

982633669543

Result

✓ Passed

CarCheck.co.uk page 5/13



MOT test number

PK11UWF

report date: 2024-03-29

989539794119

✓ Passed

MOT #3	2016-07-01 09:53
MOT test number	104699624131
Result	✓ Passed
MOT #2	2015-07-27 17:21
MOT test number	795688205208
Result	✓ Passed
MOT #1	2014-07-18 13:38

Result

Notice Small cut nearside front outer tyre wall

Advice Offside Front Seat belt damaged but webbing not significantly weakened (5.2.2a)

CarCheck.co.uk page 6/13



Tax & MOT check



Tax status	Valid until 1 April
Days left	337
MOT expiry date	10 April 2025
Full MOT history	See MOT history

Tax calculation

Vehicle class	59
Band	A
Single payment (12 months)	£ 0,00,-
Single six month payment	Not applicable
Total payable by 12 monthly instalments	Not applicable

CarCheck.co.uk page 7/13



report date: 2024-03-29

Damage history

Check the damage history for this TOYOTA. See if, where and when this TOYOTA had damage and the car repair costs. We also check if this TOYOTA was scrapped. Download the premium report here for the results.

Damage 1
Date
Category
Type
Damage 2
Date
Category
Type



Extra TOYOTA salvage check



If this vehicle was seen at a salvage auction we offer: vehicle pictures, salvage location, retail value. Download the premium report <u>here</u> for more information.

More info >

CarCheck.co.uk page 8/13



Vehicle valuation

What is this car worth? See the vehicle value of this TOYOTA in the premium report. We check: purchase value, age, mileage, MOT history, damages and online sale prices.

Trade retail value

Auction value

Average private trade value

More info >

CarCheck.co.uk page 9/13



Owner history

PK11UWF

report date: 2024-03-29

For how long did the current and previous owner(s) have this TOYOTA? How many owners did this TOYOTA have? Check it in the premium report and see all owner registrations. Download the full report here.

More info >

Plate changes

factor scincol

See in this check if this TOYOTA had different number plates.

More info >



Finance check

Check if this TOYOTA is financed, has an outstanding loan or finance agreement. If you are purchasing a vehicle it is smart to ensure that any finance that may have been taken out on this TOYOTA has been settled.

If not, and you buy this TOYOTA then you could lose the money and the car you paid for.

Download the premium report <u>here</u> and check if this TOYOTA is financed.

Finance company	
Date of agreement	
Agreement type	
Agreement term	
Agreement number	
Contact info	

Contact info

More info >

CarCheck.co.uk page 11/13



report date: 2024-03-29

Mileage check

Odometer	In miles
Mileage registrations	17
First mileage registration	2011-07-31
Last registration	2024-04-11
Complete history	See info



Registration #1	2011-07-31	13 mi
Registration #2	2014-07-18	8.070 mi
Registration #3	2015-07-27	9.721 mi
Registration #4	2016-07-01	29.013 mi
Registration #5	2017-07-31	57.938 mi
Registration #6	2018-10-12	87.090 mi
Registration #7	2018-10-12	87.090 mi
Registration #8	2019-10-04	108.019 mi
Registration #9	2020-11-12	113.043 mi
Registration #10		71.777 es
Registration #11		11.777 es
Registration #12		71.777 es
Registration #13		11.777 es
Registration #14		11.777 es
Registration #15		11.777 es
Registration #16		11.777 es
Registration #17		11.177 es

More info >

CarCheck.co.uk page 12/13



report date: 2024-03-29

Car features

S0225	Air conditioning
S0295	
50482	
50501	
50566	
50567	
50569	

Safety ratings

NCAP rating	****
Adult	88%
Children	82%
Pedestrian	68%
Safety systems	86%
Overall rating	83%
Video	see crash video



Dimensions & weight

Width	1745 mm
Height	1490 mm
Length	4460 mm
Wheel base	2700 mm
Kerb weight	1420 kg
Max. allowed weight	1805 kg

Additional information

Fuel tank capacity	45 I
Fuel delivery	Multi-Point Injection
Number of doors	5
Number of seats CarCheck.co.uk	5 page 13/13

Number of axles 2

Engine number 2ZR5054497