





report date: 2024-03-28

General information

Make	FIAT
Model	500 C LOUNGE DUALOGIC
Colour	Blue
Year of manufacture	2009
Top speed	113 mph
Gearbox	5 speed automatic

Engine & fuel consumption

Power	99 BHP
Max. torque	131 Nm at 4.250 rpm
Engine capacity	1.368 сс
Cylinders	4
Fuel type	Petrol
Consumption city	38.7 mpg
Consumption extra urban	54.3 mpg
Consumption combined	47.1 mpg
CO2 emission	135 g/km
CO2 label	E



CarCheck.co.uk page 1/13



report date: 2024-03-28

Internet history

Entry 2

Date 2023-06-27

Pictures 3

Listing price <u>View report</u>








source: cargurus.co.uk

Entry 1

Date	2021-07-29
Pictures	14

Listing price <u>View report</u>









source: autotrader.co.uk

CarCheck.co.uk page 2/13



report date: 2024-03-28

MOT history

MOT expiry date	2025-03-25
MOT pass rate	80 %
MOT passed	12
Failed MOT tests	3
Total advice items	19
Total items failed	5

MOT #15	2024-03-19 14:33
MOT test number	379527585528
Result	✓ Passed
Next expiry date	2025-03-25
Advice Offside Front Shock absorbers has	light misting of oil (5.3.2 (b))
Advice Nearside Front Tyre slightly damage	ged (5.2.3 (d) (ii))
Advice Nearside Front Shock absorbers ha	as light misting of oil (5.3.2 (b))

MOT #14		2023-03-21 12:31
MOT test	number	741596207173
Result		✓ Passed
Advice	Nearside Front tyre worn on edge	
Advice	Offside Front tyre sidewall condition	
Advice	Slight leak from both front struts	

MOT #13	2022-03-25 11:36
MOT test number	852743351480
Result	✓ Passed

CarCheck.co.uk page 3/13



report date: 2024-03-28

MOT #12 2021-03-26 16:04

MOT test number 713241540003

MOT #11 2021-03-20 13:23

MOT test number 897029728811

Result X Failed

Fail Nearside Front Suspension arm pin or bush excessively worn (5.3.4 (a) (i))

Fail Central Upper Stop lamp(s) with a multiple light source more than 1/2 not functioning (4.3.1 (a) (ii))

MOT #10 2020-03-10 16:30

MOT test number 969162612435

Result \rightarrow Passed

Minor Central Stop lamp(s) light intensity obviously reduced (4.3.3 (a) (i))

MOT #9 2019-03-12 13:29

MOT test number 229653018295

Result

Passed

MOT #8 2019-03-12 13:29

MOT test number 536512272137

Result × Failed

 Pass with rectification
 Nearside Stop lamp(s) not working (4.3.1 (a) (ii))

CarCheck.co.uk page 4/13



report date: 2024-03-28

MOT test number

Result

Advice Offside Front Shock absorber has a light misting of oil (2.7.3)

Advice Rear exhaust silencer outer skin corroded

Advice Both front tyres outer wall damage/Bridgestone/195/45R16/84V/

MOT #6 2017-10-06 12:10 **MOT** test number 903486120739 Result × Failed Rear exhaust silencer outer skin corroded **Advice** Advice Offside Front Shock absorber has a light misting of oil (2.7.3) Pass with rectification Offside Windscreen wiper does not clear the windscreen effectively (8.2.2) **Advice** Both front tyres outer wall damage/Bridgestone/195/45R16/84V/ Pass with rectification Nearside Windscreen wiper does not clear the windscreen effectively (8.2.2)

MOT test number

Result

Advice
Back box corroded

Advice
Front Slight surface corrosion on springs

Advice
Front Slight outer sidewall damage to both tyres. No cords showing

Rear Slight surface corrosion on springs

MOT #4	2015-10-09 09:18
MOT test number	315268694527
Result	✓ Passed

CarCheck.co.uk page 5/13



report date: 2024-03-28

MOT #3	2014-09-23 11:02
MOT test number	436776664249
Result	✓ Passed
MOT #2	2013-11-01 14:17
MOT test number	349805503399
Result	✓ Passed
MOT #1	2012-11-05 13:04
MOT test number	525640612337
Result	✓ Passed
Notice Nail in offside rear tyre	
Notice Both front tyres have some curb damage on outer walls	

CarCheck.co.uk page 6/13





report date: 2024-03-28

Tax & MOT check



Tax status	Valid until 1 July
Days left	63
MOT expiry date	25 March 2025
Full MOT history	See MOT history

Tax calculation

Vehicle class	48
Band	Е
Single payment (12 months)	£ 180,00,-
Single six month payment	£ 99,00,-
Total payable by 12 monthly instalments	£ 189,00,-

CarCheck.co.uk page 7/13



report date: 2024-03-28

Damage history

Check the damage history for this FIAT. See if, where and when this FIAT had damage and the car repair costs. We also check if this FIAT was scrapped. Download the premium report <u>here</u> for the results.

Damage 1
Date
Category
Type
Damage 2
Date
Category
Type



Extra FIAT salvage check



If this vehicle was seen at a salvage auction we offer: vehicle pictures, salvage location, retail value. Download the premium report <u>here</u> for more information.

More info >

CarCheck.co.uk page 8/13



report date: 2024-03-28

Vehicle valuation

What is this car worth? See the vehicle value of this FIAT in the premium report. We check: purchase value, age, mileage, MOT history, damages and online sale prices.

Trade retail value

Auction value

Average private trade value

More info >

CarCheck.co.uk page 9/13



report date: 2024-03-28

Owner history

For how long did the current and previous owner(s) have this FIAT? How many owners did Check it in the premium report and see all owner registrations. Download the full report \(\frac{1}{2} \)	

	More info >
Plate changes	
See in this check if this FIAT had different number plates.	
Number of plates	,
Current registration	NK SIE
Plate since	
Current registration	器 UK
Plate since	
	More info >

CarCheck.co.uk page 10/13



report date: 2024-03-28

Finance check

Check if this FIAT is financed, has an outstanding loan or finance agreement. If you are purchasing a vehicle it is smart to ensure that any finance that may have been taken out on this FIAT has been settled.

If not, and you buy this FIAT then you could lose the money and the car you paid for.

Download the premium report <u>here</u> and check if this FIAT is financed.

Finance company	
Date of agreement	
Agreement type	
Agreement term	
Agreement number	
0111.5	

Contact info

More info >


CarCheck.co.uk page 11/13



ML59UFA report date: 2024-03-28

Mileage check

Odometer	In miles
Mileage registrations	18
First mileage registration	2009-11-04
Last registration	2024-03-19
Complete history	See info



Registration #1	2009-11-04	12 mi
Registration #2	2012-11-05	6.069 mi
Registration #3	2013-11-01	7.617 mi
Registration #4	2014-09-23	8.895 mi
Registration #5	2015-10-09	10.462 mi
Registration #6	2016-10-11	12.210 mi
Registration #7	2017-10-06	14.070 mi
Registration #8	2017-10-06	14.070 mi
Registration #9	2019-03-12	15.612 mi
Registration #10		71.777 es
Registration #11		71.777 es
Registration #12		11.777 es
Registration #13		11.777 es
Registration #14		11.777 es
Registration #15		11.777 es
Registration #16		11.777 es
Registration #17		11.777 es
Registration #18		71.777 es

More info >

CarCheck.co.uk page 12/13



report date: 2024-03-28

Car features

S0225	Air conditioning
S0295	
50482	
S0501	
S0566	
S0567	
S0569	

Safety ratings

NCAP rating	****
Video	see crash video



Dimensions & weight

Width	1627 mm
Height	1488 mm
Length	3546 mm
Wheel base	2300 mm
Kerb weight	930 kg
Max. allowed weight	1380 kg

Additional information

Fuel tank capacity	35 I
Fuel delivery	Multi-Point Injection
Number of doors	3
Number of seats CarCheck.co.uk	4 page 13/13

Number of axles 2

Engine number 1454605