





report date: 2024-03-28

General information

Make	VOLKSWAGEN
Model	POLO SEL TDI
Colour	Silver
Year of manufacture	2010
Top speed	112 mph
0 - 60 mph	11.5 seconds
Gearbox	5 speed Manual

Engine & fuel consumption

Power	89 BHP
Max. torque	195 Nm at 1.500 rpm
Engine capacity	1.595 cc
Cylinders	4
Fuel type	Diesel
Consumption city	54.3 mpg
Consumption extra urban	76.3 mpg
Consumption combined	65.7 mpg
CO2 emission	112 g/km
CO2 label	С



CarCheck.co.uk page 1/12



report date: 2024-03-28

Internet history

Entry 1

Date 2021-02-22


Pictures 26

Listing price <u>View report</u>









source: yesauto.com

CarCheck.co.uk page 2/12



report date: 2024-03-28

	~-				
10/1/	TC	h		-	r\ /
1011		ш	51	LUI	l V
	•			-	. ,

MOT expiry date	2024-05-16
MOT pass rate	85 %
MOT passed	11
Failed MOT tests	2
Total advice items	11
Total items failed	5

MOT #13		2023-05-09 10:20
MOT test	number	396598967734
Result		✓ Passed
Next exp	iry date	2024-05-16
Minor	Offside Front Anti-roll bar linkage ball joint dust cover severely deteriorat	red (5.3.4 (b) (i))
Advice	Offside Front Tyre worn close to legal limit/worn on edge (5.2.3 (e))	
Minor	Nearside Front Anti-roll bar linkage ball joint dust cover severely deterior	ated (5.3.4 (b) (i))
Advice	Nearside Front Tyre worn close to legal limit/worn on edge (5.2.3 (e))	
Minor (b) (i))	Nearside Registration plate lamp inoperative in the case of multiple lamp	os or light sources (4.7.1

MOT #12	2022-05-17 09:40
MOT test number	198434419434
Result	✓ Passed

MOT #11	2021-04-01 12:59
MOT test number	769195899072
Result	✓ Passed

CarCheck.co.uk page 3/12



report date: 2024-03-28

MOT #10 2021-03-30 11:00 **MOT** test number 530547376149 Result × Failed Fail Offside Front Tyre tread depth below requirements of 1.6mm (5.2.3 (e)) Fail Nearside Front Headlamp aim projected beam image is obviously incorrect (4.1.2 (c)) Offside Rear Parking brake lever has excessive movement indicating incorrect adjustment (1.1.6 (c)) Fail Nearside Front Tyre tread depth below requirements of 1.6mm (5.2.3 (e)) Fail TPMS illuminated **Advice Advice** Offside Front Inner Drag link end ball joint has slight play (2.1.3 (b) (i))

MOT #9

MOT test number

Result

Advice Engine under tray fitted

Advice Offside Rear Child Seat fitted not allowing full inspection of adult belt

MOT test number

Result

Advice Offside Rear Child Seat fitted not allowing full inspection of adult belt

Engine under tray fitted

Pass with rectification position lamps (4.7.2 (a))

Result X Failed

 MOT #7
 2019-02-26 10:30

 MOT test number
 336846914910

 Result
 ✓ Passed

CarCheck.co.uk page 4/12



report date: 2024-03-28

MOT #6	2018-03-07 10:50
MOT test number	631977441309
Result	√ Passed
MOT #5	2017-03-07 11:39
MOT test number	706855273346
Result	✓ Passed
MOT #4	2016-02-26 15:16
MOT test number	677051332976
Result	✓ Passed
MOT #3	2015-03-12 17:16
MOT test number	505501675020
Result	✓ Passed
MOT #2	2014-03-14 14:39
MOT test number	876003374057
Result	✓ Passed
MOT #1	2013-03-11 12:37
MOT #1 MOT test number	2013-03-11 12:37 525710073060

CarCheck.co.uk page 5/12



report date: 2024-03-28

Tax & MOT check



Tax status	Valid until 1 May
Days left	368
MOT expiry date	16 May 2024
Full MOT history	See MOT history

Tax calculation

Vehicle class	49
Band	С
Single payment (12 months)	£ 35,00,-
Single six month payment	Not applicable
Total payable by 12 monthly instalments	£ 36,75,-

CarCheck.co.uk page 6/12




report date: 2024-03-28

Damage history

Check the damage history for this VOLKSWAGEN. See if, where and when this VOLKSWAGEN had damage and the car repair costs. We also check if this VOLKSWAGEN was scrapped. Download the premium report here for the results.

Damage 1

Date	
Category	
Туре	
Damage 2	
Date	
Category	



Extra VOLKSWAGEN salvage check



Type

If this vehicle was seen at a salvage auction we offer: vehicle pictures, salvage location, retail value. Download the premium report <u>here</u> for more information.

More info >

CarCheck.co.uk page 7/12



report date: 2024-03-28

Vehicle valuation

What is this car worth? See the vehicle value of this VOLKSWAGEN in the premium report. We check: purchase value, age, mileage, MOT history, damages and online sale prices.

Trade retail value

Auction value

Average private trade value

More info >

CarCheck.co.uk page 8/12



report date: 2024-03-28

More info >

Owner history

, <u> </u>	
For how long did the current and previous owner(s) have this VOLKSWAGEN? How many VOLKSWAGEN have? Check it in the premium report and see all owner registrations. Dow here.	

	More info >
Plate changes	
See in this check if this VOLKSWAGEN had different number plates.	
Number of plates	,
Current registration	AIS UK
Plate since	
Current registration	IK SIE
Flate since	

CarCheck.co.uk page 9/12



report date: 2024-03-28

Finance check

Check if this VOLKSWAGEN is financed, has an outstanding loan or finance agreement. If you are purchasing a vehicle it is smart to ensure that any finance that may have been taken out on this VOLKSWAGEN has been settled.

If not, and you buy this VOLKSWAGEN then you could lose the money and the car you paid for.

Download the premium report <u>here</u> and check if this VOLKSWAGEN is financed.

Finance company

Date of agreement

Agreement type

Agreement term

Agreement number

Contact info

More info >

CarCheck.co.uk page 10/12



RO10ECZ report date: 2024-03-28

Mileage check

Odometer	In miles
Mileage registrations	15
First mileage registration	2010-03-17
Last registration	2023-05-09
Complete history	See info



Registration #1	2010-03-17	14 mi
Registration #2	2013-03-11	18.431 mi
Registration #3	2014-03-14	26.858 mi
Registration #4	2015-03-12	32.930 mi
Registration #5	2016-02-26	39.832 mi
Registration #6	2017-03-07	48.541 mi
Registration #7	2018-03-07	55.106 mi
Registration #8	2019-02-26	65.323 mi
Registration #9		9.777 es
Registration #10		11.777 es
Registration #11		91.777 esi
Registration #12		11.777 es
Registration #13		91.777 esi
Registration #14		11.777 es
Registration #15		11,117 es

More info >

CarCheck.co.uk page 11/12



report date: 2024-03-28

Car features

S0225	Air conditioning
S0295	
S0482	
S0501	
S0566	
S0567	
S0569	

Safety ratings

NCAP rating	****
Adult	90%
Children	86%
Pedestrian	41%
Safety systems	71%
Overall rating	78%
Video	see crash video



Dimensions & weight

Width	1682 mm
Height	1462 mm
Length	3970 mm
Wheel base	2470 mm
Max. allowed weight	1650 kg

Additional information

Fuel tank capacity	45 I
Fuel delivery	Direct Injection
Number of doors	5
Number of seats	5

CarCheck.co.uk page 12/12

Number of axles	2

CAY 041769

Engine number