





report date: 2024-03-28

General information

Make	VOLKSWAGEN
Model	TOURAN TDI SE 5STR
Colour	Blue
Year of manufacture	2009
Top speed	110 mph
0 - 60 mph	13.5 seconds
Gearbox	6 speed Manual

Engine & fuel consumption

Power	103 BHP
Max. torque	250 Nm at 1.900 rpm
Engine capacity	1.896 сс
Cylinders	4
Fuel type	Diesel
Consumption city	37.7 mpg
Consumption extra urban	53.3 mpg
Consumption combined	47.1 mpg
CO2 emission	156 g/km
CO2 label	G



CarCheck.co.uk page 1/11




Internet history

Entry 1

Date	2021-09-19
Pictures	2
Listing price	<u>View report</u>





source: autotrader.co.uk

CarCheck.co.uk page 2/11



MOT history

MOT expiry date	2024-03-23
MOT pass rate	86 %
MOT passed	6
Failed MOT tests	1
Total advice items	12
Total items failed	2

MOT #7		2017-02-22 10:02
MOT test	number	507652198421
Result		✓ Passed
Next expi	ry date	2018-03-03
Advice	Nearside Front Suspension arm has slight play in a pin/bush rear bush (2.4.G.	2)
Advice	N\s\r tyre worn on inner edge	
Advice Offside Front Lower Suspension arm ball joint dust cover deteriorated, but preventing the ingress of dirt (2.4.G.2)		
Advice	Nearside Rear Child Seat fitted not allowing full inspection of adult belt	
Advice	Nearside Front Suspension arm has slight play in a ball joint front bush (2.4.G	i.2)
Advice Nearside Front Lower Suspension arm ball joint dust cover deteriorated, but preventing the ingress of dirt (2.4.G.2)		

MOT #6		2016-03-02 17:54
MOT test	number	626798969882
Result		✓ Passed
Advice	Nearside Rear Road wheel with a slightly distorted bead rim (4.2.A.1a)	
Advice	Nearside Rear tyre worn on inner edge	

CarCheck.co.uk page 3/11



Advice

GK09UJR report date: 2024-03-28

MOT test number

Result

Fail Offside Rear Tyre has ply or cords exposed cut in tread (4.1.D.1b)

Advice Nearside Rear tyre worn on inner edge

Fail Nearside Headlamp aim too high (1.8)

Nearside Rear Road wheel with a slightly distorted bead rim (4.2.A.1a)

MOT #4 2015-02-20 09:49 **MOT test number** 249101655063 Result ✓ Passed **MOT #3** 2014-02-11 16:56 415282744098 **MOT** test number Result Passed **Advice** Nearside Rear Tyre worn close to the legal limit (4.1.E.1) **Advice** Offside Rear Tyre worn close to the legal limit (4.1.E.1)

MOT #2	2013-02-12 15:00
MOT test number	575283543086
Result	✓ Passed

MOT #1	2012-02-16 12:25
MOT test number	475847542037
Result	✓ Passed

CarCheck.co.uk page 4/11





Tax & MOT check





Tax status	Valid until 1 September
Days left	126
MOT expiry date	23 March 2024
Full MOT history	See MOT history

Tax calculation

Vehicle class	49
Band	G
Single payment (12 months)	£ 240,00,-
Single six month payment	£ 132,00,-
Total payable by 12 monthly instalments	£ 252,00,-

CarCheck.co.uk page 5/11



Damage history

Check the damage history for this VOLKSWAGEN. See if, where and when this VOLKSWAGEN had damage and the car repair costs. We also check if this VOLKSWAGEN was scrapped. Download the premium report here for the results.

Damage 1

Date


Category

Damage 2

Type

Date

Category
Type



Extra VOLKSWAGEN salvage check



If this vehicle was seen at a salvage auction we offer: vehicle pictures, salvage location, retail value. Download the premium report <u>here</u> for more information.

More info >

CarCheck.co.uk page 6/11



Vehicle valuation

What is this car worth? See the vehicle value of this VOLKSWAGEN in the premium report. We check: purchase value, age, mileage, MOT history, damages and online sale prices.

Trade retail value

Auction value

Average private trade value

More info >

CarCheck.co.uk page 7/11



Owner history	
For how long did the current and previous owner(s) have this VOLKSWAGEN? How many VOLKSWAGEN have? Check it in the premium report and see all owner registrations. Downere.	

	More info >
Plate changes	
See in this check if this VOLKSWAGEN had different number plates.	
Number of plates	,
Current registration	IK SIE
Plate since	
Current registration	NK NEW
Plate since	
	More info >

CarCheck.co.uk page 8/11



Finance check

Check if this VOLKSWAGEN is financed, has an outstanding loan or finance agreement. If you are purchasing a vehicle it is smart to ensure that any finance that may have been taken out on this VOLKSWAGEN has been settled.

If not, and you buy this VOLKSWAGEN then you could lose the money and the car you paid for.

Download the premium report <u>here</u> and check if this VOLKSWAGEN is financed.

Finance company	
Date of agreement	
Agreement type	
Agreement term	
Agreement number	

Contact info

More info >

CarCheck.co.uk page 9/11



Mileage check

Odometer	In miles
Mileage registrations	9
First mileage registration	2009-03-03
Last registration	2017-02-22
Complete history	See info



Registration #1	2009-03-03	13 mi
Registration #2	2012-02-16	19.731 mi
Registration #3	2013-02-12	30.531 mi
Registration #4	2014-02-11	49.821 mi
Registration #5	2015-02-20	71.423 mi
Registration #6		71.777 66
Registration #7		11.777 es
Registration #8		11.777 es
Registration #9		11.777 es

More info >

CarCheck.co.uk page 10/11



Car features

S0225	Air conditioning
S0295	
S0482	
S0501	
S0566	
S0567	
S0569	

Safety ratings

NCAP rating	****
Video	see crash video



Dimensions & weight

Width	2066 mm
Height	1635 mm
Length	4391 mm
Wheel base	2677 mm
Kerb weight	1498 kg
Max. allowed weight	2210 kg

Additional information

Fuel tank capacity	60 I
Fuel delivery	Direct Injection
Number of doors	5
CarChack caluk	nago 11/11

CarCheck.co.uk page 11/11

Number of seats	7
Engine number	BXE 733752