





report date: 2024-03-29

General information

Make	BMW
Model	530 525D SE
Colour	Grey
Year of manufacture	2010
Top speed	147 mph
0 - 60 mph	7.7 seconds
Gearbox	8 speed automatic

Engine & fuel consumption

Power	201 BHP
Max. torque	450 Nm at 1.750 rpm
Engine capacity	2.993 сс
Cylinders	6
Fuel type	Diesel
Consumption city	36.2 mpg
Consumption extra urban	55.4 mpg
Consumption combined	46.3 mpg
CO2 emission	160 g/km
CO2 label	G



CarCheck.co.uk page 1/12



report date: 2024-03-29

Internet history

Entry 2

Date 2023-02-17

Pictures 28

Listing price <u>View report</u>









source: cargurus.co.uk

Entry 1

Date 2022-05-21

Pictures 50

Listing price <u>View report</u>









source: cargurus.co.uk

CarCheck.co.uk page 2/12



report date: 2024-03-29

N/I	α		uc:	t۸	r\/
101	•		115	w	ıv
	•	Γh			. ,

MOT expiry date	2025-01-03
MOT pass rate	73 %
MOT passed	11
Failed MOT tests	4
Total advice items	13
Total items failed	6

MOT #15	2023-12-21 10:03
MOT test number	414675290396
Result	✓ Passed
Next expiry date	2025-01-03

MOT #	÷14	2023-12-20 15:24
MOT t	est number	321042478511
Result		X Failed
Fail	Nearside Rear Tyre tread depth below requirements of 1.6mm (5.2.3 (e))	
Fail	Offside Rear Tyre tread depth below requirements of 1.6mm (5.2.3 (e))	

MOT #13		2022-12-20 11:19
MOT test	number	335556863413
Result		✓ Passed
Advice	Offside Front Lower Suspension component ball joint has slight play (5.3.4 (a) (i))
Advice	Nearside Front Lower Suspension component ball joint has slight play (5.3.4 (a)	(i))
Advice	Rear Tyre worn close to legal limit/worn on edge both (5.2.3 (e))	

MOT #12	2022-01-04 12:29
MOT test number	572114637130
Result	✓ Passed

CarCheck.co.uk page 3/12



report date: 2024-03-29

MOT #11

MOT test number

270683609753

Result

Advice Nearside Rear Nail in tyre on inner edge

Advice Offside Rear Tyre slightly damaged/cracking or perishing slight worn (5.2.3 (d) (ii))

MOT #10

MOT test number

743903552514

Result

Advice Offside Front Nail in tyre badly perished

Advice Offside Rear Nail in tyre has two nails in

Nearside Rear Nail in tyre

MOT #9 2019-07-02 10:12 109102039939 **MOT** test number × Failed Result Fail Offside Windscreen wiper does not clear the windscreen effectively (3.4 (b) (ii)) **Advice** Nearside Rear Nail in tyre Fail Nearside Windscreen wiper does not clear the windscreen effectively (3.4 (b) (ii)) **Advice** Offside Front Nail in tyre badly perished **Advice** Offside Rear Nail in tyre has two nails in

MOT #8

2018-06-29 15:22

MOT test number

716445659540

Result

✓ Passed

Advice Front Suspension component ball joint has slight play lower suspension ball joint (5.3.4 (a) (i))

CarCheck.co.uk page 4/12



report date: 2024-03-29

MOT #7 2018-06-29 10:11

MOT test number 937885104931

Result × Failed

Advice Front Suspension component ball joint has slight play lower suspension ball joint (5.3.4 (a) (i))

Fail Offside Front Tyre tread depth below requirements of 1.6mm (5.2.3 (e))

MOT #6 2017-07-01 10:22

MOT test number 584517145352

Result ✓ Passed

MOT #5 2016-09-10 11:20

MOT test number 548929049901

Result \rightarrow Passed

MOT #4 2016-09-10 09:14

MOT test number 406878046276

Result X Failed

Fail Tyre tread depth below requirements of 1.6mm Both rear (4.1.E.1)

MOT #3 2015-08-18 00:00

MOT test number 437205223440

Result ✓ Passed

MOT #2 2014-09-12 13:12

MOT test number 768655854235

MOT #1 2013-11-19 14:43

MOT test number 469043023452

Result
✓ Passed

CarCheck.co.uk page 5/12



report date: 2024-03-29

Tax & MOT check



Tax status	Valid until 1 July
Days left	62
MOT expiry date	3 January 2025
Full MOT history	See MOT history

Tax calculation

Vehicle class	49
Band	G
Single payment (12 months)	£ 240,00,-
Single six month payment	£ 132,00,-
Total payable by 12 monthly instalments	£ 252,00,-

CarCheck.co.uk page 6/12



report date: 2024-03-29

Damage history

Check the damage history for this BMW. See if, where and when this BMW had damage and the car repair costs. We also check if this BMW was scrapped. Download the premium report here for the results.

Damage 1
Date
Category
Type
Damage 2
Date
Category
Type



Extra BMW salvage check



If this vehicle was seen at a salvage auction we offer: vehicle pictures, salvage location, retail value. Download the premium report <u>here</u> for more information.

More info >

CarCheck.co.uk page 7/12



YC60DDN report date: 2024-03-29

Vehicle valuation

What is this car worth? See the vehicle value of this BMW in the premium report. We check: purchase value, age, mileage, MOT history, damages and online sale prices.

Trade retail value

Auction value

Average private trade value

More info >

CarCheck.co.uk page 8/12



report date: 2024-03-29

Owner	history

*		
For how long did the current and previous owner(s) have this BMW? How many owners d Check it in the premium report and see all owner registrations. Download the full report		ve?

	More info	>
Plate changes		
See in this check if this BMW had different number plates.		
Number of plates		
Current registration	UK UK	
Plate since		
Current registration	NIEZ AIS UK	
Plate since		
	More info	>

CarCheck.co.uk page 9/12



report date: 2024-03-29

Finance check

Check if this BMW is financed, has an outstanding loan or finance agreement. If you are purchasing a vehicle it is smart to ensure that any finance that may have been taken out on this BMW has been settled.

If not, and you buy this BMW then you could lose the money and the car you paid for.

Download the premium report <u>here</u> and check if this BMW is financed.

Finance company	
Date of agreement	
Agreement type	
Agreement term	
Agreement number	
Contact info	

More info >

CarCheck.co.uk page 10/12



report date: 2024-03-29

Mileage check

Odometer	In miles
Mileage registrations	18
First mileage registration	2010-11-15
Last registration	2023-12-21
Complete history	See info



Registration #1	2010-11-15	9 mi
Registration #2	2013-11-19	35.268 mi
Registration #3	2014-09-12	36.278 mi
Registration #4	2015-08-18	51.924 mi
Registration #5	2016-09-10	70.179 mi
Registration #6	2016-09-10	70.182 mi
Registration #7	2017-07-01	72.952 mi
Registration #8	2018-06-29	76.538 mi
Registration #9	2018-06-29	76.538 mi
Registration #10		11.777 es
Registration #11		11.777 es
Registration #12		11.777 es
Registration #13		11.777 es
Registration #14		11.777 es
Registration #15		11.777 es
Registration #16		11.777 es
Registration #17		11.777 es
Registration #18		71.777 es

More info >

CarCheck.co.uk page 11/12



report date: 2024-03-29

Car features

S0225	Air conditioning
S0295	
S0482	
S0501	
S0566	
S0567	
S0569	

Safety ratings

NCAP rating	****
Video	see crash video



Dimensions & weight

Width	1860 mm
Height	1475 mm
Length	4899 mm
Wheel base	1558 mm
Kerb weight	1705 kg
Max. allowed weight	2315 kg

Additional information

Fuel tank capacity	70	
Fuel delivery	Direct Injection	
Number of doors	4	
Number of seats CarCheck.co.uk	5	page 12/12

Number of axles2Engine number24817510