





report date: 2024-03-29

General information

Make	CITROEN
Model	DS3 DSTYLE
Colour	Red
Year of manufacture	2013
Top speed	118 mph
0 - 60 mph	10.9 seconds
Gearbox	4 speed automatic

Engine & fuel consumption

Power	120 BHP
Max. torque	160 Nm at 4.200 rpm
Engine capacity	1.598 сс
Cylinders	4
Fuel type	Petrol
Consumption city	30.4 mpg
Consumption extra urban	57.7 mpg
Consumption combined	43.5 mpg
CO2 emission	150 g/km
CO2 label	F



CarCheck.co.uk page 1/12



report date: 2024-03-29

Internet history

Entry 1

Date 2021-06-13

Pictures 19

Listing price <u>View report</u>









source: autotrader.co.uk

CarCheck.co.uk page 2/12



report date: 2024-03-29

MOT history	Μ	OT	h	is	to	rv
-------------	---	----	---	----	----	----

MOT expiry date	2024-07-05
MOT pass rate	80 %
MOT passed	8
Failed MOT tests	2
Total advice items	11
Total items failed	4

MOT #10	2023-06-29 15:43
MOT test number	828246839453
Result	✓ Passed
Next expiry date	2024-07-05

MOT #9	2023-06-29 12:21
MOT test number	242233603728
Result	× Failed
Fail Offside Front Track rod end ball joint has excessive play (2.1.3 (b) (i))	

MOT #8		2022-07-01 15:36
MOT test	number	566211082065
Result		✓ Passed
Advice	Offside Rear Service brake binding but not excessively (1.2.1 (f))	
Advice	Nearside Rear Service brake binding but not excessively (1.2.1 (f))	
Minor ingress of	Offside Front Track rod end ball joint dust cover damaged or deteriorated, k dirt (2.1.3 (g) (i))	out preventing the

CarCheck.co.uk page 3/12



report date: 2024-03-29

MOT #7 2022-07-01 13:17 415593987164 **MOT test number** Result × Failed **Advice** Offside Rear Service brake binding but not excessively (1.2.1 (f)) Offside Front Track rod end ball joint dust cover damaged or deteriorated, but preventing the Minor ingress of dirt (2.1.3 (g) (i)) Offside Front Anti-roll bar linkage ball joint excessively worn (5.3.4 (a) (i)) Fail **Advice** Nearside Rear Service brake binding but not excessively (1.2.1 (f)) Fail Nearside Front Anti-roll bar linkage ball joint excessively worn (5.3.4 (a) (i)) Nearside Front Suspension component ball joint excessively worn (5.3.4 (a) (i)) Fail

MOT #6	2021-06-18 12:48
MOT test number	843477488470
Result	✓ Passed
MOT #5	2020-07-06 14:41
MOT test number	100302946762
Result	✓ Passed
Advice Exhaust brackets broken but exhaust still secure	

MOT #4	2019-04-04 13:55
MOT test number	911118407868
Result	✓ Passed
Advice Nearside Front Tyre worn close to legal limit/worn on edge (5.2.3 (e))	

MOT #3	2018-04-04 09:44
MOT test number	475483901696
Result	✓ Passed

CarCheck.co.uk page 4/12



SN63DFO report date: 2024-03-29

MOT #2 2017-04-01 10:16

MOT test number 205354332131

Result ✓ Passed

Advice Offside Rear brake disc worn, pitted or scored, but not seriously weakened (3.5.1i)

Advice Nearside Rear brake disc worn, pitted or scored, but not seriously weakened (3.5.1i)

Advice Rear ex/support broken

MOT #1 2016-04-08 13:29

MOT test number 416919577025

CarCheck.co.uk page 5/12



report date: 2024-03-29

Tax & MOT check



Tax status	Valid until 1 June
Days left	33
MOT expiry date	5 July 2024
Full MOT history	See MOT history

Tax calculation

Vehicle class	48
Venicle class	40
Band	F
Single payment (12 months)	£ 200,00,-
Single six month payment	£ 110,00,-
Total payable by 12 monthly instalments	£ 210,00,-

CarCheck.co.uk page 6/12



report date: 2024-03-29

Damage history

Check the damage history for this CITROEN. See if, where and when this CITROEN had damage and the car repair costs. We also check if this CITROEN was scrapped. Download the premium report here for the results.

Damage 1
Date
Category
Type
Damage 2
Date
Category
Type



Extra CITROEN salvage check



If this vehicle was seen at a salvage auction we offer: vehicle pictures, salvage location, retail value. Download the premium report <u>here</u> for more information.

More info >

CarCheck.co.uk page 7/12



SN63DFO report date: 2024-03-29

Vehicle valuation

What is this car worth? See the vehicle value of this CITROEN in the premium report. We check: purchase value, age, mileage, MOT history, damages and online sale prices.

Trade retail value

Auction value

Average private trade value

More info >

CarCheck.co.uk page 8/12



report date: 2024-03-29

Owner history

For how long did the current and previous owner(s) have this CITROEN? How many owner have? Check it in the premium report and see all owner registrations. Download the full is	
MARKET STATE OF THE STATE OF TH	

THE REAL PROPERTY AND ADDRESS OF THE PERTY ADDRESS OF THE PERTY ADDRESS OF THE PERTY AND ADDRESS OF THE PERTY ADDR	

	More info >
Plate changes	
See in this check if this CITROEN had different number plates.	
Number of plates	,
Current registration	NK SIN
Plate since	
Current registration	NE VIK
Fights since	
	More info >

CarCheck.co.uk page 9/12



report date: 2024-03-29

Finance check

Check if this CITROEN is financed, has an outstanding loan or finance agreement. If you are purchasing a vehicle it is smart to ensure that any finance that may have been taken out on this CITROEN has been settled.

If not, and you buy this CITROEN then you could lose the money and the car you paid for.

Download the premium report <u>here</u> and check if this CITROEN is financed.

Finance company

Date of agreement

Agreement type

Agreement term

Agreement number

Contact info

More info >


CarCheck.co.uk page 10/12



report date: 2024-03-29

Mileage check

Odometer	In miles
Mileage registrations	12
First mileage registration	2013-09-09
Last registration	2023-06-29
Complete history	See info



Registration #1	2013-09-09	27 mi
Registration #2	2016-04-08	7.063 mi
Registration #3	2017-04-01	13.485 mi
Registration #4	2018-04-04	19.765 mi
Registration #5	2019-04-04	23.137 mi
Registration #6	2020-07-06	30.267 mi
Registration #7		11.777 es
Registration #8		11.777 es
Registration #9		9.777 es
Registration #10		11.777 es
Registration #11		11.777 es
Registration #12		m

More info >

CarCheck.co.uk page 11/12



report date: 2024-03-29

Safety ratings

NCAP rating	****
Adult	87%
Children	71%
Pedestrian	35%
Safety systems	83%
Overall rating	73%
Video	see crash video



Dimensions & weight

Width	1715 mm
Height	1483 mm
Length	3948 mm
Wheel base	2464 mm
Kerb weight	1145 kg
Max. allowed weight	1587 kg

Additional information

Fuel tank capacity	48 I
Fuel delivery	Multi-Point Injection
Number of doors	3
Number of seats	5
Number of axles	2
Engine number	FHCK1928107

CarCheck.co.uk page 12/12