



Mercedes-Benz



report date: 2024-03-29

General information

Make	MERCEDES
Model	C C200 CDI SPORT
Colour	Silver
Year of manufacture	2009
Top speed	132 mph
0 - 60 mph	10.2 seconds
Gearbox	5 speed automatic

Engine & fuel consumption

Power	136 BHP
Max. torque	270 Nm at 3.000 rpm
Engine capacity	2.148 cc
Cylinders	4
Fuel type	Diesel
Consumption city	30.7 mpg
Consumption extra urban	53.3 mpg
Consumption combined	42.2 mpg
CO2 emission	177 g/km
CO2 label	I





Internet history

Entry 1

Date	2021-06-11
Pictures	7
Listing price	View report



source: [autotrader.co.uk](https://www.autotrader.co.uk)



MOT history

MOT expiry date	2024-01-20
MOT pass rate	85 %
MOT passed	11
Failed MOT tests	2
Total advice items	25
Total items failed	3

MOT #13	2023-01-18 11:51
MOT test number	356021370076
Result	✓ Passed
Next expiry date	2024-01-20
Advice	Offside Front Tyre worn close to legal limit/worn on edge outer edge (5.2.3 (e))
Advice	Nearside Front Tyre worn close to legal limit/worn on edge outer edge (5.2.3 (e))
Advice	Front Brake pad(s) wearing thin (1.1.13 (a) (ii))
Advice	Rear Brake disc worn, but not excessively (1.1.14 (a) (i))

MOT #12	2022-01-18 11:59
MOT test number	787356643841
Result	✓ Passed
Advice	Offside Front Suspension arm ball joint has slight play rear (5.3.4 (a) (i))
Advice	Nearside Front Suspension arm ball joint has slight play rear (5.3.4 (a) (i))

**MOT #11**

2021-01-13 09:28

MOT test number

897458786224

Result

✓ Passed

Advice Front Brake disc worn, pitted or scored, but not seriously weakened On Inner Surface (1.1.14 (a) (ii))

Advice Nearside Front Brake pipe corroded, covered in grease or other material (1.1.11 (c))

Advice Offside Rear Service brake binding but not excessively (1.2.1 (f))

Minor Nearside Front Suspension arm ball joint dust cover severely deteriorated Front Arm (5.3.4 (b) (i))

Advice Rear Brakes imbalanced requirements only just met. It would appear that the braking system requires adjustment or repair. (1.2.1 (b) (i))

MOT #10

2020-01-21 16:05

MOT test number

779786395047

Result

✓ Passed

Advice Offside Front Tyre worn close to legal limit/worn on edge (5.2.3 (e))

Advice Central Exhaust mounting defective exhaust clamp broken (6.1.2 (a))

MOT #9

2020-01-21 12:30

MOT test number

184897599712

Result

✗ Failed

Advice Central Exhaust mounting defective exhaust clamp broken (6.1.2 (a))

MAJOR Offside Brake pipe excessively corroded front to rear (1.1.11 (c))

MAJOR Nearside Brake pipe excessively corroded front to rear (1.1.11 (c))

Advice Offside Front Tyre worn close to legal limit/worn on edge (5.2.3 (e))

MAJOR Offside Front Lower Suspension arm ball joint excessively worn rear track arm (5.3.4 (a) (i))

MOT #8

2018-10-22 09:20

MOT test number

295724826874

Result

✓ Passed

**MOT #7** 2017-05-04 11:18**MOT test number** 689233127319**Result** ✓ Passed**Advice** Both front to rear brake pipes corroded slightly**Advice** Nearside rear tyre worn on inner edge**MOT #6** 2016-05-04 10:35**MOT test number** 712293886435**Result** ✓ Passed**MOT #5** 2015-05-06 09:59**MOT test number** 895036325173**Result** ✓ Passed**Notice** Under-trays fitted obscuring some underside components**Advice** Offside Front Front wheel bearing has slight play (2.5.A.3c)**Notice** Front tyres worn on inner edge**Advice** Nearside Front Front wheel bearing has slight play (2.5.A.3c)**Notice** Engine covers fitted obscuring some components in the engine bay**MOT #4** 2014-05-09 11:15**MOT test number** 575459824148**Result** ✓ Passed



MOT #3	2014-05-08 16:19
MOT test number	226068124478
Result	✗ Failed
Fail	Nearside Rear Tyre tread depth below requirements of 1.6mm (4.1.E.1)
Fail	Offside Front Headlamp not working on dipped beam (1.7.5a)
Fail	Offside Rear Tyre tread depth below requirements of 1.6mm (4.1.E.1)

MOT #2	2013-05-01 14:11
MOT test number	629061123183
Result	✓ Passed

MOT #1	2012-05-08 15:51
MOT test number	697789022103
Result	✓ Passed



Damage history

Check the damage history for this MERCEDES. See if, where and when this MERCEDES had damage and the car repair costs. We also check if this MERCEDES was scrapped. Download the premium report [here](#) for the results.

Damage 1

Date	
Category	
Type	



Damage 2

Date	
Category	
Type	



Extra MERCEDES salvage check



If this vehicle was seen at a salvage auction we offer: vehicle pictures, salvage location, retail value. Download the premium report [here](#) for more information.

More info >



Vehicle valuation

What is this car worth? See the vehicle value of this MERCEDES in the premium report. We check: purchase value, age, mileage, MOT history, damages and online sale prices.

Trade retail value	£ 19,999
Auction value	£ 19,999
Average private trade value	£ 19,999

More info >



Owner history

For how long did the current and previous owner(s) have this MERCEDES? How many owners did this MERCEDES have? Check it in the premium report and see all owner registrations. Download the full report [here](#).

Owner	Since
Owner	Since
Owner	Since
Owner	Since
Owner	Since
Owner	Since
Owner	Since

More info >

Plate changes

See in this check if this MERCEDES had different number plates.

Number of plates	7
Current registration	 YY09HMH
Plate since	2019-06-29
Current registration	 YY09HMH
Plate since	2019-06-29

More info >



Finance check

Check if this MERCEDES is financed, has an outstanding loan or finance agreement. If you are purchasing a vehicle it is smart to ensure that any finance that may have been taken out on this MERCEDES has been settled.

If not, and you buy this MERCEDES then you could lose the money and the car you paid for.

Download the premium report [here](#) and check if this MERCEDES is financed.

Finance company	XXXXXXXXXX	XXXX
Date of agreement	XXXXXXXXXX	XXXX
Agreement type	XXXXXXXXXX	XXXX
Agreement term	XXXXXXXXXX	XXXX
Agreement number	XXXXXXXXXX	XXXX
Contact info	XXXXXXXXXX	XXXX

More info >



Mileage check

Odometer	In miles
Mileage registrations	15
First mileage registration	2009-05-19
Last registration	2023-01-18
Complete history	See info



Registration #1	2009-05-19	12 mi
Registration #2	2012-05-08	27.568 mi
Registration #3	2013-05-01	36.115 mi
Registration #4	2014-05-08	46.101 mi
Registration #5	2014-05-09	46.101 mi
Registration #6	2015-05-06	54.373 mi
Registration #7	2016-05-04	65.136 mi
Registration #8	2017-05-04	74.838 mi
Registration #9	2018-05-01	85.115 mi
Registration #10	2019-05-01	95.115 mi
Registration #11	2020-05-01	105.115 mi
Registration #12	2021-05-01	115.115 mi
Registration #13	2022-05-01	125.115 mi
Registration #14	2023-01-18	135.115 mi
Registration #15	2023-01-18	135.115 mi

More info >



Dimensions & weight

Width	2020 mm
Height	1447 mm
Length	4581 mm
Wheel base	2760 mm

Additional information

Fuel tank capacity	62 l
Fuel delivery	Direct Injection
Number of doors	4
Number of seats	5
Engine number	64681130387652