





report date: 2024-03-28

#### General information

Make	VOLVO
Model	V60 D4 INSCRIPTION
Colour	Blue
Year of manufacture	2016
Top speed	140 mph
0 - 60 mph	7.9 seconds
Gearbox	8 speed automatic

### Engine & fuel consumption

Power	190 BHP	
Max. torque	400 Nm at 2.500 rpm	
Engine capacity	1.969 сс	
Cylinders	4	
Fuel type	Diesel	
Consumption city	53.3 mpg	
Consumption extra urban	72.4 mpg	
Consumption combined	64.2 mpg	
CO2 emission	116 g/km	
CO2 label	С	



CarCheck.co.uk page 1/12



## Internet history

#### Entry 1

Date 2021-10-09

Pictures 32

Listing price <u>View report</u>









source: cargurus.co.uk

CarCheck.co.uk page 2/12



MOT history

MOT expiry date	2025-02-07
MOT pass rate	67 %
MOT passed	6
Failed MOT tests	3
Total advice items	11
Total items failed	8

MOT #9		2024-02-08 09:55
MOT test	number	966107186358
Result		<b>✓</b> Passed
Next expiry date 2025-02-07		
Advice Offside Front Tyre worn close to legal limit/worn on edge (5.2.3 (e))		
Minor	Registration plate lamp inoperative in the case of multiple lamps or light	sources (4.7.1 (b) (i))

MOT #8		2024-02-08 09:55
MOT test number		763618396917
Result		<b>X</b> Failed
Minor Registration plate lamp inoperative in the case of multiple lamps or light sources (4.7.1 (b) (i))		
Advice Offside Front Tyre worn close to legal limit/worn on edge (5.2.3 (e))		
Pass with rectification	Windscreen washer provides insuffic	cient washer liquid (3.5 (a))

MOT #7	2022-10-04 16:34
MOT test number	665127097317
Result	<b>✓</b> Passed

CarCheck.co.uk page 3/12



**MOT test number** 

YY16BPF

report date: 2024-03-28

409488293319

MOT #6

MOT test number

276558660223

Result

Fail Nearside Rear Brake pad(s) less than 1.5 mm thick (1.1.13 (a) (ii))

Fail Offside Rear Brake pad(s) less than 1.5 mm thick (1.1.13 (a) (ii))

 MOT #5
 2021-10-07 16:29

 MOT test number
 375493529766

MOT #4 2021-03-24 13:01

Result \( \sqrt{Passed} \)

Advice Nearside Front Road wheel slightly distorted (5.2.2 (c) (i))

MOT #3 2021-03-10 10:51

MOT test number 282643962981

Result X Failed

Fail Front Brakes imbalanced across an axle by more than 50% (1.2.1 (b) (ii))

Advice Front Brake pad(s) wearing thin (1.1.13 (a) (ii))

Fail Electronic stability control warning lamp indicates a fault (7.12 (e))

Fail Service brake efficiency below requirements (1.2.2 (a) (i))

Fail Offside Front Tyre has ply or cords exposed 235/40R18 (5.2.3 (d) (ii))

Fail Supplementary restraint system warning lamp indicates a fault (7.1.6 (a))

Advice Tyre worn close to legal limit/worn on edge all tyres worn on edge (235/40R18) (5.2.3 (e))

Advice Nearside Front Road wheel slightly distorted (5.2.2 (c) (i))

CarCheck.co.uk page 4/12



MOT #2 2020-03-13 15:30

**MOT test number** 624836183739

**Result** ✓ Passed

Advice Front Brake pad(s) wearing thin (1.1.13 (a) (ii))

**MOT #1** 2019-03-19 09:37

**MOT test number** 296793415336

Result \( \sqrt{Passed} \)

**Advice** Offside Rear Road wheel slightly distorted inner bead rim (5.2.2 (c) (i))

**Advice** Nearside Front Road wheel slightly distorted inner bead rim (5.2.2 (c) (i))

CarCheck.co.uk page 5/12



## Tax & MOT check



Tax status	Valid until 1 February
Days left	278
MOT expiry date	7 February 2025
Full MOT history	See MOT history

#### Tax calculation

Vehicle class	49
Band	С
Single payment (12 months)	£ 35,00,-
Single six month payment	Not applicable
Total payable by 12 monthly instalments	£ 36,75,-

CarCheck.co.uk page 6/12



Damage history

Check the damage history for this VOLVO. See if, where and when this VOLVO had damage and the car repair costs. We also check if this VOLVO was scrapped. Download the premium report <a href="here">here</a> for the results.

Damage 1
Date
Category
Type
Damage 2
Date
Category
Type



#### Extra VOLVO salvage check



If this vehicle was seen at a salvage auction we offer: vehicle pictures, salvage location, retail value. Download the premium report <u>here</u> for more information.

More info >

CarCheck.co.uk page 7/12



#### Vehicle valuation

What is this car worth? See the vehicle value of this VOLVO in the premium report. We check: purchase value, age, mileage, MOT history, damages and online sale prices.

**Trade retail value** 

**Auction value** 

Average private trade value

More info >

CarCheck.co.uk page 8/12



Owner history

For how long did the current and previous owner(s) have this VOLVO? How many owners have? Check it in the premium report and see all owner registrations. Download the full respectively.		)
********		
***************************************		
	More info	>
Plate changes		
See in this check if this VOLVO had different number plates.		
Number of plates		7
Current registration	UK UK	
Plate since		
Current registration	UK NEZ	
Plate since		
	More info	>

CarCheck.co.uk page 9/12



#### Finance check

Check if this VOLVO is financed, has an outstanding loan or finance agreement. If you are purchasing a vehicle it is smart to ensure that any finance that may have been taken out on this VOLVO has been settled.

If not, and you buy this VOLVO then you could lose the money and the car you paid for.

Download the premium report <u>here</u> and check if this VOLVO is financed.

Finance company	
Date of agreement	
Agreement type	
Agreement term	
Agreement number	
Contact info	

Contact info


More info >

CarCheck.co.uk page 10/12



Mileage check

Odometer	In miles
Mileage registrations	11
First mileage registration	2016-03-18
Last registration	2024-02-08
Complete history	See info



Registration #1	2016-03-18	28 mi
Registration #2	2019-03-19	57.434 mi
Registration #3	2020-03-13	71.840 mi
Registration #4	2021-03-10	80.321 mi
Registration #5	2021-03-24	80.382 mi
Registration #6	2021-10-07	84.088 mi
Registration #7		11.777 es
Registration #8		11.777 es
Registration #9		11.777 es
Registration #10		0.00 44
Registration #11		11.777 es

More info >

CarCheck.co.uk page 11/12



YY16BPF

report date: 2024-03-28

## Car features

50225	Air conditioning
50295	
50482	
50501	
60566	
50567	
50569	

# Safety ratings

NCAP rating	****
Adult	94%
Children	82%
Pedestrian	64%
Safety systems	100%
Overall rating	86%
Video	see crash video



# Dimensions & weight

Width	2019 mm
Height	1443 mm
Length	4963 mm
Wheel base	2941 mm
Kerb weight	1680 kg
Max. allowed weight	2270 kg

## Additional information

Fuel tank capacity	55 I	
Fuel delivery	Direct Injection	
Number of doors	4	
Number of seats CarCheck.co.uk	5 page 1	2/12