



report date: 2024-03-29

General information

Make	FIAT
Model	PUNTO 8V ACTIVE
Colour	Grey
Year of manufacture	2004
Top speed	96 mph
0 - 60 mph	14.3 seconds
Gearbox	5 speed Manual

Engine & fuel consumption

Power	59 BHP
Max. torque	102 Nm at 2.500 rpm
Engine capacity	1.242 cc
Cylinders	4
Fuel type	Petrol
Consumption city	38.7 mpg
Consumption extra urban	58.9 mpg
Consumption combined	49.6 mpg
CO2 emission	136 g/km
CO2 label	E





Internet history

Entry 3

Date	2021-07-17
Pictures	10
Listing price	View report



source: [autotrader.co.uk](#)

Entry 2

Date	2021-07-03
Pictures	10
Listing price	View report



source: [autotrader.co.uk](#)

Entry 1

Date	2021-06-16
Pictures	10
Listing price	View report



source: [autotrader.co.uk](#)

**MOT history**

MOT expiry date	2022-03-05
MOT pass rate	70 %
MOT passed	14
Failed MOT tests	6
Total advice items	55
Total items failed	30

MOT #20	2021-03-04 10:49
----------------	------------------

MOT test number	926704084408
------------------------	--------------

Result	✓ Passed
---------------	----------

Next expiry date	2022-03-05
-------------------------	------------

- Advice** Offside Front Lower Suspension arm pin or bush worn but not resulting in excessive movement (5.3.4 (a) (i))
- Advice** Offside Rear Coil spring corroded (5.3.1 (b) (i))
- Advice** Lower engine stay bar bush worn.
- Advice** Nearside Front Lower Suspension arm pin or bush worn but not resulting in excessive movement (5.3.4 (a) (i))
- Advice** Nearside Rear Coil spring corroded (5.3.1 (b) (i))

**MOT #19**

2021-03-03 10:17

MOT test number

965244724999

Result**✗ Failed**

- Advice** Lower engine stay bar bush worn.
- Advice** Nearside Rear Coil spring corroded (5.3.1 (b) (i))
- Fail** Parking brake efficiency below requirements (1.4.2 (a) (i))
- Fail** Offside Rear Brake hose ferrule excessively corroded (1.1.12 (f) (i))
- Advice** Offside Front Lower Suspension arm pin or bush worn but not resulting in excessive movement (5.3.4 (a) (i))
- Advice** Offside Rear Coil spring corroded (5.3.1 (b) (i))
- Fail** Parking brake lever has excessive movement indicating incorrect adjustment (1.1.6 (c))
- Advice** Nearside Front Lower Suspension arm pin or bush worn but not resulting in excessive movement (5.3.4 (a) (i))

MOT #18

2020-03-03 17:25

MOT test number

889964905158

Result**✓ Passed**

- Advice** Nearside Rear Coil spring corroded (5.3.1 (b) (i))
- Advice** Steering column top bearing slightly worn (2.2.2 (b))
- Advice** Lower Gearbox mounting defective
- Advice** Offside Rear Coil spring corroded (5.3.1 (b) (i))

**MOT #17**

2020-03-03 12:02

MOT test number

399215603448

Result**✗ Failed**

- Fail** Nearside Front Outer Anti-roll bar pin or bush excessively worn (5.3.4 (a) (i))
- Advice** Steering column top bearing slightly worn (2.2.2 (b))
- Advice** Offside Rear Coil spring corroded (5.3.1 (b) (i))
- Advice** Nearside Rear All direction indicators slightly discoloured (4.4.3 (a))
- Advice** Lower Gearbox mounting defective
- Fail** Offside Front Lower Suspension arm ball joint dust cover no longer prevents the ingress of dirt (5.3.4 (b) (ii))
- Fail** Offside Track rod end ball joint has excessive play (2.1.3 (b) (i))
- Fail** Windscreen washer provides insufficient washer liquid (3.5 (a))
- Advice** Nearside Rear Coil spring corroded (5.3.1 (b) (i))
- Fail** Offside Rear Position lamp adversely affected by the operation of another lamp (4.2.3 (c))
- Fail** Nearside Front Lower Suspension arm ball joint dust cover no longer prevents the ingress of dirt (5.3.4 (b) (ii))
- Fail** Offside Front Brake hose excessively twisted (1.1.12 (b) (ii))

MOT #16

2019-03-01 15:12

MOT test number

980751693451

Result**✓ Passed**

- Minor** Offside Front Brake hose slightly twisted (1.1.12 (b) (i))
- Advice** Front Tyre worn close to legal limit/worn on edge offside/nearside (5.2.3 (e))
- Minor** Front Suspension arm ball joint dust cover severely deteriorated offside/nearside (5.3.4 (b) (i))
- Advice** Offside Track rod end ball joint has slight play (2.1.3 (b) (i))

**MOT #15**

2018-03-06 15:31

MOT test number

687333195326

Result

✓ Passed

- Advice** Offside Rear coil spring corroded (2.4.C.1b)
- Advice** Front brake disc worn, pitted or scored, but not seriously weakened (3.5.1i)
- Advice** Offside Front Suspension arm ball joint dust cover deteriorated, but preventing the ingress of dirt (2.4.G.2)
- Advice** Offside Front Outer Anti-roll bar rubber bush deteriorated but not resulting in excessive movement (2.4.G.2)
- Advice** Nearside Rear coil spring corroded (2.4.C.1b)
- Advice** Nearside Front Outer Brake pad(s) wearing thin (3.5.1g)
- Advice** Nearside Front Suspension arm ball joint dust cover deteriorated, but preventing the ingress of dirt (2.4.G.2)
- Advice** Nearside Front Outer Anti-roll bar rubber bush deteriorated but not resulting in excessive movement (2.4.G.2)
- Advice** Offside Front brake binding slightly

MOT #14

2017-03-03 12:50

MOT test number

740107520725

Result

✓ Passed

- Advice** Offside Front Suspension arm ball joint dust cover deteriorated, but preventing the ingress of dirt (2.4.G.2)
- Advice** Offside Rear coil spring corroded (2.4.C.1b)
- Advice** Nearside Front Suspension arm ball joint dust cover deteriorated, but preventing the ingress of dirt (2.4.G.2)
- Advice** Nearside Rear coil spring corroded (2.4.C.1b)

**MOT #13**

2016-03-03 09:51

MOT test number

677050771709

Result

✓ Passed

Advice Offside Rear tyre cracking**Advice** Nearside Front Lower Suspension arm ball joint dust cover deteriorated, but preventing the ingress of dirt (2.4.G.2)**Advice** Nearside Rear tyre cracking**Advice** Offside Rear Lower Suspension arm ball joint dust cover deteriorated, but preventing the ingress of dirt (2.4.G.2)**MOT #12**

2016-03-02 14:43

MOT test number

514857126142

Result

✗ Failed

Fail Exhaust emissions Lambda reading after 2nd fast idle outside specified limits (7.3.D.3)**Advice** Nearside Front Lower Suspension arm ball joint dust cover deteriorated, but preventing the ingress of dirt (2.4.G.2)**Advice** Offside Rear tyre cracking**Fail** Rear Exhaust has a major leak of exhaust gases rear exhaust silencer has bad leak (7.1.2)**Advice** Nearside Rear tyre cracking**Advice** Offside Rear Lower Suspension arm ball joint dust cover deteriorated, but preventing the ingress of dirt (2.4.G.2)**MOT #11**

2015-02-12 09:09

MOT test number

178213245049

Result

✓ Passed

Advice Rear Exhaust has a minor leak of exhaust gases (7.1.2)

**MOT #10** 2014-03-03 09:43**MOT test number** 317382764083**Result** ✓ Passed**Notice** Oil leak**Notice** Child seat fitted not allowing full inspection of adult belt**Advice** Rear coil spring corroded (2.4.C.1b)**MOT #9** 2013-03-02 09:09**MOT test number** 375691163034**Result** ✓ Passed**MOT #8** 2013-02-23 09:43**MOT test number** 799774353024**Result** ✗ Failed**Fail** Nearside Front Tyre tread depth below requirements of 1.6mm (4.1.E.1)**Advice** Front Service brake: service brake efficiency only just met. It would appear that the braking system requires adjustment or repair. (3.7.B.7)**Fail** Offside Rear rear parking brake recording little or no effort (3.7.B.6a)**MOT #7** 2012-02-27 14:04**MOT test number** 615858952054**Result** ✓ Passed**MOT #6** 2011-01-28 12:43**MOT test number** 686988521083**Result** ✓ Passed



MOT #5	2011-01-28 10:13
MOT test number	479278321038
Result	✗ Failed
Fail	Nearside Front Tyre tread depth below requirements of 1.6mm (4.1.E.1)

MOT #4	2009-11-27 11:04
MOT test number	863051539307
Result	✓ Passed
Advice	Offside Rear Shock absorber has a slightly worn bush (2.7.4)
Advice	Nearside Front Shock absorber has a slightly worn bush (2.7.4)
Notice	Nail in nearside rear tyre

**MOT #3** 2009-11-20 10:09**MOT test number** 693404129336**Result** ✗ Failed**Advice** Nearside Front Shock absorber has a slightly worn bush (2.7.4)**Notice** Nail in nearside rear tyre**Fail** Rear Direction indicators not working (1.4.A.2c)**Fail** Semaphore indicator switch missing (1.4.C.1c)**Fail** Rear Rear fog lamp not working (1.3.2b)**Fail** Nearside Front Headlamp not working on dipped beam (1.7.5a)**Fail** Exhaust emissions carbon monoxide content after 2nd fast idle excessive (7.3.D.3)**Fail** Nearside Front Headlamp not working on main beam (1.7.5a)**Fail** Exhaust emissions Lambda reading after 2nd fast idle outside specified limits (7.3.D.3)**Fail** Front Direction indicators not working (1.4.A.2c)**Fail** Position lamp switch missing (1.1.A.1)**Advice** Offside Rear Shock absorber has a slightly worn bush (2.7.4)**Fail** Rear Direction indicators incorrect colour (1.4.A.2f)**Fail** Headlamp aim not tested (1.8.A.1c)**Fail** Front Brake pad(s) less than 1.5 mm thick (3.5.1g)**Fail** Offside Front Headlamp not working on dipped beam (1.7.5a)**Fail** Exhaust emissions hydrocarbon content after 2nd fast idle excessive (7.3.D.3)**Fail** Offside Front Headlamp not working on main beam (1.7.5a)**MOT #2** 2008-11-04 13:51**MOT test number** 442079008356**Result** ✓ Passed



MOT #1	2007-10-22 16:08
MOT test number	572955797237
Result	✓ Passed



Tax & MOT check

✕
Untaxed

Tax expired:
1 March 2022

✕
MOT

Expired:
5 March 2022

Tax status	Expired at 1 March 2022
Days left	789 days too late
MOT expiry date	5 March 2022
Full MOT history	See MOT history

Tax calculation

Vehicle class	48
Band	E
Single payment (12 months)	£ 180,00,-
Single six month payment	£ 99,00,-
Total payable by 12 monthly instalments	£ 189,00,-



Damage history

Check the damage history for this FIAT. See if, where and when this FIAT had damage and the car repair costs. We also check if this FIAT was scrapped. Download the premium report [here](#) for the results.

Damage 1	
Date	
Category	
Type	
Damage 2	
Date	
Category	
Type	



Extra FIAT salvage check



If this vehicle was seen at a salvage auction we offer: vehicle pictures, salvage location, retail value. Download the premium report [here](#) for more information.

More info >



Vehicle valuation

What is this car worth? See the vehicle value of this FIAT in the premium report. We check: purchase value, age, mileage, MOT history, damages and online sale prices.

Trade retail value	£ 19,999
Auction value	£ 19,999
Average private trade value	£ 19,999

More info >



Owner history

For how long did the current and previous owner(s) have this FIAT? How many owners did this FIAT have? Check it in the premium report and see all owner registrations. Download the full report [here](#).

*****	*****
*****	*****
*****	*****
*****	*****
*****	*****
*****	*****
*****	*****

More info >

Plate changes

See in this check if this FIAT had different number plates.

Number of plates	1
Current registration	*****
Plate since	2023-03-29
Current registration	*****
Plate since	2023-03-29

More info >



Finance check

Check if this FIAT is financed, has an outstanding loan or finance agreement. If you are purchasing a vehicle it is smart to ensure that any finance that may have been taken out on this FIAT has been settled.

If not, and you buy this FIAT then you could lose the money and the car you paid for.

Download the premium report [here](#) and check if this FIAT is financed.

Finance company	XXXXXXXX	XXXX
Date of agreement	XXXXXXXX	XXXX
Agreement type	XXXXXXXX	XXXX
Agreement term	XXXXXXXX	XXXX
Agreement number	XXXXXXXX	XXXX
Contact info	XXXXXXXX	XXXX

More info >



Mileage check

Odometer	In miles
Mileage registrations	24
First mileage registration	2004-09-30
Last registration	2021-03-04
Complete history	See info



Registration #1	2004-09-30	23 mi
Registration #2	2007-10-22	26.497 mi
Registration #3	2008-11-04	36.547 mi
Registration #4	2009-11-20	46.699 mi
Registration #5	2009-11-27	46.718 mi
Registration #6	2011-01-28	56.469 mi
Registration #7	2011-01-28	56.469 mi
Registration #8	2012-02-27	66.840 mi
Registration #9	2013-02-23	76.893 mi
Registration #10	2013-03-02	77.099 mi
Registration #11	2014-03-03	83.989 mi
Registration #12	2015-02-12	86.781 mi
Registration #13	2015-05-20	91.377 mi
Registration #14	2015-05-20	91.377 mi
Registration #15	2015-05-20	91.377 mi
Registration #16	2015-05-20	91.377 mi
Registration #17	2015-05-20	91.377 mi
Registration #18	2015-05-20	91.377 mi
Registration #19	2015-05-20	91.377 mi
Registration #20	2015-05-20	91.377 mi
Registration #21	2015-05-20	91.377 mi
Registration #22	2015-05-20	91.377 mi
Registration #23	2015-05-20	91.377 mi
Registration #24	2015-05-20	91.377 mi

More info >



Car features

The FIAT factory car options list is only available in the premium report.

S0225	Air conditioning
S0295	
S0482	
S0501	
S0566	
S0567	
S0569	

View the complete FIAT factory list for this vehicle [here](#).

More info >

Safety ratings

NCAP rating ★★★★☆

Video [see crash video](#)



Dimensions & weight

Width	1660 mm
Height	1480 mm
Length	3865 mm
Wheel base	2460 mm
Kerb weight	875 kg

Additional information

Fuel tank capacity	47 l
Fuel delivery	Multi-Point Injection
Number of doors	5
Number of axles	2
Engine number	2095410