





General information

Make	PEUGEOT
Model	207 HDI SW ACTIVE
Colour	Red
Year of manufacture	2013
Top speed	113 mph
Gearbox	5 speed Manual

Engine & fuel consumption

Power	92 BHP
Max. torque	230 Nm at 1.750 rpm
Engine capacity	1.560 cc
Cylinders	4
Fuel type	Diesel
Consumption city	54.3 mpg
Consumption extra urban	80.7 mpg
Consumption combined	67.3 mpg
CO2 emission	110 g/km
CO2 label	В





Internet history


Entry 1

Date Pictures 2021-12-17

14

Listing price

View report



source: autotrader.co.uk



MOT history

MOT expiry date	2025-01-01
MOT pass rate	57 %
MOT passed	8
Failed MOT tests	6
Total advice items	31
Total items failed	21

MOT #14	2024-01-02 14:06
MOT test number	337751277299
Result	✓ Passed
Next expiry date	2025-01-01
Advice Nearside Front Tyre worn close to legal limit/worn on edge (5.2.3 (e))	
Advice Offside Front Tyre worn close to legal limit/worn on edge (5.2.3 (e))	
Advice Offside Front Fog light inop.	
Advice Front Oil leak, but not excessive (8.4.1 (a) (i))	





MOT #13	2024-01-02 10:49
MOT test number	370635431987
Result	🗙 Failed
Fail Front Windscreen washer not working (3.5 (a))	
Advice Offside Front Fog light inop.	
Advice Front Oil leak, but not excessive (8.4.1 (a) (i))	
Fail Nearside Front Headlamp not working on dipped beam (4.1.1 (a) (ii))	
Fail Nearside Front Direction indicator not working (4.4.1 (a) (ii))	
Fail Rear Registration plate lamp inoperative in the case of a single lamp or all lamps	(4.7.1 (b) (ii))
Advice Offside Front Tyre worn close to legal limit/worn on edge (5.2.3 (e))	
Fail Nearside Front Windscreen wiper does not clear the windscreen effectively (3.4 (b))	o) (ii))
Fail Offside Front Headlamp not working on dipped beam (4.1.1 (a) (ii))	
FailOffside Rear Position lamp not working (4.2.1 (a) (ii))	
Advice Nearside Front Tyre worn close to legal limit/worn on edge (5.2.3 (e))	

MOT #12	2022-12-08 11:46
MOT test number	356341696225
Result	✓ Passed
Advice Front Tyre worn close to legal limit/worn on edge Both N\S and O\S (5.2.3 (e))	



MOT #11	2022-12-07 11:39
MOT test number	296717726263
Result	🗙 Failed
Fail Offside Front Direction indicator not working (4.4.1 (a) (ii))	
FailOffside Front Position lamp not working (4.2.1 (a) (ii))	
Fail Brake lever has insufficient reserve travel (1.1.2 (a))	
Advice Front Tyre worn close to legal limit/worn on edge Both N\S and O\S (5.2.3 (e))	

MOT #10		2021-12-02 09:54
MOT test	number	156278417333
Result		✓ Passed
Advice	Front Service brake fluctuating, but not excessively (1.2.1 (e))	
Advice	Undertrays fitted	
Advice	Exhaust mounting defective (6.1.2 (a))	

MOT #9	2020-09-07	14:45
MOT test	2621406	01013
Result	✓ I	Passed
Advice	Nearside Front Tyre worn close to legal limit/worn on edge (5.2.3 (e))	
Advice	Nearside Front Brake pad(s) wearing thin and offside front (1.1.13 (a) (ii))	
Advice (1.1.14 (a		ıt
Advice	Items removed from driver's view prior to test	
Advice	Nearside Front Anti-roll bar linkage ball joint has slight play and offside front (5.3.4 (a) (i))	

SJ13HCX

report date: 2024-03-29





MOT #8	2020-09-04 15:37
MOT test number	770905427346
Result	× Failed
Advice Nearside Front Brake disc worn, pitted or scored, but not seriously weakened and (1.1.14 (a) (ii))	offside front
FailNearside Rear Registration plate lamp inoperative in the case of a single lamp or all l.(ii))	amps (4.7.1 (b)
FailOffside Rear Coil spring fractured or broken (5.3.1 (b) (i))	
Advice Items removed from driver's view prior to test	
FailOffside Front Tyre fouling a part of the vehicle (5.2.3 (f))	
FailNearside Front Headlamp aim too high (4.1.2 (a))	
Advice Nearside Front Tyre worn close to legal limit/worn on edge (5.2.3 (e))	
Advice Nearside Front Brake pad(s) wearing thin and offside front (1.1.13 (a) (ii))	
FailOffside Rear Registration plate lamp inoperative in the case of a single lamp or all lar(ii))	nps (4.7.1 (b)
Advice Nearside Front Anti-roll bar linkage ball joint has slight play and offside front (5.3.	4 (a) (i))
FailOffside Front Headlamp aim too low (4.1.2 (a))	

MOT #7	2019-06-14 10:20
MOT test number	901676348914
Result	✓ Passed
Advice Front Brake disc worn, pitted or scored, but not seriously weakened (1.1.	14 (a) (ii))

МОТ #6	2019-06-14 10:20
MOT test number	377664606238
Result	× Failed
Advice Front Brake disc worn, pitted or scored, but not seriously weakened (1.1.14 (a) (ii))	
Pass with rectification	Nearside Rear Position lamp not working (4.2.1 (a))
Pass with rectification	Windscreen wiper does not clear the windscreen effectively (3.4 (b) (ii))





MOT #5		2018-05-24 10:17
MOT test number		109988764996
Result		✓ Passed
MOT #4		2018-05-24 10:17
MOT test number		353695981018
Result		🗙 Failed
Pass with rectification	Offside Headlamp aim too high (4.1.2 (a))	
MOT #3		2017-05-12 09:21
MOT test number		626010159125
Result		✓ Passed
MOT #2		2016-03-28 13.50

MOT #2		2016-03-28 13:50
MOT test n	umber	463574441091
Result		✓ Passed
Advice	Under tray fitted covering underside components.	

MOT #1	2016-03-28 08:46
MOT test number	864273857998
Result	🗙 Failed
Fail Nearside Front Anti-roll bar has excessive play in a ball joint drop link. (2.4.G.2)	
Advice Under tray fitted covering underside components.	
Advice Offside Front brake disc worn, pitted or scored, but not seriously weakened (3.5.1i)
Advice Nearside Front Brake pad(s) wearing thin (3.5.1g)	
Fail Offside Front Anti-roll bar has excessive play in a ball joint drop link. (2.4.G.2)	
Advice Nearside Front brake disc worn, pitted or scored, but not seriously weakened	l (3.5.1i)
Advice Offside Front Brake pad(s) wearing thin (3.5.1g)	



Tax & MOT check

Tax due: 1 April 2025	✓ Taxed	Expires: 1 January 2025	√ МОТ
Tax status			Valid until 1 April
Days left			337
MOT expiry date			1 January 2025
Full MOT history			See MOT history
Tax calculation			

Vehicle class	49
Band	В
Single payment (12 months)	£ 20,00,-
Single six month payment	Not applicable
Total payable by 12 monthly instalments	£ 21,00,-





Damage history

Check the damage history for this PEUGEOT. See if, where and when this PEUGEOT had damage and the car repair costs. We also check if this PEUGEOT was scrapped. Download the premium report <u>here</u> for the results.

Damage 1	
Date	FER I
Category	 A PLANE
Туре	
Damage 2	AMPLE
Damage 2	E Stand
Date	*
Category	 ante.
Туре	

Extra PEUGEOT salvage check

If this vehicle was seen at a salvage auction we offer: vehicle pictures, salvage location, retail value. Download the premium report <u>here</u> for more information.

More info \rightarrow





Vehicle valuation

What is this car worth? See the vehicle value of this PEUGEOT in the premium report. We check: purchase value, age, mileage, MOT history, damages and online sale prices.

Trade retail value	6.00.000
Auction value	4 10.000
Average private trade value	4 11 711

More info \rightarrow





Owner history

For how long did the current and previous owner(s) have this PEUGEOT? How many owners did this PEUGEOT have? Check it in the premium report and see all owner registrations. Download the full report <u>here</u>.

And a second sec	

	More info >
Plate changes	
See in this check if this PEUGEOT had different number plates.	
Number of plates	,
Current registration	
Plate since	
Current registration	
Plate since	
	More info >





Finance check

Check if this PEUGEOT is financed, has an outstanding loan or finance agreement. If you are purchasing a vehicle it is smart to ensure that any finance that may have been taken out on this PEUGEOT has been settled.

If not, and you buy this PEUGEOT then you could lose the money and the car you paid for.

Download the premium report <u>here</u> and check if this PEUGEOT is financed.

Finance company	
Date of agreement	
Agreement type	
Agreement term	
Agreement number	
Contact info	


More info \rightarrow





Mileage check

Odometer	In miles
Mileage registrations	16
First mileage registration	2013-03-30
Last registration	2024-01-02
Complete history	See info



Registration #1	2013-03-30	20 mi
Registration #2	2016-03-28	27.667 mi
Registration #3	2016-03-28	27.667 mi
Registration #4	2017-05-12	31.025 mi
Registration #5	2018-05-24	34.053 mi
Registration #6	2018-05-24	34.053 mi
Registration #7	2019-06-14	43.710 mi
Registration #8	2019-06-14	43.710 mi
Registration #9		11.777 esi
Registration #9 Registration #10		10.000 est
-		10.000 est 10.000 est 10.000 est
Registration #10		10.000 est 10.000 est 10.000 est 10.000 est
Registration #10 Registration #11		10.202 46 0.202 46 0.202 46 0.202 46 0.202 46
Registration #10 Registration #11 Registration #12		10.202 46 0.202 46 0.202 46 0.202 46 0.202 46 0.202 46
Registration #10 Registration #11 Registration #12 Registration #13		10.000 460 0.000 460 0.000 460 0.000 460 0.000 460 0.000 460 0.000 460

More info >





Car features

S0225	Air conditioning
S0295	
S0482	
\$0501	
50566	
50567	
S0569	

Safety ratings

NCAP rating	****
Adult	86%
Children	81%
Pedestrian	31%
Safety systems	97%
Overall rating	75%
Video	see crash video



Dimensions & weight	
Width	1972 mm
Height	1555 mm
Length	4149 mm
Kerb weight	1374 kg
Max. allowed weight	1743 kg
Additional information	

Fuel tank capacity	50 I
Fuel delivery	Direct Injection
Number of doors	5
Number of seats	5
Number of axles CarCheck.co.uk	2 page 14/14

Engine number

JBFM3027887