



TOYOTA



report date: 2024-03-29

General information

Make	TOYOTA
Model	IQ VVT-I FIRE AC
Colour	White
Year of manufacture	2012
Top speed	98 mph
0 - 60 mph	14.2 seconds
Gearbox	5 speed Manual

Engine & fuel consumption

Power	67 BHP
Max. torque	93 Nm at 3.600 rpm
Engine capacity	998 cc
Cylinders	3
Fuel type	Petrol
Consumption city	55.4 mpg
Consumption extra urban	74.3 mpg
Consumption combined	65.7 mpg
CO2 emission	99 g/km
CO2 label	A





Internet history

Entry 1

Date	2021-02-05
Pictures	1
Listing price	View report



source: [autoonline.co.uk](https://www.autoonline.co.uk)



MOT history

MOT expiry date	2024-06-29
MOT pass rate	73 %
MOT passed	8
Failed MOT tests	3
Total advice items	35
Total items failed	4

MOT #11	2023-06-21 09:16
---------	------------------

MOT test number	719333027959
-----------------	--------------

Result	✓ Passed
--------	----------

Next expiry date	2024-06-29
------------------	------------

- Advice** Central Exhaust has a minor leak of exhaust gases (6.1.2 (a))
- Advice** Nearside Rear Brake pipe corroded, covered in grease or other material (1.1.11 (c))
- Minor** Windscreen damaged but not adversely affecting driver's view (3.2 (a) (i))
- Advice** Offside Rear Service brake binding but not excessively (1.2.1 (f))
- Advice** Rear Exhaust mounting defective Rear exhaust bracket broken (6.1.2 (a))
- Advice** Offside Rear Brake pipe corroded, covered in grease or other material (1.1.11 (c))

**MOT #10**

2022-06-14 09:06

MOT test number

606137466492

Result

✓ Passed

- Minor** Offside Front Outer Drive shaft joint constant velocity boot severely deteriorated (6.1.7 (g) (i))
- Advice** Central Exhaust has a minor leak of exhaust gases Exhaust mount heavily corroded (6.1.2 (a))
- Advice** Nearside Rear Tyre slightly damaged/cracking or perishing Worn on Inner edge (5.2.3 (d) (ii))
- Advice** Oil leak, but not excessive Gearbox oil leak (8.4.1 (a) (i))
- Minor** Offside Front Windscreen damaged but not adversely affecting driver's view (3.2 (a) (i))
- Advice** Offside Rear Brake pipe corroded, covered in grease or other material (1.1.11 (c))
- Advice** Offside Front Inner Tyre worn close to legal limit/worn on edge Tyre tread depth on 1.6mm (5.2.3 (e))
- Advice** Nearside Rear Brakes imbalanced requirements only just met. It would appear that the braking system requires adjustment or repair. (1.2.1 (b) (i))
- Advice** Nearside Rear Brake pipe corroded, covered in grease or other material (1.1.11 (c))

MOT #9

2021-06-30 11:53

MOT test number

500871673100

Result

✓ Passed

- Advice** Nearside Rear Tyre slightly damaged/cracking or perishing (5.2.3 (d) (ii))
- Advice** Offside Front Tyre slightly damaged/cracking or perishing (5.2.3 (d) (ii))

**MOT #8** 2021-06-29 10:57**MOT test number** 817251630726**Result** ✗ Failed**Advice** Front Exhaust has a minor leak of exhaust gases (6.1.2 (a))**Advice** Offside Front Tyre slightly damaged/cracking or perishing (5.2.3 (d) (ii))**Advice** Offside Rear Nail in tyre**DANGEROUS** Nearside Front Tyre has a tear, caused by separation or partial failure of its structure (5.2.3 (d) (ii))**Advice** Nearside Rear Tyre slightly damaged/cracking or perishing (5.2.3 (d) (ii))**MOT #7** 2021-02-15 12:14**MOT test number** 681803934271**Result** ✓ Passed**MOT #6** 2019-11-20 09:31**MOT test number** 649231530924**Result** ✓ Passed**Advice** Nearside Rear Tyre worn close to legal limit/worn on edge (5.2.3 (e))**Advice** Front Brake pad(s) wearing thin (1.1.13 (a) (ii))**MOT #5** 2018-11-22 15:09**MOT test number** 695478019722**Result** ✓ Passed**Advice** Nearside Front Tyre worn close to legal limit/worn on edge (5.2.3 (e))**Advice** Exh heat shield loose/rattles

**MOT #4**

2018-11-22 10:59

MOT test number

496285747543

Result**✗ Failed****Advice** Nearside Front Tyre worn close to legal limit/worn on edge (5.2.3 (e))**MAJOR** Nearside Rear Brake disc significantly and obviously worn (1.1.14 (a) (i))**Advice** Exh heat shield loose/rattles**DANGEROUS** Nearside Rear Brake pad(s) less than 1.5 mm thick down on metal (1.1.13 (a) (ii))**MOT #3**

2017-11-29 13:25

MOT test number

867400348389

Result**✓ Passed****Advice** Rear Brake pad(s) wearing thin (3.5.1g)**MOT #2**

2017-11-24 09:53

MOT test number

626918691031

Result**✗ Failed****Advice** Rear Brake pad(s) wearing thin (3.5.1g)**Fail** Offside Brake pipe excessively corroded front to rear (3.6.B.2c)**Advice** Offside Front Tyre worn close to the legal limit (4.1.E.1)**Fail** Offside Front Windscreen wiper does not clear the windscreen effectively (8.2.2)**Fail** Front Brake pad(s) less than 1.5 mm thick (3.5.1g)**Advice** Front brake disc worn, pitted or scored, but not seriously weakened offside and nearside (3.5.1i)**Advice** Nearside Rear Brake pipe slightly corroded (3.6.B.2c)**Fail** Electronic stability system warning lamp indicates a fault (3.4.1c)



MOT #1	2015-12-08 10:59
MOT test number	322188867155
Result	✓ Passed



Tax & MOT check

✓
Taxed
Tax due:
1 July 2024

✓
MOT
Expires:
29 June 2024

Tax status	Valid until 1 July
Days left	63
MOT expiry date	29 June 2024
Full MOT history	See MOT history

Tax calculation

Vehicle class	48
Band	A
Single payment (12 months)	£ 0,00,-
Single six month payment	Not applicable
Total payable by 12 monthly instalments	Not applicable



Damage history

Check the damage history for this TOYOTA. See if, where and when this TOYOTA had damage and the car repair costs. We also check if this TOYOTA was scrapped. Download the premium report [here](#) for the results.

Damage 1

Date	
Category	
Type	



Damage 2

Date	
Category	
Type	

Extra TOYOTA salvage check



If this vehicle was seen at a salvage auction we offer: vehicle pictures, salvage location, retail value. Download the premium report [here](#) for more information.

More info >



Vehicle valuation

What is this car worth? See the vehicle value of this TOYOTA in the premium report. We check: purchase value, age, mileage, MOT history, damages and online sale prices.

Trade retail value	£ 19,299
Auction value	£ 19,299
Average private trade value	£ 19,299

More info >



Owner history

For how long did the current and previous owner(s) have this TOYOTA? How many owners did this TOYOTA have? Check it in the premium report and see all owner registrations. Download the full report [here](#).

Owner	Registration
Owner	Registration
Owner	Registration
Owner	Registration
Owner	Registration
Owner	Registration
Owner	Registration

More info >

Plate changes

See in this check if this TOYOTA had different number plates.

Number of plates	1
Current registration	DE62UUT
Plate since	2019-03-29
Current registration	DE62UUT
Plate since	2019-03-29

More info >



Finance check

Check if this TOYOTA is financed, has an outstanding loan or finance agreement. If you are purchasing a vehicle it is smart to ensure that any finance that may have been taken out on this TOYOTA has been settled. If not, and you buy this TOYOTA then you could lose the money and the car you paid for. Download the premium report [here](#) and check if this TOYOTA is financed.

Finance company	XXXXXXXXXX	XXXX
Date of agreement	XXXXXXXXXX	XXXX
Agreement type	XXXXXXXXXX	XXXX
Agreement term	XXXXXXXXXX	XXXX
Agreement number	XXXXXXXXXX	XXXX
Contact info	XXXXXXXXXX	XXXX

More info >



Mileage check

Odometer	In miles
Mileage registrations	13
First mileage registration	2012-12-11
Last registration	2023-06-21
Complete history	See info



Registration #1	2012-12-11	25 mi
Registration #2	2015-12-08	39.713 mi
Registration #3	2017-11-24	47.283 mi
Registration #4	2017-11-29	47.409 mi
Registration #5	2018-11-22	60.380 mi
Registration #6	2018-11-22	60.381 mi
Registration #7	2019-11-20	76.947 mi
Registration #8	2019-11-20	76.947 mi
Registration #9	2019-11-20	76.947 mi
Registration #10	2019-11-20	76.947 mi
Registration #11	2019-11-20	76.947 mi
Registration #12	2019-11-20	76.947 mi
Registration #13	2019-11-20	76.947 mi

More info >



Car features

The TOYOTA factory car options list is only available in the premium report.

S0225	Air conditioning
S0295	
S0482	
S0501	
S0566	
S0567	
S0569	

View the complete TOYOTA factory list for this vehicle [here](#).

More info >

Safety ratings

NCAP rating	★★★★★
Adult	91%
Children	71%
Pedestrian	54%
Safety systems	86%
Overall rating	79%
Video	see crash video



Dimensions & weight

Width	1615 mm
Height	1465 mm
Length	3430 mm
Wheel base	2340 mm
Kerb weight	830 kg
Max. allowed weight	1190 kg

Additional information

Fuel tank capacity	35 l
Fuel delivery	Multi-Point Injection
Number of doors	5
Number of seats	4

Engine number	1KR7155999
---------------	------------