



report date: 2024-03-29

General information

Make	FORD
Model	C-MAX ZETEC 100
Colour	Blue
Year of manufacture	2009
Top speed	107 mph
0 - 60 mph	12.9 seconds
Gearbox	5 speed Manual

Engine & fuel consumption

Power	100 BHP
Max. torque	145 Nm at 4.000 rpm
Engine capacity	1.596 cc
Cylinders	4
Fuel type	Petrol
Consumption city	31.7 mpg
Consumption extra urban	49.6 mpg
Consumption combined	40.9 mpg
CO2 emission	164 g/km
CO2 label	G





MOT history

MOT expiry date	2021-03-16
MOT pass rate	69 %
MOT passed	9
Failed MOT tests	4
Total advice items	15
Total items failed	14

MOT #13	2020-03-17 11:23
MOT test number	362926822936
Result	✓ Passed
Next expiry date	2021-03-16

MOT #12	2019-03-01 10:32
MOT test number	486286806082
Result	✓ Passed
Advice	Suspension arm pin or bush worn but not resulting in excessive movement both front arm .rear bushes (5.3.4 (a) (i))

MOT #11	2018-02-26 16:24
MOT test number	480398875415
Result	✓ Passed

**MOT #10**

2018-02-21 15:04

MOT test number

122400452329

Result**✗ Failed**

- Fail** Nearside Stop lamp not working (1.2.1b)
- Fail** Nearside Headlamp not working on dipped beam (1.7.5a)
- Fail** Nearside Front Tyre has a cut in excess of the requirements deep enough to reach the ply or cords inner sidewall (4.1.D.1a)
- Fail** Offside Rear Tyre has a lump, caused by separation or partial failure of its structure (4.1.D.1b)
- Fail** Offside Stop lamp not working (1.2.1b)
- Fail** Offside Front position lamp(s) not working (1.1.A.3b)
- Fail** Offside Headlamp aim beam image obviously incorrect (1.8.A.1b)
- Fail** Offside Rear Tyre has ply or cords exposed inner edge (4.1.D.1b)

MOT #9

2017-03-16 09:18

MOT test number

182739031282

Result**✓ Passed****MOT #8**

2016-04-22 13:11

MOT test number

439003354294

Result**✓ Passed**

- Advice** Nearside Front Suspension arm rubber bush deteriorated but not resulting in excessive movement (2.4.G.2)
- Advice** Offside Front Suspension arm rubber bush deteriorated but not resulting in excessive movement (2.4.G.2)
- Advice** Offside Front Tyre worn close to the legal limit (4.1.E.1)

**MOT #7** 2015-05-13 16:57**MOT test number** 135893735123**Result** ✓ Passed

- Advice** Offside Front Suspension arm rubber bush deteriorated but not resulting in excessive movement (2.4.G.2)
- Advice** Nearside Rear brake disc worn, pitted or scored, but not seriously weakened (3.5.1i)
- Advice** Nearside Front Suspension arm rubber bush deteriorated but not resulting in excessive movement (2.4.G.2)
- Advice** Offside Rear brake disc worn, pitted or scored, but not seriously weakened (3.5.1i)

MOT #6 2015-05-13 12:00**MOT test number** 109213135104**Result** ✗ Failed

- Fail** Nearside Front Brake pad(s) less than 1.5 mm thick (3.5.1g)
- Advice** Offside Rear brake disc worn, pitted or scored, but not seriously weakened (3.5.1i)
- Advice** Offside Front Suspension arm rubber bush deteriorated but not resulting in excessive movement (2.4.G.2)
- Fail** Nearside Stop lamp not working (1.2.1b)
- Advice** Nearside Rear brake disc worn, pitted or scored, but not seriously weakened (3.5.1i)
- Advice** Nearside Front Suspension arm rubber bush deteriorated but not resulting in excessive movement (2.4.G.2)

MOT #5 2014-05-12 14:13**MOT test number** 316952634160**Result** ✓ Passed**MOT #4** 2014-05-12 14:13**MOT test number** 168012034182**Result** ✗ Failed

- Pass with rectification** Nearside Headlamp not working on dipped beam (1.7.5a)
- Pass with rectification** Nearside Windscreen wiper does not clear the windscreen effectively (8.2.2)



MOT #3	2013-05-14 11:43
MOT test number	137234633114
Result	✓ Passed

MOT #2	2013-05-14 11:43
MOT test number	208304133433
Result	✗ Failed
Pass with rectification	Offside Front Headlamp not working on dipped beam (1.7.5a)
Pass with rectification	Front Windscreen washer provides insufficient washer liquid (8.2.3)

MOT #1	2012-05-17 14:00
MOT test number	699028232191
Result	✓ Passed
Notice	N/S door mirror glass broken
Notice	Items removed from driver's view prior to test
Notice	Nail in offside front tyre



Tax & MOT check

✕
Untaxed

Tax expired:
22 November 2020

✕
MOT

Expired:
16 March 2021

Tax status	Expired at 22 November 2020
Days left	1254 days too late
MOT expiry date	16 March 2021
Full MOT history	See MOT history

Tax calculation

Vehicle class	48
Band	G
Single payment (12 months)	£ 240,00,-
Single six month payment	£ 132,00,-
Total payable by 12 monthly instalments	£ 252,00,-



Damage history

Check the damage history for this FORD. See if, where and when this FORD had damage and the car repair costs. We also check if this FORD was scrapped. Download the premium report [here](#) for the results.

Damage 1

Date	
Category	
Type	

Damage 2

Date	
Category	
Type	



Extra FORD salvage check



If this vehicle was seen at a salvage auction we offer: vehicle pictures, salvage location, retail value. Download the premium report [here](#) for more information.

More info >



Vehicle valuation

What is this car worth? See the vehicle value of this FORD in the premium report. We check: purchase value, age, mileage, MOT history, damages and online sale prices.

Trade retail value	£ 19,999
Auction value	£ 19,999
Average private trade value	£ 19,999

More info >



Owner history

For how long did the current and previous owner(s) have this FORD? How many owners did this FORD have? Check it in the premium report and see all owner registrations. Download the full report [here](#).

Owner	Registration
Owner	Registration
Owner	Registration
Owner	Registration
Owner	Registration
Owner	Registration
Owner	Registration

More info >

Plate changes

See in this check if this FORD had different number plates.

Number of plates	1
Current registration	XXXXXX
Plate since	2024-03-29
Current registration	XXXXXX
Plate since	2024-03-29

More info >



Finance check

Check if this FORD is financed, has an outstanding loan or finance agreement. If you are purchasing a vehicle it is smart to ensure that any finance that may have been taken out on this FORD has been settled.

If not, and you buy this FORD then you could lose the money and the car you paid for.

Download the premium report [here](#) and check if this FORD is financed.

Finance company	REDACTED	REDACTED
Date of agreement	REDACTED	REDACTED
Agreement type	REDACTED	REDACTED
Agreement term	REDACTED	REDACTED
Agreement number	REDACTED	REDACTED
Contact info	REDACTED	REDACTED

More info >



Mileage check

Odometer	In miles
Mileage registrations	12
First mileage registration	2009-07-08
Last registration	2020-03-17
Complete history	See info



Registration #1	2009-07-08	12 mi
Registration #2	2012-05-17	32.145 mi
Registration #3	2013-05-14	34.603 mi
Registration #4	2014-05-12	49.198 mi
Registration #5	2015-05-13	58.022 mi
Registration #6	2015-05-13	58.022 mi
Registration #7	2016-05-13	58.022 mi
Registration #8	2017-05-13	58.022 mi
Registration #9	2018-05-13	58.022 mi
Registration #10	2019-05-13	58.022 mi
Registration #11	2020-03-17	58.022 mi
Registration #12	2020-03-17	58.022 mi

More info >



Car features

The FORD factory car options list is only available in the premium report.

S0225	Air conditioning
S0295	
S0482	
S0501	
S0566	
S0567	
S0569	

View the complete FORD factory list for this vehicle [here](#).

More info >

Safety ratings

NCAP rating

Video [see crash video](#)



Dimensions & weight

Width	2022 mm
Height	1595 mm
Length	4333 mm
Wheel base	2640 mm
Kerb weight	1372 kg
Max. allowed weight	1855 kg

Additional information

Fuel tank capacity	53 l
Fuel delivery	Multi-Point Injection
Number of doors	5
Number of seats	5

Number of axles	2
Engine number	9G49373