





report date: 2024-03-28

General information

Make	KIA
Model	RIO 2
Colour	Red
Year of manufacture	2013
Top speed	107 mph
0 - 60 mph	12.6 seconds
Gearbox	5 speed Manual

Engine & fuel consumption

Power	83 BHP
Max. torque	121 Nm at 4.000 rpm
Engine capacity	1.248 сс
Cylinders	4
Fuel type	Petrol
Consumption city	44.8 mpg
Consumption extra urban	64.2 mpg
Consumption combined	55.4 mpg
CO2 emission	119 g/km
CO2 label	С



CarCheck.co.uk page 1/11



CU13VPP

report date: 2024-03-28

MOT history	Μ	OT	h	is	to	rv
-------------	---	----	---	----	----	----

Advice

MOT expiry date	2024-06-20
MOT pass rate	73 %
MOT passed	8
Failed MOT tests	3
Total advice items	9
Total items failed	4

MOT #11	2023-06-01 16:33
MOT test number	248239106799
Result	✓ Passed
Next expiry date	2024-06-20

MOT #10	2022-06-15 16:47
MOT test number	588151419020
Result	✓ Passed

MOT #9	2021-06-21 09:16
MOT test number	104087113261
Result	✓ Passed

MOT #8	2021-06-15 16:31
MOT test number	526427646293
Result	X Failed
Fail Nearside Front Position lamp not working (4.2.1 (a) (ii))	

Advice Nearside Front Tyre worn close to legal limit/worn on edge (5.2.3 (e))

Offside Front Tyre worn close to legal limit/worn on edge (5.2.3 (e))

CarCheck.co.uk page 2/11



MOT #7 2020-02-25 15:53

MOT test number 985539064399

Result ✓ Passed

Minor Nearside Front Lower Suspension arm ball joint dust cover severely deteriorated (5.3.4 (b) (i))

Advice Offside Rear Tyre slightly damaged/cracking or perishing (5.2.3 (d) (ii))

Minor Nearside Side repeater lens defective which has no effect on emitted light (4.4.1 (b) (i))

MOT #6 2019-03-02 09:48

MOT test number 504389981759

Result
✓ Passed

Advice Rear Brake pad(s) wearing thin (1.1.13 (a) (ii))

Advice Nearside Rear Tyre worn close to legal limit/worn on edge 3.0 mm - 195/55R16 (5.2.3 (e))

MOT #5 2019-03-02 09:48

MOT test number 446103121680

Result × Failed

Pass with rectification Nearside Headlamp aim too high (4.1.2 (a))

Advice Rear Brake pad(s) wearing thin (1.1.13 (a) (ii))

Pass with rectification Offside Headlamp aim too high (4.1.2 (a))

Advice Nearside Rear Tyre worn close to legal limit/worn on edge 3.0 mm - 195/55R16 (5.2.3 (e))

MOT #4 2018-03-12 15:47

MOT test number 330141415709

Result

Passed

MOT #3 2017-03-08 13:57

MOT test number 246545682307

Result \(\sqrt{Passed} \)

CarCheck.co.uk page 3/11



CU13VPP

report date: 2024-03-28

MOT #2 2016-03-21 16:25

MOT test number 235453351270

Result ✓ Passed

MOT #1 2016-03-21 16:25

MOT test number 120347608706

Result × Failed

Pass with rectification Front Tyre tread depth below requirements of 1.6mm Both (4.1.E.1)

CarCheck.co.uk page 4/11



Tax & MOT check



Tax status	Valid until 1 July
Days left	64
MOT expiry date	20 June 2024
Full MOT history	See MOT history

Tax calculation

Vehicle class	48
Band	С
Single payment (12 months)	£ 35,00,-
Single six month payment	Not applicable
Total payable by 12 monthly instalments	£ 36,75,-

CarCheck.co.uk page 5/11



Damage history

Check the damage history for this KIA. See if, where and when this KIA had damage and the car repair costs. We also check if this KIA was scrapped. Download the premium report <u>here</u> for the results.

Damage 1
Date
Category
Type
Damage 2
Date
Category
Type



Extra KIA salvage check



If this vehicle was seen at a salvage auction we offer: vehicle pictures, salvage location, retail value. Download the premium report <u>here</u> for more information.

More info >

CarCheck.co.uk page 6/11



Vehicle valuation

What is this car worth? See the vehicle value of this KIA in the premium report. We check: purchase value, age, mileage, MOT history, damages and online sale prices.

Trade retail value

Auction value

Average private trade value

More info >

CarCheck.co.uk page 7/11



Owner history

,	
For how long did the current and previous owner(s) have this KIA? How many owners did Check it in the premium report and see all owner registrations. Download the full report	

Plate changes	More info >
See in this check if this KIA had different number plates.	
Number of plates	,
Current registration	IK SIN
Plate since	
Current registration	NE NE
Plate since	
	More info

CarCheck.co.uk page 8/11



Finance check

Check if this KIA is financed, has an outstanding loan or finance agreement. If you are purchasing a vehicle it is smart to ensure that any finance that may have been taken out on this KIA has been settled.

If not, and you buy this KIA then you could lose the money and the car you paid for.

Download the premium report <u>here</u> and check if this KIA is financed.

Finance company	
Date of agreement	
Agreement type	
Agreement term	
Agreement number	
Contact info	

More info >

CarCheck.co.uk page 9/11



CU13VPP

report date: 2024-03-28

Mileage check

Odometer	In miles
Mileage registrations	12
First mileage registration	2013-03-21
Last registration	2023-06-01
Complete history	See info



Registration #1	2013-03-21	6 mi
Registration #2	2016-03-21	14.104 mi
Registration #3	2016-03-21	14.104 mi
Registration #4	2017-03-08	24.118 mi
Registration #5	2018-03-12	34.796 mi
Registration #6	2019-03-02	46.422 mi
Registration #7		91,777 esi
Registration #8		11.777 es
Registration #9		11.777 es
Registration #10		11.777 es
Registration #11		11.777 es
Registration #12		

More info >

CarCheck.co.uk page 10/11



Car features

S0225	Air conditioning
S0295	
50482	
50501	
50566	
60567	
50569	

Safety ratings

NCAP rating	****
Adult	92%
Children	84%
Pedestrian	46%
Safety systems	86%
Overall rating	81%
Video	see crash video



Dimensions & weight

Width	1720 mm
Height	1455 mm
Length	4045 mm
Wheel base	2570 mm
Kerb weight	1211 kg
Max. allowed weight	1560 kg

Additional information

Fuel tank capacity	43 I
Fuel delivery	Multi-Point Injection
Number of doors	5
Number of seats CarCheck.co.uk	5 page 11/11

Number of axles 2

Engine number G4LACP057661