



report date: 2024-03-28

General information

|                     |                |
|---------------------|----------------|
| Make                | SUZUKI         |
| Model               | SX4 SZ3        |
| Colour              | Silver         |
| Year of manufacture | 2013           |
| Top speed           | 115 mph        |
| 0 - 60 mph          | 10.7 seconds   |
| Gearbox             | 5 speed Manual |

Engine & fuel consumption

|                         |                     |
|-------------------------|---------------------|
| Power                   | 118 BHP             |
| Max. torque             | 156 Nm at 4.400 rpm |
| Engine capacity         | 1.586 cc            |
| Cylinders               | 4                   |
| Fuel type               | Petrol              |
| Consumption city        | 35.8 mpg            |
| Consumption extra urban | 55.4 mpg            |
| Consumption combined    | 45.6 mpg            |
| CO2 emission            | 141 g/km            |
| CO2 label               | F                   |





Internet history

Entry 1

|               |                             |
|---------------|-----------------------------|
| Date          | 2021-02-04                  |
| Pictures      | 10                          |
| Listing price | <a href="#">View report</a> |



source: [autoonline.co.uk](#)



## MOT history

|                    |            |
|--------------------|------------|
| MOT expiry date    | 2025-04-02 |
| MOT pass rate      | 64 %       |
| MOT passed         | 9          |
| Failed MOT tests   | 5          |
| Total advice items | 28         |
| Total items failed | 7          |

|                  |                  |
|------------------|------------------|
| MOT #14          | 2024-03-22 17:11 |
| MOT test number  | 587879215532     |
| Result           | ✓ Passed         |
| Next expiry date | 2025-04-02       |

|                 |                                                                                                                                                          |
|-----------------|----------------------------------------------------------------------------------------------------------------------------------------------------------|
| MOT #13         | 2024-03-21 09:28                                                                                                                                         |
| MOT test number | 166143546424                                                                                                                                             |
| Result          | ✗ Failed                                                                                                                                                 |
| Fail            | Offside Rear Service brake excessively binding (1.2.1 (f))                                                                                               |
| Advice          | Nearside Rear Service brake binding but not excessively (1.2.1 (f))                                                                                      |
| Fail            | Offside Front Track rod end ball joint dust cover excessively damaged or deteriorated so that it no longer prevents the ingress of dirt (2.1.3 (g) (ii)) |

|                 |                                                                                                       |
|-----------------|-------------------------------------------------------------------------------------------------------|
| MOT #12         | 2023-04-03 15:33                                                                                      |
| MOT test number | 902424682063                                                                                          |
| Result          | ✓ Passed                                                                                              |
| Advice          | Front Brake disc worn, pitted or scored, but not seriously weakened worn both sides (1.1.14 (a) (ii)) |
| Advice          | Offside Rear Service brake binding but not excessively (1.2.1 (f))                                    |
| Advice          | Front Brake pad(s) wearing thin both sides close to limit (1.1.13 (a) (ii))                           |
| Advice          | Nearside Rear Service brake binding but not excessively (1.2.1 (f))                                   |

**MOT #11**

2023-03-31 10:34

**MOT test number**

379795165530

**Result****✗ Failed**

**Advice** Front Brake disc worn, pitted or scored, but not seriously weakened worn both sides (1.1.14 (a) (ii))

**Advice** Offside Rear Service brake binding but not excessively (1.2.1 (f))

**Advice** Front Brake pad(s) wearing thin both sides close to limit (1.1.13 (a) (ii))

**Fail** Offside Front Anti-roll bar ball joint dust cover no longer prevents the ingress of dirt (5.3.4 (b) (ii))

**Advice** Nearside Rear Service brake binding but not excessively (1.2.1 (f))

**MOT #10**

2022-03-29 12:43

**MOT test number**

435892632583

**Result****✓ Passed**

**Advice** Rear Coil spring corroded both (5.3.1 (b) (i))

**Advice** Ubcc

**Advice** Nearside Rear Tyre slightly damaged/cracking or perishing (5.2.3 (d) (ii))

**Advice** Front Brake pad(s) wearing thin (1.1.13 (a) (ii))

**Advice** Wheel covers fitted obstructing view of components

**Advice** Brake disc worn, pitted or scored, but not seriously weakened all (1.1.14 (a) (ii))

**MOT #9**

2022-03-29 10:44

**MOT test number**

371001999764

**Result****✗ Failed****Advice**

Ubcc

**Advice**

Brake disc worn, pitted or scored, but not seriously weakened all (1.1.14 (a) (ii))

**Advice**

Rear Coil spring corroded both (5.3.1 (b) (i))

**Advice**

Wheel covers fitted obstructing view of components

**Advice**

Nearside Rear Tyre slightly damaged/cracking or perishing (5.2.3 (d) (ii))

**Advice**

Front Brake pad(s) wearing thin (1.1.13 (a) (ii))

**Fail**

Offside Front Suspension arm ball joint excessively worn (5.3.4 (a) (i))

**MOT #8**

2021-03-30 11:12

**MOT test number**

768559923204

**Result****✓ Passed****MOT #7**

2020-09-02 14:55

**MOT test number**

959865248868

**Result****✓ Passed****Advice**

Nearside Front Tyre worn close to legal limit/worn on edge (5.2.3 (e))

**MOT #6** 2020-09-01 13:00**MOT test number** 243335220516**Result** ✗ Failed**Minor** Nearside Front Suspension arm ball joint dust cover severely deteriorated (5.3.4 (b) (i))**Fail** Nearside Front Anti-roll bar linkage ball joint dust cover no longer prevents the ingress of dirt (5.3.4 (b) (ii))**Advice** Nearside Front Tyre worn close to legal limit/worn on edge (5.2.3 (e))**Minor** Offside Front Suspension arm ball joint dust cover severely deteriorated (5.3.4 (b) (i))**Fail** Offside Front Coil spring fractured or broken (5.3.1 (b) (i))**Advice** Front Brake pad(s) wearing thin (1.1.13 (a) (ii))**MOT #5** 2019-09-09 14:33**MOT test number** 222847555433**Result** ✓ Passed**MOT #4** 2019-09-06 09:31**MOT test number** 376919141285**Result** ✗ Failed**Fail** Nearside Front Coil spring fractured or broken (5.3.1 (b) (i))**Advice** Offside Front Tyre worn close to legal limit/worn on edge (5.2.3 (e))**MOT #3** 2018-09-18 10:58**MOT test number** 848131279069**Result** ✓ Passed**MOT #2** 2017-09-07 10:13**MOT test number** 357992051885**Result** ✓ Passed**Advice** Nearside Rear Shock absorber has a light misting of oil (2.7.3)



|                 |                  |
|-----------------|------------------|
| MOT #1          | 2016-09-08 15:16 |
| MOT test number | 546735699260     |
| Result          | ✓ Passed         |



Tax & MOT check

✓  
**Taxed**  
**Tax due:**  
1 April 2025

✓  
**MOT**  
**Expires:**  
2 April 2025

|                         |                                 |
|-------------------------|---------------------------------|
| <b>Tax status</b>       | Valid until 1 April             |
| <b>Days left</b>        | 337                             |
| <b>MOT expiry date</b>  | 2 April 2025                    |
| <b>Full MOT history</b> | <a href="#">See MOT history</a> |

Tax calculation

|                                                |            |
|------------------------------------------------|------------|
| <b>Vehicle class</b>                           | 48         |
| <b>Band</b>                                    | F          |
| <b>Single payment (12 months)</b>              | £ 200,00,- |
| <b>Single six month payment</b>                | £ 110,00,- |
| <b>Total payable by 12 monthly instalments</b> | £ 210,00,- |






Damage history

Check the damage history for this SUZUKI. See if, where and when this SUZUKI had damage and the car repair costs. We also check if this SUZUKI was scrapped. Download the premium report [here](#) for the results.

|          |  |  |
|----------|--|--|
| Damage 1 |  |  |
| Date     |  |  |
| Category |  |  |
| Type     |  |  |
| Damage 2 |  |  |
| Date     |  |  |
| Category |  |  |
| Type     |  |  |



Extra SUZUKI salvage check



If this vehicle was seen at a salvage auction we offer: vehicle pictures, salvage location, retail value. Download the premium report [here](#) for more information.

More info >



Vehicle valuation

What is this car worth? See the vehicle value of this SUZUKI in the premium report. We check: purchase value, age, mileage, MOT history, damages and online sale prices.

|                             |          |
|-----------------------------|----------|
| Trade retail value          | £ 19,999 |
| Auction value               | £ 19,999 |
| Average private trade value | £ 19,999 |

More info >



Owner history

For how long did the current and previous owner(s) have this SUZUKI? How many owners did this SUZUKI have? Check it in the premium report and see all owner registrations. Download the full report [here](#).

|       |              |
|-------|--------------|
| Owner | Registration |
| Owner | Registration |
| Owner | Registration |
| Owner | Registration |
| Owner | Registration |
| Owner | Registration |
| Owner | Registration |

More info >

Plate changes

See in this check if this SUZUKI had different number plates.

|                      |                |
|----------------------|----------------|
| Number of plates     | 1              |
| Current registration | <b>SA63CDF</b> |
| Plate since          | 2024-03-28     |
| Current registration | <b>SA63CDF</b> |
| Plate since          | 2024-03-28     |

More info >



Finance check

Check if this SUZUKI is financed, has an outstanding loan or finance agreement. If you are purchasing a vehicle it is smart to ensure that any finance that may have been taken out on this SUZUKI has been settled.

If not, and you buy this SUZUKI then you could lose the money and the car you paid for.

Download the premium report [here](#) and check if this SUZUKI is financed.

|                   |            |      |
|-------------------|------------|------|
| Finance company   | XXXXXXXXXX | XXXX |
| Date of agreement | XXXXXXXXXX | XXXX |
| Agreement type    | XXXXXXXXXX | XXXX |
| Agreement term    | XXXXXXXXXX | XXXX |
| Agreement number  | XXXXXXXXXX | XXXX |
| Contact info      | XXXXXXXXXX | XXXX |

More info >



Mileage check

|                            |                          |
|----------------------------|--------------------------|
| Odometer                   | In miles                 |
| Mileage registrations      | 16                       |
| First mileage registration | 2013-09-23               |
| Last registration          | 2024-03-22               |
| Complete history           | <a href="#">See info</a> |



|                  |            |           |
|------------------|------------|-----------|
| Registration #1  | 2013-09-23 | 27 mi     |
| Registration #2  | 2016-09-08 | 17.374 mi |
| Registration #3  | 2017-09-07 | 23.856 mi |
| Registration #4  | 2018-09-18 | 30.024 mi |
| Registration #5  | 2019-09-06 | 35.870 mi |
| Registration #6  | 2019-09-09 | 35.870 mi |
| Registration #7  | 2020-09-01 | 40.757 mi |
| Registration #8  | 2020-09-02 | 40.758 mi |
| Registration #9  | 2020-09-02 | 40.758 mi |
| Registration #10 | 2020-09-02 | 40.758 mi |
| Registration #11 | 2020-09-02 | 40.758 mi |
| Registration #12 | 2020-09-02 | 40.758 mi |
| Registration #13 | 2020-09-02 | 40.758 mi |
| Registration #14 | 2020-09-02 | 40.758 mi |
| Registration #15 | 2020-09-02 | 40.758 mi |
| Registration #16 | 2020-09-02 | 40.758 mi |

More info >



Safety ratings

|             |                                 |
|-------------|---------------------------------|
| NCAP rating | ★★★★☆                           |
| Video       | <a href="#">see crash video</a> |



Dimensions & weight

|                     |         |
|---------------------|---------|
| Width               | 1755 mm |
| Height              | 1620 mm |
| Length              | 4235 mm |
| Wheel base          | 2500 mm |
| Kerb weight         | 1240 kg |
| Max. allowed weight | 1650 kg |

Additional information

|                    |                       |
|--------------------|-----------------------|
| Fuel tank capacity | 50 l                  |
| Fuel delivery      | Multi-Point Injection |
| Number of doors    | 5                     |
| Number of seats    | 5                     |
| Engine number      | M16A-1674084          |