



General information

Make	VOLKSWAGEN
Model	FOX
Colour	Yellow
Year of manufacture	2010
Top speed	92 mph
0 - 60 mph	17.5 seconds
Gearbox	5 speed Manual

Engine & fuel consumption

Power	55 BHP
Max. torque	108 Nm at 3.000 rpm
Engine capacity	1.198 cc
Cylinders	3
Fuel type	Petrol
Consumption city	36.2 mpg
Consumption extra urban	55.4 mpg
Consumption combined	46.3 mpg
CO2 emission	139 g/km
CO2 label	E





Internet history

Entry 1

Date	2022-01-12
Pictures	10
Listing price	View report



source: cargurus.co.uk



MOT history

MOT expiry date	2024-12-12
MOT pass rate	73 %
MOT passed	11
Failed MOT tests	4
Total advice items	27
Total items failed	4

MOT #15	2023-12-04 13:12
MOT test number	269905745180
Result	✓ Passed
Next expiry date	2024-12-12

MOT #14	2022-11-24 12:57
MOT test number	532823103623
Result	✓ Passed
Minor	Windscreen damaged but not adversely affecting driver's view screen scratched through swept area but dont affect view of the road (3.2 (a) (i))

MOT #13	2022-11-24 10:23
MOT test number	976349888842
Result	✗ Failed
MAJOR	Offside Windscreen washer jets misaligned and not providing sufficient fluid to the windscreen (3.5 (a))
MAJOR	Offside Front Anti-roll bar linkage ball joint dust cover no longer prevents the ingress of dirt both (5.3.4 (b) (ii))
Minor	Windscreen damaged but not adversely affecting driver's view screen scratched through swept area but dont affect view of the road (3.2 (a) (i))

MOT #12	2021-12-06 15:53
MOT test number	759107505726
Result	✓ Passed
Minor	Offside Front Anti-roll bar linkage ball joint dust cover severely deteriorated (5.3.4 (b) (i))



MOT #11	2020-11-23 13:05
MOT test number	844505533430
Result	✓ Passed
Minor	Offside Front Anti-roll bar linkage ball joint dust cover severely deteriorated (5.3.4 (b) (i))

MOT #10	2020-11-23 13:05
MOT test number	870269062196
Result	✗ Failed
Minor	Offside Front Anti-roll bar linkage ball joint dust cover severely deteriorated (5.3.4 (b) (i))
Pass with rectification	Offside Front Windscreen wiper does not clear the windscreen effectively (3.4 (b) (ii))
Pass with rectification	Nearside Front Windscreen wiper does not clear the windscreen effectively (3.4 (b) (ii))

MOT #9	2019-05-18 10:33
MOT test number	600667331813
Result	✓ Passed
Advice	Rear Rear disc pads wearing liw

MOT #8	2018-06-13 09:17
MOT test number	730605195066
Result	✓ Passed
Advice	Offside Front Tyre worn close to legal limit/worn on edge (5.2.3 (e))
Advice	Offside Rear Tyre slightly damaged/cracking or perishing (5.2.3 (d) (i))
Advice	Nearside Front Tyre worn close to legal limit/worn on edge (5.2.3 (e))
Advice	Nearside Rear Tyre slightly damaged/cracking or perishing (5.2.3 (d) (i))



MOT #7	2018-06-12 11:29
MOT test number	645129747621
Result	✗ Failed
Advice	Offside Rear Tyre slightly damaged/cracking or perishing (5.2.3 (d) (i))
Advice	Nearside Front Tyre worn close to legal limit/worn on edge (5.2.3 (e))
Advice	Nearside Rear Tyre slightly damaged/cracking or perishing (5.2.3 (d) (i))
DANGEROUS	Nearside Stop lamp(s) all not working (4.3.1 (a) (iii))
Advice	Offside Front Tyre worn close to legal limit/worn on edge (5.2.3 (e))

MOT #6	2017-04-28 16:03
MOT test number	107962166222
Result	✓ Passed
Advice	Nearside Rear Tyre cracking on sidewall
Advice	Nearside Rear Tyre has nail in tread
Advice	Offside Rear Tyre cracking on sidewall

MOT #5	2016-04-25 12:04
MOT test number	865129189814
Result	✓ Passed
Advice	Offside Front Suspension arm rubber bush deteriorated but not resulting in excessive movement (2.4.G.2)
Advice	Nearside Front Suspension arm rubber bush deteriorated but not resulting in excessive movement (2.4.G.2)

MOT #4	2015-05-05 14:56
MOT test number	457985925145
Result	✓ Passed
Notice	Offside rear tyre starting to crack
Notice	Items removed from driver's view prior to test



MOT #3 2015-05-05 14:56

MOT test number 349315225116

Result ✗ Failed

Notice Offside rear tyre starting to crack

Pass with rectification Offside Front Windscreen wiper does not clear the windscreen effectively (8.2.2)

Pass with rectification Nearside Front Windscreen washer provides insufficient washer liquid (8.2.3)

Notice Items removed from driver's view prior to test

MOT #2 2014-04-09 14:25

MOT test number 656929494026

Result ✓ Passed

MOT #1 2013-04-15 16:42

MOT test number 747095803122

Result ✓ Passed

Notice Windscreen scatched.



Tax & MOT check

✓
Taxed
Tax due:
1 March 2025

✓
MOT
Expires:
12 December 2024

Tax status	Valid until 1 March
Days left	306
MOT expiry date	12 December 2024
Full MOT history	See MOT history

Tax calculation

Vehicle class	48
Band	E
Single payment (12 months)	£ 180,00,-
Single six month payment	£ 99,00,-
Total payable by 12 monthly instalments	£ 189,00,-



Damage history

Check the damage history for this VOLKSWAGEN. See if, where and when this VOLKSWAGEN had damage and the car repair costs. We also check if this VOLKSWAGEN was scrapped. Download the premium report [here](#) for the results.

Damage 1

Date	
Category	
Type	

Damage 2

Date	
Category	
Type	



Extra VOLKSWAGEN salvage check



If this vehicle was seen at a salvage auction we offer: vehicle pictures, salvage location, retail value. Download the premium report [here](#) for more information.

More info >



Vehicle valuation

What is this car worth? See the vehicle value of this VOLKSWAGEN in the premium report. We check: purchase value, age, mileage, MOT history, damages and online sale prices.

Trade retail value	£ 10,000
Auction value	£ 10,000
Average private trade value	£ 10,000

More info >



Owner history

For how long did the current and previous owner(s) have this VOLKSWAGEN? How many owners did this VOLKSWAGEN have? Check it in the premium report and see all owner registrations. Download the full report [here](#).

Owner	Registration
Owner	Registration
Owner	Registration
Owner	Registration
Owner	Registration
Owner	Registration
Owner	Registration

More info >

Plate changes

See in this check if this VOLKSWAGEN had different number plates.

Number of plates	1
Current registration	 KP10WNY
Plate since	2024-03-29
Current registration	 KP10WNY
Plate since	2024-03-29

More info >



Finance check

Check if this VOLKSWAGEN is financed, has an outstanding loan or finance agreement. If you are purchasing a vehicle it is smart to ensure that any finance that may have been taken out on this VOLKSWAGEN has been settled.

If not, and you buy this VOLKSWAGEN then you could lose the money and the car you paid for.

Download the premium report [here](#) and check if this VOLKSWAGEN is financed.

Finance company	XXXXXXXX	XXXX
Date of agreement	XXXXXXXX	XXXX
Agreement type	XXXXXXXX	XXXX
Agreement term	XXXXXXXX	XXXX
Agreement number	XXXXXXXX	XXXX
Contact info	XXXXXXXX	XXXX

More info >



Mileage check

Odometer	In miles
Mileage registrations	16
First mileage registration	2010-04-28
Last registration	2023-12-04
Complete history	See info



Registration #1	2010-04-28	7 mi
Registration #2	2013-04-15	15.923 mi
Registration #3	2014-04-09	24.606 mi
Registration #4	2015-05-05	35.530 mi
Registration #5	2016-04-25	38.770 mi
Registration #6	2017-04-28	40.290 mi
Registration #7	2018-06-12	47.489 mi
Registration #8	2018-06-13	47.490 mi
Registration #9	2019-06-20	55.557 mi
Registration #10	2019-06-20	55.557 mi
Registration #11	2019-06-20	55.557 mi
Registration #12	2019-06-20	55.557 mi
Registration #13	2019-06-20	55.557 mi
Registration #14	2019-06-20	55.557 mi
Registration #15	2019-06-20	55.557 mi
Registration #16	2019-06-20	55.557 mi

More info >



Car features

The VOLKSWAGEN factory car options list is only available in the premium report.

S0225	Air conditioning
S0295	
S0482	
S0501	
S0566	
S0567	
S0569	

View the complete VOLKSWAGEN factory list for this vehicle [here](#).

More info >

Safety ratings

NCAP rating ★★★★★

Video [see crash video](#)



Dimensions & weight

Width	1660 mm
Height	1544 mm
Length	3828 mm
Wheel base	2465 mm
Kerb weight	1069 kg
Max. allowed weight	1480 kg

Additional information

Fuel tank capacity	50 l
Fuel delivery	Multi-Point Injection
Number of doors	3

Number of seats	4
Number of axles	2
Engine number	CHF 058721