



RENAULT




report date: 2024-03-28

General information

Make	RENAULT
Model	KANGOO EXPRESSION 16V
Colour	Red
Year of manufacture	2005
Top speed	101 mph
0 - 60 mph	12.4 seconds
Gearbox	4 speed automatic

Engine & fuel consumption

Power	95 BHP
Max. torque	148 Nm at 3.750 rpm
Engine capacity	1.598 cc
Cylinders	4
Fuel type	Petrol
Consumption city	25.7 mpg
Consumption extra urban	44.8 mpg
Consumption combined	35.3 mpg
CO2 emission	190 g/km
CO2 label	J





Internet history

Entry 1

Date	2021-08-27
Pictures	21
Listing price	View report



source: [autotrader.co.uk](https://www.autotrader.co.uk)



MOT history

MOT expiry date	2024-08-27
MOT pass rate	63 %
MOT passed	15
Failed MOT tests	9
Total advice items	43
Total items failed	11

MOT #24	2023-08-27 14:36
MOT test number	283494031787
Result	✓ Passed
Next expiry date	2024-08-27

MOT #23	2023-08-27 14:11
MOT test number	933877929292
Result	✗ Failed

- Minor

Offside Registration plate lamp inoperative in the case of multiple lamps or light sources (4.7.1 (b) (i))
- MAJOR

Rear Exhaust silencer insecure (8.1.1 (b) (i))
- Advice

Rear exhaust heat shield insecure
- MAJOR

Nearside Track rod end ball joint has excessive play (2.1.3 (b) (i))
- MAJOR

Offside Steering rack gaiter missing or no longer prevents the ingress of dirt (2.1.3 (g) (ii))
- MAJOR

Windscreen washer not working (3.5 (a))
- MAJOR

Nearside Steering rack gaiter missing or no longer prevents the ingress of dirt (2.1.3 (g) (ii))

**MOT #22**

2022-08-27 14:38

MOT test number

361188697203

Result

✓ Passed

Minor

Offside Front Steering rack gaiter damaged or deteriorated, but preventing the ingress of dirt (2.1.3 (g) (i))

Advice

Offside Front Outer Tyre worn close to legal limit/worn on edge edge (5.2.3 (e))

Advice

Offside Front Shock absorbers has light misting of oil (5.3.2 (b))

Minor

Nearside Front Steering rack gaiter damaged or deteriorated, but preventing the ingress of dirt (2.1.3 (g) (i))

MOT #21

2021-08-28 13:02

MOT test number

692676064569

Result

✓ Passed

MOT #20

2020-11-04 09:51

MOT test number

349917920257

Result

✓ Passed

Advice

Nearside Front Outer Tyre has a cut but not deep enough to reach the ply or cords side wall (5.2.3 (d) (i))

Minor

Offside Front Lower Windscreen damaged but not adversely affecting driver's view small chip (3.2 (a) (i))

MOT #19

2020-11-04 09:51

MOT test number

544318651270

Result

✗ Failed

Pass with rectification

Offside Front Headlamp aim too high (4.1.2 (a))

Advice

Nearside Front Outer Tyre has a cut but not deep enough to reach the ply or cords side wall (5.2.3 (d) (i))

Minor

Offside Front Lower Windscreen damaged but not adversely affecting driver's view small chip (3.2 (a) (i))



MOT #18	2019-10-14 14:06
MOT test number	188769939039
Result	✓ Passed
Advice	Front ABS rings rusty

MOT #17	2019-10-14 09:25
MOT test number	747902203020
Result	✗ Failed
Advice	Power steering component has slight seepage from a component pressure switch (2.1.5 (a))
Advice	Oil leak, but not excessive (8.4.1 (a) (i))
MAJOR	Offside Front Suspension component ball joint dust cover no longer prevents the ingress of dirt (5.3.4 (b) (ii))
Advice	Front ABS rings rusty

MOT #16	2018-10-26 11:30
MOT test number	329656282058
Result	✓ Passed
Advice	Nearside Front Outer Tyre worn close to legal limit/worn on edge (5.2.3 (e))
Advice	Offside Front Upper Top mount has slight play
Advice	Offside Front Tyre worn close to legal limit/worn on edge Inner + Outer edge (5.2.3 (e))
Advice	Nearside Rear Outer Tyre worn close to legal limit/worn on edge (5.2.3 (e))

**MOT #15**

2018-10-26 08:13

MOT test number

138578235974

Result**✗ Failed**

Minor Offside Registration plate lamp inoperative in the case of multiple lamps or light sources (4.7.1 (b) (i))

Advice Brake fluid close to minimum mark (1.1.10 (d) (ii))

Advice Nearside Front Outer Tyre worn close to legal limit/worn on edge (5.2.3 (e))

Advice Offside Front Tyre worn close to legal limit/worn on edge Inner + Outer edge (5.2.3 (e))

Advice Offside Front Upper Top mount has slight play

MAJOR Rear Exhaust system insecure (6.1.2 (a))

Advice Nearside Rear Outer Tyre worn close to legal limit/worn on edge (5.2.3 (e))

MOT #14

2017-10-25 16:33

MOT test number

189303662725

Result**✓ Passed**

Advice Nearside Front Macpherson strut corroded but not seriously weakened (2.4.G.1)

Advice Windscreen has damage to an area less than a 10mm circle within zone 'A' (8.3.1a)

Advice Offside Front Macpherson strut corroded but not seriously weakened (2.4.G.1)

**MOT #13**

2017-10-25 10:25

MOT test number

799172365854

Result

✗ Failed

Fail Nearside Front Steering rack gaiter split (2.2.D.2d)**Advice** Offside Front Macpherson strut corroded but not seriously weakened (2.4.G.1)**Fail** Offside Front Windscreen wiper does not clear the windscreen effectively (8.2.2)**Advice** Offside Front Play in steering rack inner joint(s)**Advice** Nearside Front Macpherson strut corroded but not seriously weakened (2.4.G.1)**Advice** Windscreen has damage to an area less than a 10mm circle within zone 'A' (8.3.1a)**Fail** Nearside Rear Registration plate lamp not working (1.1.C.1d)**MOT #12**

2016-11-03 15:00

MOT test number

385893570213

Result

✓ Passed

Advice Oil leak**MOT #11**

2016-11-03 09:49

MOT test number

174971486151

Result

✗ Failed

Fail Offside Rear rear brake binding (3.7.B.1)**Advice** Oil leak**MOT #10**

2015-10-29 11:25

MOT test number

616233296477

Result

✓ Passed

Advice Front Brake pad(s) wearing thin (3.5.1g)**Advice** Play in inner rack joints

**MOT #9** 2014-10-24 13:26**MOT test number** 447137394235**Result** ✓ Passed**MOT #8** 2013-10-29 15:08**MOT test number** 939962903301**Result** ✓ Passed**MOT #7** 2013-10-29 10:54**MOT test number** 975162303369**Result** ✗ Failed**Fail** Rear Exhaust system not adequately supported (7.1.1)**Fail** Offside Rear Seat belt locking mechanism does not secure or release (5.2.5a)**Advice** Front Tyre worn close to the legal limit (4.1.E.1)**MOT #6** 2012-11-02 10:38**MOT test number** 478277502365**Result** ✓ Passed**MOT #5** 2012-10-31 17:06**MOT test number** 947515702378**Result** ✗ Failed**Fail** Nearside Front constant velocity joint gaiter insecure to the extent that it no longer prevents the ingress of dirt etc (2.5.C.1a)**MOT #4** 2012-02-07 15:03**MOT test number** 835168232082**Result** ✓ Passed



MOT #3	2011-02-16 10:53
MOT test number	978267541025
Result	✓ Passed
MOT #2	2008-10-08 10:54
MOT test number	844432688241
Result	✓ Passed
MOT #1	2008-10-07 11:48
MOT test number	672231888227
Result	✗ Failed
Fail	Offside Front Brake pad(s) less than 1.5 mm thick (3.5.1g)
Fail	Offside Front Seat belt has a cut which has significantly weakened the webbing (5.2.2a)
Fail	Brakes imbalanced across an axle (3.7.B.5b)



Tax & MOT check

✓
Taxed
Tax due:
1 September 2024

✓
MOT
Expires:
27 August 2024

Tax status	Valid until 1 September
Days left	126
MOT expiry date	27 August 2024
Full MOT history	See MOT history

Tax calculation

Vehicle class	48
Band	J
Single payment (12 months)	£ 365,00,-
Single six month payment	£ 200,75,-
Total payable by 12 monthly instalments	£ 383,25,-



Damage history

Check the damage history for this RENAULT. See if, where and when this RENAULT had damage and the car repair costs. We also check if this RENAULT was scrapped. Download the premium report [here](#) for the results.

Damage 1

Date	
Category	
Type	

Damage 2

Date	
Category	
Type	



Extra RENAULT salvage check



If this vehicle was seen at a salvage auction we offer: vehicle pictures, salvage location, retail value. Download the premium report [here](#) for more information.

More info >



Vehicle valuation

What is this car worth? See the vehicle value of this RENAULT in the premium report. We check: purchase value, age, mileage, MOT history, damages and online sale prices.

Trade retail value	£ 15,200
Auction value	£ 15,200
Average private trade value	£ 15,200

More info >



Owner history

For how long did the current and previous owner(s) have this RENAULT? How many owners did this RENAULT have? Check it in the premium report and see all owner registrations. Download the full report [here](#).

Owner	Since
Owner	Since
Owner	Since
Owner	Since
Owner	Since
Owner	Since
Owner	Since

More info >

Plate changes

See in this check if this RENAULT had different number plates.

Number of plates	1
Current registration	SH55EXW
Plate since	2019-09-28
Current registration	SH55EXW
Plate since	2019-09-28

More info >



Finance check

Check if this RENAULT is financed, has an outstanding loan or finance agreement. If you are purchasing a vehicle it is smart to ensure that any finance that may have been taken out on this RENAULT has been settled.

If not, and you buy this RENAULT then you could lose the money and the car you paid for.

Download the premium report [here](#) and check if this RENAULT is financed.

Finance company	RENAULT FINANCE
Date of agreement	01/01/2024
Agreement type	FINANCE
Agreement term	36 months
Agreement number	123456789
Contact info	0123 456789

More info >



Mileage check

Odometer	In miles
Mileage registrations	26
First mileage registration	2005-11-17
Last registration	2023-08-27
Complete history	See info



Registration #1	2005-11-17	20 mi
Registration #2	2008-10-07	36.522 mi
Registration #3	2008-10-08	36.522 mi
Registration #4	2011-02-16	39.141 mi
Registration #5	2012-02-07	40.982 mi
Registration #6	2012-10-31	43.127 mi
Registration #7	2012-11-02	43.127 mi
Registration #8	2013-10-29	53.263 mi
Registration #9	2013-10-29	53.263 mi
Registration #10	2014-10-24	62.915 mi
Registration #11	2015-10-29	66.252 mi
Registration #12	2016-11-03	68.033 mi
Registration #13	2016-11-03	68.036 mi
Registration #14	2016-11-03	68.036 mi
Registration #15	2016-11-03	68.036 mi
Registration #16	2016-11-03	68.036 mi
Registration #17	2016-11-03	68.036 mi
Registration #18	2016-11-03	68.036 mi
Registration #19	2016-11-03	68.036 mi
Registration #20	2016-11-03	68.036 mi
Registration #21	2016-11-03	68.036 mi
Registration #22	2016-11-03	68.036 mi
Registration #23	2016-11-03	68.036 mi
Registration #24	2016-11-03	68.036 mi
Registration #25	2016-11-03	68.036 mi
Registration #26	2016-11-03	68.036 mi

More info >



Car features

The RENAULT factory car options list is only available in the premium report.

S0225	Air conditioning
S0295	
S0482	
S0501	
S0566	
S0567	
S0569	

View the complete RENAULT factory list for this vehicle [here](#).

More info >

Safety ratings

NCAP rating



Video

[see crash video](#)



Dimensions & weight

Width	1672 mm
Height	1855 mm
Length	4035 mm
Wheel base	2600 mm
Kerb weight	1120 kg
Max. allowed weight	1645 kg

Additional information

Fuel tank capacity	50 l
Fuel delivery	Multi-Point Injection
Number of doors	5
Number of seats	5

Number of axles	2
Engine number	D011141