



LM6IEHT

report date: 2024-03-29

General information

Make	VOLKSWAGEN
Model	TOURAN S TDI
Colour	Blue
Year of manufacture	2011
Top speed	114 mph
0 - 100 km/h	12.8 seconds
0 - 60 mph	12.8 seconds
Gearbox	6 speed Manual

Engine & fuel consumption

Power	77 kW / 105 HP / 106 BHP
Max. torque	250 Nm at 1.500 rpm
Engine capacity	1.598 cc
Cylinders	4
Fuel type	Diesel
Consumption city	44.8 mpg
Consumption extra urban	62.8 mpg
Consumption combined	6.3 mpg
CO2 emission	134 g/km
CO2 label	E





Internet history

Entry 5

Date	2023-12-05
Pictures	0
Listing price	View report

source: carcraft.co.uk

Entry 4


Date	2023-10-22
Pictures	10
Listing price	View report



source: cargurus.co.uk

Entry 3

Date	2021-12-03
Pictures	12
Listing price	View report



source: cargurus.co.uk

Entry 2

Date	2021-09-26
Pictures	1
Listing price	View report



source: [cargurus.co.uk](https://www.cargurus.co.uk)

Entry 1

Date	2021-09-25
Pictures	1
Listing price	View report



source: [autotrader.co.uk](https://www.autotrader.co.uk)



MOT history

MOT expiry date	2024-10-26
MOT pass rate	85 %
MOT passed	11
Failed MOT tests	2
Total advice items	14
Total items failed	2

MOT #13	2023-10-27 14:41
MOT test number	190585354442
Result	✓ Passed
Next expiry date	2024-10-26

MOT #12	2022-11-22 09:00
MOT test number	261653813465
Result	✓ Passed
Advice	Offside Rear Brake disc worn, pitted or scored, but not seriously weakened (1.1.14 (a) (ii))

MOT #11	2021-12-01 16:16
MOT test number	837519904709
Result	✓ Passed
Advice	Offside Rear Brake disc worn, pitted or scored, but not seriously weakened (1.1.14 (a) (ii))

**MOT #10**

2021-05-21 08:08

MOT test number

353384227384

Result

✓ Passed

Advice Nearside Rear Coil spring corroded (5.3.1 (b) (i))**Advice** Nearside Rear Tyre slightly damaged/cracking or perishing (5.2.3 (d) (ii))**Advice** Offside Rear Brake disc worn, pitted or scored, but not seriously weakened (1.1.14 (a) (ii))**Advice** Offside Rear Tyre slightly damaged/cracking or perishing (5.2.3 (d) (ii))**MOT #9**

2020-06-12 10:55

MOT test number

910472948415

Result

✓ Passed

Advice Offside Rear Brake disc worn, but not excessively (1.1.14 (a) (i))**Advice** Nearside Rear Coil spring corroded (5.3.1 (b) (i))**MOT #8**

2020-06-12 07:54

MOT test number

505214797192

Result

✗ Failed

Fail Nearside Rear Suspension levelling valve damaged or deteriorated and function affected rod broken (5.3.5 (b) (i))**Advice** Offside Rear Brake disc worn, but not excessively (1.1.14 (a) (i))**Advice** Nearside Rear Coil spring corroded (5.3.1 (b) (i))**MOT #7**

2019-04-26 09:54

MOT test number

895514741747

Result

✓ Passed

**MOT #6** 2018-05-04 11:05**MOT test number** 140254168038**Result** ✓ Passed**Advice** Nearside Rear Shock absorber has a light misting of oil (2.7.3)**Advice** Offside Rear Shock absorber has a light misting of oil (2.7.3)**MOT #5** 2018-05-04 09:34**MOT test number** 828664975476**Result** ✗ Failed**Advice** Nearside Rear Shock absorber has a light misting of oil (2.7.3)**Fail** Offside Rear coil spring broken (2.4.C.1a)**Advice** Offside Rear Shock absorber has a light misting of oil (2.7.3)**MOT #4** 2017-05-09 11:33**MOT test number** 162909128389**Result** ✓ Passed**MOT #3** 2016-05-23 08:15**MOT test number** 806364187696**Result** ✓ Passed**MOT #2** 2015-08-08 10:36**MOT test number** 317970725429**Result** ✓ Passed**MOT #1** 2014-09-30 17:11**MOT test number** 736173974223**Result** ✓ Passed



Tax & MOT check

✓
Taxed
Tax due:
1 January 2025

✓
MOT
Expires:
26 October 2024

Tax status	Valid until 1 January
Days left	246
MOT expiry date	26 October 2024
Full MOT history	See MOT history

Tax calculation

Vehicle class	49
Band	E
Single payment (12 months)	£ 180,00,-
Single six month payment	£ 99,00,-
Total payable by 12 monthly instalments	£ 189,00,-



Damage history

Check the damage history for this VOLKSWAGEN. See if, where and when this VOLKSWAGEN had damage and the car repair costs. We also check if this VOLKSWAGEN was scrapped. Download the premium report [here](#) for the results.

Damage 1

Date	
Category	
Type	

Damage 2

Date	
Category	
Type	



Extra VOLKSWAGEN salvage check



If this vehicle was seen at a salvage auction we offer: vehicle pictures, salvage location, retail value. Download the premium report [here](#) for more information.

More info >



Vehicle valuation

What is this car worth? See the vehicle value of this VOLKSWAGEN in the premium report. We check: purchase value, age, mileage, MOT history, damages and online sale prices.

Trade retail value	£ 19,999
Auction value	£ 19,999
Average private trade value	£ 19,999

More info >



Owner history

For how long did the current and previous owner(s) have this VOLKSWAGEN? How many owners did this VOLKSWAGEN have? Check it in the premium report and see all owner registrations. Download the full report [here](#).

Owner	Registration
Owner	Registration
Owner	Registration
Owner	Registration
Owner	Registration
Owner	Registration
Owner	Registration

More info >

Plate changes

See in this check if this VOLKSWAGEN had different number plates.

Number of plates	1
Current registration	 LM61EHT
Plate since	2020-03-29
Current registration	 LM61EHT
Plate since	2020-03-29

More info >



Finance check

Check if this VOLKSWAGEN is financed, has an outstanding loan or finance agreement. If you are purchasing a vehicle it is smart to ensure that any finance that may have been taken out on this VOLKSWAGEN has been settled.

If not, and you buy this VOLKSWAGEN then you could lose the money and the car you paid for.

Download the premium report [here](#) and check if this VOLKSWAGEN is financed.

Finance company	XXXXXXXX	XXXX
Date of agreement	XXXXXXXX	XXXX
Agreement type	XXXXXXXX	XXXX
Agreement term	XXXXXXXX	XXXX
Agreement number	XXXXXXXX	XXXX
Contact info	XXXXXXXX	XXXX

More info >



Mileage check

Odometer	In miles
Mileage registrations	19
First mileage registration	2011-12-08
Last registration	2023-10-27
Complete history	See info



Registration #1	2011-12-08	14 mi
Registration #2	2014-09-30	11.789 mi
Registration #3	2015-08-08	16.007 mi
Registration #4	2016-05-23	18.297 mi
Registration #5	2017-05-09	23.066 mi
Registration #6	2018-05-04	29.380 mi
Registration #7	2018-05-04	29.380 mi
Registration #8	2019-04-26	35.086 mi
Registration #9	2020-06-12	39.836 mi
Registration #10	2020-06-12	39.836 mi
Registration #11	2020-06-12	39.836 mi
Registration #12	2020-06-12	39.836 mi
Registration #13	2020-06-12	39.836 mi
Registration #14	2020-06-12	39.836 mi
Registration #15	2020-06-12	39.836 mi
Registration #16	2020-06-12	39.836 mi
Registration #17	2020-06-12	39.836 mi
Registration #18	2020-06-12	39.836 mi
Registration #19	2020-06-12	39.836 mi

More info >



Car features

The VOLKSWAGEN factory car options list is only available in the premium report.

S0225	Air conditioning
S0295	
S0482	
S0501	
S0566	
S0567	
S0569	

View the complete VOLKSWAGEN factory list for this vehicle [here](#).

More info >

Safety ratings

NCAP rating ★★★★★

Video [see crash video](#)



Dimensions & weight

Width	1794 mm
Height	1634 mm
Length	4397 mm
Wheel base	2678 mm
Kerb weight	1539 kg

Additional information

Fuel tank capacity	60 l
Fuel delivery	Direct Injection
Number of doors	5
Number of seats	7

Number of axles

2

Engine number

CAY 586764